EquipmentName	Workshop	CodeAndSubCode	Description	CompletionComments	DateDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
LOAD08	Wodonga - Workshop	Body\FUEL TANK	Fuel tank	Removed fuel tank & V bracket from loader	24/07/2019	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR		Wodonga Workshop	LOADER
LOAD08	Wodonga - Workshop	Body\TRL DOORS	repair door cable holder	repair door catch for when doors are open	08/03/2018	Fault	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR		Wodonga Workshop	LOADER
LOAD08	Myrtleford - Workshop	Tyres\TP07	Job Added From Invoice		21/01/2017	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR		Myrtleford Workshop	LOADER
LOAD08	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice		11/08/2016	Repair	Completed	Greenfreight Logging NSW	LOADVOLVO	Rosewood	ALR		Wodonga Workshop	LOADER