EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	HourDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
LOAD18	Myrtleford - Workshop	Insp\ANN INSP	Insp\ANN INSP annual inspection as per check list	Insp\ANN INSP	KLM AT TIME OF INSPECTION 489090 KLM AT TIME OF SERVICE 489090 REPAIRED LOWER R/H PIN COVER	23/06/2026	489090	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	VehService\AS A Service CHECK AND REPAIR DRIVERS WINDOW NOT GOING UP OR DOWN REPAIR CRACKS IN DRIVERS DOOR	VehService\AS	REPAIRED AND TESTED POWER STEERING LEAK AT STEERING BOX	22/06/2026	489090	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\MOUNTS	KLM AT TIME OF REPAIR 488434			16/01/2026	484760	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\COMPRESSOR	REPLACE AIR COMPRESSOR & GASKETS		KLM AT TIME OF REPLACEMENT 488032	19/11/2025	484760	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	MULTISPARES LTD - 3	LOADER
LOAD18	Myrtleford - Workshop	Engine\EXHAUST	CHECK OVER FLUIDS AND LEVELS TIGHTEN EXH CLAMP AT TURBO FIT SECOND HAND RHR SPRING PACK OUT OF WHITE NL12 VOLVO OUT THE BACK			10/10/2025	486760	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Susp\SPRING PACK	REPLACE RHR SPRING TRUNNION HOHUSING BUSHES & SEALS			17/06/2025	482230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\FUEL TANK	CHECK & CLEAN FUEL PICK UP IN LH FUEL TANK & CHECK ALL FUEL PIPES & HOSES & BANGO FITTINGS FOR FUEL FLOW			29/05/2025	482230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	VehService\AS	VehService\AS	KLM at time of service 486978	22/05/2025	482230	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Insp\ANN INSP	Annual inspection	Insp\ANN INSP	KLM at time of inspection 486978	22/05/2025	482230	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			14/03/2025	482230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	BEAUREPAIRES	LOADER
LOAD18	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4			14/03/2025	482230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	BEAUREPAIRES	LOADER
LOAD18	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			14/03/2025	482230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	BEAUREPAIRES	LOADER
LOAD18	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			14/03/2025	482230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	BEAUREPAIRES	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	interior light falling down refit to roof		KLM at time of repair 484708	05/02/2025	482230	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\LIGHTS	head lights to be lowed to high on low beam		KLM at time of repair 484708	05/02/2025	482230	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	VehService\AS CHECK FOR HARD STARTING FAULT. ISOLATE AND LOAD TEST BATTERIES. BOTH FINE. CHECK POWER FEEDS AND CONNECTIONS. DIAGNOSE BAD EARTH AS PROBLEM SUPPLY, FIT AND WIRE UP NEW EARTH STRAP.	VehService\AS		19/11/2024	482230	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\START MOTR	START AND TEST OK. FIT VOLVO PASSANGER SEAT RE LOCATE POWDER FIRE EXTINGUISER IN CAB			16/11/2024	482230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	MYRTLEFORD AUTO ELECTRICS - 3	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\SEAT	WASH HYD OIL OFF WINDSCREEN			30/10/2024	482230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\ELECT P&W	supply & fit seat belt & park brake alams also supply new seat belt with switch *L18 *Head lights issue *LH no low beam- RH no high beam **Park break / seatbelt alarm fault? Inspect operation of headlights, r/h side not working at all. remove guard of back of headlight and inspect, found light unplugged and inside of housing broken off adjuster, advise light needs to be replaced. Inspect operation of handbrake alarm, found horn disconnected, plug in and test. Hand brake alarm still not functioning, no power getting to horn, remove relay and test. all powers and earths good, diagnose faulty relay. replace relay and test. power getting to horn but horn faulty, relace horn and test. Hand brake alarm now working. Remove driver side headlight and fit new one, fit led globes and align headlight.			21/10/2024	481488	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	ARKON AUTO ELECTRICAL - 3	LOADER
LOAD18	Albury - Workshop	Elect\HEAD LIGHT	check all lights. all lights operational.			24/07/2024	481488	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	ARKON AUTO ELECTRICAL - 4	LOADER
LOAD18	Wodonga - Workshop	Elect\DAY LIGHTS	FIT DRLS AND WIRE UP.			05/07/2024	481488	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	Insp\INT INSP	CHECKED OVER. FUEL PROBLEM. REMOVED, CLEANED AND FITTED TANK PICK UP WITH NEW O-RING. TESTED. REPLACED FUEL FILTERS. REMOVED SUCTION PIPE AND REPLACED SUCTION FILTER.			13/06/2024	481075	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	Engine\FUEL TANK	TESTED. SUPPLY FUEL TANK PICK UP STRAINER & O RING			05/06/2024	1	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\FUEL TANK	& SEAT BELT CATCH			09/05/2024	1.4	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	CMV TRUCK AND BUS PTY LTD - 3	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\DOOR LOCK	REPLACED BAILEY CHANNEL WITH ONE FROM WREAK.			28/03/2024	480790	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Wodonga - Workshop	Engine\ALT2 DR	LOCKED ENGINE FAN. REPLACED ALTERNATOR.			19/03/2024	430683	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	Cooling\RADIATOR	over heating		check charging rate,	09/03/2024	480773	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	Elect\ALT2 DR	Alternator		R&R alternator fit 2nd hand alternator & test	08/03/2024	480699	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Myrtleford - Workshop	Hydraulics\RAM	Ram			01/02/2024	481075	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Albury Workshop	LOADER
LOAD18	Wodonga - Workshop	DrivLine\CLUTCH	NO CLUTCH PEDAL.		REPLACED MASTER CYLINDER.	01/02/2024	480430	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	DrCabRep\SEAT	seat repair			20/12/2023	480412	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	Engine\AIR CLNR	air protection filter			20/12/2023	480412	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	DrivLine\CLUTCH	clutch issue			20/12/2023	480412	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	Susp\SUSPENSION	LHR & RHF sporng blocks			20/12/2023	480412	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	Engine\EXHAUST	REPAIR EXHAUST AT MUFFLER.			21/11/2023	480130	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	DrCabElect\RADIO	REPLACED UHF MIC & HOLDER.			15/11/2023	480088	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	Air Con\CONSUMABLE	REPLACED CAB FILTER.			15/11/2023	480088	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	Elect\DRV UGHT	TIGHTENED DRIVING LIGHT.			15/11/2023	480088	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Myrtleford - Workshop	Chassis\FIRE EXTIN	CHECKED AND FITTED FIRE GEAR.			09/11/2023		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Wodonga - Workshop	DrCabRep\WIPERS	DRIVER'S SIDE WIPER.		FIT 2ND HAND WIPER ARM. ADJUSTED.	28/10/2023	479862	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	Elect\DRV UGHT	FIT NEW D/UGHTS.		FIT DRIVING LIGHTS. TESTED.	28/10/2023	479862	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	Engine	CHECKED OIL & COOLANT.			28/10/2023	479862	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Wodonga - Workshop	Elect\BATTERY	STARTING ISSUE.			24/10/2023	479746	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\BATTERY	MAE supply batteries			24/10/2023	479476	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	MYRTLEFORD AUTO ELECTRICS - 3	LOADER
LOAD18	Myrtleford - Workshop	Insp\ANN INSP	annual inspection as per check list	Insp\ANN INSP		24/10/2023	478748	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/10/2023	779748	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist check fluids check tyres	VehService\BS	REPLACED BATTERIES AND AIR CLEANER.	24/10/2023	779748	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Wodonga - Workshop	Body\HOUSEKEEP	change wiper blades			17/10/2023	479500	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up truck			01/04/2021		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\ELECT P&W	Replace Ignition Switch		Intermittent starting - inspected starter wiring etc ok Found faulty ignition barrel	25/02/2021	478916	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\HOUSEKEEP	set up on battery charger and change batteries			19/02/2021	478914	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\BREAKDOWN	jump start			18/02/2021		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\ELECT P&W	reverse lights stuck on			18/02/2021		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			30/01/2021	478412	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		30/01/2021	478412	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\SUSPENSION	RHF elphants foot u/s		repaired LH door not opening from outside	29/01/2021	478412	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\DOOR LOCK	repair LH door		fitted second door handle tested all good had to work on it in between truck been loaded	06/01/2021	476763	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\BREAKDOWN	jump start			22/12/2020	476600	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	deliver to Mill			22/12/2020	476600	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\HOUSEKEEP	check steer ubolt tension			18/12/2020	476440	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\HOUSEKEEP	check RH wheel nuts			18/12/2020	476440	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Susp\SPRING PACK	RHF steer spring broken			16/12/2020	476192	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check over engine fluid levels			16/12/2020	476192	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Susp\SPRING PACK	RHF spring broken			16/12/2020	476192	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\HOUSEKEEP	Replace LH bottom king pin cap			10/12/2020	475940	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		replaced RHS botom kingpin cap	08/12/2020	475429	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	tensioned alternator belt	08/12/2020	475429	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\FUEL TANK	RH fuel tank leaking			28/11/2020	474920	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\TAIL LIGHT	fit LH side light			14/11/2020	473984	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Chassis\FIRE EXTIN	fit fire extinguisher			14/11/2020	473984	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check fluids			10/11/2020	437184	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\EXHAUST	tighten exhaust manifold bolts			10/11/2020	437184	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\RADIO	fit AM/Fm radio			23/10/2020	472336	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\DAMAGE	repair damaged tail light bar			09/10/2020	472314	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\DAMAGE	repair LH & RH mudguards			09/10/2020	472314	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Chassis\BULLBAR	repair bumper bar cracks			09/10/2020	472314	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Unknown - Unknown	Engine\EXHAUST	Replace Exhaust manifold and Turbo Gaskets		needs roadtest and recheck all manifold bolts	07/10/2020	472336	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check over			19/09/2020	471640	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Chassis\WHEEL SEAL	Replace LHF and RHF drive hub seals L9898		readjust drive brakes after roadtest	10/09/2020	472336	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\AIR LEAK	air leak under cab			08/09/2020	9092	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\EXHAUST	check for air leak - losing air		extract broken bolt and straighten panel	29/08/2020	470626	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check fluids		check coolant and oil	29/08/2020	470626	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\SUSPENSION	Replace LHF and RHF and LHR Elephants Feet		replace all 4 feet clean up	07/08/2020	470626	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\HOUSEKEEP	Adjust LH and RH Steer King Pins			07/08/2020	470626	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/08/2020	469848	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		06/08/2020	469848	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Wodonga - Workshop	Air Con\AIR CON	Air Conditioning		RR's Pro Jan 2020 (system clean up) 05/08/20	06/08/2020		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Wodonga Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	repair dash lights and wiring			27/06/2020	468419	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\ELECT P&W	repair seat belt wiring			27/06/2020	468419	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\ELECT P&W	fit switch for reverse lights in dash			27/06/2020	468419	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up MAE			27/06/2020	468419	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\GEARBOX	Repair Sticking Gear Box Splitter			26/06/2020	468419	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\SEAT	seatbelt wont pull out			24/06/2020	468057	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	idle up lever wont stay up			24/06/2020	468057	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\BATTERY	change battery			18/06/2020	467680	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\GEARBOX	Check & adjust gearbox splitter valve		road test truck and check splitter	16/06/2020	467680	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	tacho and air guage lights n/w			06/06/2020		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\WIPERS	Rh washer jet n/w			06/06/2020		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\AIR LEAK	check for air leak			06/06/2020		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\TAIL LIGHT	fit number plate light			06/06/2020		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	repair hand throttle			06/06/2020		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\EXHAUST	made cover for hole in exhaust			30/05/2020	467230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\TAIL LIGHT	replaced clearance light			30/05/2020	467230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\DOOR LOCK	fixed door			30/05/2020	467230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Chassis\HOUSEKEEP	greased			30/05/2020	467230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	checked fluids			30/05/2020	467230	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\ALT	replaced alt and belt tested all good (shelly camp)		alternator not charging	23/05/2020	467018	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER

				travel to Shelly hup camp fitted new alt and belt started and tested all good															
LOAD18	Myrtleford - Workshop	Elect\BREAKDOWN	drove back unloaded ute				23/05/2020	467018	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
			remove/replace broken LH steer spring pack																
LOAD18	Myrtleford - Workshop	Susp\SPRING PACK	fit shackle pins and 1 bush				09/05/2020	466384	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check/adjust throttle				09/05/2020	466384	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\BOOST HOSE	boost leaks				09/05/2020	466384	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check over				09/05/2020	466384	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	clean up				09/05/2020	466384	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	road test				09/05/2020	466384	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	fit eng out of L-12 to L-18				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\ENG REBLD	fit 6x liner kits				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\ENG REBLD	fit big ends and main bearings				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\ENG REBLD	replace all head gaskets and sump gasket				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\ENG REBLD	gaskets needed to complete jobs				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\ENG REBLD	fit thermostat				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\ENG REBLD	clean up cam shaft				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\ENG REBLD	check valves on all 6 heads and replace gaskets				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\MOUNTS	fit engine mounts				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\ELECT P&W	repair gauges and wiring				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\ENG REBLD	change over any parts from L-12 eng to L-18 engine needed to complete job				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\ENG TUNE	tune engine and fuel pump				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up at Yack and return				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check all fluids and check over				02/05/2020	465879	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/03/2020	465706	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
						replaced air filter													
LOAD18	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist		VehService\AS	replaced bonnet visor	24/03/2020	465706	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\FUEL TANK	check engine breathing very heavy				21/03/2020	465695	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check fluids				07/03/2020	465034	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\DIFF OIL	replace front diff oil and inspect metal (ok)				26/02/2020	464488	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	remove and refit grip tape				25/02/2020	464488	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\JAKE BRAKE	exhaust brake not working				25/02/2020	464488	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\HEATER REP	replace heater fan				25/02/2020	464488	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\FUEL TANK	LH5 fuel tank leak after repair				25/02/2020	464488	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\FUEL TANK	Repair fuel tank leak & fit grip tape				18/02/2020	464488	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and water			check oil and water and grease up	16/02/2020	464067	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\EXHAUST	Replace broken exhaust manifold stud on 2nd cylinder head				04/02/2020	464488	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\MIRRORS	RH mirror smashes (Albury operator)				03/02/2020	462725	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/02/2020	462430	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist		VehService\AS	repair exhaust leaks	01/02/2020	462430	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check over, top up fluids				25/01/2020	461772	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\BELTS/TENS	tighten alternator belt				25/01/2020	461772	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\BELTS/TENS	replace fan belt tensioner with 2nd hand part				25/01/2020	461772	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\WINDOW REG	repair RH window runner etc.				25/01/2020	461772	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	test drive - re-inspect - ok				25/01/2020	461772	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\DOOR LOCK	RH door wont shut				15/01/2020	461263	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\DAMAGE	repair LH5 step				15/01/2020	461263	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\FUEL TANK	tank strap and straighten step				04/01/2020	460010	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\DAMAGE	mudguard repair LH5 damage				21/12/2019	460010	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\ELECT P&W	top clearance light				21/12/2019	460605	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\SUSPENSION	Replace RH steer shocker				21/12/2019	460610	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\SUSPENSION	Replace 2 x elephant suspension bushes			completed	21/12/2019	460610	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/12/2019	460604	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
						RH clearance light u/s													
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist		VehService\AS	wash truck	20/12/2019	460604	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BRK RELINE	LHF drive brake low			Checked - ok	20/12/2019	460010	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\OH&S	LH bottom leaf spring broken			Checked - ok	20/12/2019	460010	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\BELTS/TENS	fan belt idler pully worn				20/12/2019	460010	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\SEAT	seatbelt not working properly			Checked - working fine	20/12/2019	460010	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
						welsh plugs on heads leaking													
						thermostat gasket leaking coolant													
LOAD18	Myrtleford - Workshop	DrCabRep\COOL LEAKS	coolant smell check for leak			pressure. Test system	20/12/2019	460010	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
						Welsh plugs on heads leaking													
						Thermostat gasket leaking coolant													
LOAD18	Myrtleford - Workshop	DrivLine\CLUTCH	brake adjustment			Presssure test system	20/12/2019	460010	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\WORK LIGHT	no deck light				20/12/2019	460010	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	remove unused fire extinguisher bracket on deck			fit fire extinguisher	20/12/2019	460010	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
			check over																
LOAD18	Rosewood - Workshop	Body\HOUSEKEEP	#head gasket leaking badly as per photos sent to Wayne				12/12/2019		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Rosewood Workshop	LOADER
			CHECK OVER																
LOAD18	Rosewood - Workshop	Engine\HOUSEKEEP	TOP UP COOLANT			#ADDED 10 LITER COOLANT AGAIN. HEAD GASKET LEAKING	27/11/2019	459653	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Rosewood Workshop	LOADER
						TOP UP ENGINE OIL (10LITES)													
LOAD18	Rosewood - Workshop	Engine\HOUSEKEEP	CHECK OVER			TOP UP COOLENT (8LITERS)	20/11/2019	459050	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Rosewood Workshop	LOADER
			DIAGNOSE & REPAIRE AIR LEAK UNDER CABWEIRES																
LOAD18	Rosewood - Workshop	DrCabRep\AIR LEAK	WAS A CRACKED PLASTIC PUSH IN FITTING				06/11/2019	457881	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Rosewood Workshop	LOADER
LOAD18	Rosewood - Workshop	DrCabRep\SEAT	seatbelt not working properly				26/10/2019		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Rosewood Workshop	LOADER
LOAD18	Rosewood - Workshop	DrCabRep\COOL LEAKS	coolant smell check for leak				26/10/2019		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Rosewood Workshop	LOADER
LOAD18	Rosewood - Workshop	DrivLine\CLUTCH	brake adjustment				26/10/2019		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Rosewood Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\ELECT P&W	Electrical parts				12/10/2019		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\VNST/GAUGE	repair tacho not working				11/10/2019	456010	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check over L-18 top up engine oil				11/10/2019	456010	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\VNST/GAUGE	repair radiator coolant sensor				11/10/2019	456010	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	wash truck				11/10/2019	456010	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/10/2019	455002	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
						rewired and replaced reverse light													
						replaced RHR bump stop													
LOAD18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist		VehService\BS	replaced missing manifold bolts	01/10/2019	455002	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\ELECT P&W	engine brake n/w				18/09/2019	453181	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and water				18/09/2019	453181	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\DRV LN SER	grease drum line				18/09/2019	453181	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\MUDGUARDS	fit LHR mudflap				11/09/2019	452210	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\HUBCAP	oil leak LHF wheel				04/09/2019	451404	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\ELECT P&W	engine brake n/w				04/09/2019	451404	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and water				04/09/2019	451404	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\AIR LEAK	check and repair air leaks				23/08/2019	450810	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\AIR LEAK	air valve broken off tank				08/08/2019	449953	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\DAMAGE	travel to breakdown				08/08/2019	449953	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BOOSTER	Replace LH steer brake booster				06/08/2019	450280	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
						wash down diff													
LOAD18	Myrtleford - Workshop	DrivLine\AIR LEAK	Replace front diff lock diaphram			re-tap stripped threads in diff housine	06/08/2019	450280	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\AIR LEAK	remote brake valve and air lines from white volvo				03/08/2019	449834	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\AXLE REPLC	travel to breakdown in Shelly				03/08/2019	449834	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\TAIL SHAFT	remove u/s jack shaft				03/08/2019	449834	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\AIR LEAK	repair damaged air lines				03/08/2019	449834	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\DAMAGE	fit brake valve				03/08/2019	449834	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\DAMAGE	fit side step support brackets				03/08/2019	449834	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\WHEEL STUD	repaired LH steer stripped wheel stud				03/08/2019	449834	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/08/2019	449834	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
						put 10ts of engine oil in													
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist		VehService\AS	reolaced power steerina cap o-rina	03/08/2019	449834	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up MAE				01/08/2019	449560	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check fluids				01/08/2019	449560	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up from Rinlatech				06/07/2019	447202	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\HEAD LIGHT	LH headlight n/w			fit LH h/lamp bulb and clips to light	02/07/2019	447199	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check oil and water			check and top up engine oil	02/07/2019	447199	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\TAIL LIGHT	fit side light			R&R RHR side light	02/07/2019	447199	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\TAIL LIGHT	fit number plate light				02/07/2019	447199	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\COOL LEAKS	fit clamps to coolant hoses, tighten coolant hose clamps				02/07/2019	447199	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\HUBCAP	fit windows to front hubs caps				02/07/2019	447199	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	clean truck motor and bonnet				02/07/2019	447199	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Chassis\DAMAGE	straighten bent lag guard			check RHR leg pin	02/07/2019	447199	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Albury - Workshop	Engine\CONSUMABLE	repaired engine stop cable				15/06/2019		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Albury Workshop	LOADER
LOAD18	Albury - Workshop	Engine\CONSUMABLE	topped up fluids				15/06/2019		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Albury Workshop	LOADER
LOAD18	Albury - Workshop	Body\HOUSEKEEP	tightened various loose bolts and clamps				15/06/2019		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Albury Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check over				27/04/2019	446280	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check engine oil and coolant				12/04/2019	445431	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	wash oil off				12/04/2019	445431	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\SLACK ADJ	Replace LH steer 2 Cam adjuster (L683S)			washed down axle, stipped down, had wrong parts, reassembled	09/04/2019	464488	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\OIL LEAK	Re-seal rear diff			tighten rear diff and put sealant along bottom and test	09/04/2019	464488	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/04/2019	464082	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist		VehService\AS		06/04/2019	444982	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\ELECT P&W	Replace Ignition Switch - Second Hand switch fitted				22/03/2019		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	MYRTLEFORD AUTO ELECTRICS - 3	
LOAD18	Myrtleford - Workshop	Susp\SPRING PACK	Replace steer axle leaf springs				01/02/2019	44500	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\DRV LN SER	inspect thru shaft bearing				18/01/2019	441488	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/01/2019	440941	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
						repaired side marker lights													
LOAD18	Myrtleford - Workshop	VehService\CS	Service As Per Attached Checklist		VehService\CS	found large metal pieces in front diff recheck 26-2-20 ok	08/01/2019	440941	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\BREAKDOWN	travel				23/11/2018	438792	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\COOL LEAKS	coolant leak			replace g/box cooler hose at rear of head	23/11/2018	438792	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Dr

LOAD18	Myrtleford - Workshop	Steering\WHEEL ALGN	Wheel align all 3 axles top up engine oil 12lts		adj toe in w/align ok		25/09/2018	437333	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	too uo coolant 5 lts				22/09/2018	437151	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Susp\SPRING PACK	LHF spring broken (replace LHF spring and pins)				16/09/2018	437062	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	pick up loader				16/09/2018	437062	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\BATTERY	batteries flat/jump start (call out)				04/09/2018	436159	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\BATTERY	Test batteries & starting system		fit 2x new batteries		04/09/2018	436558	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\RADIO	replace UHF radio				31/08/2018	435964	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\BATTERY	check batteries - getting slow to crank				28/08/2018	435680	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\BATTERY	test both batteries				28/08/2018	435680	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\AIR LEAK	air leak behind cabin				17/08/2018	434651	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHS cab shocker (L4945)				09/08/2018	437333	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\PWR STEER	Replace power steering cap gasket				09/08/2018	437333	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\TIE ROD	Replace LHS tie rod end				09/08/2018	437333	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\WIPERS	LH wiper insert				08/08/2018	434201	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/08/2018	434201	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist alternator not charging	VehService\AS			08/08/2018	434201	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\ELECT P&W	FIT NEW 24VOLT ALTERNATOR. alternator not charging				02/08/2018	433842	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\HEAD LIGHT	RH headlight n/w				02/08/2018	433842	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\INDICATORS	repair side indicator wiring				02/08/2018	433842	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\CONSUMABLE	check oil and coolant				02/08/2018	433842	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\WINDSCREEN	Replace front windscreen		news supplied w/screen		07/07/2018	432900	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes - pulling to left				05/07/2018	432898	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS			26/06/2018	432312	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				26/06/2018	432312	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\HEAD LIGHT	headlights cutting out				19/06/2018	431732	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\DH&S	non slip tape on tank RHS and deck				19/06/2018	431732	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	wheel brake, check wheel nuts				19/06/2018	431732	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				13/06/2018	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				13/06/2018	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection as per the attached listing				08/06/2018	431331	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	take loader to Mansfield				07/06/2018	431331	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Insp\RWC COMP	roadworthy inspection				07/06/2018	431331	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Insp\RWC COMP	take Load18 to Vic Roads Benalla to clear defect				07/06/2018	431331	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	return to Myrtleford yard				07/06/2018	431331	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	Wash Truck				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\KING PIN	Replace LH & RH King pins		Road test & re-grease king pins Remove LH broken bolt for hub cap readjust all brakes replace steer boost hose		06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BRK RELINE	Reline steer brakes & fit drums				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\SUSPENSION	Replace rear steer shackle pins & bushes				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\MOUNTS	Replace LHF engine mount				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\MOUNTS	Replace RHR gearbox mount				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\SUSPENSION	Replace sway bar bushes		Replace all inner & outer wheel bearings		06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BRK RELINE	Reline all 4 drive brakes(L4396)(L4422)		fit drums to front axle		06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BRK O/HAUL	Fit 2 x drums to rear axle				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\SUSPENSION	Replace rear suspension spring pivot bushes & seals(L4391)(L4412)				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\AIR LEAK	Repair air leaks				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\DAMAGE	Replace UHF & RHF indicator lenses				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\ELECT P&W	Repair horn & dash lights(L4419)		Dash indicators & high beam		06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\WIPERS	Repair wipers & washers		fit RH wiper arm		06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	Fit new steering wheel		Repair loose steering wheel grip - did not replace		06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\MUDGUARDS	Fit RH steer mudflap				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\WINDSCREEN	Replace windscreen(L4392)		North East Windcreens		06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\REFLECTORS	Fit new rear signs		Remove old stickers & clean & refit with new		06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\DOOR LOCK	Replace RH door hinge				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\PAINT/REST	Repair rust in cab				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\SHOCK ABS	Rear drive shocker bushes				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\FUEL TANK	Fit seal to RH fuel cap				06/06/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Insp\RWC COMP	fit new front number plate				05/06/2018	6076	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\HOUSEKEEP	clean out cabin				05/06/2018	6076	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\PANELS	refit side panel driver side				05/06/2018	6076	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\PAINT/REST	clean and paint all hubs and rims				05/06/2018	6076	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\PAINT/REST	paint mudguards and fit reflective tape				05/06/2018	6076	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	test drive				05/06/2018	6076	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	replace alternator bracket bolt				05/06/2018	6076	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	check over				05/06/2018	6076	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\ELECT P&W	repair roof lights				05/06/2018	6076	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\TOOLBOX	Mount toolbox in cab + repair				30/05/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\OIL LEAK	Repair power steering oil leak at box				30/05/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\FUEL TANK	Remove RH fuel tank and fit				30/05/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\FUEL TANK	Wash fuel tank reseal front bung				30/05/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\ELECT P&W	Replace RH mirror light wiring				30/05/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\RADIO	Repair UHF cable				30/05/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\OIL LEAK	Repaire po wer steer pimp o rings/ power steering oil leak				30/05/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\GEARBOX	Adjust gearbox splitter valve		adjusted splietter valve clotch		30/05/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	Road test				30/05/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\STEER TYRE	Job Added From Invoice				24/05/2018	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				24/05/2018	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\OIL LEAK	Repair front diff housing crack		seal leak at diff lock cover on housing		15/05/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\SUSPENSION	Replace rear diff Vee stay assembly				15/05/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\AIR LEAK	Repair air leak at park brake valve				15/05/2018	430982	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/05/2018	429720	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS			15/05/2018	429720	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\SUSPENSION	replace bottom spring leaf on RHR drive spring pack				12/05/2018	429720	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\WIPERS	replace wiper blades				01/05/2018	428896	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\RADIO	replace UHF mic				01/05/2018	428896	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Workshop\MOVE ASSET	road test				27/04/2018	428908	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\DRV LN SER	grease drive line				27/04/2018	428908	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Cooling\HOUSEKEEP	L&R steer king pins need replacing				27/04/2018	428908	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BOOSTER	adj brake booster rod				27/04/2018	428896	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\AIR LEAK	Replace RHR booster hose				17/04/2018	428898	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\ELECT P&W	Repair park lights & dash lights				17/04/2018	428898	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\MOUNTS	Repair fuse box				17/04/2018	428898	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\AIR LEAK	repair air leak under seat				17/04/2018	428898	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\SUSPENSION	Replace LHR suspension foot bush				17/04/2018	428898	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	Remove damaged take cross over hose				17/04/2018	428898	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\BATTERY	Jump start and charge batteries				09/04/2018	428308	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	Check oil and coolant				09/04/2018	428308	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BOOSTER	Replace RHR booster or clamps				28/03/2018	428896	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Susp\SWAYBAR	Replace steer sway bar bushes				28/03/2018	428896	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\UNI JOINTS	Replace front jack shaft uni				28/03/2018	428896	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\GEARBOX	Repair gear stick linkage				28/03/2018	428896	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\OIL LEAK	Repair engine oil cooler leak				28/03/2018	428896	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				27/03/2018	427435	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS			27/03/2018	427435	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\DOOR LOCK	RH door wont open				02/03/2018	425698	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\FUEL TANK	replace fuel line				09/02/2018	424924	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	wash engine				09/02/2018	424924	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\WIPERS	Replace wiper inserts				09/02/2018	424924	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabRep\WINDSCREEN	Replace rear window on truck				09/02/2018	424924	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Cooling\RADIATOR	Fit radiator & intercooler out of Load12 into Load18		Clean out engine bay		09/02/2018	430958	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\JAKE BRAKE	Rekit engine exhaust brake				09/02/2018	430958	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	Repair fuel leak at injector pump		fit injector pump off L-12 to L-18		09/02/2018	430958	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\JAKE BRAKE	Check exhaust brake Remove radiator & intercooler for repair				09/02/2018	424924	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Cooling\RADIATOR	Remove intercooler to be tested				09/02/2018	424924	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\SLACK ADJ	Replace LH steer 2 cam adjuster assembly		drill out and tap broken backing plate bolt from reconditioned 1-cam assembly		09/02/2018	429720	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/02/2018	424924	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS			07/02/2018	424924	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres	Job Added From Invoice Travel to site & remove front tail shaft for repairs - return to workshop Remove & replace damaged universal joint				06/02/2018	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\UNI JOINTS	Travel back to site & refit front tail shaft				17/01/2018	423700	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres	Job Added From Invoice				30/12/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				30/12/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				30/12/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
					LH booster (OR) Adjust brakes - needs LH Steer z - 2-Cam												
LOAD18	Myrtleford - Workshop	Brakes\BOOSTER	Replace LH steer brake booster		IRH booster hose was reolaced		19/12/2017	423040	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				16/12/2017	421224	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	A Service As Per Attached Checklist	VehService\AS			16/12/2017	421224	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myr

						top up 9L engine oil]													
						hand throttle not working													
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	repair washers	02/09/2017	415239	Service	Completed	Greenfreight Loxine Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			22/08/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Insp\ANN INSP	annual inspection as per check list	Insp\ANN INSP		11/08/2017	414143	PreventativeMaintenance	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
			Remove Front Diff Housing inspect damage to front diff & Thru Shaft																
LOAD18	Myrtleford - Workshop	DrivLine\DIFF REPAIN	L3120			01/08/2017	414130	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrivLine\AXLE REPLC	travel to LOAD18 and inspect drive line			28/07/2017	414130	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrivLine\AXLE REPLC	tow truck back to w/shop for repairs			28/07/2017	414130	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabRep\SEAT	air leak at drivers seat		repair seat air line	19/07/2017	413345	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
			check and top up all fluids																
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	check lights			16/07/2017	412912	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
			clean out loader																
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	wash truck			16/07/2017	412912	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabRep\AIR LEAK	air leak at drivers seat			13/07/2017	412780	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			08/07/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Tyres	Job Added From Invoice			14/06/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/06/2017	409973	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	VehService\BS	B Service As Per Attached Checklist	VehService\BS		06/06/2017	409973	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Steering\WHEEL BRGS	replace r/hand steer wheel bearings & hub seal			04/05/2017	405810	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Steering\WHEEL ALGN	wheel align all 3 axles			03/05/2017	405638	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			29/04/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Tyres\STEER TYRE	Job Added From Invoice			14/04/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Body\MUDGUARDS	fit 2nd LH steer mudflap			07/04/2017	404378	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	check over truck			07/04/2017	404378	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Elect\TAIL LIGHT	repair LHF clearance light			07/04/2017	404378	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Chassis\HOUSEKEEP	replace missing boom stand bolts			05/04/2017	404278	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabElect\INDICATORS	Replace RHS bonnet indicator			05/04/2017	404280	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
					check power divider for by passing air into diff														
LOAD18	Myrtleford - Workshop	DrivLine\OIL LEAK	Replace front diff thru shaft seal		thru shaft is leaking but ok at this stage	05/04/2017	404290	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
					wash engine & r/test														
					reolace washers on fuel fittinss at fuel oumo														
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	Repair fuel leak at LHS of engine			05/04/2017	404290	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/04/2017	404199	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		04/04/2017	404199	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Body\DAMAGE	straigthen hand rail			15/03/2017	403198	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabElect\AIR CON	fit new fan in cabin L-18			15/03/2017	403198	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabRep\WINDOW REG	fit missing screw in L/H window winder			15/03/2017	403198	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabElect\PHONE	relocate phone speaker			15/03/2017	403198	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Steering\HOUSEKEEP	Replace LHS & RHS bottom king pin caps & o-rings			07/03/2017	403198	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/03/2017	402372	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
					check rear v-stay for movement next service														
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	LHS and RHS bottom kine pin cars need reolacine	04/03/2017	402372	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabRep\SEAT	air leak under drivers seat			03/03/2017	402005	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabRep\DOOR LOCK	drivers door wont close			02/03/2017	401638	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabRep\DOOR LOCK	drivers door wont close			01/03/2017	401607	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Steering\DAMAGE	Replace RH steer shocker mount		Complete	24/02/2017	401216	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Elect\BREAKDOWN	pack for breakdown			15/02/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Elect\BREAKDOWN	travel to Shelley			15/02/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Elect\BATTERY	fit 2x new batteries to loader			15/02/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Elect\BREAKDOWN	travel back to workshop			15/02/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Elect\BATTERY	repair battery clamps			15/02/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	Replace RHF engine mount			09/02/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/02/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	r/hand front engine mount u/s	08/02/2017		Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabRep\SEAT	remove seat belt buckle and fit new seat belt buckle to drivers side seat			04/02/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Tyres\TP09	Job Added From Invoice			01/02/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Engine\TURBO	noise from engine under load			21/01/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabRep\SEAT	seat belt wont clip in			21/01/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	engine still under powered - compared to before motor was done			21/01/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Engine\EXHAUST	engine brake very noisy			21/01/2017		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Tyres\TP07	Job Added From Invoice			21/01/2017	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Steering\OIL LEAK	check -p/steering oil leak, tighten hose & banjo fitting			05/01/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Engine\FUEL TANK	check - fuel leak. Check & tighten fuel line			05/01/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Elect\TAIL LIGHT	repair clearance lights			05/01/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/01/2017		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		05/01/2017		Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Tyres\TP04	Job Added From Invoice			30/12/2016	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Tyres\TP04	Job Added From Invoice			29/12/2016	0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	wash truck			21/12/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
					checked fuel line, fuel filters, banjo fitting & check spil timing of fuel injector														
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	Check engine lacking power and using excessive fuel		Comolete	13/12/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
					Skidz														
LOAD18	Myrtleford - Workshop	Tyres\TP04	Replace flat tyre - LHF inner		Complete	13/12/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
					Myrtleford Auto Electrics														
LOAD18	Myrtleford - Workshop	Elect\BATTERY	Check battery - starter slow to crank		Comolete	13/12/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Body\DAMAGE	repair steps on RH side			02/12/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Insp\INT INSP	fit tire gaar			02/12/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Chassis\HOUSEKEEP	check over truck			02/12/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
			Replace No. 2 piston liner kit																
			Fit big ends & main bearings																
			Replace oil pump																
LOAD18	Myrtleford - Workshop	Engine\ENG REBLD	Replace easkets		Comolete	18/11/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Engine\ENG TUNE	Tune & service engine		Complete	18/11/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrivLine\OIL LEAK	Replace thru shaft seal, bearing & yoke		Complete	18/11/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Brakes\HOUSEKEEP	check over truck			15/11/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Engine\BELTS/TENS	tighten alrenator bolt & brackets			15/11/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Engine\FUEL TANK	clamp fuel line hoses			15/11/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	tigthen clamp on oil cooler			15/11/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabRep\ELECT P&W	Replace u/s wiper washer motor. Replace u/s wiper motor		fit 2 new wiper blades	09/11/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Re-wire speedo dash light			05/11/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Elect\HEAD LIGHT	Replace RHS headlight assembly		repair L H side earth wire	05/11/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Elect\DRV LIGHT	Check driving lights - not working. Repair driving lights - not working		Complete	03/11/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Body\CONSUMABLE	Supply Grease		Complete	03/11/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/11/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	VehService\CS	Service As Per Attached Checklist	VehService\CS		01/11/2016		Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Engine\COOL LEAKS	Repair coolant leak from under cylinder heads			19/10/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
					Top up coolant & engine oil														
					Add stop leak														
LOAD18	Myrtleford - Workshop	Engine\COOL LEAKS	Check coolant level - leaking		Comolete	17/10/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
			Replace thru shaft bearing, clips, yoke, seal & nut																
LOAD18	Myrtleford - Workshop	DrivLine\DRIVES	Inspect			12/10/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Brakes\BOOSTER	travel to stanley and bypass LHF drive booster			05/10/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Brakes\BOOSTER	replace LHF brake booster on front axle			05/10/2016		Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrivLine\OIL LEAK	Replace front diff thru shaft seal			05/10/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	DrivLine\UNI JOINTS	Replace rear jack shaft uni			05/10/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/10/2016		Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	replaced 2x oil filters	04/10/2016		Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford	MLR	UTH016	Myrtleford Workshop	LOADER			
LOAD18	Myrtleford - Workshop	Tyres\TP03	Job Added From Invoice			30/07/2016	0	Repair

LOAD18	Myrtleford - Workshop	Chassis\FUEL TANK	Replace both tank strap rubbers on bottom		Complete	13/04/2016	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Susp\SPRING PACK	Replace both spring & swinging link on RHF		Complete	13/04/2016	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\MOUNTS	Clamp down fire rake		Complete	13/04/2016	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/04/2016	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
					fix exhaust bracket									
LOAD18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	reoair air leak	13/04/2016	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Susp\SPRING PACK	replace lhf & rhf steer spring packs & shackle pins & bushes also fit shackle links to rear			08/04/2016	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
					Check switch plug connection & clean, recheck									
					Remove indicator switch & replace with 2nd hand switch									
LOAD18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Indicator stuck - faulty switch		Comolete	18/03/2016	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\HOUSEKEEP	Straighten steering wheel		Complete	18/03/2016	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BRK RELINE	Reline LHF Drive brake			16/03/2016	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Susp\SPRING PACK	Replace LHR bottom spring leaf & centre bolt			16/03/2016	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Steering\STEER UNI	Replace bottom steer shaft uni			16/03/2016	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\BELTS/TENS	Replace fan belt tensioner & pulley			16/03/2016	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/03/2016	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS		15/03/2016	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\ELECT P&W	Check volt meter not working		Complete	15/03/2016	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
					Check alternator power, connections & wiring									
					Change inverter fues									
LOAD18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	No power to main dash lights		Comolete	15/03/2016	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	Wash Truck		Complete	15/03/2016	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\MUDGUARDS	Fit new RHR mudflap		Complete	15/03/2016	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
			Repair interior light											
LOAD18	Myrtleford - Workshop	DrCabElect\INST/GAUGE	Reoair Sowedo		Comoleted	20/02/2016 375644	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
			Check starting system		Myrtleford Auto Electrics									
LOAD18	Myrtleford - Workshop	Elect\START MOTR	Reolace starter motor		Comoleted	11/02/2016 374967	Reoair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
			Repair battery cables		Myrtleford Auto Electrics									
LOAD18	Myrtleford - Workshop	Elect\ELECT P&W	Replace battery terminals		Completed	11/02/2016 374967	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\HOUSEKEEP	Wash loader truck platform		completed	02/02/2016 373517	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrCabElect\HOUSEKEEP	adjust driving lights - to low		completed	29/01/2016 373360	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\MOUNTS	repair grab stand		completed	29/01/2016 373360	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	check truck engine oil coolant		completed	29/01/2016 373360	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BRK RELINE	4 x bearings & brake shoes		completed	09/01/2016	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BRK RELINE	drive hub & axle seal bearings & spaces		completed	08/01/2016	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
					replace thru shaft bearing, spacer & circlips									
LOAD18	Myrtleford - Workshop	DrivLine\OIL LEAK	replace front diff thru shaft seal		completed	07/01/2016 372304	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Body\MOUNTS	replace LHF engine mount		completed	07/01/2016 372304	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
			replace RHR shoes & seals											
LOAD18	Myrtleford - Workshop	Brakes\BRK RELINE	replace inner & outer wheel bearings		completed	07/01/2016 372304	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BRK RELINE	4 X hub seal 4 x axle seal'4 lock washer 1 stack		complete - credit in Translogix CP 2031	05/01/2016	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BRK RELINE	2 brake kits		completed	01/01/2016	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes\BRK RELINE	reline LH rear brake		completed	31/12/2015 372304	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\AS	Service As Per Attached Checklist	VehService\AS	completed	29/12/2015 372304	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	29/12/2015 372304	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
					check motor & wiring, check wiper motor fuse & check wiring to stalk. Found faulty stalk switch for wiper washer motor									
			wiper washer not working		fit second hand wiper washer switch									
LOAD18	Myrtleford - Workshop	DrCabRep\WIPERS	reolace wiper blades		completed	29/12/2015 372304	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Elect\HOUSEKEEP	fit new LED driving lights		completed	29/12/2015 372304	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
			led driving lamp											
LOAD18	Myrtleford - Workshop	Elect\ELECT P&W	mae			24/12/2015	Reoair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Susp\SWAYBAR	re-weld rh swaybar linkage		completed	28/11/2015 371085	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\FUEL TANK	check fuel pump handle leaking		completed	12/11/2015 370099	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
			check air con - only blows air - no other parts available to repair											
LOAD18	Myrtleford - Workshop	DrCabRep\AIR CON	reoair seat belt not oulline out		completed	20/10/2015 369145	Reoair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
			clean out dust from seat belt											
			fit new reverse light											
LOAD18	Myrtleford - Workshop	Elect\ELECT P&W	fit new bulb in lh headlieht		completed	13/10/2015 368890	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\FUEL TANK	Job Added From Invoice			07/10/2015 0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\DAMAGE	adjust throttle linkage		completed	02/10/2015 368814	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	DrivLine\WHEEL BRGS	Job Added From Invoice			01/10/2015 0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\TP07	Job Added From Invoice			01/10/2015 0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\TP07	Job Added From Invoice			01/10/2015 0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\FUEL TANK	fit new 24 v elec fuel pump		completed	01/10/2015 369919	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
			replace wheel spacers											
			lubricated throttle cable											
LOAD18	Myrtleford - Workshop	Engine\DAMAGE	supply bar for wheel nuts		completed	01/10/2015 368762	Fault	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\AIR CLNR	Job Added From Invoice			23/09/2015 0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS	completed	17/09/2015 367914	Service	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Engine\HOUSEKEEP	Service Job Added From Invoice			16/09/2015 0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\TP08	Job Added From Invoice			12/09/2015 0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\TP07	Job Added From Invoice			12/09/2015 0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\TP07	Job Added From Invoice			12/09/2015 0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\TP10	Job Added From Invoice			12/09/2015 0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER
LOAD18	Myrtleford - Workshop	Tyres\TP07	Job Added From Invoice			12/09/2015 0	Repair	Completed	Greenfreight Logging Vic	LOADVOLVO	Myrtleford MLR	UTH016	Myrtleford Workshop	LOADER