EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T622	Mt Gambier - Mt Gambier	DrivLine\AXLE REPLC	DrivLine\AXLE REPLC			20/10/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	COOKY'S DIESEL MECHANIC REPAIRS - 3	TRAILER
T622	Mt Gambier - Mt Gambier	Susp\SHOCK ABS	Susp\SHOCK ABS			20/10/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	COOKY'S DIESEL MECHANIC REPAIRS - 3	TRAILER
					Carried out trailer service as per Greenfreight checklist. Customer Instructions: Place vehicle on shaker & Inspected Carried out General Inpection & Checkover Greased vehicle											
T622	Mt Gambier - Mt Gambier	VehService\DS	VehService\DS D Service	VehService\DS	Comoleted oaserwork & Cleaned area	26/09/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Mt Gambier - Mt Gambier	Body\MUDGUARDS	Body\MUDGUARDS			25/09/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Mt Gambier - Mt Gambier	VehService\DS	VehService\DS D Service	VehService\DS		11/09/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	HALLORAN DIESEL - 3	TRAILER
					Fitting - Runouts x 2 Disposal - Truck Tyre											
T622	Mt Gambier - Mt Gambier	Tyres\TP9+10	Tyres\TP9+10		2 RUNOUT P 29.30 2 NWR DONE IN MOUNT GAMBIER	04/09/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BORDER BANDAG PTY LTD -3	TRAILER
T622	Mt Gambier - Mt Gambier	Elect\WORK LIGHT	work light broken		Removed broken rear work light and replaced with new unit	02/09/2026	690022	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	HALLORAN DIESEL - 3	TRAILER
T622	Myrtleford - Workshop	VehService\DS	VehService\DS D Service VehService\DS D Service	VehService\DS		14/08/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	HALLORAN DIESEL - 3	TRAILER
T622	Myrtleford - Workshop	VehService\DS	L134925	VehService\DS		28/07/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 27 + 29 + 31 VehService\DS D Service			07/07/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BORDER BANDAG PTY LTD -3	TRAILER
T622	Myrtleford - Workshop	VehService\DS	L134649	VehService\DS		03/07/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Found snapped pivot bolt on LH rear axle. Remove and replace as required, all okay.											
T622	Myrtleford - Workshop	Susp\DAMAGE	R&R PIVOT BOLT (SPRING EYE BOLT)		(Spares used from GF stock)	18/06/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Rear LHS & RHS shocker straps were worn through. Remove and replace shocker straps as required.											
T622	Myrtleford - Workshop	Susp\SHOCK ABS	BOTH REAR AXLE SHOCKER STRAPS NEED REPLACING		KWASD025/4540 SLING - ENDLESS ROUND 454MM	18/06/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					LIFT AND TIGHTEN RH SIDE MUD GUARDS											
T622	Myrtleford - Workshop	Chassis\MUDGUARDS	LIFT & TIGHTEN DRIVERS SIDE GUARDS VehService\DS D Service		Lift all 3 RHS mudguards and tighten all brackets	18/06/2026	690022	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	VehService\DS	L134293 VehService\DS D Service	VehService\DS		17/06/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	VehService\DS	L133921	VehService\DS		26/05/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Replace missing nut on #4 winch. Check over all others, all											
T622	Myrtleford - Workshop	Chassis\WINCH/STRP	NO 4 BINDER NUT MISSING		okay.	25/05/2026	690022	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Checked 2nd front bolster light, removed light and traced wiring. Found wiring was broken in bolster, cut out and											
T622	Myrtleford - Workshop	Elect\TRL LIGHTS	2ND FROM REAR BOLSTER PIN CLEARANCE LIGHTS NOT WORKING		repaired wirine. Reioined to lieht and fitted to bolster.	25/05/2026	690022	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Inspect and found missing bolts, fit new bolts and tighten											
T622	Myrtleford - Workshop	Chassis\MUDGUARDS	TIGHTEN PASS SIDE FRONT GUARD MOUNT VehService\DS D Service		LHF mudeaurd as reouired.	25/05/2026	690022	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	VehService\DS	L133573	VehService\DS		30/04/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Found work light on B trailer not working. Check for power and earth at plug - had power. Remove and replace work light and check operation, all OK											
T622	Myrtleford - Workshop	Elect\WORK LIGHT	Repair lights n/w work light VehService\DS D Service		KWFL2 HIGH POWERED ROUND FLOOD LAMP,	17/04/2026	690022	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	VehService\DS	L133342	VehService\DS		17/04/2026	690022	Service	Comoleted	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					CHECK PIVOT BUSH MOVEMENT Check pivot bushes, found rear right pivot bush worn. Remove airbag and spring. Once hanger in position refit spring with new bush then lift spring into hanger. Use rotor pull to move axle into correct position but found U bolts damaged. Replace use bolts as required and fit all components to correct positions. Tension all to spec, all OK KW0205169KT-1AL KIT-BPW PIVOT BUSH ALIGNABLE HNGR, PARA' 1 137.02											
T622	Myrtleford - Workshop	Susp\Torque Rod	CHECK PIVOT BUSH MOVEMENT		KW0313341014 U-BOLT M24X152X268 RINGFEDER FRONT MOUNT	31/03/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Found nuts loose and some seized on FL u bolts. Oxi and remove all nuts and replace with new, tension to spec, all OK KW02S2207412 NUT - LOCK M24 GRADE 10.9 8 21.20											
T622	Myrtleford - Workshop	Susp\DAMAGE	REPLACE NUTS ON FL U BOLTS		KW0254012507 WASHER- HARDENED 25/44/4	31/03/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Found RHS 2nd clearance light not working. Inspect and found break in wiring, repair wire and check light - still not working. Remove and replace light, all working as should.											
T622	Myrtleford - Workshop	Elect\TRL LIGHTS	CLEARANCE LIGHT		KW2053 RED/AMBER SIDE MARKER LAMP	31/03/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Pulled trailer over, jacked up axle and built up air. Released brakes, checked booster and wheel bearing. All ok. Adjusted axle brakes, road tested and checked temps. All											
T622	Myrtleford - Workshop	Brakes\BRAKE ADJ	Check RH front wheel, got hot and was smoking VehService\DS D Service		ok. Suspected incorrect adjustment.	30/03/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	VehService\DS	L133058 VehService\DS D Service	VehService\DS		27/03/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	VehService\DS	L099253	VehService\DS		19/03/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)			16/03/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BORDER BANDAG PTY LTD -3	TRAILER
					Found front right and rear right pivot bushes wearing down.											
T622	Myrtleford - Workshop	Susp\SUSPENSION	2 PIVOT BUSHES ??		Monitor and re-check next service	11/03/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Upon service could hear slight air leak. Spray over all air											
T622	Myrtleford - Workshop	Body\AIR FITTIN	AIR LEAKS		components and check. unable to detect leak.	11/03/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Inspect and test for power at light, no power found.											
T622	Myrtleford - Workshop	Elect\TRL LIGHTS	2 LHS CLEARANCE LIGHT NOT WORKING		Inspect loom and found break, repair break in loom and check light operation. all OK	11/03/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Jack axle and inspect LH rear wheel bearing. Check over											
T622	Myrtleford - Workshop	Chassis\WHL HUB	LH REAR WHEEL BEARING VehService\DS D Service		movement, all OK.	11/03/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	VehService\DS	L099046	VehService\DS		20/02/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
					Remove bolts for bracket, remove bracket and installed new.											
			REPLACE GUARD BRACKET ON LHS FRONT REAR. KANGAROO DAMAGE		NG660-004-02-ZINC BLDGUARD BRACKET 1 91.00											
T622	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE BRACKET FOR MUDGUARD VehService\DS D Service		NGFREIGHT FREIGHT	19/02/2026	690022	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	VehService\DS	L098729	VehService\DS		31/01/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30) VehService\DS D Service			28/01/2026	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BORDER BANDAG PTY LTD -3	TRAILER
T622	Myrtleford - Workshop	VehService\DS	L098306	VehService\DS		05/01/2026	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	Brakes\EBS Kit	CHECK & ENGINEER EBS SYSTEM			24/12/2025	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	JASON UNDERWOOD DESIGN - 3	TRAILER
					Scales on B trailer were not Bluetooth compatible with tablet. Remove and replace right weigh scale to Bluetooth one as required. Modify air line fittings 8mm to 1/4' as needed.											
					NG201-EBT-01B S/INPUT WEIGHT GAUGE 1 923.61											
T622	Myrtleford - Workshop	DrCabElect\SCALES	R&R WEIGHT SCALE		Sublet1S1121129 SUPPLY FITTING	11/12/2025	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BARRY MANEY - 3	TRAILER
T622	Myrtleford - Workshop	Chassis\WINCH/STRP	REPAIR 2 X TU AIR WINCHES			20/11/2025	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	FOREST CENTRE PTY LTD - 3	TRAILER
T622	Myrtleford - Workshop	Susp\AIR BAG	REPAIR RH REAR AIR BAG TOP MOUNT			15/11/2025	690022	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Chassis\HOUSEKEEP	FIT , DRILL AND PAINT CHECKER PLATE FOR CHASSIS			15/11/2025	690022	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Myrtleford Workshop	TRAILER
					REPLACE RHF SHOCKER & STRAPS & ALL STRAP RETAINERS FIT LIFT AXLE RUBBERS REPLACE S/ADJUSTER RETURN SPRINGS											
T622	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		14/11/2025	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		14/11/2025	690022	PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Body\PAINT/REST	prep and paint bolsters and pegs repaint sockets to white on the ends FIT UP EBS COMPONENTS TO 2ND AND 3RD AXLES			13/11/2025	690022	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Brakes\EBS Kit	CARRY OUT END OF LINE TEST (EOL)			13/11/2025	690022	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Myrtleford Workshop	TRAILER
					T622 1/2" x 1 1/2" unf b/cl 10 2.35 23.50 1/2" x 2" unf b 6 1.40 8.40 1/2" htw 20 0.70 14.00											
			CRACK TEST ALL BOLSTER PEGS & REPLACE MOUNT BOLTS													
T622	Myrtleford - Workshop	Chassis\BOLSTER	REFIT PEGS		Straighten bolster oxe.	13/11/2025	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Susp\AIR BAG	REPAIR AIR BAGS LEAKING AIR (MIDDLE AXLE) CONVERT TRAILER TO 3 X 3MTR BAYS TO SUIT 3.6 MTR LOGGS FIT 2 EXTRA BOLSTERS TO MAKE 3 BAY B TRAILER		REPLACED MIDDLE AXLE AIR BAGS	01/11/2025	690022	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Chassis\BOLSTER	FIT EXTRA WORK LIGHTS			30/10/2025	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	FOREST CENTRE PTY LTD - 3	TRAILER
T622	Myrtleford - Workshop	Chassis\WINCH/STRP	FIT 6 EXTE TU AIR WINCHES & QUICK RELEASES TO SUIT 3 BAY OF LOGGS			30/10/2025	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	FOREST CENTRE PTY LTD - 3	TRAILER
T622	Myrtleford - Workshop	Body\MOUNTS	Body\MOUNTS		remove and clean up log guard mounts front of trailer	21/10/2025	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	FOREST CENTRE PTY LTD - 3	TRAILER
T622	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE ALL 6 MUD GUARDS INSPECT ALL BRAKE %			11/09/2025	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Myrtleford Workshop	TRAILER
			CRACK TEST ALL 3 AXLES													
T622	Myrtleford - Workshop	Body\WHL HUB	INSPECT & REPACK ALL WHEEL BEARINGS & REPACE AS REQUIERED & FIT NEW SEALS			11/09/2025	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Tyres\RUN OUT	Tyres\RUN OUT TYRE POS 1-12			28/05/2025	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	BEAUREPAIRES - 3	TRAILER
T622	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		07/12/2024	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Susp\WEIGHT GAUGE	WEIGHT GUAGE NOT READING READING CORRECT WEIGHT, AROUND 5 TON UNDER.			22/03/2024		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Comp\Truck Safe	No NHVAS sticker			22/03/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Elect\WORK LIGHT	REPAIR LH WORK LIGHT.			22/03/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Chassis\EXTE TU	2ND WINCH MISSING. OTHERS ARE OLD STYLE.			22/03/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Chassis\STRAPS	LOG RACK MOUNT BENT.			22/03/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Brakes\EBS Kit	NO EBS FITTED.			22/03/2024		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Susp\WEIGHT GAUGE	WEIGHT GUAGE NOT READING READING CORRECT WEIGHT, AROUND 5 TON UNDER.			22/03/2024		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		22/03/2024		PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/12/2023	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Susp\WEIGHT GAUGE	WEIGHT GUAGE NOT READING READING CORRECT WEIGHT, AROUND 5 TON UNDER.			05/12/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/12/2023	690022	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		05/12/2023		PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Elect\WORK LIGHT	REPAIR LH WORK LIGHT.			05/12/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Chassis\EXTE TU	2ND WINCH MISSING. OTHERS ARE OLD STYLE.			05/12/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Chassis\STRAPS	LOG RACK MOUNT BENT.			05/12/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Brakes\EBS Kit	NO EBS FITTED.			05/12/2023		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	Wodonga Workshop	TRAILER
T622	Wodonga - Workshop	Chassis\CHAS CRACK	repair cracks in trailer			18/11/2023	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	0138SS	PACCAR PARTS FLEET SERVICES - 3	TRAILER

			2 x Air Winch Rebuild Kits.																
			Forest Centre Tumut																
T622	Woolonga - Workshop	Chassis\EXTE TU	PO# WW084677					22/11/2021	690022	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\EXTE TU	2ND AND 4TH WINCH FROM FRONT OF B TRAILER WON'T TIGHTEN WITHOUT BANGING THEM. THEY COME LOOSE AS LOGS SETTLE IN TRAVEL. MAY				COULDN'T FAULT 2ND WINCH. 1ST AND 4TH WINCHES NOT TENSIONING CORRECTLY. DISMANTLED, CLEANED, LUBED AND ASSEMBLED. TES	20/11/2021		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\EXTE TU	WINCH NOT TENSIONING. REPAIRED AND REPLACED VALVES AND TENSIONING ARM NOT HITTING PUSH ROD.					18/11/2021	1402653	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Body\STRAPS	2ND LAST WINCH NOT TIGHTENING UNDER PRESSURE.				TESTED WINCH OPERATION. ALL TESTED OK. THE ONLY TIME I COULD GET TO FAULT IS IF THE BARREL RELEASE WASN'T FULLY OUT.	14/11/2021		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Myrtleford - Workshop	Comp\Truck Safe	No NHVAS sticker				order	26/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Susp\SUSPENSION	RHR trailer arm shim damaged				lower "u" bolt bracket welded to position	26/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Chassis\WHL HUB	No hubbo					26/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Tyres	RHR inner tyres flat					26/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Body\LIGHTS	rear load lights/ RHR indicator				indicator ok	26/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Elect\ELECT P&W	NO SCALES SET UP ON TRAILER				scales work. Truck not supplying correct voltage	26/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Elect\TRL LIGHTS	Rear load lights not working					26/10/2021		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP				22/10/2021		PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job					22/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop	TRAILER
							8x peg bolts still to be replaced - on order												
							fit 2x winch handles												
							fit RHR spring wrap												
T622	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			replaced 4x bolster peg bolts	22/10/2021		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop	TRAILER
T622	Myrtleford - Workshop	Chassis\BOLSTER	move bolsters and winches to suit 3.7 logs				fit LHR mudguard	22/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop	TRAILER
T622	Albury - Workshop	Tyres\TPS-HI	supply and fit 2 tyres					19/10/2021	74500	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Woolonga - Workshop	Elect\ELECT P&W	NO SCALES SET UP ON TRAILER					15/10/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job					30/06/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				30/06/2021		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\SKID PLATE	Removed Block.					30/06/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Body\REFLECTORS	Chevron fallen off rear trailer.				Refit marker signs and reflectors to rear of trailer.	22/04/2021	730087	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Albury - Workshop	Body\TRL REPS	repair front bay, rear ratchet mechanism					24/02/2021		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job					07/10/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				07/10/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\MUDGUARDS	LHR outrigger bent					07/10/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Susp\SUSPENSION	RHR trailer arm shim damaged					07/10/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Body\TRL REPS	front bank rear ratchet mechanism not working				replaced front bank rear ratchet mechanism	07/10/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Workshop\MOVE ASSET	park combination					07/10/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\WINCH/STRP	Insected rolled loaxine set for an oaerational air oaerated ratchet tumble mechanism and remove. Reolaced front middle mechanism with one fro					06/10/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job					11/09/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				11/09/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job					27/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				27/08/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	DrivLine\WHL HUB	Job Added From Invoice					12/08/2020	0	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job				completed	07/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\WHL HUB	No hubbo					07/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Elect\TRL LIGHTS	Rear load lights not working					07/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed			07/08/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Tyres	RHR inner tyres flat					07/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Body\LIGHTS	rear load lights/ RHR indicator					07/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Comp\Truck Safe	fitted trucksafe ordered NHVAS					07/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Susp\SUSPENSION	requires rear bushes and pins					07/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\WHL HUB	No hubbo				parts on order	01/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Body\TOOLBOX	needs replacement					01/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\CROSS MBR	cross bracing and plates cracked					01/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Susp\AIR BAG	LHR airbag support damaged					01/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Susp\SUSPENSION	trailing arm olts and bushes need replacing					01/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Elect\TRL LIGHTS	Rear load lights not working				parts on order	01/08/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
			LHR trailing arm bolt snapped and axle shifted out at holbrook																
			replaced bolt																
			inspected trailers back at the yard and found rhr trailing arm bolt also snapped																
T622	Woolonga - Workshop	Susp\SUSPENSION	both bolts reolaced with second han bolts will need reolacinewh new bolts					18/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Susp\AIR BAG	LHR airbag support damaged					18/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Susp\SUSPENSION	trailing arm olts and bushes need replacing					18/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\MUDGUARDS	Both side rear guards worn - outriggers moving on chassis				Replaced rear guards & fixed outriggers	18/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Comp\Truck Safe	No NHVAS sticker					18/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\WHL HUB	No hubbo				Parts on order	18/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Tyres	LF duals					18/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Body\TOOLBOX	needs replacement					18/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\CROSS MBR	cross bracing and plates cracked					18/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Susp\HCV	Height control valve needs replacing				Previously completed	18/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\MUDGUARDS	rear guards need replacing				As per #295363	18/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Elect\TRL LIGHTS	Rear load lights not working				Not compatible with 5pin light plugs - wired without reverse lights	18/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP				09/07/2020		PreventativeMaintenance	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\MUDGUARDS	rear guards need replacing					09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job					09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\MUDGUARDS	Both side rear guards worn - outriggers moving on chassis					09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Comp\Truck Safe	No NHVAS sticker					09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\WHL HUB	No hubbo					09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	DrCabElect\WGHT GAUGE	no scales				previosly fitted	09/07/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Elect\TRL LIGHTS	Rear load lights not working					09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\AIR LEAK	have to keeps revs up when loading to keep air up?				checked for leaks none found	09/07/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Susp\AIR BAG	some air bags on left side of trailers don't seem to be inflated				inspected ok	09/07/2020		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				09/07/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Tyres	LF duals					09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Body\TOOLBOX	needs replacement					09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\CROSS MBR	cross bracing and plates cracked					09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Susp\HCV	height control valve needs replacing					09/07/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job					23/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				23/06/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\MUDGUARDS	Both side rear guards worn - outriggers moving on chassis					23/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Comp\Truck Safe	No NHVAS sticker					23/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\WHL HUB	No hubbo					23/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Albury - Workshop	DrivLine\WHEEL ALGN	perform laser wheel alignment at HTT					20/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Woolonga - Workshop	Body\FIFTH WHEE	remove skidplate block					18/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Workshop\MOVE ASSET	pick up driver and dropped at wheel alignment place				dropped off driver then went to ATT then TCTC to pick up parts	17/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
							ATT for loctating pins Poww055447												
T622	Woolonga - Workshop	Susp\SUSPENSION	fit new axle				replace axle	17/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Susp\AXLES	remove centre axle					09/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Workshop\MOVE ASSET	clean up					09/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	DrivLine\WHEEL BNGS	remove hub to check bearings					06/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	DrivLine\AXLE REPLC	remove axle					05/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Workshop\MOVE ASSET	move axle onto stand with forklift					05/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Body\WARRANTY	strap up axle to return to tctc to check for warranty					05/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Albury - Workshop	Chassis\WHL HUB	remove hub and check axle					05/06/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Chassis\MUDGUARDS	lhs rear and middle axle mudguards replaced					30/05/2020	689982	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Body\MUDGUARDS	repaired outriggers and replaced guards					25/05/2020	689983	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Albury - Workshop	Body\MUDGUARDS	PO FOR MUDGUARDS/FLAPS					07/05/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	VehService\DS	D Service	VehService\DS				03/05/2020		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	DrCabElect\SCALES	checked scales					03/05/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Chassis\WINCH/STRP	repaired winch handle					03/05/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					03/05/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Chassis\MUDGUARDS	replaced LHF outrigger & guard c				replaced LH outrigger & mount	29/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Body\DAMAGE	Replaced broken cab rack				Organised Repairs & loaded onto truck	28/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
							scales not working												
							checked wiring, ok. Power and earth ok												
							found low voltage from truck												
T622	Albury - Workshop	DrCabElect\WGHT GAUGE	no scales				will consult with manufacturer about requirements	21/04/2020		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Brakes	BRAKE TEST RESULTS					24/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Chassis\AIR FITTIN	REPLACE RUBBER HOSE					24/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Susp\SHOCK ABS	TIGHTENED SHOCKERS					24/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Elect\TRL LIGHTS	REPAIRE MIRROR LIGHT					24/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS				24/11/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Brakes						13/11/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS				13/11/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Chassis\WINCH/STRP	rear winch handle touching guard					08/09/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Elect\WORK LIGHT	rack and loading lights not working					08/09/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Elect\WORK LIGHT	rack lights not working					08/09/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Brakes						08/09/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	VehService\DS	VehService\DS	VehService\DS				08/09/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Chassis\WINCH/STRP	replaced 2nd and 4th straps					10/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Chassis\BOLSTER	tightened bolster bolts					10/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					10/08/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	VehService\DS	D Service	VehService\DS				10/08/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
							repaired guard damage - removed 3rd outrigger and weld												
							straightened rear guard x-bar												
T622	Albury - Workshop	Chassis\MUDGUARDS	repair L/H rear guard				reolaced all guard bolts and outrieaer bolts	06/08/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshoo	TRAILER
T622	Woolonga - Workshop	Brakes						23/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	VehService\DS	D Service	VehService\DS				23/07/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Body\OH&S	Removed damaged centre mat				Make up mount points & refit shortened original mat	19/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Woolonga - Workshop	Susp\WGHT GAUGE	Fit & calibrate scale unit					16/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					07/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	VehService\DS	D Service	VehService\DS				07/07/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Chassis\WINCH/STRP	R/H/S rear winch hits guard					06/07/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Chassis\MUDGUARDS	R/H/S rear guard patch up hole					06/07/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Elect\WORK LIGHT	rack lights not working					06/07/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Elect\WORK LIGHT	load lights not working					06/07/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Woolonga - Workshop	VehService\DS	D service	VehService\DS				22/06/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Woolonga Workshop	TRAILER
T622	Albury - Workshop	Body\HOUSEKEEP	alignment plates LR&LF					19/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Chassis\AIR FITTIN	replaced drain cock					15/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop	TRAILER
T622	Albury - Workshop	Chassis\AIR FITTIN	replaced hose clamps on main feed airlines					15/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK

T622	Albury - Workshop	Body\MUDGUARDS	refitted LHR mudguard			13/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Body\MUDGUARDS	L/H/S rear guard falling off			12/06/2019	576595	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			05/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	VehService\DS	D Service	VehService\DS		05/06/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Hydraulics\VALVES	replaced lift axle dump valve			01/06/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Elect\TAIL LIGHT	joint all wiring again L/H/S tail light out			31/05/2019	565045	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Elect\TAIL LIGHT	put tape again for all joint			31/05/2019	565045	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Tyres\DAMAGE	broken spare wheel carrier			29/05/2019	562151	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			26/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	VehService\DS	D Service	VehService\DS		26/05/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	DrivLine\WHL HUB	trailer tracking left badly			21/05/2019	552421	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Body\HOUSEKEEP	alignment plates LR&LF			17/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Body\AIR BAG	front axle airbags (replaced) LH front of rear guard outrigger ordering			17/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Chassis\MUDGUARDS	replaced LHM-RHM s.e.b			17/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Body\HOUSEKEEP	weld x-braces			17/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Tyres\TP01	RM inner tyre			17/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			17/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	VehService\DS	D Service	VehService\DS		17/05/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
					breakdown at Ironbark truck stop												
					no trailer lights												
					check fuses wiring. Check trailer supply												
					wiring in battery box found 24v fuse to reducer blow. replaced fuse. Blow again												
					bypass, reducer to supply trailer circuit												
					test ok truck returned to Albury												
					pack up parts to repair travel to depot												
					replaced reducer, replaced fuses												
					now supply 12v to trailer												
					return truck to work												
T622	Albury - Workshop	Elect\TRL LIGHTS	no trailer lights tightened LHF, RHF & LHM sebolts		80km travel	09/05/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	DrivLine\AXLE REPLC	tightened middle axle u-bolts			05/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			05/05/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	VehService\DS	D Service	VehService\DS		05/05/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	VehService\DS	D Service	VehService\DS		04/05/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			17/04/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Albury - Workshop	VehService\DS	D Service	VehService\DS		17/04/2019		Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
					no scale												
					check power at unit power 7 earth												
					ordered new display												
					tightened up cover mat on chassis												
					replaced scales display/control box												
					repaired wiring												
T622	Albury - Workshop	DrCabElect\SCALES	scales not working		calibrated trailer taoe weiahts	13/04/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Albury Workshop		TRAILER
T622	Myrtleford - Workshop	Body\HOUSEKEEP	fit cab guard to trailer			05/04/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Body\TRL LEGS	adjust trailer leg			05/04/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Body\TRL LEGS	weld handle bracket			05/04/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Chassis\WINCH/STRP	fit new quick release latches to trailers			28/03/2019	S15299	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Chassis\WINCH/STRP	fit new quick release cables to trailers			28/03/2019	S15299	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Susp\SUSPENSION	Replace RHM spring eye bush			26/03/2019	S14606	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Body\MUDGUARDS	Repair LHR mudguard mount bracket move quick release latches down to prevent damage			26/03/2019	S14606	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Chassis\WINCH/STRP	repair cables as needed			23/03/2019	S13218	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/03/2019	S13218	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/03/2019	S13218	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Chassis\WINCH/STRP	replace strap on 2nd last winch			19/03/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Chassis\DAMAGE	remove winch mount for repairsLS880. remove winch mount for repairs			19/03/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/03/2019	S03889	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		13/03/2019	S03889	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHF Shocker			09/03/2019	S03889	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes			08/03/2019	499818	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Elect\WORK LIGHT	Repair Work Lights			02/03/2019	S13218	Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	VehService\DS	Service As Per Attached Checklist	VehService\DS		28/02/2019	493069	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/02/2019	493069	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Chassis\WINCH/STRP	Repair 2 x Air Winches - not working correctly			20/02/2019		Fault	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Body\HOUSEKEEP	wash trailer and acid wash rims			16/02/2019	483432	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Elect\WORK LIGHT	Repair Reverse W/Light Wiring short			15/02/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Chassis\BOLSTER	Move 2nd Bolster & B Trailer			15/02/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Elect\ELECT P&W	repair and check scales			09/02/2019	483265	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Chassis\WINCH/STRP	Repair & Reco the first 2 Air winches			25/01/2019	483623	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2019	373965	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/01/2019	373965	Service	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Tyres\CTI Drive	remove tyre inflation			23/01/2019	483260	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Body\MUDGUARDS	replace mudguard			23/01/2019	483260	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Chassis\SPAREWHEEL	make up spare wheel carrier clamp			23/01/2019	483260	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Chassis\WINCH/STRP	move air winch and tidy up airlines			19/01/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Brakes\AIR LEAK	tighen up booster and brake hose clamps			19/01/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Chassis\BOLSTER	move and tighten up bolsters			19/01/2019		Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER
T622	Myrtleford - Workshop	Insp\ANN INSP	Roadworthy check on trailer (LS600)		RHF & LHF & RHR shocker strap u/s	10/01/2019	483256	Repair	Completed	Greenfreight Logging Vic	FlatTow	Mt Gambier	STK	013855	Myrtleford Workshop		TRAILER