EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T471	Albury - Workshop	Chassis\DAMAGE	Repair Accident Damage			01/10/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\CHAS CRACK	Rear cross member cracked			01/10/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Myrtleford - Workshop	Brakes\ABS	CHECK EBS POWER SUPPLY AND FOR FAULTS		INSPECTED POWER SUPPLY AND FOR FAULTS AFTER DAYS FULL WORK AND REPAIRS ALL GOOD NO FAULTS AND GOOD POWER SUPPLY KLM AT TIME OF INSPECTION 1.579535	15/07/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Myrtleford Workshop	TRAILER
T471	Albury - Workshop	Brakes\EBS FAULTS	L/H Middle wheel speed sensor		completed by TP JS	13/07/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	Brakes\BRK RELINE		BRAKES WERE RELINED BY WODONGA WORKSHOP	10/07/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Myrtleford - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	NOT ABLE TO GET EBS KLM DUE TO NO POWER TO TRAILER FROM TRUCK	08/07/2026	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Myrtleford Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		28/06/2026	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\HCV	REPLACE HCV			28/06/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR FITTN	Repair Middle Left Air Bag Fitting		completed by JS MB	25/06/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			20/06/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	A.ROMERO	17/06/2026	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			06/06/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	COMPLETED BY SMc	05/06/2026	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		28/05/2026	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VServLab	SERVICE		completed by JS	28/05/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Brakes\AIR LEAK	Air leak middle axle, not sure where leak is coming from?		completed by JS	25/05/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR LEAK	Check for suspected air leak on trailer.		completed by JS	19/05/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	completed by TP JS	15/05/2026	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	SMc TP	07/05/2026	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4		(23-24) LOW	30/04/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2		(21-22) LOW	30/04/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6		(25-26) LOW	30/04/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
					done already											
T471	Albury - Workshop	Body\MUDGUARDS	Remove broken mud flaps on front axle		TP JS	28/04/2026	990928	Fault	Completed	Greenfreight Loxene NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	completed by TP,JS	28/04/2026	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
					checked coudnt find it											
T471	Albury - Workshop	Elect\ELECT P&W	R/HAND SIDE LIGHT KEEPS FALLING OUT		TP.JS	28/04/2026	990928	Fault	Completed	Greenfreight Loxene NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	R/H Guard Broken.			31/03/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	Repair shockabsorber mounts			26/03/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	rear axel needs reline			24/03/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	Front axle brake reline.			24/03/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	rhm shock leaking		Wheeping	24/03/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	R/H middle axle brake reline.			24/03/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\INDICATORS	R/H/R indicator missing.			23/03/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			17/03/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	KR SM	13/03/2026	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRAKE ADJ	Check & Adjust Brakes		Drove Trailer over pit Checked & Adjusted Brakes	11/03/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\HCV	Ride Control Valve Came Of Mounting Bracket		Opened workshop, brought truck & trailer/s over pit, reattached HCV, checked and adjusted suspension height, parked truck over in logging compound.	06/03/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)		WORN OUT	25/02/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Brakes\EBS FAULTS	broken or unplugged brake sensor wire on the rear axel hanging down		Completed by SMc	18/02/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		14/02/2026	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		31/01/2026	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)		LOW	20/01/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)		LOW	20/01/2026	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		17/01/2026	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RLR/MN	Replace Gypsy Motor			08/01/2026	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS	Serviced By Shane Mc Cabe & Cheyne O'Brien	31/12/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		21/12/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			20/12/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)		RIMZ WILL BE USED R/O - TYRES WORN	20/12/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	RHF shock absorber is falling off			19/12/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BOOSTER	LHF Brake Booster Missing/replace.			19/12/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
					* Customers contacted dealership to report breakdown											
					* Customer advised that failed brake booster - fallen off											
					* Technician sourced additional parts											
					* Technician then travelled to breakdown site, GF depot											
					* Inspected trailer to diagnose failure											
					* Located confirmed failed front LHS brake booster											
					* Removed booster											
					* Reduce replacement booster rod to length & installed											
					* Connected air system components											
					* Pressurised, test, confirm & quality check repair											
					* Returned trailer to service											
					* Technician returned home											
			Brakes\BOOSTER		-											
			BREAKDOWN REPAIR		TRAVEL: No Travel Charged											
T471	Albury - Workshop	Brakes\BOOSTER	T097234			04/12/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		03/12/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\Punct	Tyres\Punct POS 28		UNREPAIRABLE PUNCTURE	27/11/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	REPLACE 1ST BOLSTER WEAR PADS			22/11/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		22/11/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)			15/11/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			12/11/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Susp\HCV	CALLOUT - TRAVELLED TO AND FROM TRAILER. REPAIRED HCV.			05/11/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		30/10/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR LEAK	Repair air leak in air line.			16/10/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis	Front right bolster cracked			15/10/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis	Lhs second bolster cracked			15/10/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis\CROSS MBR	Cross Brace On A-Trailer			15/10/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR BAG	Front Left Air Bag			15/10/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis	Lhm shock weld cracked			15/10/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\HCV	Height Control Valve Lever Keeps Coming Apart			15/10/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		15/10/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis	Cross brace infront of rear air tank cracked on the rhs			15/10/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service			15/10/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis	Umbilical arm mount cracked			15/10/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		07/10/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6			07/10/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)			25/09/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			25/09/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		25/09/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis\FIFTH WHEE	REPLACED TURNTABLE TEFLON WEAR PADS.			25/09/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\CLEANSKN	Rearleft inner tire worn			25/09/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT TO SPARE			19/09/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Chassis\EXTE TU	Quick Release Front One Doesn't Work Properly			19/09/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\MUDGUARDS	Some New Mud Flaps On The Back Off A-Trailer			19/09/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		19/09/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		12/09/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\HCV	Height Control Valve Come Apart I Put Back Together Double Check			01/09/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		30/08/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\HCV	Check Ride Height & Adjust As Required.			27/08/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis\EXTE TU	Replace Broken Release Cable (Front)			25/08/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	REPAIR BROKEN QUICK RELEASE CORD.		REPLACED CABLE	22/08/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RLR/MN	TIGHTEN SPROCKET ON THE GYPSIE.		REPLACED BOLTS	22/08/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	STRAIGHTEN BENT MUDGUARD BRACKET ON THE FRONT R/HAND GUARD.			17/08/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		17/08/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Brakes\EBS FAULTS	DIAGNOSED AND REPLACED WHEEL SPEED SENSOR.			06/08/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR BAG	REPLACED LF LR AIRBAGS			06/08/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		06/08/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	REPLACED LF GUARD. STRAIGHTENED MOUNTS.			05/08/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Elect\DAMAGE	Replace Damaged Lights On L/h/S Of Trailer, Due To Trailer Hitting Wire Rope On Hwy.		-marker lights repaired and replaced as required.	01/08/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis\MUDGUARDS	Repair/Replace Damaged L/H Front Guard, Due To Trailer Hitting Wire Rope On Hwy.			01/08/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Body\AMB ARM	REPAIRED UMBILICAL ARM.			25/07/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			Front right hand shock still missing and top mount broken,		REPLACED REAR TOP SHOCK MOUNTS- INSIDE TO BE WELDED ON PIT.											
T471	Albury - Workshop	Susp\SHOCK ABS				25/07/2025	990928	Fault	Completed	Greenfreight Loxene NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			RHF shock missing													
T471	Albury - Workshop	Susp\SHOCK ABS	RHM shock leakine			25/07/2025	990928	Fault	Completed	Greenfreight Loxene NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			24/07/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			24/07/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Elect\ELECT P&W	Replace light plugs on second slide bolster			23/07/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Body\HOUSEKEEP	First quick release cord broken			23/07/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis\AMB ARM	REPLACE UMBILICAL ARM BEARINGS.			23/07/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	Needs new breaks			23/07/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	Requires reline urgently			23/07/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	RELINE front and Rear axles			23/07/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	Wear pads on bolsters worn			23/07/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	RF SHOCK MISSING. RM LEAKING.			18/07/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	REPLACE LF SEB.		Previously completed	18/07/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		18/07/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp	Front right shock missing needs one fitted			18/07/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
					Reversed trailer onto pit due to front door track damaged. Inspected. Parts required.											
T471	Albury - Workshop	Susp\AIR LEAK	Air leak in middle axle group		Reolaced leakine cvclinder	18/07/2025	990928	Fault	Completed	Greenfreight Loxene NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Body	Passenger bush begining to wear needs			18/07/2025	990928	Fault	Completed	Greenfreight Loxene NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR BAG	REPLACE FRONT AIRBAGS.		Previously completed	18/07/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		05/07/2025	990928	PreventativeMaintenance	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		05/07/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	REPLACE BROKEN QUICK RELEASE CORD.			01/07/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6			30/06/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		25/06/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		11/06/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\FIFTH WHEE	LOCKING PIN ON SLIDER NOT LOCKING IN DUE TO WORN SLIDER BUSHES.			11/06/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8			04/06/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4			04/06/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BORDER BANDAG PTY LTD - 4	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	RELINED LM			31/05/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	VehService\DS D Service

T471	Albury - Workshop	Body\MUDGUARDS	R/H front guard needs replacing			01/05/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		24/04/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Susp\HCV	HEIGHT CONTROL BROKEN HAD TO LIFT IT MANUALLY TO GET IT HOME.		Previously completed	24/04/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP13+12	Tyres\TP13+12			22/04/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
					TCTC PO created T093467														
					Signed off to reset system														
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		17/04/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	PACCAR PARTS FLEET SERVICES - 4	TRAILER			
T471	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10			05/04/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		02/04/2025	990929	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	VehService\DS	Service			27/03/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Hydraulics\HYD LEAKS	HYDRAULIC LEAK AT FRONT OF TURNTABLE.		PREVIOUSLY COMPLETED.	27/03/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		27/03/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4			24/03/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2 + 3-4			24/03/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Albury - Workshop	Body\MUDGUARDS	LHF guard has kangaroo damage			24/03/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Brakes\BRK RELINE	RELINED LR.			20/03/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
					ADJUSTED WHEEL BEARINGS.														
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	K.RYAN 3½ HOURS LABOUR.	20/03/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Chassis\CHAS CRACK	Repair Cracks In Gypsy Motor Plate			18/03/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Chassis\FIFTH WHEE	Chassis\FIFTH WHEE FAB UP PUSH BAR			18/03/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Chassis\AIR LEAK	right hight valve leaking bad need fixing		Replaced Height Control Valve Lift Cylinder, Tested & Checked for Leaks, All Good, Returned Trailer Back To Service.	06/03/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12			04/03/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES	TRAILER			
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Reline rear axle	27/02/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Body\MUDGUARDS	L/H Front Guard rubbed thru.		Very small hole driver to monitor	27/02/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10			26/02/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Albury - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		19/02/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP5+6	Tyres\TP5+6			18/02/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8			18/02/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Wodonga - Workshop	Chassis\CHAS CRACK	Right side Hanger to bottom flange of chassis rail Crack.			12/02/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		11/02/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Body\MUDGUARDS	REPLACE MISSING STONE FLAP UNDER CHASSIS.			03/02/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Body\BOLSTER	Fit Reflective Strip/Tape to Stauntons.		Dan not on Job	03/02/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	check turn table for movement in pin or on chassis. (Parts Supplied By Maxi Parts P/O: T093749)			03/02/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AIR LEAK	AIR LEAK ON HEIGHT LEVELLER RAM. (AIR LINE CABLE TIED)			03/02/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AXLES	lift axle not working			03/02/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SPRING HANG	Repair RH Z spring rear axle			03/02/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	TIGHTEN LOAD CHAIN.			03/02/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\DAMAGE	Broken Guard Bracket (above load chain @ T-Table)			03/02/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		03/02/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AXLES	LIFT AXLE NOT WORKING			03/02/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP9+10	Replace Tyres On Positions 9&10. (Wodonga Tyre & Auto P/O: T091584)			28/01/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Wodonga - Workshop	Susp\HCV	REPAIR RIDE HEIGHT CONTROL ARM.			24/01/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP09	Tyres\TP09			23/01/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Wodonga - Workshop	Chassis\CHAS CRACK	Repair Cracked Hangers & X-members (middle & Rear Axles)			21/01/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Middle axle rhs tire showing ware can tire fitter please inspect	21/01/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12			17/01/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2			17/01/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4			17/01/2025	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Myrtleford - Workshop	Tyres\TP10	replace flat tyre RH rear inner			10/01/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Myrtleford Workshop	TRAILER			
T471	Wodonga - Workshop	Body\AMB ARM	Adjust/Check Umbilical cable.		Lead looks fine to me need unloded to test properly	09/01/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
					Replace mud gaurd														
T471	Wodonga - Workshop	Chassis\MUDGUARDS	Replace damaged mudguard			09/01/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\EXTE TU	Lubricate front wing (stiff to operate)		Pull apart clean and lube	09/01/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes\BRK RELINE	Reline Middle & Rear Axles		Reline all brake shoes repack middle axel tighten 3 shocks	09/01/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Reline all Axels	08/01/2025	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Elect\ELECT P&W	REPLACE BROKEN SIDE LIGHT. REAR RIGHT SIDE.			08/01/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VServLab	SERVICE			08/01/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VServLab	SERVICE			08/01/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Body\MUDGUARDS	REPLACE DAMAGE MUDGUARD.		Replace mud guard and fit new flaps	08/01/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Elect\DRV LIGHT	Replace broken side light rear right side		Cracked Lens still working Russell sain leave it	08/01/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\EXTE TU	LUBRICATE FRONT WINCH. (STIFF TO OPERATE)			08/01/2025	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Myrtleford - Workshop	Susp\SHOCK ABS	replace missing shocker bolt LH middle axle			13/12/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Myrtleford Workshop	TRAILER			
T471	Myrtleford - Workshop	Chassis\WINCH/STRP	repair winch release latch spring			12/12/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Myrtleford Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Needs Re-line	11/12/2024	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\WINCH/STRP	REPAIR QUICK RELEASE CATCH.		REPAIRED. KEITH R.	10/12/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\EXTE TU	Replace Quick Release Hook.			10/12/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Drivline\WHEEL ALIGN	Wheel Alignment. (Hume Truck Technics P/O: T090471)			29/11/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	HUME TRUCK TECHNICSP/L-4	TRAILER			
T471	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10			28/11/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Albury - Workshop	Tyres\TP7+8	Tyres\TP7+8			28/11/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Albury - Workshop	Tyres\TP11+12	Tyres\TP11+12			28/11/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		16/11/2024	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Myrtleford - Workshop	Chassis\WINCH/STRP	1st winch latch needs replacing old one bent			16/11/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Myrtleford Workshop	TRAILER			
T471	Myrtleford - Workshop	Hydraulics\HYD LEAKS	oil leak front of b-trailer but from hoses on a-trailer			16/11/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Myrtleford Workshop	TRAILER			
T471	Wodonga - Workshop	Elect\ELECT P&W	Light Plug Going Into "B" Trailer Keeps Dropping Out.			12/11/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Steering\WHEEL ALIGN	A trailer crabs to left			09/11/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		09/11/2024	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		01/11/2024	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Job not allocated until after finished	25/10/2024	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP1+2	Tyres\TP1+2			24/10/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Myrtleford - Workshop	Elect\ELECT P&W	repair ebs wiring that has pulled out of plug		repaired wiring tested and all good replaced fuses in cab that were blown	23/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Myrtleford Workshop	TRAILER			
					This time allocation includes all 3D Rnfs														
					Service done by cherysh and Cody														
T471	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Rnfs done by me	16/10/2024	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471			First winch xtn housing cracked on both sides needs repairing																
T471	Wodonga - Workshop	Chassis\WINCH/STRP	Cracked webbing behind spare wheel			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Elect\DRV LIGHT	REPAIR BROKEN SPOT LIGHT BRACKET.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\WINCH/STRP	First winch xtn housing cracked on both sides needs repairing			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\AIR LEAK	AIR LEAK.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SHOCK ABS	REMOVE BROKEN SHOCKER.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\MUDGUARDS	Rtplace black mudflap under chassis			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\DAMAGE	Gypsy motor mount plate cracked rhs and lhs			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Gippsprep Workshop	TRAILER			
T471	Wodonga - Workshop	Body\BOLSTER	2nd bolster cracks at doublers plate			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Elect\ELECT P&W	REPLACE MISSING SIDE LIGHT ON THE LEFT.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE MISSING LM SHOCK SPACER.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AXLES	LR AXLE SADDLE CRACKED.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\DAMAGE	Gypsy motor mount plate cracked rhs			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\BOLSTER	2nd bolster cracked doublers plate			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Body\BOLSTER	2nd bolster cracks at doublers plate			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\DAMAGE	Gypsy motor mount plate cracked rhs and lhs			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\HCV	HEIGHT CONTROL VALVE HAS FALLEN APART.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Elect\ELECT P&W	REPLACE MISSING SIDE LIGHT.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\HCV	ADJUST RIDE HEIGHT.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\WINCH/STRP	First winch xtn housing cracked on both sides			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471			Webbing in chassis cracked lhs																
T471	Wodonga - Workshop	Chassis\CHAS CRACK				16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Elect\WORK LIGHT	MOUNT REAR WORK LIGHT.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\AIR LEAK	REPAIR AIR LEAK.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\AIR LEAK	AIR LEAK.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SUSPENSION	REPLACE SPRING EYE BOLT.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\MUDGUARDS	Replace Missing Mud Flap In Front Of Front Axle Under Chassis			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AIR LEAK	REPAIR AIR LEAK ON LIFT AXLE.			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Tyres\PRES CHECK	Replace Worn Tyres On Centre Axle On The Left Side. (Check All Tyres)			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471			Webbing in chassis cracked lhs																
T471	Wodonga - Workshop	Chassis\CHAS CRACK			L.	16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
			First winch xtn housing cracked on both sides needs repairing																
T471	Wodonga - Workshop	Chassis\WINCH/STRP	Cracked webbing behind spare wheel			16/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			15/10/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			15/10/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Wodonga - Workshop	VServLab	SERVICE			10/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		10/10/2024	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	Service			10/10/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT 7			27/09/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Albury - Workshop	Tyres\TP9+10	Tyres\TP9+10+11+12			27/09/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Wodonga - Workshop	Susp\SUSPENSION	Replace Broken U-Bolts L/H Middle Axle.			26/09/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Susp\AIR BAG	Replace Blown Air Bag Centre Left. (MM Diesel's P/O: T088056)		Previously completed	26/09/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	MM DIESEL - 4	TRAILER			
T471	Albury - Workshop	Tyres\TP3+4	Tyres\TP3+4			24/09/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 4	TRAILER			
T471	Myrtleford - Workshop	Tyres\TP3+4	Tyres\TP3+4			21/09/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BEAUREPAIRES - 3	TRAILER			
T471	Myrtleford - Workshop	Tyres\TP07	replace flat Tyre LH front outer (used spare of trailer)			20/09/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Myrtleford Workshop	TRAILER			
			Webbing in chassis cracked lhs																
T471	Wodonga - Workshop	Chassis\CHAS CRACK				30/08/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		30/08/2024	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SUSPENSION	Lift Axel Not Working			20/08/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	Service			20/08/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AXLES	Repair lift axle			20/08/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AXLES	LIFT AXEL NOT WORKING			20/08/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AIR BAG	Air bags are flat			20/08/2024	990928

						First winch xtn housing cracked Middle right shock absorber removed to be replaced after getting g nut from tctc o. Monday 3/6/24 re dean												
T471	Wodonga - Workshop	VehService\DS	VehService\DS		VehService\DS		01/06/2024	990928	Service	Completed	Greenfreight Loxene NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Body\MUDGUARDS	fit new mudflaps				01/06/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service		VehService\DS	II	01/06/2024	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP		Insp\ANN INSP		01/06/2024	990928	PreventativeMaintenance	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\BOLSTER	1st bolster passenger side flip			Trailer is loaded can't complete this job	01/06/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis\AIR LEAK	Repair air on trailer (Boags Diesel P/O: T			1	31/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BOAG'S DIESEL MECHANICS	TRAILER
T471	Wodonga - Workshop	Body\MUDGUARDS	REPLACE MUDFLAPS.				29/05/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Tyres\TPS+2	Tyres\TPS+2				23/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Body\MUDGUARDS	NEEDS L/H FRONT AXLE GUARD (HIT A ROO)				09/05/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\BOLSTER	TURNED 2ND BOLSTER PEG.				01/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SHOCK ABS	REPLACED LM SHOCK MOUNT.				01/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\EBS FAULTS	CHECKED CODES. REPLACED RM LR RR SPEED SENSORS AND RINGS. REPLACED RM SENSOR CABLE. CLEARED CODES.				01/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis	GYPSY MOUNTS CRACKED.				01/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		01/05/2024	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				01/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CHAS CRACK	WEBBING CRACKED LHS. 1ST WINCH MOUNT SMALL CRACK.				01/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	DrivLine\DRV LN SER	grease nipples need replacing				01/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SPRING HANG	front and middle right spring wraps broken				01/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService	service				01/05/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SHOCK ABS	lift axle not working				01/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SUSPENSION	lift axle not working				01/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Body\AIR LEAK	check for air leaks				01/05/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	ADJUSTED LOAD CHAIN. REPAIRED 2ND BOLSTER LIGHTS.	23/04/2024	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				23/04/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\EXTE TU	FRONT WINCH BODY LOOSE. WINCH RELEASE FRONT BAY DOESN'T RELEASE.				23/04/2024	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres	fitted by workhop no pos				23/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		07/04/2024		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				07/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.				07/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CHAS CRACK	WEBBING CRACKED LHS. 1ST WINCH MOUNT SMALL CRACK.				07/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CROSS MBR	1ST WINCH MOUNT CRACKED.				07/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	DrivLine\DRV LN SER	grease nipples need replacing				07/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SPRING HANG	front and middle right spring wraps broken				07/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\EXTE TU	FRONT WINCH BODY LOOSE. WINCH RELEASE FRONT BAY DOESN'T RELEASE.				07/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TPS+10	Tyre Position 9 + 10				04/04/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
						* Inspected trailer & confirmed repairs required * Ballast axles * Removed wheel end equipment * Removed hubs, drums & brakes * Found all s-cams to be worn * Hit out s-cams * Fit new s-cams, tubes & bushes * Replaced ABS sensors & pulse rings as required * Checked wheel bearings * Found RHF & LHM bearings to be worn * Removed & replaced bearings as required * Cleaned & re-packed remaining bearings * Fit new brake shoes * Refit all other components & greased as required * Adjusted brakes & bearings * Aligned & tensioned all to specifications * Test all operations - All ok											
T471	Albury - Workshop	Brakes\BRK RELINE	CARRY OUT FULL BRAKE RELINE				05/03/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Workshop\MOVE ASSET	hook trailer up to yard truck and park in the lane way				01/03/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SUSPENSION	RHM Alignment Plate			replaced SEB, spring wrap & alignment plate	28/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp\BREAKDOWN	u-bolts snapped				23/02/2024	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	BOAG'S DIESEL MECHANICS	TRAILER
T471	Albury - Workshop	Tyres\TPT+8	Tyre Position 7 + 8				22/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TPS+10	Tyre Position 9 + 10				22/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TPS1+12	Tyre Position 11 + 12				22/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		13/02/2024		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				13/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect\TAIL LIGHT	REPLACE BROKEN LIGHTS ON R/HAND SIDE OF REAR LIGHT BAR.				13/02/2024		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	DrivLine\DRV LN SER	grease nipples need replacing				13/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SPRING HANG	front and middle right spring wraps broken				13/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			travel out to greenfright yard check lights found lights found lights are shorting out againe got told just rewire the whole taillights wiring. remove wiring broken side markers and number plate lights and rh taillight since th is brand new. travel back to shop pickup parts. travel back out to														
T471	Albury - Workshop	Elect\TRL LIGHTS	ewenfrraht ward reolace wirine and liehts test ok.				07/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TPS2	Tyre Position 12				06/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\CLEANSION	no pos - fitted tyres by driver				02/02/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				31/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CHAS CRACK	WEBBING CRACKED LHS. 1ST WINCH MOUNT SMALL CRACK.				31/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CROSS MBR	1ST WINCH MOUNT CRACKED.				31/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		31/01/2024		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TPS+10	Tyre Position 9 + 10				24/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				13/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Tyres	R/H INNER TYRE HAS A LEAK.				13/01/2024		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
						CHECK INDICATOR AND LIGHT ISSUES FOUND RH TAIL LIGHT AND T471 MOISTURE DAMAGED												
T471	Wodonga - Workshop	Elect\INDICATORS	SHORT IN BUNKERS WHEN TRAILERS ARE WET.			REPLACE AS REQUIRED	13/01/2024		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		13/01/2024		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TPS+4	Tyre Position 3 + 4				06/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				05/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK AROUND TRI.			REPLACED AIRBAG.	05/01/2024		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.				05/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		05/01/2024		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	REPLACED HYDRAULIC FITTINGS. TIGHTENED GYPSY MOTOR FITTINGS AND CROSSMEMBER BOLTS. REPAIRED AIR LINES TO B TRAILER.	21/12/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK AROUND TRI.				21/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CROSS MBR	1ST WINCH MOUNT CRACKED.				21/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			turntable push bar loose & cracked at bolt hole.														
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	Turn table need adjustine.				15/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CHAS CRACK	WEBBING CRACKED LHS. 1ST WINCH MOUNT SMALL CRACK.				15/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		15/12/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	Service				15/12/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\BRAKE ADJ	ADJUST BRAKES.				14/12/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE MISSING SHOCKER BOLT NUT. RHF TOP.				14/12/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TPS+6	Tyre Position 5 + 6				14/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TPS+10	Tyre Position 9 + 10				14/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Susp\AIR BAG	Replaced LHM Air Bag				09/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			turntable push bar loose & cracked at bolt hole.														
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	Turn table need adjustine.				05/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CHAS CRACK	WEBBING CRACKED LHS. 1ST WINCH MOUNT SMALL CRACK.				05/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\BRK RELINE	Reline RR wheel Assembly.			REPLACED S-CAM, BEARINGS, SPEED RING, AXLE NUT AND LOCK RINGS.	02/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CROSS MBR	bolts loose chassis to light bar				01/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	Replaced T/Table Top, Pins & Bushes				01/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SUSPENSION	replace lift axle components			REMOUNTED LH GUARD AND 1ST CROSSMEMBER. ADJUSTED AXLE.	30/11/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CHAS CRACK	chassis webbing cracked			REPLACED FRONT AXLE HANGER BOSSES.	30/11/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	DrivLine\ELECT P&W	Axle lift fault.				30/11/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SUSPENSION	LIFT AXLE NOT WORKING.				30/11/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SUSPENSION	Re-fit Lift Axle Mechanism				30/11/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	Service				30/11/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			TRAVEL TO DEPOT														
			CHECK TRAILER LIGHTS POPPING FUSES AND NO REAR INDICATORS														
			CHECK AND FOUND MANY SECTIONS OF DAMAGED/FAULTY TRAILER WIRING NEEDING TO BE REPLACED														
			LOCATE ALSO TRAILER BASES AND PLUGS NEEDING TO BE REPLACED ON TRUCK AND TRAILERS														
T471	Albury - Workshop	Elect\ELECT P&W					30/11/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				22/11/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Hydraulics\HYD LEAKS	hydraulic coupling leak				22/11/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CROSS MBR	bolts loose chassis to light bar				22/11/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect\INDICATORS	INDICATORS TRIPPING CIRCUIT BREAKER.				22/11/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist The following breakdown repair for Greenfreight Logging Pty Ltd, to a Elphington Trailer, vin# 6L9T25003A2E10303, registration#77382-S & number fleet number#T471 included:		VehService\DS	REPLACED HYDRAULIC COUPLINGS AND LM SHOCK BOLT.	22/11/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			* Customers contacted dealership to report breakdown * Customer advised that middle axle RHS brake booster had failed * Technician sourced additional parts * Technician then travelled to breakdown site, Jingellic Road, NSW * Inspected trailer to diagnose failure * Located confirmed failed RHS mid axle brake booster * Removed booster * Reduce replacement booster od to length & installed * Connected air system components * Pressurised, test, confirm & quality check repair * Returned trailer to service														
T471	Albury - Workshop	Brakes\BOOSTER	* Technician returned home				11/11/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job REPLACE HANGER BOSSES.				31/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	DrivLine\ELECT P&W	LIFT AXLE OUT OF SERVICE UNTIL BOSSES ARE REPLACED				31/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SUSPENSION	replace lift axle components				31/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CHAS CRACK	chassis webbing cracked				31/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Hydraulics\HYD LEAKS	hydraulic coupling leak				31/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\CROSS MBR	bolts loose chassis to light bar				31/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			turntable push bar loose & cracked at bolt hole.														
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	Turn table need adjusting.				31/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect\TRL LIGHTS	lights at 2nd bolster intermittant				31/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SUSPENSION	LIFT AXLE NOT WORKING.				31/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	REPLACED STRAPS, 2ND BOLSTER MAGNETIC SWITCH AND LF SHOCK.	31/10/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\WINCH/STRP	REPLACE FRONT QUICK RELEASE CORD.				20/10/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SUSPENSION	LIFT AXLE NOT WORKING.				20/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		20/10/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.				20/10/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TPS+10	Tyre Position 9 + 10				18/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\WINCH/STRP	Front bolster remote release missing.				17/10/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	DrivLine\ELECT P&W	Axle lift fault.			REMOVED COMPONENTS FOR LIFT AXLE UNTILL BOSSES CAN BE REPLACED.	14/10/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\HCV	Check Operation Of HCV & RTR Valve			CHECKED. OK.	14/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SUSPENSION	Tightened RHM U-Bolts				14/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TPT+8	Tyre Position 7 + 8				06/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER

T471	Albury - Workshop	Tyres|TP11+12	Tyre Position 11 + 12				06/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AXLES	LIFT AXLE N/A.				06/10/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			06/10/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
					found faul code to RHR axle-											
T471	Wodonga - Workshop	Brakes|EBS FAULTS	Repair EBS Faults		removed wheels & hub reset sensor after checking ohms - OK		06/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes|BOOSTER	Replaced RHR B/Booster		replaced sensor ring & reassemble. Cleared codes		06/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			Replaced Broken Shocker-LHM													
T471	Wodonga - Workshop	Susp|SHOCK ABS	Tightened Loose Shocker Bolts-LHF.RHM				06/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			Tightened LHM SEBOLT		Dismantled LHF to replace components, worn sebosses, put old parts back on with new SEB											
T471	Wodonga - Workshop	Susp|SUSPENSION	LHF SEB		left lift axle airbae and sorine off		06/10/2023	Reair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|SUSPENSION	replace lift axle components				06/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			chassis webbing cracked													
T471	Wodonga - Workshop	Chassis|CHAS CRACK	winch extension cracked				06/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Hydraulics|HYD LEAKS	hydraulic coupling leak				06/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|CROSS MBR	bolts loose chassis to light bar				06/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			turntable push bar loose & cracked at bolt hole.													
T471	Wodonga - Workshop	Chassis|FIFTH WHEE	Turn table need adjustme				06/10/2023	Reair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect|TRL LIGHTS	lights at 2nd bolster intermittant				06/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres|TP1+2	Tyre Position 1 + 2				03/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres|TP3+4	Tyre Position 3 + 4				03/10/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				29/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS	TIGHTENED FRONT SHOCKS. CHECKED ABS CODES.		29/09/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Myrtleford - Workshop	Susp|AIR BAG	REPAIRED AIR LEAK LIFT AXLE AIRBAG.				24/09/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Myrtleford Workshop	TRAILER
T471	Myrtleford - Workshop	Chassis|AIR LEAK	REPAIRED AIR LEAK AT AIR TANK.				24/09/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Myrtleford Workshop	TRAILER
T471	Myrtleford - Workshop	Elect|EJECT P&W	REPAIRED SCALE PLUG.				24/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Myrtleford Workshop	TRAILER
T471	Wodonga - Workshop	Susp|SUSPENSION	Suspension To High- Adjusted To Correct Height				20/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist (TCTC)													
T471	Albury - Workshop	VehService|DS	Purchase Order Number: T081048	VehService|DS			14/09/2023	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				14/09/2023	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis|EXTE TU	1ST WINCH MOUNT CRACKED.				14/09/2023	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Comp|Truck Safe	REPLACE NHVAS STICKER.				14/09/2023	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Body|MUDGUARDS	REPLACE BROKEN FRONT LEFT MUDGUARD.				14/09/2023	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Susp|AIR BAG	REPLACE LIFT AXLE AIRBAG.				14/09/2023	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			Brake Reline (Mast Parts)													
T471	Albury - Workshop	Brakes|BRK RELINE	Purchase Order Number: T080745				02/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis|CHAS CRACK	Weld/Repair Various Cracks				02/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Brakes	REPAIRED BRAKES AND GUARDS.				02/09/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				31/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Body|MUDGUARDS	REPLACE BROKEN FRONT LEFT MUDGUARD.				31/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	REPLACE LIFT AXLE AIRBAG.				31/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|EXTE TU	1ST WINCH MOUNT CRACKED.				31/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Comp|Truck Safe	REPLACE NHVAS STICKER.				31/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			31/08/2023	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.				31/08/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	REPLACE BLOWN AIRBAG ON LIFT AXLE.				23/08/2023	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres|TP9+10	Tyre Position 9 + 10				22/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres|TP11+12	Tyre Position 11 + 12				22/08/2023	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				18/08/2023	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist (TCTC)													
T471	Albury - Workshop	VehService|DS	Purchase Order Number: T080402	VehService|DS			18/08/2023	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis|BOLSTER	2ND BOLSTER CRACKS AT MOUNT.				18/08/2023	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Body|MUDGUARDS	FRONT L/H GUARD BROKEN.				18/08/2023	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres|TRDS	Tyre Position 5				18/08/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/08/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			11/08/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE TRAILER.				11/08/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres|TP5+6	Tyre Position 5 + 6				11/08/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				01/08/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Body|MUDGUARDS	REPLACE MUDFLAPS. ORDERED.				01/08/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|BOLSTER	2ND BOLSTER CRACKS AT MOUNT.				01/08/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AXLES	LIFT AXLE NOT WORKING.		REPLACED LIFT AXLE CYLINDER AND ADJUSTED RIDE HEIGHT.		01/08/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	AIR LEAK ON LIFT AXLE AIRBAG.				01/08/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|HCV	HEIGHT CONTROL VALVE/ LIFT AXLE VALVE TO BE REPLACED.				01/08/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Body|MUDGUARDS	REPLACE ALL MUDFLAPS.				01/08/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			01/08/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE TRAILER.				01/08/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
					TRAVEL TO GREENFREIGHT YARD											
					test and blinker not working											
					check and found popped CB reset and test and found shorting out on RH side											
T471	Albury - Workshop	Elect|INDICATORS	CHECK BLINKERS N/W		check and found short to earth on trailer lead from A to B reapir and test and found workine fine		01/08/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.				20/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AXLES	LIFT AXLE NOT WORKING.				20/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect|INDICATORS	NO INDICATORS.		FOUND BLOWN FUSE.		20/07/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	AIR LEAK ON LIFT AXLE AIRBAG.				20/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|HCV	HEIGHT CONTROL VALVE/ LIFT AXLE VALVE TO BE REPLACED.				20/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Body|MUDGUARDS	REPLACE ALL MUDFLAPS.				20/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			20/07/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Body|MUDGUARDS	REPLACE MUDFLAPS. ORDERED.				20/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|BOLSTER	2ND BOLSTER CRACKS AT MOUNT.				20/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes|BOOSTER	Replaced RHM B/Booster				12/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|SHOCK ABS	Replaced RHM Seized Shocker				12/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes|BOOSTER	REPLACE BROKEN BOOSTER.				12/07/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes|BOOSTER	REMOVED RM BROKEN BOOSTER.				12/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	Replaced RHR Airbag				11/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	REPLACE BLOWN AIRBAG.				11/07/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect|BRK LIGHT	BRAKE LIGHTS STUCK ON BOTH TRAILERS.				01/07/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	L/H REAR AIRBAG LEAK.				01/07/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AXLES	LIFT AXLE NOT WORKING.				01/07/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	REAR LEFT AIRBAG IS LEAKING.				01/07/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
					Removed middle axle wheels.											
T471	Wodonga - Workshop	Elect|EJECT P&W	EBS Issues		Reolaced ABS sensor and sensor rines.		01/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|WINCH/STRP	REPAIR/ REPLACE LR QUICK RELEASE CABLE MOUNT.				28/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			28/06/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|FIFTH WHEE	REPAIR GUARD FOR HOSES AND CABLES AT TURNTABLE.				28/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AXLES	LIFT AXLE NOT WORKING.				28/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp	LIFT AXLE NOT WORKING.		Refer job # 413548		28/06/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AXLES	LIFT AXLE NOT WORKING.		Refer job # 413548		28/06/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	Replace LHR airbag.				28/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|SPRING HANG	Replace LHM Spring eye bush bolt & nut.				28/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	A SERVICE.				28/06/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres|TP1+2	Tyre Position 1 + 2				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres|TP7+8	Tyre Position 7 + 8				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres|TP9+10	Tyre Position 9 + 10				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres|TP11+12	Tyre Position 11 + 12				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|FIFTH WHEE	REMOVE REQUIRED UNKS AND ADJUST LOAD CHAIN.				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	REPLACE LEAKING LR AIRBAG.				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	REPLACE LEAKING LR AIRBAG.				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS	ADJUSTED LOAD CHAIN. REPAIRED LH TAIL LIGHT WIRING.		14/06/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect|TRL LIGHTS	TRAILER LIGHT PLUG DOESN'T SEAT IN FEMALE CONNECTOR ON "B" TRAILER PROPERLY AND WRIGGLES OUT THROUGH THE NIGHT.				14/06/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	L/H REAR AIRBAG LEAKING AIR.				14/06/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|FIFTH WHEE	TIGHTEN LOAD CHAIN.				14/06/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AXLES	LIFT AXLE NOT WORKING.				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes|EBS FAULTS	EBS LEAD IS UNPLUGGED. BRAKING IS FAR TOO SEVERE SINCE TCTC REPAIRED BRAKES.				14/06/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp	LIFT AXLE NOT WORKING.				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AXLES	LIFT AXLE NOT WORKING.				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.				14/06/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|WINCH/STRP	REPAIR/ REPLACE LR QUICK RELEASE CABLE MOUNT.				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|FIFTH WHEE	REPAIR GUARD FOR HOSES AND CABLES AT TURNTABLE.				14/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect|TRL LIGHTS	TRAILER LIGHT PLUG DOESN'T SEAT IN FEMALE CONNECTOR ON "B" TRAILER PROPERLY AND WRIGGLES OUT THROUGH THE NIGHT.				04/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	REPLACE LEAKING LR AIRBAG.				04/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	REPLACE LEAKING LR AIRBAG.				04/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				04/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|FIFTH WHEE	REMOVE REQUIRED UNKS AND ADJUST LOAD CHAIN.				04/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	L/H REAR AIRBAG LEAKING AIR.				04/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|FIFTH WHEE	TIGHTEN LOAD CHAIN.				04/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AXLES	LIFT AXLE NOT WORKING.				04/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes|EBS FAULTS	EBS LEAD IS UNPLUGGED. BRAKING IS FAR TOO SEVERE SINCE TCTC REPAIRED BRAKES.				04/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp	LIFT AXLE NOT WORKING.				04/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.				04/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			04/06/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.				04/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				27/05/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|FIFTH WHEE	REMOVE REQUIRED UNKS AND ADJUST LOAD CHAIN.				27/05/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	REPLACE LEAKING LR AIRBAG.				27/05/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect|TRL LIGHTS	TRAILER LIGHT PLUG DOESN'T SEAT IN FEMALE CONNECTOR ON "B" TRAILER PROPERLY AND WRIGGLES OUT THROUGH THE NIGHT.				27/05/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp|AIR BAG	L/H REAR AIRBAG LEAKING AIR.				27/05/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis|FIFTH WHEE	TIGHTEN LOAD CHAIN.				27/

					- Raise front axle and support.														
					- Remove broken shock mount and snapped u-bolts.														
					- Lower spring and replace spring wrap.														
					- Refit spring and replace bolts as required.														
T471	Myrtleford - Workshop	Susp\SPRING HANG	LIFT AXLE HANGER CRACKED.		- Lower axle and tension all.		29/04/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Myrtleford - Workshop	Elect\TRL LIGHTS	TRAILER LIGHT PLUG DOESN'T SEAT IN FEMALE CONNECTOR ON "B" TRAILER PROPERLY AND WRIGGLES OUT THROUGH THE NIGHT.				29/04/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Myrtleford - Workshop	Brakes\BRK RELINE	DURING SERVICE FOUND AXLE 3 BOTH SIDES AND AXLE RHS BRAKE LININGS LOW				29/04/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
			CRACK TEST BOLSTER PEGS																
T471	Albury - Workshop	Chassis\BOLSTER	no cracks found				29/04/2023		Reair	Completed	Greenfreight Loxeine NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
			Trailer winch mechanism.																
			Remove seized drive hub and clean up spindle, polish up all																
			surfaces and replace seal. Dismeantle hyd motor and																
T471	Albury - Workshop	Chassis\WINCH/STRP	dismantle and repair. Reelace motor and setup and test unit.				20/04/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\JAMB ARM	replace all hoses for umbilical arm				13/04/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
			Repair umbilical arm electrical																
			Rapid Hydraulics PO# WW077457																
T471	Wodonga - Workshop	Elect\ELECT P&W	Rapid Hydraulics P/O: WW077698				24/03/2023	990928	Reair	Completed	Greenfreight Loxeine NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
			WIRE UP A & B TRAILERS AS REQUIRED																
			travel to job and help remove scale wiring																
			GF to refit pack up and travel back																
T471	Albury - Workshop	Elect\ELECT P&W	TRAVEL TO GREEN FREIGHTS YARD				23/03/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				10/03/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Susp\SPRING HANG	LIFT AXLE HANGER CRACKED.				10/03/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/03/2023		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
			No Channel 3 Scales		Replaced Scale Plug. (domcar)														
T471	Wodonga - Workshop	Elect\ELECT P&W	Needs to come off the road to reolace wirne.		Purchase Order Number: WW077432		08/03/2023		Reair	Completed	Greenfreight Loxeine NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
					Test scale plugs, Master slave to transducer harness good.														
					Master to plug on front of trailer good.														
					Master slave to rear plug through umbilical arm open circuit.														
					Drop and disconnect T472.														
					Strip umbilical arm scale plug harness, given to Arkon to make new one.														
					Notified Shaun to refer hydraulic hoses to Rapid.Replaced light plug harness and covered in conduit and nylon hose for extra protection.														
					Cut out damaged constant air hoise and made up new one.to be covered in spiral wrap and refitted.														
					Wraped brake hose in spiral wrap.														
					Replace hydraulic hoses.														
					Spiral wrap, hydraulic hoses and replace EBS loom.														
			No Channel 3 Scales		Replace slide lock supply hoses and scale loom.														
T471	Wodonga - Workshop	Elect\ELECT P&W	Needs to come off the road to reolace wirne.		Reolace constant air hose.		08/03/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6				05/03/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2				01/03/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12				01/03/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				01/03/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/03/2023		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Susp\SPRING HANG	LIFT AXLE HANGER CRACKED.				01/03/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes\EBS FAULTS	REPLACED LM RM WHEEL SENSORS. CLEARED CODES. UNHOOKED.				01/03/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			23/02/2023	990928	Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				23/02/2023	990928	Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Unknown	SERVICE.				23/02/2023	990928	Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	Replaced Load Chain, Gypsy & All Rollers				23/02/2023	990928	Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\HOUSEKEEP	SWEEP OFF BROOM HANDLE BROKE OFF, NEED REPLACED.				23/02/2023	990928	Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				22/02/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	Replace Worn Load Chain				03/02/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Workshop\MOVE ASSET	Unhooked Trailer From Fleet No: #999		HOOKED UP TO 984.		02/02/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	Replaced Load Chain, Gypsy & All Rollers				02/02/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/01/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	TIGHTENED LOOSE BOOSTER FITTING.		28/01/2023		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Elect\ELECT P&W	REWIRE SCALE PLUG.				21/01/2023		Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/01/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\CHAS CRACK	SMALL CRACKS 6TH FROM FRONT WEBBING.				20/01/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\BOLSTER	2ND BOLSTER CRACKED BOTH SIDES REAR.				20/01/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Susp\SPRING HANG	LF HANGER CRACKED.				20/01/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	REPLACE LOAD CHAIN.				20/01/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/01/2023		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Hydraulics\HOSES	REPAIRED LEAKING HYDRAULIC HOSE.				18/01/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/01/2023	990928	Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				12/01/2023	990928	Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Body\MUDGUARDS	REPLACE GUARDS.				12/01/2023	990928	Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Body\MUDGUARDS	REPLACE RH MUDGUARD.				12/01/2023	990928	Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes\BRAKE ADJ	CHECK BRAKES.				12/01/2023	990928	Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4				11/01/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/01/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Body\MUDGUARDS	REPLACE RH MUDGUARD.				06/01/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/01/2023		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	REPLACE LOAD CHAIN.				06/01/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Body\MUDGUARDS	REPLACE GUARDS.				20/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\CHAS CRACK	SMALL CRACKS 6TH FROM FRONT WEBBING.				20/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/12/2022		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\BOLSTER	2ND BOLSTER CRACKED BOTH SIDES REAR.				20/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Susp\SPRING HANG	LF HANGER CRACKED.				20/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes\BRK RELINE	RELINE RR.		UNHOOKED B TRAILER. REUNED RR. REPLACED RR WHEEL SENSOR AND LM SENSOR LEAD. SWAPPPED REAR LEADS AS FITTED INCORRECTLY. CHECKED WHEEL BEARINGS. ADJUSTED LM LR. HOOKED UP		20/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Susp\SUSPENSION	Replaced Lift Axle Bolt Nut- Worn				16/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Susp\SUSPENSION	REPLACE SPRING EYE BOLT NUT.				16/12/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Albury - Workshop	Body\CHN/RUR/MN	Chain, Roller & Mounts				08/12/2022	990928	Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Wodonga - Workshop	Body\CHN/RUR/MN	Replaced Rear Load Rollers				08/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Myrtleford - Workshop	Chassis\HOUSEKEEP	straighten bent rail				08/12/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Myrtleford Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				08/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Body\MUDGUARDS	REPLACE GUARDS.				08/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\CHAS CRACK	SMALL CRACKS 6TH FROM FRONT WEBBING.				08/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/12/2022		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes\EBS FAULTS	REPLACE SPEED SENSOR ON R/HAND SIDE.		DIAGNOSED AND REPLACED RM RR SENSORS.		08/12/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Unknown	SERVICE.				08/12/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Unknown	SERVICE.				08/12/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				30/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/11/2022		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Body\MUDGUARDS	REPLACE GUARDS.				30/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\CHAS CRACK	SMALL CRACKS 6TH FROM FRONT WEBBING.				30/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				24/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			24/11/2022		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Albury - Workshop	Tyres\TP1+2	Tyre Position 1 + 2				24/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				19/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
			Adjust load chain and inspect issue with loading T472																
T471	Wodonga - Workshop	Body\CHN/RUR/MN	ADJUSTED. STILL NOT LOADING CORRECTLY.				19/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/11/2022		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Body\CHN/RUR/MN	Adjust load chain and inspect issue with loading T472		ADJUSTED CHAIN. STILL HAVING ISSUES LOADING. ADVISED DRIVER TO FLAT TOW.		16/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				11/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
					- RH mudguard split														
					- Cracked weld on second bolster both sides														
					- FL spring wrap broken														
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	- Both front mudflaps damaged		11/11/2022		Service	Completed	Greenfreight Loxeine NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Albury - Workshop	Tyres\TP04	Tyre Position 4				07/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
			questioned Beaurepaires why the same pos was changed in a matter of days																
			Beaurepaires reply																
			Just asked the truckfitters,																
			The positions were right apparently the tread came off the Tyres and greenfreight are putting in a claim for the retreads.The trailer was put into																
T471	Albury - Workshop	Tyres\TP7+8	the boys workshop for two new drive tyres				05/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
					Inspect for Hydraulic leaks. Inspected & topped up hydraulic oil on PM999.														
					Tested operation, hydraulic oil squirting out amongst cover for connectionson front of trailers.														
					Washed amonst truck and trailer removed cover and inspected during operation hydraulic hose rubbed against gusset in trailer. Driver checked with operations to swap out trailers with T521/522														
					until repairs complete.														
T471	Wodonga - Workshop	Hydraulics\HYD LEAKS	Major Hydraulic Leak		Swaooed trailers over for driver. hooked 984 to T471/472 and moved into awnine for raoid to reoair.		04/11/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				03/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/11/2022		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4				03/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				03/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				03/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\BOLSTER	2ND BOLSTER GUSSETS CRACKED.				02/11/2022	990928	Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Tyres\TP05	RIM INNER TYRE BULGING.				02/11/2022	990928	Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Comp\Truck Safe	NHVAS STICKER OUT OF DATE.				02/11/2022	990928	Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Hydraulics\HYD LEAKS	hydraulic hose to gypsy motor leaking		rapid Powa074844		02/11/2022	990928	Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12				30/10/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Wodonga - Workshop	Chassis\MUDGUARDS	Replaced LH Guard				27/10/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Albury - Workshop	Susp\AXLES	Setup axle, line bore and re-bush S-Cam as required				26/10/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Albury Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/10/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			21/10/2022		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Drivline\WHEEL SEAL	LM RM LR HUB SEALS LEADING.				19/10/2022	990928	Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
			Replace broken spring wrap		- Lower spring eye and replace broken spring wrap.														
T471	Wodonga - Workshop	Susp\SUSPENSION	RHR SPRING WRAP REPORTED TO BE BROKEN. CHECK ALL AND REPAIR AS REQUIRED		- Raise sprine eve and tension.		19/10/2022	990928	Repair	Completed	Greenfreight Loxeine NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
					CUSTOMER REPORTS AXLES 1 & 3 REQUIRE RELINE. CHECK ALL BRAKES AND RELINE AS REQUIRED														
					- Raise and support axles.														
					- Remove wheels, hubs and brakes.														
					- Inspect and found 5x linings required replacement.														
					- Decision made to replace all.														
					- Found 5x s-cams to have excessive movement.														
					- Decision made to replace all.														
					- Found middle axle scam bore to be excesively worn and unable to hold new bush.														
					- Remove axle and send to Wodonge engineering for repair.														
					- Reinstall axle with new s-cams and linings.														
					- Replaced 1x damaged ABS sensor and pulse ring														
					- Replace remaining s-cams, tubes and brake linings.														
					- Replace drums as oversized.														
					- Clean and inspect hubs and bearings, ok.														
					- Refit hubs and adjust bearings.														
T471	Wodonga - Workshop	Brakes\BRK RELINE	Reline all Brakes and replace S-Cams as required.		- Fit wheels and lower axles. Tension wheel nuts		19/10/2022	990928	Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Susp\AIR BAG	Replace U/S Airbags as required.				19/10/2022	990928	Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/10/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Body\MUDGUARDS	FIT NEW MUDFLAP ON FRONT LEFT.				15/10/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/10/2022		Service	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Unknown	SERVICE.				15/10/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Tyres\TP05	RIM INNER TYRE BULGING.				15/10/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		
T471	Wodonga - Workshop	Comp\Truck Safe	NHVAS STICKER OUT OF DATE.				15/10/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy&PW	Albury	ATK	773825	Wodonga Workshop	TRAILER		

T471	Wodonga - Workshop	Driv/ine\WHEEL SEAL	LM RM LR HUB SEALS LEAKING.				15/10/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\BRK RELINE	RELINE RR.				15/10/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.				15/10/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/10/2022 990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/10/2022 990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LHS BRAKES.				06/10/2022 990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				17/09/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/09/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP04	fit runout				03/09/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				27/08/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED LR SEB.		27/08/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\BRK RELINE	RELINE LHS BRAKES.				27/08/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				19/08/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\BOLSTER	2ND BOLSTER GUSSETS CRACKED.				19/08/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Body\MUDGUARDS	FIT NEW MUDFLAP.				19/08/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/08/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP3+2	supply and fit 4 tyres				17/08/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6				17/08/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Elect\ELECT P&W	FIT NEW PLUG ON SUDE BOLSTER.		REPLACED 2ND BOLSTER LIGHT MAGNETIC CONNECTOR.		17/08/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/08/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\BOLSTER	2ND BOLSTER GUSSETS CRACKED.				11/08/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Body\MUDGUARDS	FIT NEW MUDFLAP.				11/08/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REUINED RR BRAKE. REPAIRED TOOLBOX.		11/08/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.				11/08/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				04/08/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			04/08/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\AXLES	LIFT AXLE NOT WORKING.		CHECKED POWER. FOUND PIN IN SOCKET PUSHED IN. PULLED PIN TO CORRECT POSITION.		02/08/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/07/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED RIDE HEIGHT.		28/07/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				17/07/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist CALLED OUT TO SHELLEY.	VehService\DS			17/07/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\AIR LEAK	BRAKES DRAGGING. GETTING HOT.		FOUND AND REPAIRED AIR LEAK. CHECKED ADJUSTMENT.		15/07/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\BOLSTER	2ND BOLSTER GUSSETS CRACKED.				12/07/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService	Service		DONE 6/7/22		12/07/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	Check T/Table jaws		UNHOOKED. INSPECTED. FITTED DOGBONES.		12/07/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/07/2022 990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/07/2022 990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP11+12	supply and fit 2tyres				05/07/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Elect\ELECT P&W	Bad connection slide bolster light				29/06/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				22/06/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\BOLSTER	2ND BOLSTER GUSSETS CRACKED.				22/06/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			22/06/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect\TRL LIGHTS	Cleaned pins for 2nd bolster				22/06/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
					Reline LHM, RHM & RHR brakes and bearings											
					Refit umbilical arm											
					Replaced lift axle velves (not filling airbag)											
					Hookup T472											
					Tensioned LHM wheel nuts											
T471	Wodonga - Workshop	Brakes\BRK RELINE	Both middle axles and RHR due for reline		Adjusted brakes		22/06/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.				22/06/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/06/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/06/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				04/06/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\BOLSTER	2ND BOLSTER GUSSETS CRACKED.				04/06/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Driv/ine\WHEEL ALGN	Trailers tracking out badly.				04/06/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			04/06/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/05/2022 990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				25/05/2022 990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.		Refer to Job # 382153		25/05/2022 990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				19/05/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED STRIPPED LM SHOCK BOLT.		19/05/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect\ELECT P&W	REPLACE L/H SIDE LIGHT ON CHECKER PLATE.		REPLACED LIGHT AND WIRING.		19/05/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.				19/05/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.				19/05/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\BOLSTER	2ND BOLSTER GUSSETS CRACKED.				19/05/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP7+8	supply and fit 2tyres				12/05/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				12/05/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/05/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\HCV	CHECK HEIGHT ON SUSPENSION.		ADJUSTED.		03/05/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				30/04/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/04/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\EBS FAULTS	EBS DISCONNECTED. PULLS UP ON MOST L/H BENDS WHEN LOADED		CHECKED CODES AND FOUND RR AXLE ABS CABLE LOOSE.		27/04/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/04/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\BRK RELINE	RELINE REAR AXLE.				15/04/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/04/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				02/04/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Comp\Truck Safe	REPLACE DAMAGED NHVAS STICKER.				02/04/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Tyres\TP11+12	RR INNER TYRE U/S.				02/04/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Tyres	TYRE FITTER TO CHECK ALL TYRES PLEASE.				02/04/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/04/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\BRK RELINE	RELINE REAR AXLE.				02/04/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE				02/04/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP3+4	SUPPLY AND FIT 2TYRES				02/04/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\EXTE TU	REPLACE FRONT WINCH.		REPLACED		31/03/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\EXTE TU	FRONT WINCH FAULTY.		REPLACED		31/03/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SUSPENSION	REPLACE BROKEN 2 SPRRING.		REPLACED RF SPRING AIRBAG AND HARDWARE.		31/03/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12				24/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP5+6	SUPPLY AND FIT 6 TYRES				24/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				24/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				19/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	ADJUST LOAD CHAIN.				19/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SPRING HANG	LIFT AXLE HANGER CRACKED.				19/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Body\TOOLBOX	TOOLBOX LID NEEDS RE-SECURING.				19/03/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE.				19/03/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Tyres\TP11+12	RR INNER TYRE U/S.				19/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	TIGHTENED FRONT AXLE U-BOLTS.		19/03/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				12/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Comp\Truck Safe	REPLACE DAMAGED NHVAS STICKER.				12/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Driv/ine\WHEEL ALGN	Trailers tracking out badly.				12/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Tyres	TYRE FITTER TO CHECK ALL TYRES PLEASE.				12/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/03/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\WINCH/STRP	Straighten Winch Handle.		Straightened 2nd winch handle.		04/03/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				04/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			04/03/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	A SERVICE				04/03/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Comp\Truck Safe	REPLACE DAMAGED NHVAS STICKER.				04/03/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE				22/02/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				22/02/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			22/02/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SPRING HANG	LIFT AXLE HANGER CRACKED.				22/02/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				16/02/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			16/02/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\FIFTH WHEE	ADJUST LOAD CHAIN.				16/02/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE				16/02/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\EXTE TU	T PIECE ON AIR WINCH FITTING BROKEN.		REPLACED TAP. TESTED.		15/02/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				08/02/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SPRING PACK	RHR Spring cap broken.				08/02/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Driv/ine\WHEEL ALGN	Trailers tracking out badly.				08/02/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/02/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect\ELECT P&W	REPLACED RH REVERSE LIGHT. PARKED.				08/02/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP11+12	supply and fit 2tyres				06/02/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP1+2	supply and fit 5 tyres				03/02/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP06	Tyre Position 6				03/02/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				03/02/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/01/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\HCV	Repair HCV rod end				20/01/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/01/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Unknown	SERVICE				20/01/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP7+8	supply and fit 2tyres				18/01/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				13/01/2022	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			13/01/2022	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Susp\SUSPENSION	REPAIR SUSPENSION ON REAR AXLE.		INSPECTED REAR AXLE. FOUND RH ALIGNMENT PLATE WELD BROKEN. MEASURED, WELDED AND REPLACED PLATE. ASSEMBLED AND REPLACED SHOCK.		07/01/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
					Broken wheel studs - removed hub assembly.											
					Replaced all wheel studs(damaged, Broken and Worn)											
T471	Wodonga - Workshop	Driv/ine\Rims	Replace broken studs and replace tyres.		Reassembled hub assembly and fitted 2 new tyres/wheels and tensioned.		05/01/2022	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\BRK O/HAUL	REQUIRES REUNES				30/12/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				24/12/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\BRK O/HAUL	REQUIRES REUNES				24/12/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			24/12/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes\ABS	ABS LIGHT ON. ADJUSTED WHEEL BEARINGS AND RESET SENSORS.				21/12/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				18/12/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Body\CHN/RLR/MIN	Chain Adjuster Bearings and Chain Rollers in need of attention.		CHECKED. OK. ADJUUSTED LOAD CHAIN.		18/12/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brak

T471	Wodonga - Workshop	Brakes\BRK O/HAUL	REQUIRES RELINES			25/11/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Unknown	SERVICE			25/11/2021	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/11/2021	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AIR BAG	RF & LHM Airbags			19/11/2021	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Tyres\TP02	P2 Tyre U/S			19/11/2021	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/11/2021	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Unknown	SERVICE		#361185	19/11/2021	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP9+10	supply and fit 2 tyres			17/11/2021	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/11/2021	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AIR BAG	LIFT AXLE AIR BAG BLOWN			10/11/2021	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/11/2021	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AIR BAG	REPLACE LIFT AXLE AIR BAG.		#360183	10/11/2021	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Unknown	A SERVICE			10/11/2021	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Unknown	SERVICE			10/11/2021	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP1+2	supply and fit 3tyres			05/11/2021	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP03	Tyre Position 3			05/11/2021	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
					CHECKED AND ADJUSTED ALL BRAKES. RR HOTTER THAN THE REST. JACKED UP RR AXLE, CHECKED WHEEL BEARINGS. OK. CHECKED BRAKE APPLICATION. OK.														
T471	Wodonga - Workshop	Brakes\BRAKE ADJ	AXLE HUBS SEEM HOTTER THAN SHOULD BE PLEASE CHECK		DRIVER TO MONITOR.	02/11/2021	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/10/2021	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/10/2021	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP11+12	supply and fit 2 tyres			28/10/2021	982559	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
					Replaced 2nd bolster light plug & socket.														
T471	Wodonga - Workshop	Elect\TRL LIGHTS	Slide bolster plug faulty.		Tested lights all OK.	19/10/2021	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/10/2021	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Body\CHN/RUR/MN	Chain Adjuster Bearings and Chain Rollers in need of attention.			16/10/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	DrivLine\WHEEL ALIGN	Trailers tracking out badly.			16/10/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/10/2021	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\MUDGUARDS	Replace torn mudflap.		Replaced all mudflaps on A trailer.	16/10/2021	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
					Checked forpower at solenoids and Aux switch in chassis. No power found.														
					Checked at plug in front of trailer OK.														
					Pins inside socket were pushed in.														
					Pulled back out - power to solenoids and Aux switch, now working.														
T471	Wodonga - Workshop	Susp\AXLES	Please fix lift axle		Lift axle workine correctly.	16/10/2021	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SUSPENSION	LIFT AXLE NOT WORKING		Refer Job# 357526	16/10/2021	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AXLES	Lift axel doesn't work.		Refer Job# 357526	16/10/2021	990928	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SPRING HANG	Replaced LHF Spring eye bush.			16/10/2021	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SHOCK ABS	Replaced RHM Shock.			16/10/2021	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\AMB ARM	Replaced all umbilical arm bearings and front umbilical arm.			16/10/2021	990928	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service due.	VehService\DS	Refer Job# 357298	16/10/2021	990928	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Elect\TRL LIGHTS	REVERSE LIGHTS AND WORK LIGHTS WIRED BACK TO FRONT		#356438	08/10/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/10/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/10/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service due.	VehService\DS	Refer Job# 356290	06/10/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP3+4	supply and fit2 tyres			30/09/2021	625700	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/09/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	Service Due.	VehService\DS	Refer Job# 355295	28/09/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Tyres\Punct	Puncture Repair			24/09/2021	625600	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\BOLSTER	Faulty plug on slide bolster.		Repaired wiring Harness at front bolster.	18/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AXLES	Lift axel doesn't work.			18/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/09/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\BOLSTER	Power lead fitting into front sliding bolster broken.		Refer Job# 354382	18/09/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AXLES	Lift Axle has not worked for weeks.		Refer Job# 354383	18/09/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\MUDGUARDS	Replace left mudgaard.		Replaced LHF Guard.	18/09/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SPRING HANG	Replaced RHR Spring eye bush, spring wrap and spring eye bolt.			18/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\AIR LEAK	Repaired air leaks @ middle axle.			18/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Tyres\RUN OUT	fit to spare			16/09/2021	625000	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP5+6	supply and fit 2 tyres			14/09/2021	624650	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\BOLSTER	Faulty plug on slide bolster.			07/09/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AXLES	Lift axel doesn't work.			07/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/09/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService	Service Due.		Refer Job# 352836	07/09/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/09/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AIR BAG	RF & LHM Airbags			01/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Tyres\TP02	P2 Tyre U/S			01/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Body\CHN/RUR/MN	Chain Adjuster Bearings and Chain Rollers in need of attention.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	Service due.	VehService\DS	Refer Job# 352207	01/09/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service Due.	VehService\DS	Refer Job# 352207	01/09/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
					Found lift axle air line and booster air line had rubbed through.														
					Removed and replaced both.														
T471	Wodonga - Workshop	Chassis\AIR LEAK	Air leak with brakes off.		Tested which had corrected the issue.	28/08/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\AIR LEAK	Repair Air Leak.		Refer Job# 352091	28/08/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP5+6	Supply and fit 2 tyres, 1 puncture repair			28/08/2021	622500	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			28/08/2021	622500	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/08/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\BOLSTER	Plug on side bolster faulty.			26/08/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\AXLES	Left Axle not working.			26/08/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/08/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Steering\WHEEL ALIGN	Perform laser wheel alignment on triaxle			19/08/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/08/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/08/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes\AIR LEAK	Air leak at first tank.		Replaced service line coupling and fitting to B-Trailer.	17/08/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
			Major air leak under trl																
T471	Wodonga - Workshop	Chassis\AIR LEAK	Booster/Air line??		Refer Job# 350550	17/08/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	Service due.	VehService\DS	Refer Job# 350192	17/08/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/08/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\EXTE TU	Faulty air supply to front strap.			10/08/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Hydraulics\HYD LEAKS	Hydraulic cpouplings leaking.			10/08/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/08/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	Service due.	VehService\DS	Refer Job# 349624	10/08/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
			Fill hydraulic tank and unload trailer for access.																
			Remove hose protection plates under skid plate.																
			Call rapid for hose repair.																
T471	Wodonga - Workshop	Hydraulics\BREAKDOWN	Handed iob over to dav shift.			04/08/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
					Repair blown hydraulic hose.														
T471	Wodonga - Workshop	Hydraulics\BREAKDOWN	blown hydralics hose		Refill 970 hydraulic tank and test.	04/08/2021	918407	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Hydraulics\HOSES	Repair broken hydraulic hose.		Refer Job# 348629	04/08/2021	918407	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/07/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/07/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service due.	VehService\DS	Refer Job# 348222	30/07/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/07/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/07/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SPRING HANG	Spring eye bush			24/07/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\AS	Service due.			24/07/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Body\CHN/RUR/MN	Removed and Replaced chain adjuster pully.			16/07/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes\BRAKE ADJ	Adjusted Brakes.			16/07/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			14/07/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	TIGHTENED SHOCKS	14/07/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/07/2021	254548	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/07/2021	254548	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Unknown	Due for Service			07/07/2021	254548	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Elect\INDICATORS	RH Front indicator.			07/07/2021	254548	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\SUZI COIL	Slide lock not working.		Slide not working - Plugged connector into trailer.	01/07/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/06/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SPRING HANG	Spring eye bush		Replaced right hand middle spring eye bush.	30/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\EXTE TU	Front winch jams on release.		Driver to monitor.	30/06/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Unknown	B Service.		Refer Job# 344385	30/06/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\AIR LEAK	Locate & replaced/repaired air hoses at middle axle.			29/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP3+4	Supply and fit 2 tyres			24/06/2021	616353	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
T471	Wodonga - Workshop	DrivLine\WHEEL BRGS	LR/LM/LF/RM/RF needs adjusting.			24/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Chassis\MUDGUARDS	Cracked Gaurds.			24/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Body\BOLSTER	Cracks in second bolster.			24/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SPRING PACK	RHR Spring cap broken.			24/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SUSPENSION	Left Hand Front Spring Eye Bush.		Completed includes replacing RHM brake booster.	24/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/06/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SUSPENSION	Left Hand Front Spring Eye Bush.			22/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Unknown	Service due.			22/06/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP11+12	Supply and fit 2 tyres			22/06/2021	615533	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/06/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Wodonga - Workshop	Susp\SPRING PACK	RHR Spring cap broken.			19/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER			
T471	Albury - Workshop	Tyres\TP7+8	Supply and fit 2 tyres			16/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
					Low brakes on front and second axle.														
					LHF - 20 RHF - 20														
					LHM - 20 RHM - 10														
T471	Albury - Workshop	Brakes	Service due.		LRR - 70 RRR - 70	12/06/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
			REPAIR LOOSE SHOCKERS .																
T471	Albury - Workshop	Susp\SHOCK ABS	* Tensioned loose shockers on trailer as required			12/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
					.														
					* Ballast & remove wheel equipment														
					* Check all wheel bearings & adjust all bearings to specification														
					* Install wheel equipment & removed ballast														
T471	Albury - Workshop	Steering\WHEEL BRGS	Check Wheel Bearing Adjustment		* Test, confirm & quality check newair	12/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER			
					found R/H rear indicator broken														
T471	Albury - Workshop	Elect\INDICATORS	BROKEN INDICATOR		* Removed/reolaced broken indicator	12/06/2021

					checked chain for alignment/twist issues. All good													
T471	Rosewood - Workshop	Body\CHN/RLR/MN	adjust load chain		adjusted chain and test ran outside. All wood		25/05/2021	Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Rosewood Workshop		TRAILER
			chain (load chain) had come off roller															
T471	Rosewood - Workshop	Body\CHN/RLR/MN	loosened chain and relocated on roller				25/05/2021	Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Rosewood Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP9+10	Supply and fit 2 tyres				22/05/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/05/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
					REPAIR AIR LEAK FROM VALVE ON TRAILER.													
					* Inspected & found leak during service													
					* Removed air lines & fittings from valve													
					* Removed/replaced valve													
					* Installed fittings & air lines onto valve													
					* Tested for leaks/all ok													
T471	Wodonga - Workshop	Chassis\DAMAGE	Lift Axle pneumatic ram bent.		* Repair complete		21/05/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 20/5/21		21/05/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		Fold up trailers and reverse into top shed for repairs.		01/05/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/05/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
			RHM Top shock bolted incorrectly.															
T471	Wodonga - Workshop	Susp\SUSPENSION	RHM trailine arm missine sorine wrapper.				01/05/2021	Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	Chassis\DAMAGE	Lift Axle pneumatic ram bent.				01/05/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	Unknown	Service due				01/05/2021	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	Chassis\CHAS CRACK	Multiple cracks in the normal spots.				01/05/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	Susp\SHOCK ABS	Left Middle Shock mount snapped.				01/05/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	Unknown	Service Due.				01/05/2021	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	Susp\SPRING PACK	Assit Greg replace RHM spring arm.				28/04/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
					Broken R/H/M spring and upper shock bolt.													
T471	Wodonga - Workshop	Susp\SPRING PACK	Broken Z spring middle right axle.		Removed and reolaced broken sorine and shock mount. also had R/H/M outter tvre reolaced.		28/04/2021	Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Albury - Workshop	Tyres\TRDB	Supply and fit 1 tyre - worn tyre due to rock damage				28/04/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				25/04/2021 575246	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/04/2021 575246	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	Chassis\CHAS CRACK	Multiple cracks in the normal spots.				25/04/2021 575246	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	Susp\SHOCK ABS	Left Middle Shock mount snapped.				25/04/2021 575246	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP5+2	Supply and fit 2 tyres				22/04/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP7+8	Supply and fit 2 tyres				15/04/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				14/04/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			14/04/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP5+6	Supply and fit 2 tyres				10/04/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\STRAPS	Supply Remote Release Kit				09/04/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Wodonga - Workshop	Brakes\BOOSTER	Replace left hand Brake Booster.		Replaced Booster.		08/04/2021 563723	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	Chassis\STRAPS	Repair quick release catches.		Repair 2 x load winche latches - include parts run to TCTC.		08/04/2021 563723	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Albury - Workshop	Chassis\STRAPS	front quick release hook bent				02/04/2021	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			02/04/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\STRAPS	replaced 1st q/r hook (damaged)				02/04/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\CHN/RLR/MN	adjusted load chain				02/04/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
			tightened x-member bolts															
			50% 50%															
			70% 70%															
T471	Albury - Workshop	Chassis\CROSS MBR	70% 60%				02/04/2021	Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			02/04/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				26/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			26/03/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	DrivLine\WHEEL BRGS	LR/LM/LF/RM/RF needs adjusting.				26/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Wodonga - Workshop	Susp\AXLES	Checked over U-Bolts tensioned to 450NM.				26/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
T471	Albury - Workshop	Susp\HCV	lift axle issue airbag inflation				21/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				21/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	trailer service	VehService\DS			21/03/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Hydraulics	Supply Hydraulic Loading Roller and consumables				19/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\WORK LIGHT	load lights				18/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\CHN/RLR/MN	load rollers				18/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	rewire 2nd bolster				18/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\CHN/RLR/MN	tension load chain				18/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				18/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			18/03/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP13+12	Supply and fit 2 tyres				16/03/2021 550532	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	repair power con to slider bolster lights		replace power cable to 2nd bolster and fit new plug end		14/03/2021	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP05	Supply and fit tyre				12/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP10	Supply and fit 1 tyre				11/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	Supply Tail Lights, Socket and Magnetic Plug				10/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					A/Service bolster wiring tail light													
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		repair		10/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/03/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\AIR BAG	Supply Air Bag and Air Bag nut				03/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\CHN/RLR/MN	Supply Chain Roller Crossmembers, Hammerlock & Pivot Shaft				02/03/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				28/02/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					replaced RHM airbag													
					removed 6 links and adjusted load chain													
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced chain rollers x2		28/02/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				13/02/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			13/02/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\BOLSTER	replaced bolts in bolster mounts				11/02/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP5+6	replace 2 tyres				10/02/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop		TRAILER
			Carry out Brake reline where required, replace wheel bearings, drums and s-cams/bushes															
			Jack up rear and middle axles, removed wheels, drums and brakes. Replaced wheel bearings, brake linings and s-cams along with bushes.															
T471	Albury - Workshop	Brakes\BRK RELINE	LHR drum was reolaced. Tensioned wheels and adjusted wheel bearinas to spec				09/02/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Engine\AIR LEAK	Supply Drain Valve				06/02/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				06/02/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					tightened LHM shocker bolt													
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced 1st air tank drain cock		06/02/2021	Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	DrivLine\SHOCK ABS	Supply Consumables- Bolt Shocker Mount, Nut Washer & Shocker Tube				05/02/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	Forest Centre to supply Auto Tensioner, Big Drum, Strap, Brackets and Plates				03/02/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\CONSUMABLE	supply, ratchet grab hooks, brackets, connectors, indicator insert				26/01/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP7+8	replace 2 tyres				23/01/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				23/01/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					LH indicator													
					RH load chain anchor bolts and anchors													
					hov adjusted suspension													
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	reolaced ratchet doe		23/01/2021	Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				15/01/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					straightened front umbilical arm													
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	reolaced RHM shocker		15/01/2021	Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				08/01/2021	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/01/2021	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				17/12/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/12/2020	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	press in seb's				16/12/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					dismantled umbilica; arm section at turntable pivot													
					replaced section of constant air hose													
T471	Albury - Workshop	Chassis\AIR LEAK	air leak umbilical cord		repaired hydraulic lines		11/12/2020	Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					assembled with new protection													
					dismantled umbilical arm section at turntable pivot													
					replaced section of constant air hose													
					repaired hydraulic lines													
T471	Albury - Workshop	Chassis\AIR LEAK	air leak umbilical cord		assembled with new protection		11/12/2020	Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				08/12/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					repaired tail light wiring													
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tightened FL sorine eve bolt		08/12/2020	Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			06/12/2020	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
			remove bent bolster pin and inspect for cracks. None															
T471	Rosewood - Workshop	Chassis\BOLSTER	rotate and reinstall				04/12/2020	Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Rosewood Workshop		TRAILER
T471	Albury - Workshop	Body\LIGHTS	side lights not working sliding bolster				04/12/2020	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	replace chain guide on 2nd bolster		replaced 2nd bolster chain guide. Repaired catch. Tested		02/12/2020	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				20/11/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					removed regulator for exte winches													
					replaed air winched over to exte type													
					repaired winch													
					replace t/table top													
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	reolace turnion bushes and oins		20/11/2020	Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				14/11/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					replaced lift axle valves													
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tightened tail bar mounts		14/11/2020	Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\LIGHTS	repaired bolster lights wiring in chassis				08/11/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				05/11/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					repaired scale plug to 'B' trailer													
					adjusted load chain													
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tightened RHM & RHR shocker bolts		05/11/2020	Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\LIGHTS	1st bolster lights				05/11/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				21/10/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			21/10/2020	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				21/10/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	middle lights out				21/10/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	DrivLine\WHEEL BRGS	need adjusting				21/10/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\AIR BAG	Lift axle airbag needed				21/10/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	replace pull cord at front winch				21/10/2020	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\DAMAGE	low air front right inside tyre				21/10/2020	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\HOUSEKEEP	loose checker plate front top				21/10/2020	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			21/10/2020	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\ELECT P&W	2nd bolster wiring				15/10/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\AIR LEAK	maxi leak				15/10/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\LIGHTS	RH tail light wiring				15/10/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	lube winches				15/10/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				15/10/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	Trailer Service	VehService\DS			15/10/2020	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	DrivLine\WHEEL BRGS	PO FOR WHEEL BEARINGS				07/10/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\ABS	diamnosed abs faults. Reolaced loom to sensor 2a. Reolaced RHR missine hub comoonents. Reolase 1A & 2A sensors. Resacked an checked RHR b				03/10/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	Trailer Service	VehService\DS			03/10/2020	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\ELECT P&W	LEFT INDICATOR. RIGHT INDICATOR AND REVERSE LAMPS SHORTING TOGETHER. CHECK WIRING. LOCATE DAMAGED/BURNT HARNESS FROM STRAP				28/09/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				27/09/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			27/09/2020	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\HCV	PO FOR WIRING PARTS FOR HCV				20/09/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\AXLES	tighten u-bolt rear axle				18/09/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	repaired winch mount				18/09/2020	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER

T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			18/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	A Service	VehService\DS		18/09/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\LIGHTS	short in trailer lights indicators flashin			17/09/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\LIGHTS	indicators not working			17/09/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Service	VehService\DS		17/09/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	bolster plug			15/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			15/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		15/09/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\AIR LEAK	air leak		replace blown maxi line called out to Hyne timber Mill. Trailers wont load up, stuck half way found leak on umbilical and low oil level	11/09/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Rosewood - Workshop	Hydraulics\HOSES	blown hydraulic hose umbilical line		tooored us and eot trailers "unloaded" and send it back to Albury workshop	10/09/2020	Fault	Completed	Greenfreight Loxeine NSW	Kennedy@PW	Albury	ATK	773825	Rosewood Workshop	TRAILER
T471	Rosewood - Workshop	Brakes\BOOSTER	replace booster RHF			04/09/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Rosewood Workshop	TRAILER
T471	Rosewood - Workshop	Brakes\AIR LEAK	diagnose air leak in brake system			04/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Rosewood Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		02/09/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	replace broken hammer lock		replaced broken v-stay hammerlocks. Re-fitted load chain and adjusted	27/08/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	reline brakes on front axle replace LH and RH s/cams and bushes			25/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK O/HAUL	replace LH & RH brake drums			25/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\AIR LEAK	replaced leaking maxi line			22/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\HCV	repaired supply lines to ride height adjustment ram			22/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\AIR LEAK	air leak underneath			22/08/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\HOUSEKEEP	loose checker plate front top			22/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Myrtleford - Workshop	Brakes\BRK RELINE	brake reline front axle fit LH & RH s/cams and bushes			20/08/2020	Repair	Completed	Greenfreight Loxeine NSW	Kennedy@PW	Albury	ATK	773825	Myrtleford Workshop	TRAILER
T471	Myrtleford - Workshop	Brakes\BRK O/HAUL	fit 2x broken drums			20/08/2020	Repair	Completed	Greenfreight Loxeine NSW	Kennedy@PW	Albury	ATK	773825	Myrtleford Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			09/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		09/08/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	lub winch's			05/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	replace winch straps			05/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	tension u-bolts			05/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TAIL LIGHT	repaired wiring to RHS tail lights			05/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			05/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Trailer Service	VehService\DS		05/08/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Myrtleford - Workshop	Brakes\BRK RELINE	reline middle and rear axles replace 4x s/cams and bushes replace 4x brake drum			04/08/2020	Repair	Completed	Greenfreight Loxeine NSW	Kennedy@PW	Albury	ATK	773825	Myrtleford Workshop	TRAILER
T471	Myrtleford - Workshop	Brakes\BRK O/HAUL	reolace LHM w/bearings			04/08/2020	Repair	Completed	Greenfreight Loxeine NSW	Kennedy@PW	Albury	ATK	773825	Myrtleford Workshop	TRAILER
T471	Albury - Workshop	Body\HOUSEKEEP	PO FOR PLUG MAGNETIC			30/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	change 2nd bolster plug			29/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			29/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Trailer Service	VehService\DS		29/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TAIL LIGHT	lights repair			21/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			21/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Trailer Service replaced 2nd bolster lights socket. Repaired wiring	VehService\DS		21/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\EJECT P&W	repaired wiring to indicators			18/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			18/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service diagnosed and repaired wiring to brake and tail lights	VehService\DS		18/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TAIL LIGHT	reaplaced socket			17/07/2020	Repair	Completed	Greenfreight Loxeine NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			12/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		12/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice			03/07/2020 1234	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			03/07/2020 1234	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	PO FOR BRAKE PAD			01/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	tightened LHM shocker bolts			30/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	replaced lear pads on 2nd bolster			30/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Comp\Truck Safe	replaced truck safe label			30/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			30/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		30/06/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\TRL LEGS	replaced pin in leg			28/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			22/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	tighten r/h/m shocker bolt			22/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS		22/06/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Rosewood - Workshop	Susp\HOUSEKEEP	replace nut on spring eyebolt			20/06/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Rosewood Workshop	TRAILER
T471	Albury - Workshop	Chassis\TRL ROLLBK	replaced 1st q/release cable and hook			16/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BOOSTER	repaired air leak at rear axle b/boosters			16/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			09/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS		09/06/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	Tightened bolster pivot bolts			09/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	tightened RHM shocker bolt			03/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			03/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		03/06/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR LEAK	lift axles leaking air when up		replaced lift axle airbag	30/05/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			30/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Service	VehService\DS		30/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			15/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR BAG	Lift axle airbag needed			15/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS		15/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\HOSES	replace leaking air hose		replaced damaged/rubbed air hoses at rear axle	12/05/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			07/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	Turned 2nd LHS bolster peg			07/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	Adjusted load chain			07/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	Tightened RHM shock bolts			07/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	Repaired winches			07/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS		07/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			02/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		02/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	order susp parts			29/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	straighten bent quick release hook			26/04/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\DAMAGE	low air front right inside tyre			26/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Service	VehService\DS		26/04/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	straightened 1st q/r hook			26/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	straightened hold down mount			26/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			26/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		26/04/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		22/04/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			22/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		15/04/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\TOOLBOX	tightened toolbox onto chassis			08/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			08/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		08/04/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	replace pull cord at front winch			25/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Service	VehService\DS		25/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\AIR FITTIN	replaced coupling to B Trailer			24/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			24/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		24/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\EJECT P&W	repaired scales loom replaced plug			22/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	replace brakes on 2nd & 3rd axles inspect bearings & S cams		sublet to TCTC	20/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Elect\EJECT P&W	locate repair power loss to trailer lights in umbilical arm			18/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\AIR FITTIN	replace air fittings		replaced damaged air couplings	17/03/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Workshop\MOVE ASSET	drive to TCTC and separate trailers			15/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			11/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		11/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			05/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Service	VehService\DS		05/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job D Service			25/02/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Reelaced HCV rod cylinder	VehService\DS		25/02/2020	Service	Completed	Greenfreight Loxeine NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BOOSTER	remove replace RHR booster		remove replace RHR booster	19/02/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Service	VehService\DS	Carry out trailer service	19/02/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Rosewood - Workshop	Brakes\AIR LEAK	replace air hoses		repair booster hose leak (replace 2)	18/02/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Rosewood Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	repaired lights plug to 1st bolster front winch ram valve leak			18/02/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	truck loaded - some checks visual only			12/02/2020	Repair	Completed	Greenfreight Loxeine NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			12/02/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Service	VehService\DS		12/02/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			02/02/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		02/02/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	tightened loose FL seb bolt			25/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		25/01/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			18/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		18/01/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			11/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		11/01/2020	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/12/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS		28/12/2019	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Elect\TRL LIGHTS	middle lights out			28/12/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Driving\WHEEL BRGS	need adjusting			28/12/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	adjusted load chain			14/12/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			14/12/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D Service	VehService\DS		14/12/2019	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR BAG	REPLACED LH AIR BAG			10/12/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	TEST RESULTS			09/12/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\AIR FITTIN	REMOVED & REPLACED LIFT AXLE HOSE			08/12/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS		08/12/2019	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\AIR LEAK	airline rubbed thru height control supply			07/12/2019	Fault	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	TEST RESULTS			26/11/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\HCV	REPLACED LIFT AXLE VALVES			26/11/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS		26/11/2019	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes				21/11/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\BOLSTER	2ND BOLSTER LH CLAMP PLATE BENT			21/11/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService/DS	D SERVICE	VehService\DS		21/11/2019	Service	Completed	Greenfreight Logging NSW	Kennedy@PW	Albury	ATK	773825	Wodonga Workshop	TRAILER
					TURNED LIFT AXLE SWITCH OFF AT VALVES TAPPED VALAVES TO MAKE AIR SUPPLY RH AIRBAG										
T471	Albury - Workshop	Susp\SUSPENSION	SCALES OUT BY 4 TONE; FOUND RH AIR BAG FLATE		VALAVES NEED REPLACEING (WILL ORDER)	15/11/2019	Repair	Completed	Greenfreight Loxeine NSW	Kennedy@PW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	TIGHTE

T471	Albury - Workshop	Body\MUDGUARDS	right front outrigger bent guard damaged			07/11/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS		07/11/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Tyres\TP03	Removed & replaced flat tyre - P3		Tensioned all whell nuts & put tyre card in truck for driver	04/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			26/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		26/10/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes				19/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\HOSES	REPLACED DAMAGED			19/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		19/10/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	removed and replaced 1st winch strap			15/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes				04/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		04/10/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	REPLACED 2ND BOLSTER PLUG.			02/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	REPAIRED DOG			01/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes				27/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BOOSTER	RHM B/BOOSTER		REPLACED RUBBER B/BOOSTER HOSE AT MIDDLE AXLE	27/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		27/09/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes				20/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D SERVICE	VehService\DS		20/09/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Brakes				15/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		15/09/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\WINCH/STRP	2nd hand winch ceased up			08/09/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\TRANS DSL	2nd winch sealing up			08/09/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D SERVICE	VehService\DS		08/09/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice			01/09/2019 10	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			01/09/2019 10	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	GUARD AROUND FRONT WINCH CRACKED			31/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	new short mudflaps front axle			31/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	ADJUST- CABLE FOR FIRST WINCH			31/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\HOSES	Hoses			31/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	1st bolster passenger side turn around slide lock grease			31/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	bolsters to be turned around			31/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	replace RH mudflap			31/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	front winch not tensioning please check for jaw movement in A Trailer turntable jaws			31/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\FIFTH WHEE	slop noticed by loader driver under loader			31/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS		31/08/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
					hydraulic leak. Diagnosed ruptured hydraulic hose at rear umbilical arm pivot. Fitted joiner and extra protection											
T471	Albury - Workshop	Hydraulics\HYD LEAKS	hydraulic oil leak coming from umbilical cord		topped up hydraulic oil and tested	29/08/2019	Fault	Completed	Greenfreight Lavene NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Brakes				24/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		24/08/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Brake test results attached			17/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		17/08/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As attached To This Job			09/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		09/08/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	crack tested and relined LHF, RHF and LHM axles			09/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\TRL ROLLBK	replaced 2nd quick release cable			09/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Workshop\CLEAN	cleaned up after job completion			09/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\TRL ROLLBK	2nd quick release cable broken			09/08/2019 369545	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	tightened LHF and LHM shocker bolts			02/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BOOSTER	replaced loose b/booster mount nuts (LHM)			02/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			02/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		02/08/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	Chassis\MUDGUARDS	Removed & replaced LHF guard			25/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Brake test results attached			21/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
					Diagnose LHF sensor										
					Remove hub & replace sensor										
T471	Wodonga - Workshop	Brakes\EBS FAULTS	EBS fault		Refit. clear faults & pack up	21/07/2019	Repair	Completed	Greenfreight Lavene NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		21/07/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		20/07/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	front winch not tensioning			12/07/2019 7629	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\ELECT P&W	power connection poor 2nd bolster lights			12/07/2019 7629	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	tightened shocker bolts			12/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	replaced 2nd bolster light plug			12/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			12/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		12/07/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		03/07/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes				03/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
					Fitted 2x new tyres										
T471	Wodonga - Workshop	Tyres\TP10	L/R/I tyre punctured		1x flat. 1x R/O	30/06/2019	Repair	Completed	Greenfreight Lavene NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	Brakes	Brake test results attached			29/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		29/06/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
			broken winch handle needs replacing												
T471	Albury - Workshop	Chassis\WINCH/STRP	2nd winch		replaced missing winch handle	26/06/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\AIR LEAK	repaired air leaks			26/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Wodonga - Workshop	VehService\DS	D service	VehService\DS		20/06/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Wodonga Workshop	TRAILER
T471	Albury - Workshop	Chassis\CONSUMABLE	replaced LHB u-bolts			15/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			15/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		15/06/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\HOSES	blown hydraulic hose "umbilical cord"		repaired damaged hyd hose in umbilical arm	13/06/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\CONSUMABLE	checked and topped up hydraulic oil (replaced filter)			13/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Workshop\MOVE ASSET	tested load/unload function of trailer			13/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			05/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		05/06/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BOOSTER	replaced b/booster hoses			30/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\RAM	straightened front umbilical arm			30/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			30/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		30/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
					fitted 2x new tyres to P-7 and P-										
					tensioned all wheel nuts										
T471	Albury - Workshop	Tyres\TP01	removed and replaced flat tyre P-7 had no run outs		out tyre card in truck for driver	27/05/2019	Repair	Completed	Greenfreight Lavene NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR BAG	replaced lift axle airbag mudflaps			23/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
			replaced air fitting at rear tank												
T471	Albury - Workshop	Susp\HOUSEKEEP	adjusted suspension			23/05/2019	Repair	Completed	Greenfreight Lavene NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			23/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		23/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			15/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		15/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	left side light out 2nd bolster			09/05/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	DrivLine\WHEEL BRGS	crack test and reline rear axle			09/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Workshop\CLEAN	cleaned up after job completion			09/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	repaired 2nd bolster marker light			09/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	RM seb			09/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			09/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		09/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			02/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		02/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			02/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		02/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	T Service	VehService\DS		01/05/2019 6582	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			17/04/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		17/04/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	replaced LHM shocker			07/04/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			07/04/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	replaced 2nd bolster stops			31/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	adjusted load chain			31/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\AIR LEAK	repaired air leak at rear tank			31/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			31/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		31/03/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\DAMAGE	replaced broken slide lock anchor (LHS)			28/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			23/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		23/03/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS		23/03/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\VALVES	lift axle valve			16/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			14/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		14/03/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	replaced LHB light bar bolts (seized)			07/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			07/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		07/03/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Insp\ANN INSP	D Service			28/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\DAMAGE	Repaired tyre damage (RHR)			28/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	replaced RHR mudflap			28/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\REFLECTORS	replaced RH safety sign			28/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	repaired wiring to RHR light assembly			28/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			28/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Rosewood - Workshop	Chassis\BOLSTER	1st bolster passenger side flip			26/02/2019 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Rosewood Workshop	TRAILER
T471	Rosewood - Workshop	VehService\AS	A service due			26/02/2019 0	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Rosewood Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	replace R/F trailer guard			23/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MOUNTS	straighten mounting bracket			23/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			21/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		21/02/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\VALVES	dismantle, cleaned and reassembled lift axle valves			20/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
					scales not reading correctly										
					found no air in R airbag on front axle										
					remove faulty/stuck lift axle valve										
					refit valve										
T471	Albury - Workshop	Body\AIR LEAK	lift axle bags empty RHS		test ok	16/02/2019	Fault	Completed	Greenfreight Lavene NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\DRV TYRES	changed rear axle tyre			13/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			13/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		13/02/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
					trailer wouldn't load										
T471	Rosewood - Workshop	Susp\HCV	trailer riding too high		trailer's rear 2 axles were off the ground	06/02/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Rosewood Workshop	TRAILER
					replaced bent and aging height control rod and adjusted height control valve										
					travel to Tooma Rd										
			change tyre and fix air leak		replace flat tyre on rear axle (no spare o-trailer)										
T471	Rosewood - Workshop	Tyres\DRV TYRES	call out		had to make up air fittine to ouma baes us directly from comoressor in trailer as it was unsafe to climb under railer and lift handle was not workine	05/02/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Rosewood Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	replaced failed bearings in 2nd winch			03/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\TRANS DSL	2nd winch sealing up			02/02/2019 5468	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS		02/02/2019 5468	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			02/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS		02/02/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Rosewood - Workshop	Body\AIR LEAK	air leak rear airbag adjustment leaver			31/01/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Rosewood Workshop	TRAILER

T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				26/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			26/01/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	front winch - not working most times		replaced malfunctioning 1st winch ram and valve		20/01/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				19/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			19/01/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			19/01/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Workshop\MOVE ASSET	Move Assets		hookup		10/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	Trailer Lights		clean out light plugs/sockets		10/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\BOOST HOSE	Boost Hose		replaced constant air coupling (female)		10/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Workshop\CLEAN	Clean Workshop		clean up after job completion		10/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	RELINE MIDDLE AXLE				10/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR BAG	REPLACE 3X AIR BAGS split trailers				10/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Workshop\MOVE ASSET	fit block to T472				09/01/2019	Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\VALVES	replaced female coupling T472				09/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	repaired 2nd bolster light plug				23/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	replaced both winch straps				23/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				23/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			23/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				18/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			18/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Licence	Job Added From Invoice				12/12/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	repaired wiring to 2nd bolster plug				11/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				11/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			11/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Rosewood - Workshop	Elect\INDICATORS	right hand indicator doesn't work				06/12/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Rosewood Workshop	TRAILER
T471	Albury - Workshop	Brakes\BOOSTER	tightened RHM b/booster				05/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	tightened RHM & LHM shocker bolts				05/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	replaced load chain anchor plate bolts				05/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				05/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			05/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\DAMAAGE	Damaged Equipment		repaired broken hydraulic motor guard		30/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\MOUNTS	Mounts		cross member mount		30/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	Mudguards & Mudflaps		repaired mudflaps		30/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\CHAS CRACK	Chassis Crack		repaired various cracks		30/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	back mudflaps				29/11/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			28/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				28/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				22/11/2018 1	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				22/11/2018 1	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				21/11/2018 1	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				21/11/2018 1	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				21/11/2018 1	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				18/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			18/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice				16/11/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				10/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			10/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\ABS	checked for ABS codes - nil				08/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	replaced 1st winch q/r cable				08/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\HOSES	tightened loose hose clamps				08/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	replaced bolts on bolster bumb bar				08/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP51	removed spare wheel carrier and welded cracks				08/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\REFLECTORS	Load stickers		Replcad peg load stickers		01/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D service completed as per checklist	VehService\DS			01/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\HOSES	fix umbilical arm - hoses twisted and sticking out		repaired umbilical arm hoses		25/10/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BOOSTER	replaced rubbed or damaged b/booster hoses at middle and rear axles				25/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	repaired bent winch handle				25/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				25/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			25/10/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				19/10/2018 170000	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				18/10/2018 170000	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				11/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	adjusted load chain				11/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	replaced load rollers				11/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			11/10/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Workshop	Job Added From Invoice				09/10/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	tightened top shocker bolts				03/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			03/10/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				03/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	tightened guard bolts				26/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				26/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			26/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				26/09/2018 169000	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				26/09/2018 169000	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	replaced centre mat and springs				19/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				19/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			19/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\HOSES	leaking hose on height adjuster valve		repaired rubbed hoses at middle axle		13/09/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				13/09/2018 168175	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				13/09/2018 168175	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\AXLE CT	crack test and reline RHR axle				11/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	tightened top shocker bolts				09/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TAIL LIGHT	replaced LH tail light				09/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\ELECT P&W	repaired RHF 1st bolster light				09/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				09/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			09/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				07/09/2018 10	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	Repaired 1st winch replaced ram, rod, pin and tap				02/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR FITTIN	Repaired air lines				02/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\ELECT P&W	Repaired plugs to 2nd bolster lights				02/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\HCV	Replaced HCV rod cylinder				01/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				01/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			01/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	tightened LHM & RHR wbolts				01/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	REPLACE SEB AND WRAP				30/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\ELECT P&W	2nd bolster light connection poor				29/08/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			29/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	RHR spring eye bush and wear plates (welded in)				29/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				29/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			29/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\MOTOR	REPLACE HYD. MOTOR FOR GYPSY.				26/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\STCH GUARD	REPLACE CENTRE MAT				24/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				21/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			21/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				17/08/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Engine	Job Added From Invoice				17/08/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice				16/08/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				16/08/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BOOSTER	REPLACE BOOSTER				15/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\DAMAAGE	CRACKED RIM ON AS SPARE		FITTED STEER RIM OFF 939		14/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\HCV	repaired HCV rod assembly				12/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				12/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			12/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice				10/08/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				10/08/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				10/08/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\AXLE CT	crack test & reline LHM & LHR axles				09/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\DRY TYRES	fitted run outs to LHM axle				09/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BOOSTER	replaced RHM b/booster				09/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	brake reline				09/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\HOSES	tidy up umbilical arm hosing				05/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	tightened top shocker bolts				05/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				05/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			05/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR BAG	REPLACE AIR BAG				03/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	checked brake percents				02/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\MOTOR	replaced motor guard				02/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\MOTOR	drained and refilled motor reduction box				02/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	adjusted load chain				02/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	tightened top shocker bolts				02/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR BAG	replaced LHR airbag				02/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\MOTOR	prepped and painted motor guard				02/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\MOTOR	replaced guard bushes				02/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	DrivLine\WHEEL BRGS	replaced front umbilical arm bearings				29/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	tightened shocker bolts				29/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				29/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			29/07/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				22/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			22/07/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice				17/07/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				17/07/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				17/07/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	tightened LHR u-bolts				05/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				05/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			05/07/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\HOSES	fix air leak has control valve		replaced rubbed air hoses to HCV cylinder and b/booster hoses at middle axle		04/07/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice				28/06/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				28/06/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\ROTATION	Job Added From Invoice				28/06/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				28/06/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP

T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				20/06/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Workshop\MOVE ASSET	unhook trailers T471-T472				20/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				20/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			20/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice				16/06/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	DriveLine\WHEEL ALGN	Rear axle out of alignment		Replaced broken RHR alignment plate		14/06/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				14/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			14/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				06/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			06/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				29/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			29/05/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice				22/05/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				22/05/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				22/05/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	tightened top shocker bolts				20/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\ABS	checked ABS code				20/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				20/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	Service	VehService\DS			20/05/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	T Service	VehService\DS			19/05/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				12/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	Tightened RHR U bolts				12/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			12/05/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\FIFTH WHEE	Replaced trunion's, bushes, pins and nylon pads				05/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				05/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			05/05/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				05/05/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				05/05/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	idler pully ceased up		removed '4' links from chain pulley and bearings		03/05/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	chack chain tension		adjusted load chain		03/05/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Workshop\MOVE ASSET	drop off T472				03/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	replaced rear load chain pulley and bearings				03/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\FIFTH WHEE	removed T/table top to replace trunion mounts				03/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\FIFTH WHEE	wrong one's ordered, reassembled T/table and trunions				03/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Workshop\MOVE ASSET	hooked up and tested				03/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\FIFTH WHEE	correct one's on order				03/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				27/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			27/04/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice				24/04/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				24/04/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				24/04/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				20/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\BOOSTER	Replaced LHF B booster				20/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	Tightened top shocker bolts				20/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\AIR LEAK	Repaired air leak at middle axle				20/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	DriveLine\WHEEL BRGS	Checked and adjusted all wheel bearings				20/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Engine\FAULT CODE	Checked for ABS codes - nil				20/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			20/04/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	LHR seb				12/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\FIFTH WHEE	t/table wear pads				12/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\FIFTH WHEE	t/table top wear plates				12/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	DriCabRep\DOOR LOCK	replaced slide lock cylinder				12/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\FIFTH WHEE	repaired 1st quick release				12/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				12/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			12/04/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					checked slide lock's picks												
T471	Albury - Workshop	DriCabRep\DOOR LOCK	check slider pins are locking in properly (when empty unlocks itself sometimes)		greased slide locks		08/04/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\AIR LEAK	repaired PTO air leak				08/04/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\ABS	checked and cleared ABS codes				29/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				29/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			29/03/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				23/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			23/03/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice				21/03/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
			blown hyd. Hose in umbilical arm														
T471	Albury - Workshop	Hydraulics\HOSES	umeras hoses. find hose that was damaged. recair and cut back toeether				20/03/2018	Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshoo		TRAILER
T471	Albury - Workshop	Wash\WASH	test all functions, washed truck and trailer				20/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Hydraulics\OIL/FILTER	checked hyd oil level				20/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\ABS	checked ABS codes				17/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				17/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			17/03/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				09/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Servic	VehService\DS			09/03/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Workshop	Job Added From Invoice				06/03/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes					02/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			02/03/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				01/03/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				01/03/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
			check all lines - hanging down		rewired scales loom to B Trailer supply												
T471	Albury - Workshop	Elect\ELECT P&W	scales has been nioved out		re-calibrated scales		28/02/2018	Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshoo		TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	2nd hand winch ceased up				28/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				28/02/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice				24/02/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				24/02/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				24/02/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				24/02/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	R7R VALVE HANDLE POPS IN AT TIMES		LHF spring wrap		22/02/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	REPLACED LF WRAP, AIR BAG AND LIFT AXLE BUSHES		22/02/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\AIR BAG	middle axle airbags				22/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\HCV	suspension dump valve				22/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\AXLES	lift axle bushes				22/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				22/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			15/02/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				15/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	brake reline				15/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\AIR BAG	replaced LHR airbag				15/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\FIFTH WHEE	replaced skid plate stiffener bolts				15/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	DriveLine\WHEEL BRGS	tightened wheel bearings				15/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice				08/02/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				08/02/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				08/02/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				08/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					tightened shocker bolts												
					repaired wiring to 1st bolster lights												
					replaced female hyd. Coupling on front of trailer												
T471	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	tightened u-bolts LHM axle		08/02/2018	Service	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshoo		TRAILER
T471	Albury - Workshop	Elect\INDICATORS	indicators keep blowing fuse				02/02/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\INDICATORS	indicators keep blowing fuse				02/02/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\ELECT P&W	followed wiring for rubs and found damaged wires at light bar plug. Replaced plug and removed damaged wiring. Also found rubbed indicator wi				02/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\ELECT P&W	dismantle and check wiring for indicators with re-power				31/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\FIFTH WHEE	Replaced RHR alignment plate				31/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	u-bolts, nuts and shocker plate				31/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				31/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D Service	VehService\DS			31/01/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TAIL LIGHT	indicators - shorting out				31/01/2018 30246	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\HCV	FIX HCV HOSES				24/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			24/01/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\AIR LEAK	Travel to Woomargama to repair air leak				23/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice				23/01/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				23/01/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				23/01/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				16/01/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	REPLACE 2ND STRAP		Replaced winch straps		16/01/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\INDICATORS	INDICATORS SHORTING OUT		Checked indicators wiring and cleaned connections		13/01/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\HCV	R7R VALVE HANDLE IN CHECK AND REPAIR AIR LINES.RUBBING.				11/01/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\AIR LEAK	MIDDLE AXLE HCV BEEN RUBBING JOINER. PUT IN BOOSTER HOSE.				11/01/2018	Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshoo		TRAILER
T471	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			11/01/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	DriveLine\INDICATORS	indicators breaker in truck checked wiring for short				11/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				11/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	checked indicators for faults - ok		04/01/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				04/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	T Service	VehService\DS			04/01/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					Replaced RHM shocker & bolt												
T471	Albury - Workshop	Susp\SHOCK ABS	REPLACED RHM SHOCKER AND BOLT		Removed tyres to get bolt out		30/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	REPAIR MUD GUARD		Cut out & replaced worn metal guard top		30/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\BRK RELINE	RELINE FRONT AND MIDDLE AXLE.		Crack test and reline LHF and LHM axles		29/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Workshop\CLEAN	Clean up after job				29/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	FRONT WINCH SKIPPING ON GEARS				29/12/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	FRONT WINCH REPAIR				29/12/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	REPLACE FRONT WINCH				29/12/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	REPLACE LHF GUARD				29/12/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\DRV TYRES	changed LHM inner tyre				21/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Workshop\CLEAN	cleaned dirty rims				21/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\HOUSEKEEP	CHECK TYRE LIFTING BAR THAT IT IS NOT HITTING ON RTR VALVE		check tyre changing bar for spare seems to be rubbing on ebs lever		19/12/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\STCH GUARD	replace log on front winch		refer job #144526		19/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\STCH GUARD	replace log on front winch				19/12/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService\DS	T Service	VehService\DS			19/12/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	FRONT WINCH SKIPPING ON GEARS				19/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\HCV	R7R VALVE HANDLE IN CHECK AND REPAIR AIR LINES.RUBBING.				19/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\AIR LEAK	MIDDLE AXLE HCV BEEN RUBBING JOINER. PUT IN BOOSTER HOSE.				19/12/2017	Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshoo		TRAILER
T471	Albury - Workshop	Body\HOUSEKEEP	CHECK TYRE LIFTING BAR THAT IT IS NOT HITTING ON RTR VALVE

T471	Albury - Workshop	Chassis\WINCH/STRP	FRONT WINCH SKIPPING ON GEARS					14/12/2017 7947	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Workshop\W/S MAINT	pick up part's					12/12/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\HOSES	BLOWN HYD. HOSE			replaced hyd hose (damaged section)		12/12/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Hydraulics\OIL/FILTER	topped hyd. Oil up (10lts approx.)					12/12/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice					05/12/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice					05/12/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice					05/12/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS				02/12/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					02/12/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS				25/11/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					25/11/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	tighten chain			adjusted load chain		19/11/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS		TIGHTEN RHM SHOCKER BOLT		16/11/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					16/11/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					09/11/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS				09/11/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	LH TAIL LIGHT NOT WORKING AT TIMES.					02/11/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	LH TAIL LIGHT					02/11/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS		Tightened loose shockers		02/11/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					02/11/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice					01/11/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\INDICATORS	NO INDICATORS-POPPED CIRCUIT BREAKER					01/11/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice					31/10/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice					31/10/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice					31/10/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice					31/10/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\HOUSEKEEP	fit reflective tape to pegs					29/10/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS				26/10/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	REPLACE WORN/DAMAGED MUD FLAPS					26/10/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\WORK LIGHT	RH WORK LIGHT LOOSE			tightened lights #133701		26/10/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	REPLACE FRONT QR ON FRONT WINCH			made new cable and mounts. Purchased springs from Wodonga spring works. Set up to return automatically to avoid breakage		26/10/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	new-short mudflaps front axle					26/10/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	new rear mudflaps			removed and replaced mudflaps		26/10/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\ELECT P&W	right work light loose					26/10/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	DriveLine\SHOCK ABS	tightened shocks					26/10/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					26/10/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Service	VehService\DS				26/10/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice					24/10/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice					24/10/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice					24/10/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\AXLE CT	back RH axle - running too hot again					22/10/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BRAKE ADJ	checked and adjusted bearing and brake					22/10/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	CHECK REAR AXLE ALIGNMENT AND HEIGHT.					21/10/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Elect\TAIL LIGHT	TAIL LIGHTS SHORTING			both tail light assy s/s		19/10/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS				18/10/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					18/10/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\DRV TYRES	replace RHR axle tyres (puncture)					18/10/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop		tightened LHF bolt														
T471	Albury - Workshop	DriveLine\SHOCK ABS	tightened top shocker bolts					18/10/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
						noisy bearings on RHR axle											
						dismantle and wash bearings											
						found damaged bearing											
T471	Albury - Workshop	DriveLine\WHEEL BRGS	RHR HUB RUNNING HOT.			reolaced bearings		08/10/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					01/10/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Service	VehService\DS		FIT BOOSTER		01/10/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	1ST WINCH KNOB BROKEN					24/09/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS				24/09/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	GUARD AROUND FRONT WINCH CRACKED					19/09/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS		Tightened loose shocks and U bolts		19/09/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\ABS	TRAILER ABS LIGHT ON			AS PRER JOB#124858		19/09/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
						broken hammer lock on load adjuster bar											
						removed bar and RH chassis bracket											
						straightened bracket, remount, fit 2 new hammer locks and adjuster (old one bent)											
T471	Albury - Workshop	Body\CHN/RUR/MN	CHAIN ANCHOR HAMMER LOCK BROKEN			new bolt		08/09/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\ABS	TRAILER ABS LIGHT ON					08/09/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
						found and repaired rubbed air hose to HCV cylinder rod											
T471	Albury - Workshop	Susp\AIR LEAK	AIR LEAK MIDDLE AXLE			will need comolete hoses reolaced at later date		06/09/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	AIR BAGS WENT FLAT			checked RTR value operation		06/09/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	REPLACE FRONT WINCH HANDLE					05/09/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice					31/08/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS				30/08/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					30/08/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					23/08/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Service	VehService\DS				23/08/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					16/08/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	Service	VehService\DS				16/08/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Insp\RWC COMP	Fit EBS NHVAS stickers and compliance plate					14/08/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	REPLACE MUD FLAPS IN FRONT OF LIFT AXLE					10/08/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	CHECK WINCHES					10/08/2017	Fault	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService/DS	D SERVICE	VehService\DS		REPLACED SHOCKER BOLT		10/08/2017	Service	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					10/08/2017	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres	Job Added From Invoice					08/08/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice					08/08/2017 0	Repair	Completed	GreenFreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice					08/08/2017 0

T471	Albury - Workshop	Brakes/JBRK RELINE	Reline RR wheel.					27/11/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				25/11/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\TOOLBOX	Step broken off toolbox					11/11/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				11/11/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				04/11/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	Extend power lead to 2nd bolster lights					04/11/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\CHN/RLR/MN	Lube hold down dog.					27/10/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				26/10/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Check and record brakes					26/10/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				20/10/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					20/10/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP17	Job Added From Invoice					18/10/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP21	Job Added From Invoice					18/10/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\CTI Drive	CTI air leak					14/10/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					12/10/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					replace spare tyre carrier													
					L/M wrap & bush													
T471	Albury - Workshop	VehService/DS	D service	VehService\DS	RR airbae			12/10/2016	Service	Completed	Greenfreight Loxwine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	Please repair leaking hose		repaired split b/booster hose at RHR axle			07/10/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\AIR LEAK	Air leak		replace HCV cylinder			05/10/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\AIR LEAK	Air line CTI line maybe					01/10/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				01/10/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					01/10/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP13	Job Added From Invoice					30/09/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	tighten bolster stopper bracket					27/09/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				24/09/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					24/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	Replace damaged guard. Blown tyre.		replace guard & outrigger			23/09/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP21	Job Added From Invoice					20/09/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP19	Job Added From Invoice					20/09/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP15	Job Added From Invoice					17/09/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\AIR LEAK	Air leak					17/09/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\AIR LEAK	Air leak		replaced rubbed airlines			16/09/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					tighten securing bolts													
T471	Albury - Workshop	Body\TOOLBOX	Fix toolbox support		replaced bolt & mount spacer			16/09/2016	Fault	Completed	Greenfreight Loxwine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				16/09/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					16/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	LF mudguard needs replacing		replaced guard			08/09/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS	unhook & hook up			08/09/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					08/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\AIR LEAK	Air leak when brakes applied		Repaired rubbed air line middle axle			03/09/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				02/09/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					02/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP51	Job Added From Invoice					27/08/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					adjusted suspension height													
T471	Albury - Workshop	VehService/DS	D service	VehService\DS	resained 2nd bolster wirine			24/08/2016	Service	Completed	Greenfreight Loxwine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					24/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP20	Job Added From Invoice					16/08/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\HOUSEKEEP	Umbilical arm bearings worn		replaced bearings			14/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					as above													
T471	Albury - Workshop	VehService/DS	D service	VehService\DS	resained olue wirine 2nd bolster			14/08/2016	Service	Completed	Greenfreight Loxwine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					14/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	first winch tap leaking air		replaced tap			11/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\CTI Drive	Air leak		repair CTI leak			11/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	2nd bolster side light out LH side					06/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS	tightened loose shockers			06/08/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					06/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes\AIR LEAK	Air leak under tri.		Replaced rubbed brake hoses.			03/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\HCV	Loose HCV cylinder		tightened lower mounting bolt.			03/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS	as above			27/07/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					27/07/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	2nd bolster lights not working		repaired wiring to plug on 2nd bolster			24/07/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\CHN/RLR/MN	fix ratchet for dog and chain					16/07/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	LH side light not working 2nd bolster		cleaned light and plug working ok			16/07/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				16/07/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TRL LIGHTS	short in indicators		found rubbed wiring on tail light bar			09/07/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	2nd bolster catching on chain		repaired catch			09/07/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				08/07/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					08/07/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TAIL LIGHT	fix 2nd bolster light plug fell apart. fix 2nd bolster light plug fell apart		refitted plug for 2nd bolster lights			05/07/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP51	Job Added From Invoice					01/07/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP51	Job Added From Invoice					01/07/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Body\CHN/RLR/MN	place for dog and chain to be stored					30/06/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\CTI Drive	check for CTI air leaks					30/06/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				30/06/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					30/06/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\CTI Drive	CTI air leak at tri.		replaced air line up axle on LHM.			23/06/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					rebuild winch.													
T471	Albury - Workshop	Chassis\WINCH/STRP	front winch-very hard, seizing up.		But not fitted. Still ok			22/06/2016	Fault	Completed	Greenfreight Loxwine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS				18/06/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes/JBRK RELINE	Reline LH middle axle.		as per attached reline sheet			11/06/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					replaced drain cock													
T471	Albury - Workshop	Susp\AIR LEAK	air leak around back axle and middle		resealed lamo LHR airbae fittinas			11/06/2016	Fault	Completed	Greenfreight Loxwine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\AIR LEAK	air leak at tri.		replaced lift axle dump valve			10/06/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TAIL LIGHT	no tail lights on trailers		replace 2nd bolster plug which was shorting			09/06/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
					as above													
T471	Albury - Workshop	Body\CHN/RLR/MN	fit ratchet dog		make us mounts to suit			05/06/2016	Repair	Completed	Greenfreight Loxwine NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS	as above			05/06/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					05/06/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	fix lift axle		repaired as per Job #22296			03/06/2016 257856	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Elect\TAIL LIGHT	RH rear tail light and side marker very dull.		repaired wiring			03/06/2016 257856	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\CTI Drive	CTI leak		replaced air line in LH front axle.			25/05/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	VehService/DS	D service	VehService\DS	as above			25/05/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Brakes	check and record brakes					25/05/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop		TRAILER
T471	Albury - Workshop	Tyres\TP13	Job Added From Invoice					24/05/2016 0

T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/12/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP19	Job Added From Invoice				19/12/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP19	Job Added From Invoice				19/12/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP19	Job Added From Invoice				19/12/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP20	Job Added From Invoice				19/12/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				12/12/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/12/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP21	Job Added From Invoice				11/12/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP21	Job Added From Invoice				11/12/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP21	Job Added From Invoice				11/12/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	chain for dog - please fix				11/12/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	adjust load chain				09/12/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP13	Job Added From Invoice				05/12/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/12/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				02/12/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis	fix chain for dog				02/12/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes\BOOSTER	check booster hose front axle from valve to T-piece		replaced hose from brake booster to valve		28/11/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				24/11/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\BOLSTER	weld cracked stiffeners				24/11/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp	tighten loose shocks				24/11/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			24/11/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\CTI Drive	air leak				21/11/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			14/11/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				14/11/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp	tighten top shocker bolts				14/11/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	replace front booster hose				14/11/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/11/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				05/11/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis	fix back axle hoses, lift axle coming down at times				04/11/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	straighten safety chain supports				30/10/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				29/10/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			29/10/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			21/10/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				21/10/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	check chain adjustment		adjust load chain		21/10/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	tighten rhm shocker				21/10/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\CTI Drive	fitting off spinner cracked		replace rhm		17/10/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR BAG	replace lhm air bag				17/10/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\HCV	tighten height control bracket on axle		replace HC rubber and tighten bracket		17/10/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\CHN/RUR/MN	fix dog and chain				14/10/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				13/10/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			13/10/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MOUNTS	Job Added From Invoice				07/10/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/10/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				03/10/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\MUDGUARDS	guard rhf axle destroyed by roo, replace outrigger + toolbox step				02/10/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\CTI Drive	CTI link to valve bent				02/10/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\MUDGUARDS	Job Added From Invoice				02/10/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP17	Job Added From Invoice				26/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP17	Job Added From Invoice				26/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP17	Job Added From Invoice				26/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP20	Job Added From Invoice				26/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP20	Job Added From Invoice				26/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP22	Job Added From Invoice				25/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP22	Job Added From Invoice				25/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\TP22	Job Added From Invoice				25/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				24/09/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\WINCH/STRP	front winch not working at times		driver to monitor		24/09/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			24/09/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\SUSPENSION	Job Added From Invoice				22/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Body\SUSPENSION	Job Added From Invoice				22/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				16/09/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Tyres\CTI Drive	repair CTI leaks, replace outer slinger, repair rhm CTI line				16/09/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Steering\WHEEL BRGS	check both front wheel bearings				16/09/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			16/09/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				09/09/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	replace lhm bottom shocker mount plate, replace lhm shocker, replace lhm alignment plate, replace lhm u-bolts				09/09/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/09/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\AIR BAG	Service Job Added From Invoice				08/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SUSPENSION	Service Job Added From Invoice				08/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Susp\SHOCK ABS	Service Job Added From Invoice				08/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER
T471	Albury - Workshop	Chassis\SUSPENSION	Service Job Added From Invoice				08/09/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Albury	ATK	773825	Albury Workshop	TRAILER