EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T403	Albury - Workshop	Tyres\RUN OUT	Tyres\RUN OUT 2-3-10-11			26/02/2025	680500	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	BEAUREPAIRES - 4	TRAILER
T403	Wodonga - Workshop	Body\BOLSTER	Remove Bolster		Wrong bolster	14/02/2025	680500	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\BOLSTER	REPAIR CRACKED BOLSTER STIFFENERS.			22/03/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\DAMAGE	ASSESSED DAMAGE.			31/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Body\STRAPS	REPLACE BOTH REAR ROPE			24/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/01/2024		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\BOLSTER	REPAIR CRACKED BOLSTER STIFFENERS.			24/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\BOLSTER	REPLACE BOLSTER PIVOT WASHERS.			24/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	DrCabElect\SCALES	calibrate scales			11/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Elect\TRL LIGHTS	2nd bolster lights			11/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Elect\TRL LIGHTS	rear light bar side light			11/01/2024		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	TURNED SEVERAL BOLSTER PEGS. REMOVED LEG. BROKEN GUSSETS (MOUNTS) CALIBRATED SCALES.	28/12/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/12/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes\ABS	EBS KICKING IN			05/12/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Body\STRAPS	REPLACE BOTH REAR ROPE		NONE IN STOCK.	05/12/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/12/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/10/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/10/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Wodonga - Workshop	Body\AIR LEAK	AIR LEAK		repair air leak & tidy up airlines	09/10/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\EBS FAULTS	CHECK EBS COMING ON TOO SERVERE.		CHECKED EBS CODES.	28/09/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/09/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/09/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\BOLSTER	Repair bolster cylinder, new rod and seals.			22/08/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\MOUNTS	Bore out qty of pistol brackets, machine and fit sleeves into brackets. Cut pins out of angle brackets and straighten brackets and weld in new sins.			25/07/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\BOLSTER	Repairs to bolster cylinder.			28/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	Body\MOUNTS	Setup in mill and bore out pistol shaped bracket. Rebush bracket.			23/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\BRK RELINE	RELINED AND CRACK TESTED ALL AXLES. REPLACED RF BOOSTER AND ALL YOLKS.			20/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\BOLSTER	CRACK TESTED BOLSTER PEGS. REPLACED BOLSTER. PAINTED BOLSTERS AND PEGS. CHANGED BOLSTERS TO 3 METER BAYS. REWIRED. CHANGED HYDRAULIC LINES TO SUIT. TESTED.			20/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Wodonga - Workshop	Brakes\BRK RELINE	FULL RELINE.			20/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/06/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			01/06/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/05/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/05/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\BRAKE ADJ	brake adjust			07/05/2023		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/05/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	adjust all RH wheel bearing and RH rear	02/05/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Tyres\TP05	Tyre Position 5			15/04/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\AIR FITTIN	replace air coupling's front of trailer			23/03/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Tyres\TP02	Tyre Position 2			23/03/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/03/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/03/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/02/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/02/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Body\FIFTH WHEE	unhook			07/02/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\AIR LEAK	air leak at brake booster LHR			07/02/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Tyres\TP9+10	REPLACED LR TYRE.			29/01/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	wash trailer	25/01/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/01/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/01/2023		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\BACK PLATE	replace damage RHR lower brake backing plate			06/01/2023		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist													
T403	Myrtleford - Workshop	VehService\DS	TCTC POR LO75742	VehService\DS		14/12/2022	680500	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonwa Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/12/2022	680500	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Susp\SHOCK ABS	WELD NEW LOWER SHOCKER MOUNT ON RHR			02/12/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/12/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		adjusted wheel bearing's											
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	VehService\DS	welded bar back on	01/12/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/11/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Body\HOUSEKEEP	washed down wheels			22/11/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\AIR LEAK	air leak over tri with black button in			17/11/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/11/2022		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist			03/11/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job	VehService\DS	checked EBS	03/11/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/10/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Tyres\TP11+12	supply and fit 2tyres			18/10/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\AIR LEAK	Air leak over tri			01/10/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/09/2022		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/09/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\MUDGUARDS	Guard Damage			13/09/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Tyres\TP5+6	supply and fit 2tyres			13/09/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\BOLSTER	Rtpair bolster cylinder.			07/09/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\CROSS MBR	reweld cross member			06/09/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\MUDGUARDS	weld up RH mudguard			06/09/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\EBS KH	check E.B.S			06/09/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/09/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/08/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/08/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Body\MUDGUARDS	LH mudflap			29/07/2022		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/07/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/07/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/07/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/07/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/07/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/07/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/06/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/06/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Hydraulics\RAM	REMOVE AND REPLACE BOLSTER RAM			28/05/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/05/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/05/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\WINCH/STRP	winch air tap leaking			18/05/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Hydraulics\MOTOR	loading issue - changed motor oil and changed pump			13/05/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Body\CHN/RLR/MN	tensioned gypsy chain			13/05/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\EBS KH	REPLACE EBS MODULE		Transpec supply part	11/05/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\EBS KH	INSPECT EBS MODULE DAMAGE FOR RELPACEMENT			11/05/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/05/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/05/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Tyres\TP04	supply and fit 1 tyre			06/05/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/04/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	adjust LHM & RHR wheel bearing	21/04/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\BOOSTER	brakes sticking on after use			09/04/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/03/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	front and middle axles adjusted wheel bearings	26/03/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\BOLSTER	INSPECT AND REPLACE BOLSTER PIVOTS AS NEEDED			15/03/2022	680500	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/03/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/03/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\BRK RELINE	reline x3 axles			17/02/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/02/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/02/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\BRK RELINE	TCTC supply parts			08/02/2022	680500	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/01/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/01/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/01/2022		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist		check and adjust all wheel bearings											
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	rewire rear bolster lights fix chain down doe	15/01/2022		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/12/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	rewired rear bolster light	21/12/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP05	supply and fit 1 tyre			18/12/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/12/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/12/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Body\CHN/RLR/MN	FIT TIE DOWN CHAIN			01/12/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\BRK O/HAUL	brakes dragging			23/11/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Body\FIFTH WHEE	hook up trailers			20/11/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Susp\WHEEL ALIGN	wheel align all 3 axles			12/11/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Body\PAINT/REST	CLEAN AND WASH TRAILER			11/11/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Body\REFLECTORS	Multiple reflectors missing or broken.			05/11/2021	680500	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\WINCH/STRP	3 x winch straps frayed.			05/11/2021	680500	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\BOLSTER	Bolsters have cracks in them.			05/11/2021	680500	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Body\WHL HUB	ADJUST ALL WHEEL BEARINGS		fit new adjuster nut to RHM axle	02/11/2021	680500	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			30/10/2021	680500	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/10/2021	680500	Service	Completed	Greenf

T403	Wodonga - Workshop	Chassis\MUDGUARDS	LHF Outrigger U/S					Refer Job # 151694			28/09/2021	680500	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Tyres\TP01	LHF Tyre U/S								28/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								16/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Susp\SPRING HANG	LHR Spring wrapper broken.					PREVIOUSLY COMPLETED			16/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						16/09/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\BOLSTER	SMALL CRACKS IN BOLSTERS. WEAR PADS WORN.								16/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	Service due.		VehService\DS			Refer job# 353916			16/09/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								11/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS			CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 10/9/21			11/09/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Body\REFLECTORS	REPLACE BROKEN & MISSING REFLECTORS								11/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								03/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						03/09/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Body\REFLECTORS	Multiple reflectors missing or broken.								03/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\WINCH/STRP	3 x winch straps frayed.								03/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\BOLSTER	Bolsters have cracks in them.								03/09/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								26/08/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						26/08/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	Service due.		VehService\DS			Refer Job# 351408			26/08/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Susp\AIR BAG	Replace RHR airbag - Side Cut.					Replaced air bag. Checked air bags both a full height & lowered.			24/08/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Susp\AIR BAG	Right hand rear air bag leaking badly - hole.					No fault found.			21/08/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP1+2	Supply and fit 3 tyres 1 puncture repair POS 1								20/08/2021	658400	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6								20/08/2021	658400	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	Chassis\WINCH/STRP	FIT DYNEEMA WINCH ROPE KIT								20/08/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						18/08/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								18/08/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Susp\SPRING HANG	LHR Spring wrapper broken.								18/08/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 9/8/21		VehService\DS						10/08/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								28/07/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist								28/07/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								23/07/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Elect\TRL LIGHTS	Rear passenger side light not working.								23/07/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS			CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 19/7/21			23/07/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								20/07/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						20/07/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								13/07/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						13/07/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								07/07/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						07/07/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								02/07/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						02/07/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								26/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist Retrieve Hydraulic cylinder for LHR Bolster.																			
T403	Wodonga - Workshop	VehService\DS	Fit up Hydraulic cylinder for LHR Bolster.		VehService\DS						26/06/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Unknown	Service due.								26/06/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Body\BOLSTER	Both Hydraulic rams leaking on rear bolster.								26/06/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								18/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						18/06/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Body	Chassis\MUDGUARDS Straighten L/H/S stretch guard.					Straighten LHF Quarter panel.			13/06/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\MUDGUARDS									13/06/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP11+12	Supply and fit 2 tyres								13/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								11/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						11/06/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP7+8	Supply and fit 2 tyres								09/06/2021	654440	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								03/06/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						03/06/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP9+10	Supply and fit 2 tyres								02/06/2021	628550	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP1+2	Suply and fit 2 tyres								29/05/2021	6455828	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								27/05/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\STRAPS	2nd quick release cable frayed inspect and repair					Couldn't fault			27/05/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Susp\SUSPENSION	LHR Trailing arm wearing inside hanger.					Checked but couldn't find any wear.			27/05/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\MUDGUARDS	Left hand stretch guard loose.					No time to repair.			27/05/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS			CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 26/5/21			27/05/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	DrivLine\WHEEL BRGS	LHF Adjusted.								27/05/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								20/05/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						20/05/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP3+4	Supply and fit 2 tyres								13/05/2021	616550	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								08/05/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Body\LIGHTS	3rd and 4 th Bolster Clearance Lights flickering					no faults found			08/05/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\STRAPS	2nd quick release cable frayed please replace.					replaced cable			08/05/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\MUDGUARDS	Left hand stretch guard loose.								08/05/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\STRAPS	Second quick release cable about to break.					cable replaced			08/05/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Unknown	Service Due								08/05/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
								Inspected & diagnosed loose guard * Tightened up guard as required * Inspected & found damaged reflectors													
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS			* Installed reflectors where neouired			08/05/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP12	Puncture Repair								01/05/2021	614300	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP5+6	Supply and fit 2 tyres								01/05/2021	624466	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP09	Puncture repair								01/05/2021	624466	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job								30/04/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Chassis\STRAPS	2nd quick release cable frayed inspect and repair								30/04/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						30/04/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Unknown	Service due								30/04/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Susp\SUSPENSION	LHR Trailing arm wearing inside hanger.								30/04/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Wodonga - Workshop	Unknown	Service Due								30/04/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								23/04/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service		VehService\DS			replaced 3rd o/r cable			23/04/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	pistol bracket broken front bolster					replaced LHF rkg (bolster pivot arm)			22/04/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								17/04/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\ELECT P&W	repaired/replaced broken wiring to 3rd and 4th bolster lights								17/04/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\AIR LEAK	repaired air leaks at 1st axle								17/04/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service		VehService\DS						17/04/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								10/04/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						10/04/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\TRL LIGHTS	Repair Lights								10/04/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\AIR LEAK	Repair Air Leaks								10/04/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	VehService\DS	Service		VehService\DS						10/04/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
								TCTC CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET. 30/3/2021													
T403	Albury - Workshop	VehService\DS	Service Due		VehService\DS			Grease			31/03/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\TRL LIGHTS	bolster wiring								21/03/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service		VehService\DS			Trailer Service			21/03/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\AIR FITTIN	replace brake lines middle axle (too short)					remove replace maxi line			11/03/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								11/03/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
								repaired booster lines														
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS			replaced LH stretch guard and repaired outrigger and tail bar			11/03/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\STRAPS	rebuilt winch								10/03/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								28/02/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						28/02/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Steering\WHEEL STUD	Supply wheel nut								26/02/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\ELECT P&W	bolster lights intermittent (back bay)					repaired wiring to rear bolster lights			24/02/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Steering\WHEEL STUD	stripped wheel nut middle axle R/H/S (run mark on rim)					replaced stripped wheel nut and tensioned wheel nuts (RHM axle)			24/02/2021		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service		VehService\DS						19/02/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								18/02/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						18/02/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
			Brake Reline. Customer reports the triler may need some brake relines, Diagnose and repair as required Inspected and confirmed all required replacing. Jacked up axles and supported on stands. Remove wheels, hubs and brakes. Removed s-cams and replaced along with bushes, replaced wheel bearings, brake lining and drums. Fitted new ABS sensor to RHM.																			
T403	Albury - Workshop	Brakes\BRK RELINE	Adjusted brakes and wheel bearings to spec								16/02/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP9+10	Supply and fit 2 tyres								16/02/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	repaired 4th winch mount								09/02/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								04/02/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						04/02/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								04/02/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						04/02/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								29/01/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS						29/01/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP7+8	REPLACE 2 TYRES								23/01/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								20/01/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS			adjusted suspension height			20/01/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service		VehService\DS						20/01/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								12/01/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS			repaired indicator wiring			12/01/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								06/01/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS			replaced RHR shocker			06/01/2021		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	DrivLine\SHOCK ABS	Supply Shock Absorber, Plug & LED								06/01/2021		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job								17/12/2020		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
								replaced all winch straps tightened seb bolts and u-bolts														
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\

T403	Albury - Workshop	Brakes	Record Check Results As Attached TO This Job				16/10/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			16/10/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			07/10/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				07/10/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			07/10/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\MUDGUARDS	replaced RH stretch guard		straightened RH outrigger and replaced stretch guard		30/09/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	Body\REFLECTORS	Job Added From Invoice				27/09/2020	0	Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				25/09/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			25/09/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	fit bump stops to rear bolster				15/09/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WHEEL BRGS	adjusted rear axle wheel bearings				13/09/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				13/09/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	turn bolster pegs				04/09/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				04/09/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			04/09/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\Rims	PO FOR MACHINED RIM				04/09/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			29/08/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\AIR LEAK	repaired booster lines				29/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	repaired bolster stiffeners				29/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				29/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			29/08/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\CPR/RLR/MN	replace hammer lock for safety pin		replaced broken hold down chain hammerlock		27/08/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Workshop\MOVE ASSET	travelled to and from Wodonga depot download trailer ecm's				25/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Engine\FAULT CODE	download truck ecm's and check for obvious faults				25/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				20/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			20/08/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			14/08/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\AIR LEAK	repaired booster lines				14/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\AIR LEAK	repaired suspension leak				14/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				14/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	PO FOR BOLSTER PEG-WAITING ON P/WORK				14/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\BOOSTER	repaired booster hoses				07/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				07/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			07/08/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	Susp\AXLES	align trailer axles - scrubbing middle axle not tracking straight		RR's pre Jan 20 (system clean out) 05/08/20		06/08/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Elect\ELECT P&W	no brake lights or R/H/S indicator				05/08/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	replaced RHR 'NKP (broken)				01/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\ABS	repaired air leak and wiring to ABS control unit (fog damaged)				01/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	turned 1st bolster, 3rd LH and 4th LH bolster pegs				01/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				01/08/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service repaired wiring to 3rd bolster	VehService\DS			01/08/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	tightened loose booster				31/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\HOUSEKEEP	tightened tail bar				31/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				31/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			31/07/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	replaced 3rd bolster peg (LHS)				28/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	L/H peg on 3rd bolster broken at base				25/07/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				14/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			14/07/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				08/07/2020	1234	Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				09/07/2020	1234	Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\BRK RELINE	reline all 3 axles replace all s/cams and bushes fit RHF and RHR brake drums				08/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes\BRK O/HAUL	reolace RHR inner and outer w/bearinas		hot hubs		08/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Albury - Workshop	Brakes\BRAKE ADJ	check brake adjust (running hot after relign)		adjusted brakes		07/07/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				07/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			07/07/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\ELECT P&W	PO FOR PARTS				01/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			30/06/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\ABS	check ABS issue				30/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\ELECT P&W	replace rear tail light and repair wiring				30/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				30/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	po for straps				23/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\ABS	checked ABS codes				21/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\ELECT P&W	tightened bearing. Cleaned out plug and socket				21/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	replaced winch straps				21/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				21/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			21/06/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				16/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			16/06/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				11/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			11/06/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			03/06/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			03/06/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Comp\Truck Safe	fitted trucksafe sticker				03/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				03/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	Susp\HCV	repaired air leak @ HCV				30/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				28/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			28/05/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				21/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			21/05/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\AIR BAG	PO FO AIRBAG				13/05/2020	404505	Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\ELECT P&W	KIT- SENSOR WABCO (PO) diagnosed and replaced loom and sensor for ABS				07/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\ABS	tested and cleared codes				02/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				02/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			02/05/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	tightened 2nd winch mount bolts				26/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			26/04/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	2nd winch loose in mounting brackets				26/04/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			26/04/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SPRING PACK	replace R/H front z spring		replaced broken z-spring (RHF)		25/04/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\LIGHTS	repaired wiring to last bolster lights				19/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\LIGHTS	tightened 3rd bolster mount bolts				19/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				19/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			19/04/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\ELECT P&W	repaired 3rd bolster lights				15/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				15/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			15/04/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				05/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			05/04/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	turn pegs				27/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				27/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	carry out trailer service	VehService\DS			27/03/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	DriVcine\WHEEL ALIGN	perform laser wheel alignment on triaxle B trailer- at HTT				25/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				24/03/2020	0	Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice				24/03/2020	0	Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				19/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			19/03/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\MUDGUARDS	PO FOR SHIELD MUDFLAP				17/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\BRK RELINE	remove and replace all required brake shoes. Whist replacing shoes please remove hubs and inspect s-cams.		inspect all trailer brakes and confirmed right hand side rear axle brakes needed replacement. lacked ua vehicle and installed chasis support stands. removed hub assa		04/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			03/03/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\ABS	resecure abs cables on middle axle				03/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				03/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	tightened 3rd bolster pivot bolts				23/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\GEARBOX	repaired air leak at LHR b/booster				23/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				23/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			23/02/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\MUDGUARDS	replaced RH stretch guard				16/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				16/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			16/02/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			12/02/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				12/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	side lights not working rear 2 bolsters		locate repair power loos to rear bolsters		05/02/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\TRL LIGHTS	side lights not working rear 2 bolsters				05/02/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\LIGHTS	repair RH indicator				04/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				04/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	carry out trailer service	VehService\DS			04/02/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		Tightened LHM U Bolts		23/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	iahtened RHF Shocker Bolt		23/01/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\SUSPENSION	replaced LHF shocker				14/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\AIR TANKS	repaired air leak at 1st tank valve				14/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Result As Attached To This Job				14/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			14/01/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	Body\TRL REPS	Cut rollers out of curtain & start patching curtain				11/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Susp\AIR BAG	Replace air bag		TCTC part inv		10/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Body\AIR BAG	replaced RHF airbag				07/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\ELECT P&W	repaired wiring to LH brake light				07/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\HOUSEKEEP	tightened tail bar mounts				07/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				07/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			07/01/2020		Service	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Engine\HOUSEKEEP	replaced RTR solenoid				05/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\MUDGUARDS	modified guard				05/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy8PW		Myrtleford	MTK	562

T403	Albury - Workshop	Body\AIR BAG	RF AIR BAG RUBBED				04/12/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\BOLSTER	TIGHTENED BOLSTER PIVOTS				04/12/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	TEST RESULTS				04/12/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			04/12/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			03/12/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
						R/R sensor, checked wiring, found unplugged													
T403	Wodonga - Workshop	Chassis\FAULT CODE	Check active fault codes			Reconnected & cleared code	01/12/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER			
T403	Wodonga - Workshop	Chassis\AIR FITTIN	Found air valve broken			Replaced & tested	01/12/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER			
T403	Albury - Workshop	Susp\SUSPENSION	REPLACED BROKEN SPRING,WRAP,BUSH,BOLT/NUT			ALIEMENMENT PLATE & WEAR WASHERS	28/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	TEST RESULTS				22/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\BOLSTER	ADJUSTED UHF PEG				22/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			22/11/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\HCV	Damaged RTR valve			New unit will have to be ordered	20/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes					15/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\SHOCK ABS	TIGHTEN L/R SHOCKER				15/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			15/11/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes					08/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			08/11/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\SUSPENSION	Press bushes into 2 x springs				07/11/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\SUSPENSION	tightened 2x s.a.b				27/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Engine\BOOST HOSE	repaired booster air hoses				27/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Comp\Truck Safe	NHVAs sticker				27/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\HOUSEKEEP	removed and replaced UHF axle cable				27/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\SHOCK ABS	tightened loose shockers				27/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			27/10/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				27/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\SUSPENSION	Replaced broken 2 springs (RHF)				17/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\MUDGUARDS	replaced chassis stiffener and guard mount				13/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\MUDGUARDS	repaired outrigger				13/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\MUDGUARDS	reweld R/H front guard brace				10/10/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			10/10/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				10/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			10/10/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
						called out to Mundaroo													
T403	Rosewood - Workshop	Body\AIR FITTIN	replace broken airbag fitting			replace broken air fitting or height control valve	09/10/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Rosewood Workshop	TRAILER			
T403	Albury - Workshop	Brakes				reoair end of air aloe	01/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres	DRIVER ROTATED 2X TYRES WORN (NO FITTR)				01/10/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			01/10/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes					24/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\MUDGUARDS	R/H/S stretch guard outrigger cracked				24/09/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\MUDGUARDS	R/H outrigger on stretch guard cracked at chassis rail				24/09/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\MOUNTS	chassis rail mounts for R/H outrigger bent				24/09/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\HCV	REPLACED DAMAGED SUSPENSION CONTROL UNIT				24/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Elect\ELECT P&W	REMOVED, STRAIGHTNED & WELD DAMAGED CONTROL UNIT GUARD				24/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\BOLSTER	RHF OUTRIGGER MOUNT				24/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			24/09/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes					17/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			17/09/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\WINCH/STRP	lube winches				06/09/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes					06/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\AIR BAG	REPLACED UHF AIRBAG				06/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\HOUSEKEEP	Housekeeping				06/09/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			06/09/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\ABS	RHF sab			Previously completed	31/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\STCH GUARD	Replace centre stretch guard (between chassis rails)			Previously completed	31/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\EBS FAULTS	check EBS sensors brakes coming on			previously completed	31/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres	middle axle R/H/S tryres worn on shoulder			Previously completed	31/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\AIR LEAK	repair air leak				29/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Elect\ELECT P&W	replaced sensor loom 1B				29/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				29/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			29/08/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\WINCH/STRP	lube winches				29/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			29/08/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\HCV	checked suspension/ride height				25/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\ABS	checked ABS codes for sensor 2B				25/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\DAMAGE	found unplugged/damaged cable				25/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	DriLine\WHEEL BRGS	repaired. Adjusted wheel bearings				25/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Hydraulics\RAM	replaced front bolster hydraulic ram				25/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Hydraulics\RAM	front bolster lift ram leaking				24/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\EBS FAULTS	check EBS				24/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\HCV	check suspension/ride height				24/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				17/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			17/08/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\TRL ROLLBK	replace/refit quick release cable back bay			repaired rear quick release cable	15/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\TRL ROLLBK	remote release cables broken on rear bay			replaced both q/release cables on rear bay	14/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				09/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			09/08/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\MUDGUARDS	R/H outrigger on stretch guard cracked at chassis rail				08/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\MOUNTS	chassis rail mounts for R/H outrigger bent				08/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\TRL ROLLBK	pull cables quick release back by broken/frayed				08/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			08/08/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\BRK RELINE	crack tested and relined LHF, LHM & LHR axles				06/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
			unloaded trailer and replaced flat tyre																
T403	Albury - Workshop	Tyres\TPSB	tensioned all wheel nut's				05/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
			loaded trailer and parked truck																
T403	Albury - Workshop	Workshop\MOVE ASSET	out tyre card in truck for driver				05/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
			packed up all wheel and tools																
T403	Albury - Workshop	Workshop\CLEAN	shut up shed				05/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
						Unloaded trailer & replaced tyre													
						Tensioned all wheel nuts													
						Loaded trailer & parked truck													
						Put tyre card in cabin for driver													
T403	Wodonga - Workshop	Tyres\TPSB	Flat tyre PB			Packed up whees & tools & shut up shed	05/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER			
T403	Albury - Workshop	Chassis\MUDGUARDS	both quick release cables broken back bay				04/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\MUDGUARDS	R/H/S stretch guard outrigger cracked				04/08/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
						replaced RHR bolster pivot mount and bush													
T403	Albury - Workshop	Chassis\BOLSTER	broken pivot pin inside back bolster			realigned bolster	03/08/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Wodonga - Workshop	Brakes					31/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER			
T403	Wodonga - Workshop	VehService\DS	D Service	VehService\DS			31/07/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER			
T403	Wodonga - Workshop	Brakes					23/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER			
T403	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS			23/07/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER			
T403	Albury - Workshop	Body\CHN/RLR/MN	replased hold down chain				16/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				16/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			16/07/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				09/07/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			09/07/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Wodonga - Workshop	Brakes	Brake test results attached				29/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER			
T403	Wodonga - Workshop	VehService\DS	D Service	VehService\DS			29/06/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			25/06/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\CONSUMABLE	replase brake hoses front axle (cracked to short)			replaced brake hoses	25/06/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				25/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				16/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			16/06/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Tumut - Workshop	Tyres	middle axle R/H/S tryres worn on shoulder				15/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Tumut Workshop	TRAILER			
T403	Tumut - Workshop	VehService\DS	Service	VehService\DS			15/06/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Tumut Workshop	TRAILER			
			replaced broken bolster pivot bracket - 3rd bolster																
			swapped bent 3rd and 4th bolsters																
			replaced 4th bolster wear pads																
			replaced broken, missing and loose clamping bolts																
			repaired lights wiring																
T403	Albury - Workshop	Chassis\BOLSTER	reslaced LHR u-bolts saddle				06/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				06/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			06/06/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
			crack test and relines RHF & RHM axles																
T403	Albury - Workshop	Chassis\AXLE CT	washed and inspected bearings				06/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Workshop\CLEAN	cleaned up after job completion				06/06/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Elect\TAIL LIGHT	R/H/S rear clearance light broken on tail light bar				06/06/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			06/06/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Insp\ANN INSP	D Service				29/05/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				29/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			29/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\EBS FAULTS	check EBS sensors brakes coming on				21/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	A Service	VehService\DS			21/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				21/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			21/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	DriLine\AXLE REPLC	replaced LH axle cable				11/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				11/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			11/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				04/05/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			04/05/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\CROSS MBR	replaced cross member bolts				27/04/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				27/04/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			27/04/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				17/04/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			17/04/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	Service	VehService\DS	D service completed		10/04/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				03/04/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			03/04/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				27/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			27/03/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\SHOCK ABS	tighten loose shockers				19/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				19/03/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			19/03/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
						broken fitting in front air tank													
T403	Albury - Workshop	Susp\AIR FITTIN	air fitting broken of air t

T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				20/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			20/02/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\ELECT P&W	L/H/S indicator dull/flashing erratic			cleaned out lights plugs/sockets	13/02/2019	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				12/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			12/02/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\BOOSTER	replaced R/F booster				06/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				06/02/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			06/02/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job Service				27/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	R/B veb	VehService\DS			27/01/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\BRK RELINE	RELINE			crack test and relined RHR axle	18/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				16/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			16/01/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP09	Tyre Position 9			replaced pos 9 tyre with spare from T402	15/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SHOCK ABS	replaced RHR shocker				10/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				10/01/2019	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			10/01/2019	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job Service				22/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	NHVAS sticker required	VehService\DS			22/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SHOCK ABS	tightened shocks				15/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				15/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			15/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Engine	Job Added From Invoice				11/12/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	repaired RF spring hanger				07/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				07/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			07/12/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	Winches & Straps			fit air winches	06/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	fit airline for airwinches				05/12/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				30/11/2018 2	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\CLEANSION	Job Added From Invoice				30/11/2018 2	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				25/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			25/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				20/11/2018 1	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	VehService\DS	VehService\DS	D service completed- see attached		17/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body	Job Added From Invoice				08/11/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\DAMAGE	Damaged Equipment			replaced narp	06/11/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	VehService\DS	VehService\DS	D service completed		06/11/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Wodonga - Workshop	Body\DH&S	replaced peg load stickers				31/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				28/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			28/10/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				24/10/2018 2	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\CLEANSION	Job Added From Invoice				24/10/2018 2	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				17/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			17/10/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	press SEB				13/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Workshop\MOVE ASSET	pick up parts from ATT				13/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\STCH GUARD	straightened and weld damaged stretch guard mount and bracket				13/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	replaced LHF spring eye bosses, wear plates, sebolt and seb				13/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\BOLSTER	repaired 2nd bolster (LHS)				13/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\REFLECTORS	replaced damaged/missing amber reflectors				13/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				12/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\MOUNTS	repair LH stretch guard mount and bracket LHF sebcss cracked and seb				12/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\FIFTH WHEE	tumed LHR peg				12/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\BOOSTER	replaced LHR b/booster				12/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			12/10/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\BOOSTER	REPLACE BOOSTER				12/10/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				26/09/2018 10	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				26/09/2018 10	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\BOOSTER	repaired booster hoses				21/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\AXLE CT	crack tested and relined LHF, LHM and LHR axles				21/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	DrivLine\WHEEL BRGS	washed and inpected bearings				21/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Workshop\CLEAN	cleaned up after job completion				21/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				19/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			19/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	SUPPLY SUS PARTS				12/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	Replaced 1st winch sj/release cable				12/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	Replaced LHM seb				12/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	Tightened LHF sebolt				12/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				12/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			12/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			04/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	tightened sebolt LHF				04/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SHOCK ABS	replaced LHR top shocker nut (missing)				04/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				04/09/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			04/09/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			31/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	PRESS IN SB SEB				16/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\BOOSTER	REPLACE BOOSTER				15/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\BOOSTER	Replaced RHR B/ Booster				15/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				15/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			15/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			07/08/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				07/08/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				31/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			31/07/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS	REPLACE AIR BAG		22/07/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\AIR BAG	Replaced RHM airbag				22/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				22/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			22/07/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\SUSPENSION	LHR shocker mount broken				20/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			17/07/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	tightened loose LF seb				17/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SHOCK ABS	replaced RHM bottom shock mount - fitted shock				17/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SHOCK ABS	tightened shocks				17/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\MUDGUARDS	replaced guard bolts				17/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				17/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres	Job Added From Invoice				17/07/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				17/07/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				17/07/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres	Job Added From Invoice				12/07/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\BRK RELINE	brake reline				11/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			08/07/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\ABS	replaced damaged ABS sensor (RHM axle)				08/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				08/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\AXLE CT	crack test and reline RHM axle				08/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	DrivLine\WHEEL BRGS	wash and inspect bearings				08/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\ELECT P&W	replaced sensor ring				08/07/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\ELECT P&W	check for rubbed wire in rear light bar			cleaned out trailer light socket and plug tested lights (ok)	05/07/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				29/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			29/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres	Job Added From Invoice				28/06/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres	Job Added From Invoice				28/06/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				28/06/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				28/06/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				24/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			24/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Tumut - Workshop	VehService\DS	Service	VehService\DS			23/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Tumut Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			14/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				14/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			14/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				05/06/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			03/06/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				31/05/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Myrtleford - Workshop	Tyres	Job Added From Invoice				31/05/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				31/05/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Myrtleford Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			29/05/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\BOOSTER	replaced RHM b/booster				29/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	tightened LHF sebolt				29/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	tightened RHF u-bolts				29/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				29/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\AIR BAG	replaced rear axle airbags				22/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\AIR FITTIN	replaced air hose to RHR airbag				22/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	tightened LF seb bolt				19/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\AIR BAG	rear airbags - replace when time				19/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\CHAS CRACK	RF hanger small crack requires welding				19/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				19/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			19/05/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres	Job Added From Invoice				17/05/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				17/05/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				17/05/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				12/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\BOOSTER	Repaired leaking booster hoses				12/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	Repaired sticking 2nd winch. Replaced handle and strap.				12/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			12/05/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				11/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	Replaced front winch and strap				11/05/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			11/05/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres	Job Added From Invoice				09/05/2018 0	Repair	Completed	Greenfreight Logging NSW	K

T403	Albury - Workshop	Brakes\ABS	checked ABS				29/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				27/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			27/04/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
					checked for codes - active													
					-LHM axle continuity problem													
					-removed wheels, cleaned sensor and sensor ring													
T403	Albury - Workshop	Brakes\ABS	trailer ABS light on		-refit wheels and checked codes - nil		24/04/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	DrivLine\WHEEL BRGS	checked and adjusted all wheel bearings				21/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Susp\HCV	checked and adjusted suspension height				21/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Engine\FAULT CODE	checked for codes - nil				21/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Susp\AIR BAG	replaced LHM airbag				21/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Chassis\BOLSTER	replaced front bolster (NKP) - LHS				21/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Susp\AIR FITTIN	repaired suspension valve hosing				21/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				21/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			21/04/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes\ABS	trailer ABS light coming on check				21/04/2018 459711	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			21/04/2018 459711	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres	Job Added From Invoice				14/04/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				14/04/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				14/04/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				12/04/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				12/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			12/04/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
					checked ABS codes													
T403	Albury - Workshop	Brakes\ABS	trailer ABS light come on again		reset ECM		07/04/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				06/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Engine\FAULT CODE	Checked for codes - NIL				06/04/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			06/04/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Susp\SUSPENSION	tightened spring eye bolts				28/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				28/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			28/03/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Susp	Job Added From Invoice				28/03/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				27/03/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Susp\SHOCK ABS	Replaced LHM shocker				21/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				21/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			21/03/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Job Added From Invoice				18/03/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Body\MOUNTS	removed RHM shocker (bottom mount broken)				15/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	DrivLine\SUSPENSION	replaced middle axle cables				15/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Body\MOUNTS	repaired (weld) rod on middle axle - ABS cable mounts				15/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			15/03/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Susp\SHOCK ABS	tightened LHR shocker				15/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				15/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres	Job Added From Invoice				15/03/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				15/03/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				15/03/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Chassis\CHAS CRACK	tumad all pegs on LHS and checked for cracks				14/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Chassis\BOLSTER	2nd and 3rd bolsters LHS bent. Check for crack and turn in				10/03/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Chassis\AXLE CT	Crack test and reline LNM axle				08/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes\EBS FAULTS	Replaced damaged pulse ring				08/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Workshop\CLEAN	Clean up after jobs				08/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Susp	Job Added From Invoice				08/03/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes\ABS	RHF seb				06/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	DrCabElec\SPRING HANG	replaced LHF spring eye bolt				06/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				06/03/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			06/03/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				01/03/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Susp\AIR LEAK	air leak - replaced several hoses to middle axle b/boosters				27/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
			replaced LR bottom shock mount - fitted shock															
T403	Albury - Workshop	Susp\SHOCK ABS	repaired u-bolt saddle				27/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				27/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			27/02/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Susp\AIR BAG	right hand airbag on lift axle slow to inflate				21/02/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
			checked for active codes - wheel sensor pulse range															
			removed RHM wheel and cleaned pulse ring and reset sensor															
T403	Albury - Workshop	Brakes\EBS Kit	checked and cleaned codes - ok				21/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			16/02/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	check and adjusted all wheel bearings		16/02/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				16/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes\BRK RELINE	brake reline				16/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				11/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			11/02/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres	Job Added From Invoice				10/02/2018 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	DrivLine\DAMAGE	REPLACED CRACKED RIM				07/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Susp\AIR BAG	REPLACE AIR BAG				05/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes\BOOSTER	REPLACE BOOSTER				05/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Body\AIR BAG	replaced rear axle airbags				04/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes\BOOSTER	replaced LHF b/booster				04/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Chassis\SUSPENSION	LHR shocker mount broken				04/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			04/02/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				04/02/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Body\AIR BAG	check air bags				03/02/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			03/02/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			18/01/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				18/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Chassis\WINCH/STRP	REPLACE 2ND WINCH STRAP				17/01/2018	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	AIR BAG		11/01/2018	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes\BOOSTER	tightened RHR b/booster				11/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				11/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Body\AIR BAG	replaced LHR airbag				11/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Body\MUDGUARDS	replaced front mudflaps				11/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Chassis\AIR LEAK	repaired air leak at air tank				11/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	DrivLine\SHOCK ABS	tightened shocker bolts				11/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Body\REFLECTORS	replaced damaged/missing reflectors				11/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
					Crack tested & relined RNF & RHF axles													
					cracked tested and relined RHR axle													
T403	Albury - Workshop	Brakes\BRK RELINE	RELINE RF, RM, RR AND LR.		cracked tested and relined LHR axle		05/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Workshop\CLEAN	cleaned after job				05/01/2018	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres	Job Added From Invoice				28/12/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				28/12/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				28/12/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			24/12/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				24/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Body\MUDGUARDS	REPLACE MUD FLAP ON REAR OF TRAILER		replaced LHS mudflap		19/12/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\DAMAGE	tyre damage				19/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Body\LIGHTS	replaced LHS brake/tail, reverse lights				19/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Body\REFLECTORS	replaced dnot sign and paint				19/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				17/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			17/12/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres	Job Added From Invoice				15/12/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				15/12/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				15/12/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres	Job Added From Invoice				13/12/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				13/12/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				13/12/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Chassis\HOUSEKEEP	WELD CRACKS				13/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				10/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D Service	VehService\DS			10/12/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Elect\ELECT P&W	short in brake lights		checked brake lights fault found in worn socket at front of A trailer		08/12/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
			travel to Bandiana Link Rd. Wodonga															
T403	Albury - Workshop	Workshop\MOVE ASSET	re-load trailer after load shifter				08/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Chassis\WINCH/STRP	replaced straps where required				08/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Workshop\CLEAN	cleaned up area				08/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Chassis\WINCH/STRP	SUPPLY WINCH STRAP				07/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
					REPLACE RHF AIR BAG													
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	TIGHTENED TOP SHOCKER BOLTS		03/12/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				03/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Body\AIR BAG	replaced RHF air bag				03/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	DrivLine\SHOCK ABS	tightened top shocker bolts				03/12/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Wodonga - Workshop	VehService\AS	A Service Required				03/12/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			28/11/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				28/11/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres	Job Added From Invoice				25/11/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				25/11/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				25/11/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres	Job Added From Invoice				22/11/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				22/11/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				22/11/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
					SEB													
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	Reolaced RHF seb and sorine wras		19/11/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attachd To This Job				19/11/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			12/11/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				12/11/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	repaired wiring to L/H tail light		04/11/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				04/11/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
					TIGHTENED RHM BEARING													
T403	Albury - Workshop	Brakes\ABS	ABS FAULTS		CLEARED FAULTS		03/11/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres	Job Added From Invoice				02/11/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				02/11/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				02/11/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Chassis\WINCH/STRP	REPLACE REAR STRAP BACK BAY.				28/10/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS	FIT REFLECTIVE TAPE TO PEGS		28/10/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER		
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				28/10/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK

T403	Wodonga - Workshop	Brakes\AIR LEAK	air leak under front of tri			tightened drain coul	12/10/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			08/10/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				08/10/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		Tightend / replaced bolts for mudguards	29/09/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Hydraulics\BOLSTER	REAR 2 BOLSTERS VERY SLOW TO STAND UP.			Checked hydraulic pressures	22/09/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			22/09/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\WINCH/STRP	REPLACE MIDDLE STRAP ON LAST BAY.			Replaced winch strap on rear bay	16/09/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			13/09/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\BRK RELINE	RELINE LF WHEEL			crack test and reline LHF axle	05/09/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\BRK RELINE	Clean after relines				05/09/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\EBS KH	MOVE AIR TANK AND MODIFY PLUMBING TO SUIT.				05/09/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			03/09/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice				25/08/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Hydraulics\RAM	REAR 2 BOLSTERS VERY SLOW TO STAND UP.			ADJUST HYD. PRESSURE ON TRUCK. 185OPSI	21/08/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			20/08/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				20/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\ABS	ABS FAULT				14/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\BRK RELINE	replaced failed ABS components & reline				14/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				14/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			14/08/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres	Job Added From Invoice				11/08/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\WINCH/STRP	REPLACE REAR WINCH KNOB				11/08/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\ABS	FOUND FAULT IN LH HUB FOR ABS.				05/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			05/08/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\SUSPENSION	REPLACED SEB AND WRAP			replaced lhf seb wrap alignment plate, wear plates and repaired hanger/bosses	05/08/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\ABS	ABS light on				03/08/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		Replaced LH no plate light	30/07/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\HCV	air leak from airline into height control valve			replaced damaged supply hose to HCV	27/07/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\EBS KH	fit EBS				26/07/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Insp\ANN INSP	Roadworthy inspection completed while fitting up EBS				26/07/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				25/07/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			25/07/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Elect\INDICATORS	LH REAR INDICATOR NOT WORKING				23/07/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\EBS KH	CERTIFY EBS MOD.				23/07/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			19/07/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\MOUNTS	MAKE UP COVER PLATE OVER RTR VALVE				17/07/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Workshop\MOVE ASSET	UNHOOK 402/403 - HOOK UP 403 AS SINGLE EBS KIT				17/07/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\EBS KH	FITTED JB DSTR				09/06/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			04/06/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			28/05/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			19/05/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Elect\TAIL LIGHT	LH SIDE OUTSIDE TAIL LIGHT OCCASIONALLY NOT WORKING.			REPAIRED BROKEN WIRE	15/05/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\STCH GUARD	REPLACE LHS STRETCH GUARD-TORN			REPLACED STRETCH GUARD	13/05/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			13/05/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres	Job Added From Invoice				08/05/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				08/05/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				08/05/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		tight L/F seb bolt	05/05/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results				05/05/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres	Job Added From Invoice				28/04/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice				28/04/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice				28/04/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results				27/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			27/04/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	A Service	VehService\DS			27/04/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\AIR BAG	RHR AIR BAG LEAKING			replaced airbag	14/04/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			14/04/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results				14/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\AIR LEAK	repair air leak / broken hose off valve			repaired air leak	12/04/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			06/04/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results				06/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
						REPAIRED LHS MARKER DAMAGE.													
T403	Albury - Workshop	Elect\DAMAGE	REPLACE BROKEN CLEARANCE LIGHT LHS TAIL LIGHT BAR			REPLACED REFLECTOR	05/04/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Elect\TRL LIGHTS	REPAIR 3RD BOLSTER LIGHT			REPAIRED WIRING	05/04/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			28/03/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP13	Job Added From Invoice				24/03/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\BOLSTER	REPLACE BROKEN FIRST BOLSTER HYD. PIVOT ARM. (NXP)				19/03/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			19/03/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP15	Job Added From Invoice				11/03/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			10/03/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			03/03/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			23/02/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP21	Job Added From Invoice				21/02/2017 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\BRK RELINE	CRACK TEST AND RELINE LR AXLE			crack test & reline LHR axle	21/02/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\MUDGUARDS	REPLACE LHS REAR MUD FLAP. MISSING			REPLACED BOTH MUD FLAPS	15/02/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			14/02/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Elect\TRL LIGHTS	REFIT LHS CLEARANCE LIGHT			REFIT CLEARANCE LIGHT	12/02/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\CHN/RUR/MN	REPLACE SAFETY HOLD DOWN CHAIN				10/02/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS			05/02/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\BRAKE ADJ	check brake % for future relines				29/01/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			26/01/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\WINCH/STRP	replace front winch handle				21/01/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Elect\TRL LIGHTS	Front bolster light around the wrong way				19/01/2017	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
						change trailer couplings													
T403	Albury - Workshop	VehService\DS	D service	VehService\DS		replaced booster hose	18/01/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
						removed bolster from T374. Then fitted to T403. Ordered new bolster.													
						Rubbed back and painted bolster. Refit to T374													
T403	Albury - Workshop	Chassis\BOLSTER	Replace front Bolster. Cracked			Cleaned up after iob	18/01/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\BOLSTER	Weld bolsters			Sublet weld job to Aldonga Eng.	18/01/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\WINCH/STRP	replace front winch mount				10/01/2017	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			10/01/2017	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			21/12/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	A Service	VehService\DS			21/12/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP17	Job Added From Invoice				17/12/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\CHN/RUR/MN	Replace chain for dog.				17/12/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	Service	VehService\DS			14/12/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			14/12/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP11	Job Added From Invoice				13/12/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP17	Job Added From Invoice				13/12/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP19	Job Added From Invoice				13/12/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\SPRING PACK	Broken spring rear axle LH side				08/12/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			08/12/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP13	Job Added From Invoice				01/12/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			27/11/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			17/11/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\STCH GUARD	Replace RH stretch guard				10/11/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			10/11/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\AIR LEAK	Air leak under tri. (valve)				08/11/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
						replace 2nd strap													
						replaced R middle seb & spring wrap													
T403	Albury - Workshop	VehService\DS	D service	VehService\DS		replaced L reverse light	04/11/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\WINCH/STRP	Replace QR cable for middle winch rear bay.				02/11/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			27/10/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes\BRK RELINE	Reline brakes x5 as per reline sheet				19/10/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			16/10/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	check and record brakes				16/10/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job				07/10/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/10/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	check and record brakes				07/10/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			07/10/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP15	Job Added From Invoice				30/09/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP14	Job Added From Invoice				21/09/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Elect\TRL LIGHTS	front bolster lights dull/flickering			replaced light	18/09/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			18/09/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	check and record brakes				18/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Body\HOUSEKEEP	replaced "long vehicle" sign bolts and bushes			as above	09/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			08/09/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	check and record brakes				08/09/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			31/08/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	check and record brakes				31/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService	A Service				31/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP15	Job Added From Invoice				27/08/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis\WINCH/STRP	replace 1st and 3rd strap				25/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			25/08/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	check and record brakes				25/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService	C Service				25/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis	replace front strap middle bay				25/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Chassis	replace front strap back bay				25/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Susp\HCV	Check HCV. Scales playing up.			replace HCV axle mount & rubber	16/08/2016	Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS			16/08/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	check and record brakes				16/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	VehService\DS	D service	VehService\DS		as above	11/08/2016	Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Brakes	check and record brakes				11/08/2016	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP11	Job Added From Invoice				06/08/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER			
T403	Albury - Workshop	Tyres\TP21	Job Added From Invoice				06/08/2016 0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925

T403	Albury - Workshop	Tyres\TP20	Job Added From Invoice					05/07/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP20	Job Added From Invoice					05/07/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP20	Job Added From Invoice					05/07/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SUSPENSION	cracked SEB boss			weld crack		01/07/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SPRING PACK	replace broken 'Z' spring			replace 'Z' spring. Had a hell of a time getting it out and in. replace bolt and wear washers.		29/06/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				26/06/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	check and record brakes					26/06/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\STCH GUARD	straighten front guard on RH side of tri.			remove guard and pull guard out. Refit guard		22/06/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				19/06/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP18	Job Added From Invoice					10/06/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP18	Job Added From Invoice					10/06/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP18	Job Added From Invoice					10/06/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
						checked wiring in rear light bar for rubbed wires. Ok												
T403	Albury - Workshop	Elect\TAIL LIGHT	electrical short in trailer			cleaned trailer plugs and sockets. Ok		10/06/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\TRL LIGHTS	3rd bolster marker lights not working.					09/06/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				09/06/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	check and record brakes					09/06/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
						replaced 3rd peg.												
T403	Albury - Workshop	Chassis\BOLSTER	Straighten 3rd bolster peg LH side			Crack tested and straightened oxe bv Aldonaa Ene.		03/06/2016		Fault	Completed	Greenfreight Loxeine NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshoo	TRAILER
T403	Albury - Workshop	Body\CHN/RLR/MN	replaced over centre dog			fitted rachet style dog		03/06/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\AIR LEAK	air leak under tri			replaced maxi valve		02/06/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS		as above		02/06/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	check and record brakes					02/06/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\STCH GUARD	Replace LH stretch guard			replaced guard		24/05/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS		as above		22/05/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	check and record brakes					22/05/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP17	Job Added From Invoice					17/05/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP17	Job Added From Invoice					17/05/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP17	Job Added From Invoice					17/05/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	Replace rear strap			as above		15/05/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS		as above		15/05/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\TRL LIGHTS	intermittent short in tail lights/clearance lights			Checked over trailer for shorts. Could not find short. Repaired some bared wires. Could not get it to short again.		12/05/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	replace winch handle			middle winch rear day winch handle		12/05/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\STCH GUARD	replace springs on stretch guard			4 springs on centre mat		12/05/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP21	Job Added From Invoice					10/05/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	2nd winch strap needs replacing. Worn					10/05/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\WORK LIGHT	Back up lights flickering					10/05/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				10/05/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	check and record brakes					10/05/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				03/05/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	check and record brakes					03/05/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect	LH indicator not working repaired broken wire					01/05/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				22/04/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	check and record brake					22/04/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\STCH GUARD	replace springs on stretch mat.					19/04/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\MUDGUARDS	Replace bolt on LH guard bracket and repair guard.					19/04/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Insp\ANN INSP	Annual inspection					13/04/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService	Service					13/04/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\TAIL LIGHT	reverse lights not working					13/04/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
						found broken wire in umbilical arm and rubbed wires - replaced 7 core on umbilical arm on T402												
T403	Albury - Workshop	Elect\TRL LIGHTS	no reverse lights					13/04/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				13/04/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP21	Job Added From Invoice					12/04/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP18	Job Added From Invoice					12/04/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				07/04/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	check and record brakes					07/04/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				01/04/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	check and record brakes					01/04/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS		as above		22/03/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	Replace 2nd winch quick release cable.					18/03/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp\SPRING HANG	ramp/hanger cracked			weld ramp		12/03/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\AIR LEAK	air leak at maxi valve			replaced CA 400 valve		12/03/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				12/03/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	check and record brakes					12/03/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	replace front winch strap			as above		09/03/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP15	Job Added From Invoice					08/03/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP15	Job Added From Invoice					08/03/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP15	Job Added From Invoice					08/03/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				04/03/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	check and record brakes					04/03/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				25/02/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect\TRL LIGHTS	3rd bolster clearance lights not working. #rd bolster clearance lights not working			plugged plug back in - tidy up wiring		25/02/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	check and record brakes					25/02/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS		As per attached service sheets		18/02/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D service	VehService\DS				11/02/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
						relined front and middle axles. Replaced wheel bearings and cams on L/H and L/M. and cam only on R/F.												
T403	Albury - Workshop	Brakes\BRK RELINE	reline front and middle axle.			Crack test axles and inspect wheel bearinas.		02/02/2016		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshoo	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					29/01/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				29/01/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Wodonga Workshop	TRAILER
T403	Albury - Workshop	Brakes\BRK RELINE	relined rear axle			relined rear axle. Replaced L and R cams. Replaced L/H wheel bearings and drum.		26/01/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				13/01/2016		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					13/01/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Body\HOUSEKEEP	strap			completed		13/01/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes\AIR LEAK	hose/fittings					05/01/2016		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Elect	replace lh indicator					05/01/2016		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP19	Job Added From Invoice					01/01/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\CASE STOCK	Job Added From Invoice					01/01/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TYRE FIT	Job Added From Invoice					01/01/2016	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					26/12/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				26/12/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
			spring wrap															
T403	Albury - Workshop	Susp\SPRING PACK	tctc			Completed		19/12/2015		Repair	Completed	Greenfreight Loxeine NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshoo	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					17/12/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				17/12/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	replace worn brake hose line has joiner in it from 2nd to last axle					17/12/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				10/12/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					10/12/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	repair quick release cable					08/12/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				02/12/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					02/12/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Tyres\TP22	Job Added From Invoice					01/12/2015	0	Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					25/11/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				25/11/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					17/11/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				17/11/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Susp	tighten loose shocks					17/11/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					07/11/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				07/11/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
			winch mount															
T403	Albury - Workshop	Chassis\WINCH/STRP	elphinstone			completed		07/11/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Chassis\WINCH/STRP	fit extension to rear bay middle strap					04/11/2015		Fault	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					28/10/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				28/10/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS				11/09/2015		Service	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER
T403	Albury - Workshop	Brakes	Record Check Results As Attached To This Job					11/09/2015		Repair	Completed	Greenfreight Logging NSW	KennedyBPW	Myrtleford	MTK	562925	Albury Workshop	TRAILER