

04082203

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Safety Box 15081 Regent Postal Outlet Winnipeg, MB, R2C 5C7 1-204-985-0920

A01-21
DECAL
Manitoba C088015

Date Inspection Started: 23 DAY, 04 MO, 26 YR.
Date Inspection Completed: 23 DAY, 04 MO, 24 YR.
Inspection Expiry Date: 30 DAY, 04 MO, 27 YR.

Station Number: _____
Mechanic Number: _____
Station Phone Number: _____
Vehicle Owner: _____
Address: _____ City: _____ Province: _____ Postal Code: _____ Phone: _____

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous
Licence Number: _____ Prov.: _____ NSC #: _____
Odometer Reading: 119955 Odom. Type: km mi
Vehicle Identification Number: 21F10P1Y1S1Y1B151G1V121813191516 Make: PL Model: Chevy Year: 96 Unit #: _____
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR _____ KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Section 1 - Power Train: Defects (if any) _____
Section 2 Suspension: Defects (if any) _____
Section 3 - Brake Systems: 3H 3A
Defects (if any) _____ Circle Brake Type _____
Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection
Section 4 - Steering: Defects (if any) _____
Section 5 - Instruments & Auxiliary Equipment: Defects (if any) washer Motor (1)
Section 6 - Lamps: Defects (if any) License Plate Light (1) Reflector (2)
Section 7 - Electrical System: Defects (if any) _____
Section 8 - Body: Defects (if any) Body on Hood spring cable (1)
Section 9 - Tire & Wheel: Defects (if any) _____

Brake Inspection Type: A B C D E

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	3/8	3/8	15.077	15.077	1	1
2	3/8	1/2	16.602	16.592	1.25	1.25
3	5/8	3/8	16.579	16.562	1.25	1.25
4						
5						

Final Measurement

Axle	Tread Depth				Air Pressure					
	Initial		Corrected		Initial		Corrected			
	L	R	L	R	L	R	L	R		
1		21	21					100	100	
2	19	17	16	17			100	100	100	100
3	4	6	23	26			100	100	100	100
4										
5										

Section 10 - Coupling Devices: Defects (if any) _____

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: _____