EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T29S	Wodonga - Workshop	Tyres\TP5+6	LH MIDDLE INSIDE TYRE SIDEWALL SPLIT.			01/10/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\EXTE TU	No air winches.			01/10/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Elect\INDICATORS	RIGHT INDICATOR NOT WORKING.			01/10/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Insp\ANN INSP	carry out annual inspection			01/10/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/02/2022	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/02/2022	444551	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Tyres\TP5+6	LH MIDDLE INSIDE TYRE SIDEWALL SPLIT.			01/02/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Albury - Workshop	Tyres\TP7+8	supply and fit 2 tyres			28/01/2022	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/01/2022	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/01/2022	444551	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/12/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAK UNDER TRI.		REPAIRED AIR LEAK AT RF AIR BAG	16/12/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED RF BARAKE ADJUSTER.	16/12/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/12/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/12/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\EXTE TU	No air winches.			03/12/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	Inspected function of RF brake chamber found insufficient movement Removed airlines and checked air flow - all good Removed brake chamber from slack adjuster and axle mount Checked movement of brake chamber - seized Removed brake chamber completely Prepped and fitted new brake chamber Checked operation of brakes – booster now moves but brakes still not working Checked slack adjuster - worn Fitted customer supplied slack adjuster Adjusted all brakes Carried out brake test – failed Re-adjusted brakes, tested again - failed Carried out the same checks as above on RR axle Found brake chamber to be seized Removed chamber from trailer Prepped and fitted new chamber Checked operation of brakes - working Carried out brake test - Passed Checked function of reverse lights Found both lights work but has open circuit in loom somewhere Called customer, they organised Arkon to come and fix Prepped area of axle that was cracked	03/12/2021		PreventativeMaint	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Albury - Workshop	Insp\RWC COMP	VIC ROADWORTHY INSPECTION		Welded up cracked area of axle Travel to Blacklocks & return, check rear mounted floodlights not working. Connect test lead & verify operation of trailer lighting circuits. Found short behind L/H back up lamp, broken connector behind R/H back up lamp, melted terminal in connector for tail lamps. Remove lights & unclip rear harness for access. Replace damaged connectors & the short that caused them to melt, tension loose terminals on stop/tail lamp.	11/11/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Elect\TRL LIGHTS	Trailer worklight/reverse light not working		Reassemble & test.	05/11/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Wodonga - Workshop	Workshop\MOVE ASSET	Take 638 to Blacklocks to move T29S into their workshop and return to yard			02/11/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Workshop\MOVE ASSET	HOOK UP TO 929			28/10/2021	437271	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\FIFTH WHEE	FIT NEW TURNTABLE BLOCK. HOOK UP TO T224			23/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\AIR LEAK	Air leak RHR Corner.			09/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Elect\WORK LIGHT	work lights don't work when you need them			09/10/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\ABS	abs brakes coming on around right bends			09/10/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Elect\WORK LIGHT	No work lights.			09/10/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\AIR LEAK	Air leak in Tri.			09/10/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\EXTE TU	No air winches. Bolts to secure Bolsters to Chassis. Supplied by Ultimate fasteners Wodonga			09/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\BOLSTER	PO# WW 067241			21/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Workshop\MOVE ASSET	MOVED OUT OF SHED. BRAKES NOT ADJUSTED, ALMOST DROPPED. SORTED OUT. HOOKED I			15/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\AIR BAG	Front axle airbags cracked and split.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SHOCK ABS	Lower shock bushes worn.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BRAKE ADJ	Excessive play in LHR S Cam Bushes.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BRK O/HAUL	LHR Drum heavily glazed.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BRK RELINE	RHR Brake lining contaminated.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BRK O/HAUL	LHF and LHM Drums oversize.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BRK O/HAUL	One drum seaized on.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BOOSTER	RHF Booster clevis missing split pin.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BOOSTER	LHM Axle clevis lock nut not secure.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BOOSTER	RHR Booster missing cap.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Elect\HOUSEKEEP	Rear axle all wiring loose.		Supply and fit new Skid plate. 20 x Countersunk Bolts required.	01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\SKID PLATE	Skid Plate Cracked left hand side, (Worn Excessive)		Ultimate Fasteners PO# WW067636	01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\SKID PLATE	Skid Plate loose.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\KING PIN	King Pin worn.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SPRNG HANG	LHF Hanger Cracked.(Through other repairs.)			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SPRNG HANG	LHM Spring perch cracked.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\AIR BAG	RHF Airbag plate bent.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SHOCK ABS	LHM Top shock bush worn.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SPRNG HANG	RHR Spring keeper broken.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SPRNG HANG	Tension all U-Bolts			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SPRNG HANG	Tension LHR Spring bolt.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	DrivLine\WHEEL BRGS	LHM Bearing failing.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\BOLSTER	Front RH and LH Bolster cracks.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\BOLSTER	2nd Bolster chassis brace cracked.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Hydraulics\HOSES	Hydraulic lines insecure rubbng on spare tyre.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\SPAREWHEEL	Front spare wheel carrier wearing into chassis rail.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\BOLSTER	3rd bolster is loose wearing into rail.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\AIR BAG	Front axle airbag top mount cracked.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\AXLE CT	LH Chassis rail at 1st axle advanced rust.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\AIR TANKS	Air tank at front axle loose bolts.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\AIR TANKS	2nd axle air tank bolts loose/missing.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\CROSS MBR	4th and 5th cross members bent.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\RWC COMP	Compliance plate unable to be read.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Body\REFLECTORS	Front reflectors missing.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Elect\TRL LIGHTS	Front right hand marker light cracked.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Elect\TRL LIGHTS	Right Rear marker light insecure.			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis				01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Albury - Workshop	Insp\RWC COMP	Carry Out roadworthy and clear NVHR defects			01/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BRAKE ADJ	Excessive play in LHR S Cam Bushes.		Cant Fault	31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BRK O/HAUL	LHR Drum heavily glazed.		Clean LHF & LHR hub and drum faces. Found RHR hub seal weeping and brakes getting low. Removed brakes and hub. Difficulty removing old anchor pin bushes. Had to die grind and chisel out as they were seized. Retrieved parts from trailer shed to rebuild hub. Kit. Anchor pins were tight, had to file and linish bushes to suit. Finish fitting brake kit and hub, brake drum and tyres. Adjusted hub.	31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BRK RELINE	RHR Brake lining contaminated.		Take axles off stands and torque all wheel nuts.	31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BRK O/HAUL	LHF and LHM Drums oversize.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BRK O/HAUL	One drum seaized on.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BOOSTER	RHF Booster clevis missing split pin.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BOOSTER	LHM Axle clevis lock nut not secure.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BOOSTER	RHR Booster missing cap.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Elect\HOUSEKEEP	Rear axle all wiring loose.		Made Bracket and Welded on.	31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER

					Cant find crack. Visually inspected skid plate. Appears to be still in spec. Confirm with Andrew. Attempt to undo bolts holding skid plate on. Mosst seized or stripped. Pick up new bolts from Ultimate Fasteners.											
T29S	Wodonga - Workshop	Chassis\SKID PLATE	Skid Plate Cracked left hand side, (Worn Excessive)		Bolts to be cut off. Rear bolts loose - trailer stand in the way.	31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\SKID PLATE	Skid Plate loose.		Weld up large crack.	31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\KING PIN	King Pin worn.		Tested king pin Requires replacing.	31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SPRNG HANG	LHF Hanger Cracked.(Through other repairs.)			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SPRNG HANG	LHM Spring perch cracked.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\AIR BAG	Front axle airbags cracked and split.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SHOCK ABS	Lower shock bushes worn.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\AIR BAG	RHF Airbag plate bent.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SHOCK ABS	LHM Top shock bush worn.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SPRNG HANG	RHR Spring keeper broken.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SPRNG HANG	Tension all U-Bolts			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SPRNG HANG	Tension LHR Spring bolt.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	DrivLine\WHEEL BRGS	LHM Bearing failing.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\BOLSTER	Front RH and LH Bolster cracks.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\BOLSTER	2nd Bolster chassis brace cracked.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Hydraulics\HOSES	Hydraulic lines insecure rubbng on spare tyre.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\SPAREWHEEL	Front spare wheel carrier wearing into chassis rail.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\BOLSTER	3rd bolster is loose wearing into rail.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\AIR BAG	Front axle airbag top mount cracked.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\AXLE CT	LH Chassis rail at 1st axle advanced rust.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\AIR TANKS	Air tank at front axle loose bolts.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\AIR TANKS	2nd axle air tank bolts loose/missing.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\CROSS MBR	4th and 5th cross members bent.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\RWC COMP	Compliance plate unable to be read.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Body\REFLECTORS	Front reflectors missing.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Elect\TRL LIGHTS	Front right hand marker light cracked.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Elect\TRL LIGHTS	Right Rear marker light insecure.			31/08/2021	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\AXLES	repair cracked L/H/F & L/H/R spring saddles			28/08/2021	43698	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Albury - Workshop	Tyres\TP11+12	Supply and fit 2 tyres			27/08/2021	436980	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/08/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/08/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Body\REFLECTORS	LHF Reflector missing.			27/08/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\AIR LEAK	Air leak RHR Corner.			27/08/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Tyres\FITMENT	RHR Inner tyre U/S			27/08/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
					Fit new LHF shock. Cleaned upper shock base due to it being damaged when cutting old shock out. Fit new shock and straightened lower shock mount.											
T29S	Wodonga - Workshop	Susp\SHOCK ABS	LHF Shock blown. Reline RHF and LHM Brakes. Anchor pin bushes were seized and had to get assistance to hit out with a bar and sledge		Inspected trailer before leaving.	27/08/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes\BRK RELINE	hammer.			27/08/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Workshop\MOVE ASSET	Move trailers - Includes Smoko and moving other trucks out of the way.			27/08/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Susp\SHOCK ABS	Remove RHF Blown shock.			27/08/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Workshop\MOVE ASSET	Move trailer out of shed and clean bay.			27/08/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Albury - Workshop	Tyres\TP1+2	Supply and fit 6 tyres			12/08/2021	292000	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			12/08/2021	292000	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			12/08/2021	292000	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/07/2021	418085	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/07/2021	418085	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\AIR LEAK	Fix air leak at rear of trailer behind right hand rear axel.			28/07/2021	416812	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/07/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	repair air winch	22/07/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Elect\WORK LIGHT	work lights don't work when you need them			10/07/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\AIR FITTIN	change couplings		Completed.	10/07/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/06/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	Body\BOLSTER	RH side second bolster no bolt to hold it in.			25/06/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/06/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			27/05/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		27/05/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	Tyres\TP5+6	replace 2 tyres			13/02/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Rosewood - Workshop	Tyres\TP9+10	replace 2 tyres			13/02/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Rosewood - Workshop	Tyres\TP12	fit run out			13/02/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			22/01/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		22/01/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	Brakes\EBS Kit	replace RHR wheel speed sensor			15/01/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
					bolster peg broken remove bolt and bolster peg											
T29S	Rosewood - Workshop	Chassis\BOLSTER	replace cracked bolster (peg) repair abs brakes		fit new bolster peg	09/01/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	Brakes\EBS Kit	-coming on when not braking			19/12/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Tumut - Workshop	Brakes\ABS	abs brakes coming on around right bends			17/12/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Tumut Workshop	TRAILER
T29S	Tumut - Workshop	Elect\ELECT P&W	fit electrical plug to front cover			10/12/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Tumut Workshop	TRAILER
T29S	Wodonga - Workshop	Chassis\AIR FITTIN	air hose was cut in half on the front of the B Trailer when the loader driver dropped a log		RR's pre Jan 20 (system clean out) 05/08/20	06/08/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\MUDGUARDS	Replace LHF mud guard			30/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	TWIN CITY TRUCK CENTRE - OLD	TRAILER
T29S	Myrtleford - Workshop	Body\MUDGUARDS	Fit 2 x front mudflaps			30/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	TWIN CITY TRUCK CENTRE - OLD	TRAILER
T29S	Myrtleford - Workshop	Body\AIR LEAK	Repair air leaks			30/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	TWIN CITY TRUCK CENTRE - OLD	TRAILER
T29S	Myrtleford - Workshop	Susp\SHOCK ABS	Replace RHF shocker			30/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	TWIN CITY TRUCK CENTRE - OLD	TRAILER
T29S	Myrtleford - Workshop	Susp\HOUSEKEEP	Reweld LHR spring wear plate			30/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	TWIN CITY TRUCK CENTRE - OLD	TRAILER
T29S	Myrtleford - Workshop	Susp\DAMAGE	Repair axle saddle cracks and align plates			30/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	TWIN CITY TRUCK CENTRE - OLD	TRAILER
T29S	Myrtleford - Workshop	Brakes\BRK RELINE	Reline Rear Axle			30/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	TWIN CITY TRUCK CENTRE - OLD	TRAILER
T29S	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			30/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
T29S	Rosewood - Workshop	VehService\DS	Order Number # R9218	VehService\DS		30/07/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	TWIN CITY TRUCK CENTRE - 4 - OLD	TRAILER
T29S	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			18/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		18/07/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Albury - Workshop	Tyres\CASE STOCK	Job Added From Invoice			18/07/2020	1	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice			18/07/2020	1	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			18/07/2020	1	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice			18/07/2020	1	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Rosewood - Workshop	Body\BREAKDOWN	call out broken air lines front of trailer		called out 3:30am to Pond creek. Loader dropped log on B Trailer air supply	16/07/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	Body\AIR LEAK	repaired as best I could with what I had, proper repair to be done at change over called out again later in day, took correct fittings			16/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	Body\AIR LEAK	repaired properly for long term			16/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			10/07/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		10/07/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	Susp\SUSPENSION	check front axle - out of line			08/07/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
					called out trailer (I was already at a call out in area) loader had damaged the rear deck plate and broken fitting out of HCV when picked up by grapple to "move trailer"											
T29S	Rosewood - Workshop	Susp\DAMAGE	call out, broken air fitting at HCV		travel home	01/07/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	Elect\ELECT P&W	check for visible signs of scale wiring damage			26/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	Brakes	Record Check Results As Attached To This Job			26/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Rosewood - Workshop	VehService\DS	D Service	VehService\DS		26/06/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T29S	Albury - Workshop	Susp\SUSPENSION	order new pivot bush & wrapper leaf			19/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T29S	Albury - Workshop	Elect\TAIL LIGHT	repaired wiring to rear lights			06/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	VehService\DS	D Service	VehService\DS		02/06/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			02/06/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	VehService\DS	D Service	VehService\DS		26/05/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			26/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Susp\SHOCK ABS	RHF shocker		as per #286794	12/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			12/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Susp\SHOCK ABS	RHF shocker		Checked all suspension components	12/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Chassis\SHOCK ABS	RHF shocker		As per #286793	12/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/05/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	VehService\DS	Due for D Service	VehService\DS	As per #286791	12/05/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Susp\SHOCK ABS	RHF shocker			05/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			05/05/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T29S	Albury - Workshop	VehService\DS	D Service	VehService\DS		05/05/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER

T295	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			28/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/04/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Chassis\STRAPS	order strap 75xp			21/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T295	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			21/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D Service	VehService\DS		21/04/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Chassis\SHOCK ABS	RHF shocker			15/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes	Record Checked Results As Attached To This Job			15/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D Service	VehService\DS		15/04/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			04/04/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D Service	VehService\DS		04/04/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Susp\SHOCK ABS	RHF shocker			29/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			29/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D Service	VehService\DS		29/03/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Susp\AIR BAG	RHS airbag rear come away from base		replaced RHR airbag	27/03/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Wodonga - Workshop	Insp\DEFECT	cleared defect for logging			25/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
			inspected "crack in support part of chassis" found 18mm crack in bottom of chassis stiffener													
T295	Albury - Workshop	Chassis\CHAS CRACK	in front of front axle RHS repaired stiffener			25/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes\BOLSTER	repaired wiring to 3rd bolster light			20/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			20/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D Service	VehService\DS		20/03/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			12/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D Service	VehService\DS		12/03/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\AS	Carry Out Trailer Service			08/03/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes\EBS FAULTS	EBS issue			08/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			08/03/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes\BRAKE ADJ	trailer brakes very sensitive			06/03/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Elect\WORK LIGHT	work lights don't work when you want them			06/03/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Chassis\BOLSTER	repaired rear bolster light wiring			29/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Elect\WORK LIGHT	repaired work light wiring			29/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			29/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D Service	VehService\DS		29/02/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\AS	Due for D Service			29/02/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Elect\WORK LIGHT	work lights not working			29/02/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Elect\TAIL LIGHT	back clearance lights not working			29/02/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			14/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D Service	VehService\DS		14/02/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes\BRK RELINE	brake reline carried out by TCTC		fit 2 x new air bags	14/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T295	Albury - Workshop	DrivLine\WHEEL BRGS	all bearings require adjusting. Wodonga w/shop doesn't have tools required		repaired while doing brake reline	14/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T295	Albury - Workshop	Susp\SHOCK ABS	front and rear shocks loose		repaired while doing brake reline	14/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T295	Albury - Workshop	Elect\WORK LIGHT	work lights don't work when you need them			12/02/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes\BRAKE ADJ	brakes are very savage after being relined work before everything else			12/02/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Myrtleford - Workshop	Tyres\DAMAGE	fit two tyres			11/02/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Body\DAMAGE	straighten outrigger			11/02/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Albury - Workshop	Chassis\SUSPENSION	RHR shocker bolt			19/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			19/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D Service	VehService\DS		19/01/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes\BRAKE ADJ	brake adjustment			16/01/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			15/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T295	Albury - Workshop	Elect\TRL LIGHTS	replaced bolster light			15/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/01/2020		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
					repaired air leaks at maxi valve											
T295	Albury - Workshop	Chassis\AIR LEAK	air leak		repaired air leaks at rear tank	14/01/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Elect\ELECT P&W	short in the rear load lights			14/01/2020		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Elect\WORK LIGHT	repaired work lights wiring			14/01/2020		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/12/2019	249098	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T295	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/12/2019	249098	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T295	Wodonga - Workshop	DrivLine\WHEEL BRGS	all bearings require adjusting. Wodonga w/shop doesn't have tools required			28/12/2019	249098	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T295	Wodonga - Workshop	Susp\SHOCK ABS	front and rear shocks loose			28/12/2019	249098	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
					CUT OUT OLD BRAKEN BOLTS IN SHOCKER MIDLLE											
					REPAIR CRACKS IN HANGER											
					PREP FOR SHOCKER MOUTS FOR NEW ONES TO BE MOUNTED											
T295	Wodonga - Workshop	Susp\SHOCK ABS	REPAIRS		STARTED FITTING REAR SPRING ARM BUSHERS	25/12/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER
T295	Albury - Workshop	Brakes	TEST RESULTS			12/12/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Chassis\CHAS CRACK	CRACKS - MANY			12/12/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Susp\SHOCK ABS	TIGHTENED SHOCKS			12/12/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		12/12/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Rosewood - Workshop	VehService\DS	D SERVICE	VehService\DS		29/11/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T295	Rosewood - Workshop	Brakes	TEST RESULTS			29/11/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Rosewood Workshop	TRAILER
T295	Albury - Workshop	Chassis\AIR FITTIN	REPAIR DAMAGED FITTING / COUPLING FROM LOG DAMAGE			17/11/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Hydraulics\HOSES	hub hose is broken off			16/11/2019		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Chassis\AIR FITTIN	air hose was cut in half on the front of the B Trailer when the loader driver dropped a log			16/11/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes				15/11/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		15/11/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes				05/11/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		05/11/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\AS	due for A Service			05/11/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Tyres\CASE STOCK	Job Added From Invoice			01/11/2019	219401	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice			01/11/2019	219401	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice			01/11/2019	219401	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes				25/10/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		25/10/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes				18/10/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		18/10/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			12/10/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D Service	VehService\DS		12/10/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes				09/10/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Body\HOSES	TIGHTEN HOSE CLAMPS			09/10/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Susp\SHOCK ABS	TIGHTEN SHOCKER BOLTS			09/10/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	d service	VehService\DS		09/10/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Elect\INDICATORS	reapired wiring to RH outer indicator			04/10/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Brakes				01/10/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Chassis\FIFTH WHEE	SPARE TYRE STOPPERS, WEARING INTO CHASSIS			01/10/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Chassis\CHAS CRACK	NUMEROUS CRACKS			01/10/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Chassis\WINCH/STRP	2 WINCH STAPS		TIGHTTENED CHASSIS LONLES	01/10/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D SERVICE	VehService\DS		01/10/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Myrtleford - Workshop	Elect\WORK LIGHT	no work lights			24/09/2019		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Albury - Workshop	Brakes				22/09/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Body\ELECT P&W	REPAIRED WIRING TO RHR BOLSTER LIGHT			22/09/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	Susp\AXLES	Axles			22/09/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Albury - Workshop	VehService\DS	D SERVIES	VehService\DS		22/09/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Albury Workshop	TRAILER
T295	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/09/2019	191018	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/09/2019	191018	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/09/2019	187570	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fitted new tail light	04/09/2019	187570	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Brakes\EBS Kit	check EBS - brakes applying hard, stopping			28/08/2019	180748	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Hydraulics\DAMAGE	repair hydraulic fitting on T295			27/08/2019	180292	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/08/2019	177348	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced winch handle	17/08/2019	177348	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/08/2019	172827	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit shocker bolt to RHM	08/08/2019	172827	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/08/2019	168716	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/08/2019	168716	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Susp\SHOCK ABS	Replace RHR shocker			26/07/2019	165672	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/07/2019	164302	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced damaged hyd fitting	25/07/2019	164302	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/07/2019	159381	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit new RH inner tail light and boot	19/07/2019	159381	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/07/2019	154349	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/07/2019	154349	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Body\FIFTH WHEE	unhook T-39 and hook up to T295			10/07/2019	149982	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Body\AIR FITTIN	straightened air lines			10/07/2019	149982	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T295	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/06/2019	149981	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER

						replaced bolster pivot bushes												
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tightened loose spring eye bolts	22/06/2019	149981	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/06/2019	148630	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
					replaced shocker bolt													
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	cleaned bark bolster ram and tightened fittings	18/06/2019	148630	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/06/2019	146414	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/06/2019	146414	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\MUDGUARDS	shorten mudflaps			04/06/2019	145352	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\HOUSEKEEP	repair rear bar, mudflaps, lights etc.			01/06/2019	144191	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/05/2019	143491	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/05/2019	143491	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BRK RELINE	Crack Test & Reline Rear Middle Axles			23/05/2019	144191	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SUSPENSION	Repair Or Replace Rear Axle U Bolt Saddles			23/05/2019	144191	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/05/2019	141202	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/05/2019	141202	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/05/2019	138644	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/05/2019	138644	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/05/2019	136474	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/05/2019	136474	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/05/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced LED tail light	07/05/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/05/2019	131757	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/05/2019	131757	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes			19/04/2019	127682	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BRAKE ADJ	front 2 axles locking on			19/04/2019	127682	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/04/2019	127682	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/04/2019	127682	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\ELECT P&W	electric "B" brake not working			17/04/2019	126059	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/04/2019	126055	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/04/2019	126055	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/04/2019	123268	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/04/2019	123268	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/04/2019	120709	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/04/2019	120709	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\HOUSEKEEP	check over trailers			29/03/2019	118513	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\MUDGUARDS	replace damaged RHF mudguard			29/03/2019	118513	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\BOLSTER	check folding bolster bushes for wear and replace as necessary			26/03/2019	118513	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/03/2019	118512	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/03/2019	118512	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/03/2019	116086	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/03/2019	116086	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
					repair side light wiring													
T29S	Myrtleford - Workshop	Elect\INDICATORS	Repair 2nd RHS bolster indicator		repair rear tail light	14/03/2019	118513	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/03/2019	114771	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/03/2019	114771	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/03/2019	111566	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/03/2019	111566	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/02/2019	108858	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
					RHM tyre inner needs replacing													
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	1x winch handle	28/02/2019	108858	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/02/2019	106509	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/02/2019	106509	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/02/2019	103202	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/02/2019	103202	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/02/2019	100966	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/02/2019	100966	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHF bottom shocker bolt			08/02/2019	99370	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/02/2019	98770	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
					fit new female coupling to brake line													
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	front axle tyres wearing bad may need wheel alignment	07/02/2019	98770	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/02/2019	96732	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/02/2019	96732	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\HYDRAULICS	replace hydraulic hose			01/02/2019		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2019	93432	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/01/2019	93432	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/01/2019	90357	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
					replace LHF s/eye bush													
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	weld spring saddle crack LHF	18/01/2019	90357	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair skid plate crack			15/01/2019	118513	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/01/2019	88257	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/01/2019	88257	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SUSPENSION	Replace LHR spring eye bush			09/01/2019	90357	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/01/2019	85874	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/01/2019	85874	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/12/2018	83439	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/12/2018	83439	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/12/2018	80289	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced RHR top shocker bolt	18/12/2018	80289	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\CASE STOCK	Job Added From Invoice			16/12/2018	72408	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			16/12/2018	72408	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			16/12/2018	72408	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\WINCH/STRP	replace 2 straps			14/12/2018	78982	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/12/2018	77738	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/12/2018	77738	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/12/2018	74843	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	axle strap	01/12/2018	74843	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/11/2018	71817	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/11/2018	71817	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels		fit drums to rear axle only	22/11/2018	75860	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/11/2018	69472	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/11/2018	69472	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/11/2018	66683	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/11/2018	66683	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			30/10/2018	62363	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced ride height gromet	30/10/2018	62363	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/10/2018	60196	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/10/2018	60196	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/10/2018	444551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/10/2018	444551	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/10/2018	99295	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/10/2018	99295	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SUSPENSION	Replace LHR top spring saddle		refit shocker	06/10/2018	62363	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/10/2018	53857	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/10/2018	53857	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/09/2018	51266	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/09/2018	11266	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres	Job Added From Invoice			23/09/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			23/09/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			23/09/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Hydraulics\RAM	ram to front bolster broken			18/09/2018	49754	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	work lights on with/H indicator			14/09/2018	48804	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/09/2018	48804	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/09/2018	48804	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHR bottom shocker bushes			12/09/2018	53857	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/09/2018	47867	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/09/2018	47867	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SUSPENSION	trailer not tracking - unstable			07/09/2018	46897	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\ELECT P&W	scales not working			06/09/2018	46372	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			06/09/2018	45702	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			06/09/2018	45702	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres	Job Added From Invoice			06/09/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	replace RH 3rd bolster light keeper			05/09/2018	46312	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Hydraulics\HYD LEAKS	hydraulic fitting broken off			01/09/2018	4570	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/08/2018	44595	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER

T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/08/2018	44595	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	fit x3 new straps	23/08/2018	42860	PreventativeMaint	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/08/2018	42190	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPAIR TRL CRACKS	18/08/2018	42190	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			14/08/2018	38071	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/08/2018	39667	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/08/2018	39667	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres	Job Added From Invoice			28/07/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			28/07/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			28/07/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/07/2018	36801	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/07/2018	36801	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\ELECT P&W	check lights			20/07/2018		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Insp\RWC COMP	fit rego sticker			19/07/2018		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/07/2018	34494	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/07/2018	34494	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\MUDGUARDS	Check & replace damaged mud guards			03/07/2018	37144	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair bolster lights			03/07/2018	37144	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		replaced LHR side marker	28/06/2018	32062	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tightened skid plate bolts	28/06/2018	32062	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline rear axle			15/06/2018	31075	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/06/2018	29152	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/06/2018	29152	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\WORK LIGHT	repair work lights			13/06/2018	28765	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/06/2018	26889	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/06/2018	26889	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/05/2018	22467	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/05/2018	22467	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres	Job Added From Invoice			19/05/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			19/05/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			19/05/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\WORK LIGHT	load lights out on rear			18/05/2018	23758	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\WINCH/STRP	rear winch bearings tight			18/05/2018	23758	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres	Job Added From Invoice			12/05/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			12/05/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			12/05/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SUSPENSION	Replace RHR U-Bolt saddle			12/05/2018	24467	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		fit new RHR s/eye bush	10/05/2018	22246	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit 2 new shocker bushes RHR	10/05/2018	22246	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\EBS Kit	check air leak			02/05/2018	20106	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/05/2018	19842	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/05/2018	19842	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\WINCH/STRP	quick release cable not enough to grab fix on third winch			29/04/2018	19481	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\WINCH/STRP	quick release cable on first winch broken			25/04/2018	18634	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SPRNG PACK	broken spring and wrap on RHF axle		replace broken RHF spring and wrap	19/04/2018	17210	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/04/2018	17210	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/04/2018	17210	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres	Job Added From Invoice			17/04/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			17/04/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			17/04/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SUSPENSION	Replace LHF shocker			04/04/2018	19842	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SUSPENSION	Replace LHR shocker bushes			04/04/2018	19842	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/04/2018	1490	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/04/2018	1490	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\AIR LEAK	check air leaks on rear			30/03/2018	14520	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\STCH GUARD	replace chassis stretch guard			29/03/2018	14119	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair reverse lights			24/03/2018	14119	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	repair first bolster lights		clean out balk from chassis	24/03/2018	14119	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/03/2018		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/03/2018		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/03/2018	234101	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	plugged rear axle wheel sensors in and retied	07/03/2018	234101	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice			01/03/2018	8111	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/02/2018	7766	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/02/2018	7766	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/02/2018	5374	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/02/2018	5374	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Hydraulics\OIL LEAK	broken seal leaking			10/02/2018	4797	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/02/2018	3011	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/02/2018	3011	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/01/2018	35343	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	repair wiring to bolster lights	19/01/2018	35343	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/01/2018	32303	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/01/2018	32303	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Hydraulics\OIL LEAK	Repair hydraulics fitting on front of the trailer			06/01/2018		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\ELECT P&W	Calibrate span weight on scales			22/12/2017	29695	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/12/2017	29408	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/12/2017	29408	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\ELECT P&W	scales not working			20/12/2017	29063	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres	Job Added From Invoice			19/12/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			19/12/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			19/12/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			16/12/2017	26974	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			16/12/2017	26974	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/12/2017	26351	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	change RHR t/light	13/12/2017	26351	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/11/2017	23506	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/11/2017	23506	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\HOUSEKEEP	front axle driver side spring eye bolt loose			18/11/2017	22529	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	DrCabElect\SCALES	Fit new scale wire to trailer			15/11/2017	23509	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SPRNG HANG	Replace RHF Spring hanger L3512. Replace RHF Spring hanger			11/11/2017	21808	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace RHF Spring eye bush			11/11/2017	21808	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\AIR BAG	Replace RHF Airbag			11/11/2017	21808	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\MUDGUARDS	Repair mudguard mounts			11/11/2017	21808	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\AIR LEAK	Replace air bag dump valve & check system			09/11/2017	21808	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\AIR LEAK	air sometimes leaking out of airbag dump/raise because the button is cracked			07/11/2017	21627	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/11/2017	21332	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced LHF axle straps	04/11/2017	21332	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\WINCH/STRP	binder handle missing			02/11/2017	21332	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\AIR FITTIN	check airbag dump valve button			27/10/2017		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\HOUSEKEEP	valve working ok truck has to have full air for valve to work			27/10/2017		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\ELECT P&W	Check & repair scales on rear trailer			26/10/2017	21332	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\WORK LIGHT	no rear work lights			25/10/2017		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/10/2017	19523	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/10/2017	19523	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\HOUSEKEEP	replace broken axle catch cable			21/10/2017	18971	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\AIR FITTIN	airbag dump valve blocked			21/10/2017	18971	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/10/2017	16384	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/10/2017	16384	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	no indicators, side lights and stoplights. no indicator, side lights and stoplights			03/10/2017	15476	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/09/2017	14310	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/09/2017	14310	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	DrCabElect\SCALES	Calibrate Scales			19/09/2017	13015	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/09/2017	12301	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/09/2017	12301	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Insp\INT INSP	fit srt stickers to bolster pegs			14/09/2017	11679	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\FIFTH WHEE	hook up T29S			13/09/2017	11363	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\BOLSTER	fit 3rd bolster stops			12/09/2017	11362	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Insp\RWC COMP	fit new LV signs			12/09/2017	11362	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Insp\RWC COMP	fit I.D. plate			06/09/2017	10673	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\WORK LIGHT	rear reverse light not always coming on			05/09/2017	10672	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER

T29S	Myrtleford - Workshop	Brakes\EBS Kit	move slack adjuster and B/booster push rod to bottom hole and check adjuster angle			05/09/2017	10672	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/09/2017	10672	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/09/2017	10672	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\INDICATORS	trailer indicators don't work			30/08/2017	8349	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\WINCH/STRP	middle strap locking jaw wont open fully			29/08/2017	7595	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			22/08/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/08/2017	5279	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/08/2017	5279	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/08/2017	1084	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/08/2017	1084	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\EBS Kit	Program EBS			05/08/2017		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\EBS Kit	Check & Engineer trailer			05/08/2017		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
					repaired checker plate											
T29S	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	repair LH 2nd bolster indicator wiring	05/08/2017		PreventativeMaint	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/08/2017		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
					fit new hubbo											
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit new rego label	05/08/2017		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\EBS Kit	Fit EBS to rear axle Fit 3 x new axles hub to hub			28/07/2017		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\AXLES	Replace axle saddles L3328			14/07/2017		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\WHEEL ALGN	Wheel align all 3 axles			14/07/2017		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/06/2017	186561	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/06/2017	186561	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\MUDGUARDS	LH middle mudguard			20/06/2017	183300	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/06/2017	182103	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/06/2017	182103	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres	Job Added From Invoice			02/06/2017	176017	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			02/06/2017	176017	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			02/06/2017	176017	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/06/2017	176453	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/06/2017	176453	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/05/2017	172805	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/05/2017	172805	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\PANELS	checker plate at back needs tightening			19/05/2017	171603	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\AIR LEAK	replace SR3 valve on trailer 295			11/05/2017	16832	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\AIR LEAK	air leak RH side getting worse			10/05/2017	167739	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BOOSTER	R/Hand front brake flow to release			10/05/2017	167739	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BOOSTER	replace brake booster			10/05/2017	167739	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/05/2017	16832	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/05/2017	16832	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\AIR LEAK	air leak coming from RH side, loses air while loading			05/05/2017	166098	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres	Job Added From Invoice			27/04/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	DrCabElect\SCALES	at the time of loading back end trailer scale doesn't work weight stays the same			25/04/2017	162783	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	DrCabElect\SCALES	Check Scales			25/04/2017	162783	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/04/2017	162783	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/04/2017	162783	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\AIR LEAK	Check brakes - slow to release		Complete	21/04/2017	162348	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\AIR LEAK	losing air while parked			14/04/2017		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			14/04/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\FIFTH WHEE	unhook trailer			08/04/2017		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			07/04/2017	158756	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/04/2017	158515	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/04/2017	158515	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	check lights and repair			30/03/2017	15712	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BOOSTER	replace R/hand front bake booster			30/03/2017	157529	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\ALT	fit three new brake hose			30/03/2017	157529	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\AIR LEAK	check for air leaks			30/03/2017	157529	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SPRNG HANG	Repair LHF spring hanger cracks			18/03/2017	157529	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\AXLES	Repair rear axle saddle cracks			18/03/2017	157529	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace RHF spring eye bush			18/03/2017	157529	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/03/2017		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/03/2017		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			10/03/2017	151722	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			08/03/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\STCH GUARD	canvas center needs fixing			04/03/2017		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\HOUSEKEEP	check over trailer			04/03/2017		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	DrivLine\WHEEL BRGS	check and adjust wheel bearings as required			04/03/2017		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\MUDGUARDS	repair LHF mudguards outrigger			03/03/2017	150734	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/03/2017	149867	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/03/2017	149867	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			14/02/2017	144365	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/02/2017	144365	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\HOUSEKEEP	replace LH & RH middle spring eye bushes			11/02/2017	144074	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\PANELS	repair chassis cover			11/02/2017	144074	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	Rewire last bolster lights		check and R&R LH reverse light	02/02/2017	144074	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels & adjust all bearings			02/02/2017	144074	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			01/02/2017	139825	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice			01/02/2017	139825	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/02/2017	142039	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/02/2017	142039	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/01/2017	137663	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/01/2017	137663	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BOOSTER	fit new brake booster to RHM axle			13/12/2016		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			28/11/2016	125157	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			28/11/2016	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice			26/11/2016	127046	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/11/2016	129620	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/11/2016	129620	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	inside LH light falling off replace u/s winch strap			28/10/2016		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\WINCH/STRP	fit new winch return spring to 2ns & 3rd bolsters			26/10/2016	88463	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/10/2016	120437	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/10/2016	120437	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\AIR LEAK	Replace LHR brake booster hose & clamps		Complete	05/10/2016	115870	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\AIR LEAK	Repair air leak at front of trailer - under mat		Complete	05/10/2016	115870	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair trailer lights		trailer light problem in truck (952)	04/10/2016	115870	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair rear checker plate		Complete	04/10/2016		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice Repair short in trailer lights			24/09/2016	111491	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	3rd bolster unplugged			20/09/2016	112992	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/09/2016	1109811	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/09/2016	1109811	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/08/2016		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/08/2016		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	RHS right light tail is cutting in and out			23/08/2016	100979	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/07/2016	91979	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/07/2016	91979	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Insp\RWC COMP	mount trailer rego tag			14/07/2016	87882	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\PANELS	tigthen rear checker plate bolts			14/07/2016	87882	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\AIR LEAK	replace brake hose on rear axle			09/07/2016	86177	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\STCH GUARD	repair cover mat bracket			09/07/2016	86177	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/06/2016	83137	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/06/2016	83137	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SPRNG PACK	Replace LHF spring pack & wraper		Complete	16/06/2016		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\MUDGUARDS	Replace LHF & LHM mudguards		Complete	27/05/2016	75800	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/05/2016	74463	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/05/2016	74463	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\FIFTH WHEE	Repair skid plate cracks			18/05/2016	73297	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\WHL HUB	Check wheel bearing adjustment			18/05/2016	73297	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BRK ROTOR	Replace LHR disc rotor			18/05/2016	73297	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	Complete	16/05/2016	72337	PreventativeMaint	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\AIR BAG	repair airbags RHS			10/05/2016		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\AIR BAG	replace RHM airbag mount bolts			10/05/2016		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER

T29S	Myrtleford - Workshop	Chassis\WINCH/STRP	repair 1st winch on RHS -winding to tight		Rinlatech Engineering	03/05/2016	69160	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SPRNG HANG	repair rhr spring hanger eye bolt boss cracks. Remove wheels for repairs		Complete	27/04/2016	68256	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\HOUSEKEEP	Remove & refit guard and wheels for repairs		Complete	27/04/2016	68256	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/04/2016	68525	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/04/2016	68525	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Body\DAMAGE	repair rollover damage repairs to chasses m/gaurds replace king pin carry out w/aligh			15/04/2016		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	31/12/2015	67376	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	31/12/2015	67376	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Chassis\HOUSEKEEP	tighten bolts in checker plate cover on rear. tighten bolts in checker plave cover on real disc rotor + brake parts		completed	19/12/2015	64002	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BRK RELINE	tctc		completed	18/12/2015		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BRK RELINE	crack test + reline rear axle		completed	12/12/2015	64002	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes\BOOSTER	replace rhr brake booster		completed	12/12/2015	63385	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	11/12/2015	62774	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	11/12/2015	62774	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	rhr outer indicator not working			04/12/2015		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	repair rh bolster indicator		completed	28/11/2015	59605	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	27/11/2015	57734	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	27/11/2015	57734	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	14/11/2015	53445	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist 2 hyd fittings	VehService\DS	completed	14/11/2015	53445	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Hydraulics\HOSES	rinl		completed	06/11/2015		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	29/10/2015	48408	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	29/10/2015	48408	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\ELECT P&W	Repair wiring in male plug to B trailer		completed	21/10/2015	44210	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\TRL LIGHTS	repair wiring in trailer plug		completed	20/10/2015	44162	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Elect\ELECT P&W	repair side lights front bolster replace rhf spring wrap replace lhr shocker bush		completed	16/10/2015	44162	Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SHOCK ABS	replace rhm disc rotor		completed	16/10/2015	63385	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	15/10/2015	43192	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	15/10/2015	43192	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/09/2015		Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/09/2015		Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			24/09/2015	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	16/09/2015	33398	Service	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	16/09/2015	33398	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Myrtleford - Workshop	Susp\SHOCK ABS	Service Job Added From Invoice			16/09/2015	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Myrtleford Workshop	TRAILER
T29S	Wodonga - Workshop	Elect	check lh indicator +replace faulty wire			28/08/2015		Fault	Completed	Greenfreight Logging NSW	Kennedy	Albury	ATK	50729S	Wodonga Workshop	TRAILER