EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	Inspect and repair binders as required		Removed strap from binder. Unbolted and removed reel, installed new reel and refit strap. Travel to yard and remove all bolsters pins will need to take forklift to remove to be sent to JD's for crack testing Drive forklift around to Greenfreight yard. Take workshop ute and trailer to Greenfreight yard with tools required. move truck to underneath trailers and move trailers to be able to access bolsters. Undo all nuts and bolts, connect each pin up to forklift and lift out. Put all bolster pins into trailer and deliver to JD's Metal fab for repair. Move trailers back in line, disconnect truck and move back to correct trailers.	28/11/2025	515150	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Body\BOLSTER	Body\BOLSTER		Completed for T277 & T278. Total of 12 bolster pins THE DOG ON THE FIRST BOLSTER NEED SHORTER DOG TO REDUCE MOVEMENT IN BOLSTER Measure length of dog. Attempt to source new part, all out of stock. Brought trailer to yard and manufactured angle bracket. Prepped area & set welder to specification. Welded bracket in place & painted. Found 2nd bolster to be loose, support bracket was bent. Re bent back in shape & test. All ok	06/11/2024	515150	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Chassis\BOLSTER	Chassis\BOLSTER		Checked terminals and found to be dirty and not contacting. Spread and cleaned terminals. Also checked B trailer and found to have loose earth wire in terminal. Refit wire and tested, all lights okay. Tightened loos spot light as required.	30/09/2024	511159	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	Elect\ELECT P&W			19/09/2024	511159	Repair	Unlocked	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	VehService\DS	VehService\DS DrivLine\WHEEL BRGS REPLACE ALL BEARING NUTS & GASKETS Jacked axle and supported. Removed hub and locking nuts. Greased front bearing and re fit locking nuts by sequence.	VehService\DS		13/09/2024	511159	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	DrivLine\WHEEL BRGS	Refit hub cover Chassis\BOLSTER MISSING BOLT IN BOLSTER Removed a bolster bolt to measure up size. Re-fit bolt and			10/09/2024	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Chassis\BOLSTER	tension to spec. Fit new bolt in place and tension to spec. Body\BOLSTER 2ND BOLSTER LH INDICATOR N/W RH WORK LIGHT ON HEADBOARD N/W On inspection found 2nd bolster indicator on L/H side n/w. Checked wiring & found corrosion in wires to the bolster.			10/09/2024	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Body\BOLSTER	Repaired & rejoined Brakes\BRAKE ADJ - S-Cam CHECK BRAKES - SCAM GONE INTO DRUM MIDDLE AXLE On inspection found s-cam had gone into the drum on the middle axle. Jacked & supported axle. Removed the wheels & drum. Removed hub & s-cam. S-cam was unserviceable. Cleaned up s-cam tube and fit with new s-cam. Refit hub with new nut. Reinstalled brakes, adjusted wheel bearings. Shimmed slack adjuster & fit. Tension wheel nuts and carried out brake adjustment.			10/09/2024	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Brakes\BRAKE ADJ				10/09/2024	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Chassis\SCALES	still having issues with scales Ride height valve needs moving to center axel			04/09/2024	502892	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		29/08/2024	502890	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Chassis\BOLSTER	Check & Tighten All Bolster Bolts. (Barry Maney P/O: L088458)		Loose bolt, replace and tighten. Tightened loose bolster bolts. Found RH front bolster bolt could not be tightened. Removed bolt and installed new, tightened to spec.	28/08/2024	502890	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Chassis\BOLSTER	Missing Bolster Bolt. (Barry Maney P/O: L088287)		MISSING BOLT IN BOLSTER Removed a bolster bolt to measure up size. Re-fit bolt and tension to spec. Fit new bolt in place and tension to spec. 2ND BOLSTER LH INDICATOR N/W RH WORK LIGHT ON HEADBOARD N/W On inspection found 2nd bolster indicator on L/H side n/w.	18/08/2024	491668	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Elect\INDICATORS	Multiple Lights N/W (Barry Maney P/O: L088287)		Checked wiring & found corrosion in wires to the bolster. Repaired & rejoined. CHECK BRAKES - SCAM GONE INTO DRUM MIDDLE AXLE On inspection found s-cam had gone into the drum on the middle axle. Jacked & supported axle. Removed the wheels & drum. Removed hub & s-cam. S-cam was unserviceable. Cleaned up s-cam tube and fit with new s-cam. Refit hub with new nut. Reinstalled brakes, adjusted wheel bearings. Shimmed	18/08/2024	491668	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Brakes\BRK RELINE	Check Brakes (Barry Maney P/O: T088287)		slack adjuster & fit. Tension wheel nuts and carried out brake adjustment. REPLACE ALL BEARING NUTS & GASKETS Jacked axle and supported. Removed hub and locking nuts.	18/08/2024	491668	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	DrivLine\WHEEL BRGS	Replace All Wheel Bearing's (Barry Maney P/O: L088287)		Greased front bearing and re fit locking nuts by sequence. Refit hub cover.	18/08/2024	491668	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		13/08/2024	491668	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	CHECK FAULT TRAILER LIGHTS TRIPPING Susp\AIR LEAK AIR LEAK IN A OR BE NOT SURE. Found air leak under deck plate, was split from cable tie, driver was in a rush so put 1/2' barb joiner in and clamped			11/08/2024	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	JF MECHANICALS - 3	TRAILER
T277	Myrtleford - Workshop	Susp\AIR LEAK	with hose clamps. Tested for leaks, all okay.			31/07/2024	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	PACCAR PARTS FLEET SERVICES - 3	TRAILER
T277	Myrtleford - Workshop	VehService\DS	VehService\DS	VehService\DS		24/07/2024	465012	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	VehService\DS	VehService\DS CHECK AND REPACK ALL BEARINGS Lift axles, removed wheels and hubs. Removed bearings, cleaned bearings and stub axles. Repack bearings with new grease, fit new seals and refit to hubs. Refit wheels and tensioned axle nuts to spec. Repeat process for all axles. Replaced bearings for RH middle axle as the bearing outer race was turning in the hub. Could not source new hub. Applied loctite to outer race for repair. Will need replacing when brakes are low. KWTRPTSH1RTAUS-10 CLEANING RAGS - COLOR T SHIRT 10 KG BAG 1 26.47KWT04-8681 WASHER-AXLE TAB LOCK YORK AXLE 6 16.26KWT04-4098 NUT-OUTER YORK 6 68.34KWSET4137T1M CONTAINS HM212049 & HM212011 1 54.98KWSET4147T1M CONTAINS HM218248 & HM218210 1 82.50NG013336511 LOCTITE RETAINING680 1 79.13NGIT12413 NUT 1 38.82NGIT2414 WASHER 1 6.11NGIT12415 NUT 1 24.50NGIT7970044 TAB LOCKWASHER 1 2.36KWT04-4042 GASKET-SUIT S&6 HOLE HUB CAP 6 14.22KWT04-STM-0743G SEAL-GREASE TRAILER 6 99.78POL	VehService\DS		11/07/2024	465012	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Body\WHEEL BRGS	GREASE-CASTROL SPHEEROL			11/07/2024	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	PACCAR PARTS FLEET SERVICES - 3	TRAILER
T277	Myrtleford - Workshop	Tyres\CLEANSKIN	Tyres\CLEANSKIN 5-12			04/07/2024	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BEAUREPAIRES - 3	TRAILER
T277	Myrtleford - Workshop	Tyres\TP5+6	Tyres\TP5+6+9+10+11+12			27/06/2024	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BEAUREPAIRES - 3	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service PO# L048366 NO POWER TO CONTROL BOX FOR SCALES - Removed fuses & checked for power, 12.1 volts. Removed control box and found power to switch had started to fall off. Placed back on, still no power to scales unit. Removed dash, found it was switched to NF mode. Switched power to on, all okay. Refitted dash. LABOUR $270 INDICATOR STALK FAILED - remove and replace stalk - run wiring and connect. Resolder x1 wire	VehService\DS		20/06/2024	460755	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Body\HOUSEKEEP	back into loom, all okay. D Service As Per Attached Checklist			20/05/2024	438268	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	PACCAR PARTS FLEET SERVICES - 3	TRAILER
T277	Myrtleford - Workshop	VehService\DS	PO# L085258	VehService\DS		08/05/2024	465012	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/05/2024	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			06/04/2024	438268	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			29/03/2024	438268	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Elect\TAIL LIGHT	NO TAIL LIGHT. ALL STOP LIGHTS, No PLATE LIGHT WORKING.		BRAKE LIGHTS N/W - Removed plug, trace wiring & found broken wires. Run new section of wire & joined. Reinstalled plug.	28/03/2024	438268	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Body\MUDGUARDS	RH REAR GUARD LOOSE - Removed rear lights from light bar, cut off top cover plate bolts. Cut off guard bolts that were damaged. Fit new bolts in guard, fitted cover with new bolts and tighten. Refit lights, checked, all okay. AFTER HRS BREAK DOWN - PARKER LIGHTS ON REAR OF TRAILER N/W			28/03/2024	438268	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	inspected tail light wiring and found broken wire for parker lights, repaired wire for parker lights. Tidy up and retested. All okay.			27/03/2024	438268	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			22/03/2024	438268	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	VehService\DS	PO# L084898	VehService\DS		22/03/2024	438268	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Tyres\Punct	8			15/03/2024	438268	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	LH & RHM GUARDS NEED REPLACING - Unbolt and removed damaged mud guards. Measure and drilled holes in new guards. Mounted guards, tensioned bolts.			09/03/2024	429287	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Brakes\BRAKE ADJ	CHECK BRAKES - Jacked up middle axle. Removed wheels and brake drums. Remove brake shoes. Hit out anchor pins, found to be tight on LH side. Straightened out backing plate. Assemble new brakes and installed. Fit new drums, refit wheels. Tensioned wheel nuts and adjust brakes.			09/03/2024	429287	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Susp\SHOCK ABS	RHM SHOCKER LEAKING R&R - Undo and removed shocker bolts. Hit and pry out leaking shocker. Compress new shocker and installed with new bolts, tensioned.			09/03/2024	429287	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			08/03/2024	429287	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	VehService\DS	PO# L084539	VehService\DS		08/03/2024	429287	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Body	TIGHTEN OR REPLACE DECK PLATE BOLTS - Removed all loose deck plate bolts. Replaced nut & bolts, tighten.			23/02/2024	399140	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Steering\WHEEL BRGS	CHECK WHEEL BEARINGS - Jack up axle and check wheel bearings. Adjust front right & front left. Did not have enough new lock washers in stock to adjust all wheels bearings. Will adjust next service when parts are in.			23/02/2024	399140	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Brakes\BRK RELINE	RH FRONT BRAKE - Found brake low during service, jack up and remove wheels. remove drum & brake linings. Fit new & adjust, all okay.			23/02/2024	399140	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER

T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				23/02/2024	419933	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	VehService\DS	PO# L084212	VehService\DS			23/02/2024	419933	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Tyres\TP02	Tyre Position 2				10/02/2024		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Chassis	TIGHTEN/ REPLACE BOLT PLATE ON BACK OF TRAILER.				09/02/2024		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				09/02/2024	408952	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	VehService\DS	PO# L083886 AIR BAG BROKEN BASE PLATE HANGING OFF - Jacked RH front chassis and supported. Removed deck plate. Dumped air, disconnect air lines and removed air bag. Change over plate & fittings to new air bag. Installed new air bag and connect air lines. Remove safety stands & lowered axle. Adjust ride	VehService\DS			09/02/2024	408952	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Albury - Workshop	Susp\AIR BAG	height, refit deck plate, all okay.				03/02/2024	405446	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				25/01/2024	399140	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	VehService\DS	PO# L083541	VehService\DS			25/01/2024	399140	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Chassis\SCALES	Scales A/HRS BREAKDOWN TRAILER PULLED SUZI WIRING OUT - Meet driver at BMG workshop & inspect fault. Found male trailer plug had come apart & had no B trailer lghts. Arranged new part. Removed plug, disconnect wiring. Found snapped wires, tidy up & rejoined. Strip back wires & joined into new trailer plug. Tested lights, all okay. Mounted plug & checked no				23/01/2024	397381	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Elect\SUZI COIL	further damage.				17/01/2024	391800	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				13/01/2024	391011	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	VehService\DS	PO# L083308	VehService\DS			13/01/2024	391011	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Chassis\BOLSTER	SECND BOLSTER NEEDS PINS PUT IN TO STOP IT FROM FALLING BACKWARDS.				12/01/2024	465012	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Brakes\AIR LEAK	REPLACE AIR LINE WITH JOIN IN IT. LET GO. COST 4 TYRES.		REPLACE AIR LINE W JOINER - Locate air line with joiner in it, remove length of hose from under deck plate. Got new hose and cut to length connect in and secure hose with other lines and protect.		12/01/2024	465012	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Brakes	LH MIDDLE S-CAM FALLEN INTO DRUM - jacked middle axle, removed wheels & brake drum. Remove brake shoes and pushed s-cam back into position. Refit slack adjuster, shimmed to spec. Checked slack adjuster, all okay. Refit brake components, refit wheels and tensioned wheel nuts, lowered axle.				12/01/2024	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				12/01/2024		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12				12/01/2024		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				08/12/2023	379797	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	VehService\DS	PO# L082828	VehService\DS			08/12/2023	379797	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Susp\AIR BAG	NEW AIRBAG LEAKING RIGHT SIDE BACK (REPLACE)		FRONT AXLE AIR BAGS WON'T PUMP UP - Inspected the airbags, all bags had air supply. Front axle was sitting lower than the rest of the axles. Dumped air from airbags & then pumped back up, ride height valve working correctly. Inspected all air supply lines, all okay. Tested pressure protection valve & found the valve for air tank had failed. Repalced pressure protection valve, adjust ride heights Found drain valves had broken cords, repalced. Check over all ride heights and now sitting correctly.		08/12/2023	378281	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	A AND B TRAILERS SPRAY ALL AIRBAGS AND FITTINGS SOAP WATER. CHECK FOR AIR LEAKS PLEASE.				08/12/2023	378281	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Susp\HCV	ADJUST RIDE HEIGHT. NO CLEARANCE ON MUDGUARDS.		Inspect ride height, found to be out of adjustment. Moved adjuster along ride height rod until height was correct. Check clearance between wheel & guards all okay. Truck returned, adjusted ride height a second time to a higher level. Sitting better now. Found air fitting to be leaking. Replaced the fitting & tested for leaks. all okay. Did not replace as was replaced prev month & could not fault. Advise if symtons persist.		07/12/2023	367853	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Susp\HCV	NEW RIDE HEIGHT VALVE TO BE PUT ON A TRAILER.				07/12/2023	367853	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Brakes\BOOSTER	BOOSTER FITTING LEAKING FRONT PASSENGER SIDE.		Jacked up middle axle, removed wheels & brake drums. Found shoes worn unevenly, foundation plate is bent & holes for anchor pins are worn out. Installed new brake shoes. Recommend axle replacement soon. Refit drums & wheels. Tensioned wheel nuts to spec & adjust brake.		07/12/2023	367853	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Susp\HCV	ADJUST RIDE HEIGHT. NEED TO GET HAND UNDER FRONT GUARD.				07/12/2023	367853	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				23/11/2023	367853	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	VehService\DS	oter number is L082423	VehService\DS			23/11/2023	367853	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Tyres\TP3+4	replace tyres				22/11/2023	366546	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop		TRAILER
T277	Myrtleford - Workshop	Tyres\TP7+8	reolace tyres R&R BOOSTER - RH middle booster was leaking. Removed old booster, cut rod to length & refit.				21/11/2023	366174	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BEAUREPAIRES - 3		TRAILER
T277	Myrtleford - Workshop	Brakes\BOOSTER	Tension bolts & hose clamps, adjust brake.				12/11/2023	359749	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	ANNUAL INSPECTION - Carried out annual inspection as per checklist.		12/11/2023	359749	PreventativeMai	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	TARE WEIGHTS KEEP MOVING. CANNOT LOAD ACCURATELY ON A AND B TRAILERS.				12/11/2023	359749	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				12/11/2023	359749	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	VehService\DS	PO# L082217	VehService\DS			12/11/2023	359749	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Tyres\Re-Tor	1-10				03/11/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				02/11/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2				02/11/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6				02/11/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2				02/11/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6				02/11/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				02/11/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				26/10/2023	348146	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	VehService\DS	po# L081863	VehService\DS			26/10/2023	348146	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Susp\HCV	PLEASE PUT A NEW RIDE HEIGHT VALVE ON A TRAILER.		REPLACE RIDE HEIGHT VALVE - Removed faulty ride height valve, change over fittings to new. Installed new valve, adjusted ride height to spec, all okay.		26/10/2023	348146	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Susp\AIR BAG	BLOWN AIR BAG LH MIDDLE - Unbolt and removed air bag and fittings. Found fittings were damged Installed new air bag and fittings. Tensioned all mountings & replaced bolts for spring. Tested, all okay				21/10/2023	345108	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				29/09/2023	337092	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L081365	VehService\DS			29/09/2023	337092	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Susp\SHOCK ABS	REPALCE BROKEN SHOCKER - Remove and reolace broken shocker.				22/09/2023	332983	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes\BOOSTER	RH MIDDLE BOOSTER HANGING - Found the booster and push rod had separated. Mount threads also pulled out of booster. Removed hoses and push rod from slack adjuster. Measured rod length of booster on the same axle & cut new booster rod to size. Changed over fittings & fit new booster. Also found RH front slack adjuster had come off s-cam. Replaced slack adjuster & shimmed to spec.				22/09/2023	332983	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Susp\AIR BAG	AFTER HRS BREAKDOWN - NO AIR IN A TRAILER Travelled to trailer broken down at Tantanoola. Inspect trailer, no air in bags. Found axle ride height control arm was hanging down on axle. Refit arm and adjust ride height. Air bags refilled, all okay. S-CAMS FALLEN INTO DRUMS - Jacked front axle, removed wheels. Removed drums & shoes. Removed backing plates & wheel tubes. Checked RH side s-cams & welded damaged tube & cleaned. Refit wheels, adjusted hub nut to spec & tensioned. Lowered axle, adjust brakes, greased all points. PARTS $174.87 LABOUR $750.00 Remove L/H side hub. Removed LH side s cams & replaced with new. Repaired LH slack adjuster & shimmed. Refit brakes on both sides. Refit RH wheels, tensioned. Refit LH hub, replaced hub nut kit TOTAL $				19/09/2023	328981	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes					16/09/2023	328936	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				15/09/2023	328936	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L081065	VehService\DS			15/09/2023	328936	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Tyres\FITMENT	3 REPAIR LOCKING PIN				12/09/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Body	Pin was missing from pivot pont for fold up trailer. Sourced new bolt. Cut and grind to fit into trailer lock install split pin to secure. REPLACE LOW BRAKES Found LH front and both rear axle brakes were past wear limit. Jacked up LH front axle, removed wheels, brake drums & shoes. Installed new shoes & drums. Refit wheels, adjust brakes, tensioned.				07/09/2023	322767	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes\BRK O/HAUL	Repeat process for both rear brakes.				30/08/2023	317966	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				29/08/2023	317466	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L080589	VehService\DS			29/08/2023	317466	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				18/08/2023	311825	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	CONNECT A & B TRAILER WORK LIGHT SO ON SWITCH NOT ONLY IN REVERSE. (ON CHRISTMAS WISH LIST) D Service As Per Attached Checklist				18/08/2023	311825	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L080272	VehService\DS			18/08/2023	311825	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Elect\INDICATORS	REPLACE OUTER INDICATOR RHS		Found RH rear indicator was missing. Tidy up wires, installed new light and joined wiring. Test, okay		16/08/2023	309674	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				01/08/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L079977 REPLACE BOOSTER Found RH Front booster failed. Removed booster, cut off mounting studs from chassis.	VehService\DS			01/08/2023		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes\BOOSTER	Air hammered out, cut down and fit new booster. Replaced hose clamps, built up air, adjust brake.				26/07/2023	293690	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/07/2023	289543	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Elect\TAIL LIGHT	OUTER L/H TAIL LIGHT NEEDS NEW RUBBER. (READY TO FALL OUT)				20/07/2023	289543	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Elect\WORK LIGHT	WORK LIGHTS NOT WORKING. D Service As Per Attached Checklist				20/07/2023	289543	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L079647	VehService\DS			20/07/2023	289543	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Tyres\TP11	Tyre Position 11				08/07/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				04/07/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L079358	VehService\DS			04/07/2023		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Susp\AIR LEAK	Repair Air Leaks				28/06/2023	271356	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/06/2023	266536	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	CONNECT A & B TRAILER WORK LIGHT SO ON SWITCH NOT ONLY IN REVERSE. (ON CHRISTMAS WISH LIST) D Service As Per Attached Checklist				20/06/2023	266536	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L079051	VehService\DS			20/06/2023	266536	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist				08/06/2023	258777	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	VehService\DS	PO# L078824	VehService\DS			08/06/2023	258777	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3		TRAILER
T277	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				02/06/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop		TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/05/2023	248456	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	CONNECT A & B TRAILER WORK LIGHT SO ON SWITCH NOT ONLY IN REVERSE. (ON CHRISTMAS WISH LIST)				25/05/2023	248456	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop		TRAILER

			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L078527	VehService\DS			25/05/2023	248456	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				18/05/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\EBS FAULTS	Trailer EBS module faults				17/05/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/05/2023	239422	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Elect\WORK LIGHT	REPAIR R/H WORKLIGHT.				05/05/2023	239422	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	CONNECT A & B TRAILER WORK LIGHT SO ON SWITCH NOT ONLY IN REVERSE. (ON CHRISTMAS WISH LIST)				05/05/2023	239422	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	PO# L078126	VehService\DS			05/05/2023	239422	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
			Crack Testing															
T277	Myrtleford - Workshop	Chassis\BOLSTER	Remove all bolster pins & carry out testing. All ok, none cracked.				25/04/2023	235161	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/04/2023	230161	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\WORK LIGHT	REPAIR R/H WORKLIGHT.				14/04/2023	230161	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	CONNECT A & B TRAILER WORK LIGHT SO ON SWITCH NOT ONLY IN REVERSE. (ON CHRISTMAS WISH LIST)				14/04/2023	230161	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L077749	VehService\DS			14/04/2023	230161	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/03/2023	220354	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Wodonga - Workshop	VehService\DS	Barry Maney PO# L077480	VehService\DS			28/03/2023	220354	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			Missing Shocker Bolt															
			Inspect broken bolt behind air tank. Removed wheels to access. Pry out bolt, shock extended, fit zip ties to prevent extending anymore. Push in new bolt, secured															
T277	Myrtleford - Workshop	Susp\SHOCK ABS	with new nut & washer. Refit wheels, tensioned and removed cable ties				18/03/2023	213511	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6				18/03/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\FITMENT	9&10				17/03/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Albury Workshop	TRAILER
T277	Mvrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/03/2023	208741	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	PO# L077100	VehService\DS			11/03/2023	208741	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Tyres\TP1+2	Tyre Position 1 + 2				25/02/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/02/2023	200772	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Chassis\FIFTH WHEE	LONGER UMBILICAL BETWEEN A AND B TRAILERS.				24/02/2023	200772	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	PO# L076823	VehService\DS			24/02/2023	200772	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	ORDERED AND PICKED UP PARTS FROM BARRY MANEY. REPLACED LIGHTS PLUG.				08/02/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Mvrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/02/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	PO# L076415	VehService\DS			02/02/2023		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12				31/01/2023		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/01/2023	182977	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/01/2023	182977	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Mvrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/12/2022	169490	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L075706	VehService\DS			14/12/2022	169490	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	ALL WIRES NEED TO BE REWIRED- NEW JUNCTION BOX.				08/12/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	LOAD LIGHTS NOT WORKING.				08/12/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	BETWEEN A & B TRAILERS. PLUGS/ CONNECTORS FOR SCALES AND ELECTRICS NEED TO BE REDONE SO NO WIRES ARE EXPOSED AND CONNECTORS (PLUGS) ARE				08/12/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				02/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10				02/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP12	puncture repair				02/12/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Alburv Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/12/2022	162800	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRK RELINE	RELINE RM.		HAS 50% LININGS.		01/12/2022	162800	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	TAKE PRESSURE OFF WIRES GOING INTO PLUGS ON BOTH A AND B TRAILERS.				01/12/2022	162800	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	NO. PLATE LIGHT NOT WORKING.				01/12/2022	162800	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L075462	VehService\DS			01/12/2022	162800	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Mvrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	ELEC CABLE BETWEEN A&B TIDY UP.				25/11/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
			Repair lights															
			Check, found broken wire to RH brake light.															
			Inspect junction box, also broken chassis earth.															
T277	Myrtleford - Workshop	Elect\TAIL LIGHT	Repaired wiring. Checked all ok. Worklights n/w, suspect issue with junction boxes. Check at next service				22/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
T277	Mvrtleford - Workshop	Brakes\BRK RELINE	RELINE RM.				19/11/2022	153420	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/11/2022	153420	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L075208	VehService\DS			19/11/2022	153420	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			After hours - blown airbag															
T277	Myrtleford - Workshop	Susp\AIR BAG	Remove &replace airbag. Straighten base plate				11/11/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/11/2022	144202	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	LHS FRONT MUDFLAP NEEDS REPLACING.				05/11/2022	144202	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\INDICATORS	Right hand blinker outside keeps falling off.				05/11/2022	144202	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L074947	VehService\DS			05/11/2022	144202	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			05/11/2022	144202	PreventativeMai	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			ELEC CABLE BETWEEN A + B TRAILER NEEDS ATTENTION.															
			Replace7 Pin Plug.															
			Travel to yard, remove and replace damaged plug.															
			Checked Lights all OK.															
			Trailer returned lights not working. Disconnect plug.															
			Found pins pushed in, alter pins and refit plug, all OK.															
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	Barry Maney PO# L074766. ELEC CABLE BETWEEN A + B TRAILER NEEDS ATTENTION.				25/10/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/10/2022	131630	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L074644	VehService\DS			19/10/2022	131630	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/10/2022	123102	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\WHEEL ALGN	WHEEL ALIGNMANT. CRABBING.				07/10/2022	123102	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	LEAD BETWEEN A & B TRAILER NEEDS TO BE REDONE. HAS FALLEN APART ALREADY.				07/10/2022	123102	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
					no rear trailer lights													
					Trace wiring, corroded & broken wires at junction.													
					Repaired wires, rejoined. Tested tail light n/w													
T277	Myrtleford - Workshop	Elect\TAIL LIGHT	LHS TAIL LIGHT NOT WORKING.		R&R tail ligh, all good		07/10/2022	123102	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L074479	VehService\DS			07/10/2022	123102	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP11+12	supply and fit 2tyres				28/09/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/09/2022	113442	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\WHEEL ALGN	WHEEL ALIGNMANT. CRABBING.				22/09/2022	113442	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	LEAD BETWEEN A & B TRAILER NEEDS TO BE REDONE. HAS FALLEN APART ALREADY.				22/09/2022	113442	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L074215	VehService\DS			22/09/2022	113442	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Alburv - Workshop	Elect\CLAIMS	Trailer olue keeps falline out. eo to GF vard to reoair. went to reolace & all bolts seized. cut off and reolaced. checked all liahts ok				13/09/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Alburv Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				13/09/2022	104474	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L073997	VehService\DS			13/09/2022	104474	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\Re-Tor	Re-Torque				10/09/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\AIR LEAK	Repair air leak, repair hose, cut off end & refitted cable tie up				03/09/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	LH indicator on with brake light. trace fault to shorted wire. repaired & cable tie up				03/09/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Mvrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/08/2022	91514	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\WHEEL ALGN	WHEEL ALIGNMANT. CRABBING.				30/08/2022	91514	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L073748	VehService\DS			30/08/2022	91514	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes\BOOSTER	Hole in booster hose middle axle, cut ties & fitted joiner & 2 airlines, covered in rubber.				26/08/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Wodonga - Workshop	DrCabElect\RADIO	Checked UHF speaker not working removed dash panel & was unplugged - refited				26/08/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 4 tyres				26/08/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP7+8	Tyre Position 7 + 8				26/08/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				17/08/2022	81107	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Wodonga - Workshop	VehService\DS	Barry Maney PO# L073505	VehService\DS			17/08/2022	81107	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Body\AIR LEAK	REPAIRED AIR LEAK.				10/08/2022	465012	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	REPLACE ELECTRICAL PLUG FROM A TRAILER TO B TRAILER.				10/08/2022	465012	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	REPLACE TRAILER PLUG FROM A TRAILER TO B TRAILER.				10/08/2022	465012	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\AIR LEAK	Air leak		found rubbed section of hose. Cut and rejoined with brass joiner. Fitted Silicone wrap around hoses to protect		04/08/2022	73331	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	Supply new mudflap - fitted by driver				04/08/2022	73331	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 2tyres				02/08/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				28/07/2022	71311	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Susp\WHEEL ALGN	WHEEL ALIGNMANT. CRABBING.				28/07/2022	71311	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Wodonga - Workshop	VehService\DS	Barry Maney PO# L073196	VehService\DS			28/07/2022	71311	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			Wire pulled out of trailer plug.															
			Repiar wires and fitted new 7 pin plug.															
T277	Myrtleford - Workshop	Chassis\SUZI COIL	Tested lights all OK.				16/07/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				05/07/2022	60528	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Wodonga - Workshop	VehService\DS	Barry Maney PO# L072750	VehService\DS			05/07/2022	60528	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP3+4	supply and fit 2tyres				05/07/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP5+6	supply and fit 2tyres				24/06/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Mvrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				16/06/2022	50223	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres	FLAT TYRE MIDDLE AXLE RHS OUTSIDE.				16/06/2022	50223	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	REPLACE MISSING MUDFLAP AND ANTI SAIL BRACKET.				16/06/2022	50223	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	SIDE LIGHT 2ND BOLSTER LHS NOT WORKING.				16/06/2022	50223	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L072386	VehService\DS			16/06/2022	50223	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/06/2022	42471	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist															
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L072165	VehService\DS			01/06/2022	42471	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\AIR LEAK	wash trailer and fit brake valve				23/05/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/05/2022	32032	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier STK	43648S	Wodonga Workshop	TRAILER

T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist Barry Maney PO# L071801	VehService\DS		17/05/2022	32032	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP07	fit runout			03/05/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job D Service As Per Attached Checklist			28/04/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L071484	VehService\DS		28/04/2022		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/04/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	DrivLine\WHEEL BRGS	Fit all new bearings.			12/04/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis	CHECK FOR MOVEMENT IN HINGE JOINT D Service As Per Attached Checklist			12/04/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	Barry Maney PO# L071231	VehService\DS		12/04/2022		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP3+4	supply and fit 2tyres			08/04/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	Scales not working on T278 trace fault to broken wires in T277. Repaired wiring			06/04/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			25/03/2022	2355	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\BOOSTER	BOOSTER HOSE LHS. MAXI HOSE.			25/03/2022	2355	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Susp\SHOCK ABS	FL SHOCK LOOKS NACKERED. OIL. D Service As Per Attached Checklist			25/03/2022	2355	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	PO # L070889 RELINE ALL THREE AXLES	VehService\DS		25/03/2022	2355	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\BRK RELINE	Fit S-Cams and Drums.		-Jack up and put on stands -Removed wheels and drums -Removed brake shoes -Measured all brake drums and found to be over sized -Inspected all s-cams and bushes, found to have excassive movement, all news-cams and s-cam tubes with bues ordered. -Inspected all slack adjusters, found all to have excessively worn cleves pin holse, New slack adjusters ordered -Remove all bearing cones and clean hubs -install all new wheel bearings and pack with grease -Fit the news-cam tubes with new mounting plates and weld plates on -Fit news-cams and shim as required -Fit new slack adjusters with new clevis pins -Found brake boost rod lenghts to be all different, measured and cut to correct lenghts, found LHF booster yoke and nut loose and threads damaged, new booster was installed -Fit new grease nipples to s-cam tubes then grease everything -Fit all the brake shoes on -Install hubs and wheels then adjust wheel bearings as required. -Fit new hubo to cap -Tension all wheels -Grease and adjust brakes as required	18/03/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\BRK RELINE	REQUIRES RELINES		-Check over, Repair complete	18/03/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	DrivLine\WHEEL BRGS	Fit all new bearings.		-Found 6 damaged mudguards, Removed all guards, some bolts had to be cut as the were sezed. ordered new guards and bolts, measure up guards then bolt up, check over -repair complete.	18/03/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\MUDGUARDS	Fit 6 x mudgaurds.		Replaced mudflaps as requested	18/03/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Susp\SUSPENSION	Replace all worn suspension parts.		REPLACE BROKEN.LH REAR U-BOLT AS REQUIRED, INSPECT ALL SPRING EYE BUSHES AND SRPING WRAPS AND REPAIR AS REQUIRED. -Found LHR u-bolt to be snapped and dog bone to be bent, inspected the rest of the u-bolts to find they were all miss matched and different lenghts, Removed all u-bolts and ordered new corrected u-bolts, inspected all dog bones and found 4 cracked, used 3 good ones from the B-trailer and got 1 from Wayne. -Removed air bag lower mounts and spring eye bolts to inspect spring eye bushes, Found all bushes to be excessively worn, Press out all spring eye bushes and press in new bushes. -Found FLH alignment pdowel to be snapped, Die grind wled off dowel to try to remove, dowel was seazd in hole need to use the oxy to remove, Fit new dowel once removed. -Cut out all spring eye wear plates, ordered new plates had to get aldonga to make some as we could only get 6 ordered in. -Weld new plates in -Refit springs into trailer with new spring eye bolts and nuts, -Tension u-bolts then tension spring eye bolts at ride height. -Check over, Repair complete.	18/03/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Susp\SHOCK ABS	Replace worn shocks		- Found LHM shock leaking, Removed shock then fit a new shock. - Found LHR bottom shock bolt loose and damaged, Removed bolt and fit a new bolt then tighten. - Found crackes through out the hole trailer, repained cracks as required. once crackes were repaired crackes were painted.	18/03/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\CHAS CRACK	Carry out welding repairs		Note - There were a lot of cracks to weld and find took some time complete	18/03/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	DrivLine\WHEEL ALGN	Conduct Wheel alignement on all three axles at Hume TruckTechnics.		Perform laser wheel alignment	18/03/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Carry Out D-Service	18/03/2022		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Wodonga - Workshop	Body\MUDGUARDS	R/H/R MUD FLAP MISSING		REPLACED.	17/02/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/02/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/02/2022		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes\BRK RELINE	REQUIRES RELINES			02/02/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\AIR LEAK	A trailer second booster blow hose Myrtleford mechanics replacing		repair air leak middle axle RHS booster	01/02/2022		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Albury - Workshop	Tyres\TP9+10	SUPPLY AND FIT 4 TYRES			25/01/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			25/01/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/01/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes\BRK RELINE	RELINE RR			21/01/2022		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/01/2022		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Albury - Workshop	Tyres\TP1+2	supply and fit 2tyres			04/01/2022	259615	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/12/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/12/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes\BRK RELINE	RELINE RR			23/12/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Susp\SUSPENSION	REPLACE LR U-BOLTS AND MOUNT PLATE			17/12/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes\BRK O/HAUL	RM RELINE			15/12/2021	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/12/2021	465012	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/12/2021	465012	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Unknown	T SERVICE DUE			15/12/2021	465012	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/12/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Chassis	BOLT ON A TRAILER SNAPPED GREASE POINT ABOVE TURNTABLE.		REPLACED BOLT.	08/12/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes\BRAKE ADJ	TRAILER BRAKES PROBABLY NOT ADJUSTED WHEN SERVICED.			08/12/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/12/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Susp\SUSPENSION	REPLACE LR U-BOLTS AND MOUNT PLATE			08/12/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes\BRK O/HAUL	RM RELINE			26/11/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/11/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Elect\ELECT P&W	LF CEARANCE LIGHT OUT			26/11/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/11/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/11/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/11/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/11/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/11/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Body\MUDGUARDS	MUD FLAP LHS COMING OFF			11/11/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/11/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Tyres\TP7+8	Right hand centre tyres worn. MUD FLAP LHS COMING OFF Mudflap broken off to be completed next service. D Service As Per Attached Checklist			03/11/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Body\MUDGUARDS				03/11/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	Repained/Replaced air hose at ABS module.	VehService\DS		03/11/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/10/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Susp\SPRNG HANG	LHR U Bolts snapped.		Removed LHR U-Bolts + mount from T224 to replace broken parts on LHR of T277.	27/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Tyres\TP7+8	Right hand centre tyres worn.			27/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Albury - Workshop	Tyres\TP11+12	fit 2 runouts			19/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/10/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Albury - Workshop	Tyres\TP5+6	supply and fit 4 tyres			14/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			14/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Susp\SHOCK ABS	RHM RHR SHOCKS LEAKING			12/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Body\MUDGUARDS	MUD FLAP LHS COMING OFF			12/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/10/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Susp\Torque Rod	REPLACED LH REAR SPRING EYE BUSH			02/10/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/10/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		02/10/2021		PreventativeMai	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Elect\WORK LIGHT	No work lights unless in reverse driving out of bush blind.			28/09/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/09/2021		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Chassis\AIR LEAK	Leaking air line on A trailer.			28/09/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Body	LHM S Cam previously came undone and shifted in behind hub.			28/09/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	DrivLine\WHL HUB	Replaced S Cam, S Cam tube, brakes and rebuild hub. Grease and adjust Brakes. RH LH 80 80 60 30			21/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Brakes\BRAKE ADJ	60 80		Replace S cams + brakes and Wheel bearings.	21/09/2021		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Chassis\WINCH/STRP	Front winch on A trailer broken air fitting.. Front winch on A trsiler broken air fitting.		Fix air leaks on front air winch.	16/09/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Elect\TAIL LIGHT	No Brake liahts on indicators on trailers.		Insoect trailer liaht issue. Wrone blue bluezed in.	16/09/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Wodonga - Workshop	Chassis\WINCH/STRP	Front winch strap doesn't tighten.		Refer Jobl 354131	16/09/2021		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER

					* Raised front & rear axles												
					* Removed required wheel equipment												
					* Removed brake linings												
					* Inspected s-cams & bushes/all ok												
					* Inspected wheel bearings/all ok												
					* Repacked wheel bearings												
					* Installed new brake linings & secured												
					* Installed wheel equipment												
					* Adjusted wheel bearings												
					* Replaced L/H front slack adjuster due to not working correctly												
				Reline LHF and LHR Axles	* Adjusted brake sas required												
				Done by TCTC	* Lowered down axles												
T277	Wodonga - Workshop	Brakes\BRK RELINE	CARRY OUT BRAKE RELINE ON L/H REAR & L/H FRONT AXLES - 14/9/21		* Repair complete	15/09/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
					* Undone shocker bolts as required												
				Both middle axle shocks need replacing.	* Removed/replaced middle axle shockers												
				Done by TCTC	* Tensioned shockers as required												
T277	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE MIDDLE AXLE SHOCKERS		* Repair complete	15/09/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Susp\SHOCK ABS	RHM RHR SHOCKS LEAKING			14/09/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			14/09/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED LHM SLACK ADJUSTER	14/09/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Unknown	Service due.		#353681	14/09/2021	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Brakes\L.H.M	LHM S-CAM CIRCLIP MISSING AND S-CAM HAS SHIFTED UP AGAINST BACK OF HUB. PULL APART AND INPECT. RE-SECURE S-CAM AND REASSEMBLE			03/08/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Brakes\BRAKE ADJ	Logging trailer adjusted brakes and greased, found LM axle s-cam is off from slack adjuster.			31/07/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Susp\SHOCK ABS	repair shock bolt		REMOVED WHEELS AND GUARD. PICKED UP BOLT FROM ULTIMATE FASTENERS. REPLACED SHOCK BOLT. RE-ASSEMBLED A	30/07/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
			Remove digital weight gauges from log trailers parked down in front corner of yard.														
			Fit to T277/278.														
			Parts on order require air fittings to plum 1/4 " weight gauge into 3/8" air bags.														
T277	Wodonga - Workshop	Susp\WGHT GAUGE	Completed on Job# 348037			27/07/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonea - Workshop	Susp\WGHT GAUGE	Finish Plumbine weight aauge.			27/07/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonea Workshop	TRAILER		
			Logging tuck and trailer repair light left side.														
T277	Wodonga - Workshop	Elect\TRL LIGHTS	Clearance light and blinker light.			24/07/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
					1st bolster light inspected and found wiring throgh bolster faulty.												
					Ran new wires for light and reconnected.												
					All Working.												
T277	Wodonga - Workshop	Elect\TRL LIGHTS	2 x Clearance lights not working.		Sunny replaced 2nd bolster light.	24/07/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Rosewood - Workshop	Tyres\TP3+4	replace 2 tyres			08/07/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonea Workshop	TRAILER		
T277	Rosewood - Workshop	Susp\AIR BAG	replace front right hand side airbag		replace RHF airbag and repair lower mount and re-plumb	08/07/2021	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Rosewood Workshop	TRAILER		
T277	Rosewood - Workshop	Susp\AIR BAG	replace LHF airbag			08/07/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Rosewood Workshop	TRAILER		
T277	Rosewood - Workshop	Elect\ELECT P&W	replace RHF&LHF shockers (remove wheels to do so)			08/07/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Rosewood Workshop	TRAILER		
T277	Rosewood - Workshop	Elect\ELECT P&W	trailer plug		replace damaged trailer plug and repair wiring (called in by driver)	06/07/2021	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Rosewood Workshop	TRAILER		
T277	Rosewood - Workshop	Body\HOUSEKEEP	basic check over for outtine back to work			29/06/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Rosewood Workshop	TRAILER		
T277	Albury - Workshop	Tyres\TP1+2	Supply and fit 2 tyres			23/06/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Rosewood - Workshop	Body\HOUSEKEEP	check over			17/06/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Rosewood Workshop	TRAILER		
T277	Tumut - Workshop	Body\HOUSEKEEP	check over			17/06/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Tumut Workshop	TRAILER		
T277	Tumut - Workshop	Chassis\WINCH/STRP	fit 2x winch straps			17/06/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Tumut Workshop	TRAILER		
T277	Wodonea - Workshop	Susp\SHOCK ABS	LHF shock blown #SA009TRP			17/06/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonea Workshop	TRAILER		
T277	Wodonga - Workshop	Brakes\SLACK ADJ	LH scam tube free			17/06/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		17/06/2021	PreventativeMai	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
			No lights on B-Trailer.														
			Found wiring had been pulled from light plug and plug was damaged.														
T277	Wodonga - Workshop	Elect\TRL LIGHTS	Replaced and rewired new light plug and tested all OK.			10/06/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/06/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/06/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonea - Workshop	Susp\SHOCK ABS	RHF & LHM shocks blown			10/06/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonea Workshop	TRAILER		
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/05/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/05/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Susp\SHOCK ABS	LHF shock blown #SA009TRP			13/05/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Brakes\SLACK ADJ	LH scam tube free			13/05/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Brakes\SLACK ADJ	LH scam pushed throuah - slack adiuster not on		reseat LR scam remove drums brakes reinstall	13/05/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Unknown	Service due.			30/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/04/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Myrtleford - Workshop	Brakes\BRK RELINE	replaced L/H middle. R/H middle. R/H front and R/H rear linings			23/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER		
T277	Myrtleford - Workshoo	Brakes\BRK O/HAUL	replaced R/H middle s-cam			23/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshoo	TRAILER		
T277	Myrtleford - Workshop	Body\TOOLBOX	iahtened loose toolbox			23/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER		
T277	Myrtleford - Workshop	Susp\SHOCK ABS	replaced 1st axle shockers			23/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER		
			BRAKE RELINE														
			CUSTOMER REPORTS THE TRAILER REQUIRES BRAKE RELINES, CARRY OUT RELINES AS REQUIRED - 22/4/21														
			.														
			* Supported required axles with stands														
			* Removed required wheel equipment														
			* Replaced R/H front, both middle axle & R/H rear brake linings														
			* Repacked required wheel bearings														
			* Replaced R/H middle rear s-cam														
			* Reinstalled all wheel equipment														
			* Adjusted required wheel bearings														
			* Lowered trailer from stands														
			* Adjusted all brakes														
T277	Albury - Workshop	Brakes\BRK RELINE	* Repair complete			23/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
			SHOCKER														
			REPAIR BROKEN SHOCKERS ON 1ST AXLE AS REQUIRED														
			.														
			* Diagnosed broken front axle shockers														
			* Removed/replaced shockers as required														
T277	Albury - Workshop	Susp\SHOCK ABS	* Repair complete			23/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
			TOOLBOX														
			TIGHTEN UP LOOSE TOOL BOX														
			.														
T277	Albury - Workshop	Body\HOUSEKEEP	* Tightened tool box with new bolts & washers as required			23/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			14/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Chassis\AIR LEAK	repaired air leaks (replaced air hoses)			14/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Body\LIGHTS	replaced 2nd bolster (LHS sidemarker and indicator lights)			14/04/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	VehService\DS	D Service	VehService\DS		14/04/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Wodonea - Workshop	Brakes	Record Check Results As Attached To This Job			25/03/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonea Workshop	TRAILER		
T277	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/03/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Wodonga - Workshop	Brakes\SLACK ADJ	fix s-cam R.M. with Greg			25/03/2021 595576	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER		
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			12/03/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/03/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Tyres\TP9+10	Supply and fit 2 tyres			09/03/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Brakes\BOOSTER	Supply Booster			05/03/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			03/03/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
					includes replacing RHM brake booster												
					repaired suspension air leaks												
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	LR inner tyre s/s - Beaurepairs notified	03/03/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Brakes\BOOSTER	RHM 30/30			03/03/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Susp\AIR LEAK	RHF hose leaking			03/03/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Tyres\TP5+6	Supply and Fit 2 tyres			26/02/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Tyres\TP7+8	Supply and Fit 2 tyres			26/02/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			19/02/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
					LH no. plate light												
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	LH work light	19/02/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			29/01/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
					replaced broken u-bolts (LHF)												
					replaced all hub caps												
					found contaminated FL hub from incorrect cap												
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	organised repairs	29/01/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	VehService\DS	Service	VehService\DS		28/01/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			20/01/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Susp\AIR BAG	RF airbag replace when time available			20/01/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/01/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			13/01/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/01/2021	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Tyres\Punct	repair puncture			01/01/2021	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			22/12/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
					tightened shocker bolts												
					tightened cross members												
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	repaired LHS tail lights wirings	22/12/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Chassis\WHL HUB	loose screws on bearing caps on wheel hubs		tightened all hub caps. Replaced missing bolts	20/12/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Myrtleford - Workshop	Tyres	Tyres			12/12/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER		
					Carry out brake reline replace all wheel bearings and s-cams/bushes												
					jacked up and supported on stands, removed wheels, brakes and hubs. Removed and replaced all wheel bearings, s-cams													
					and tubes and fitted new brake linings.												
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		Adjusted wheel bearings brakes and grease all	01/12/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
					Replace RHF Airbag												
T277	Albury - Workshop	Susp\AIR BAG	RF airbag replace when time available		Removed and replaced airbag as required, tensioned and applied sealant	01/12/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	reolaced broken ubolts (RHM)	01/12/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Susp\SUSPENSION	Suspension			20/11/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			14/11/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced/repair airlines - fittings into B Trailer	14/11/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Tyres	Tyres			07/11/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	VehService\DS	Service	VehService\DS		07/11/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Brakes\AIR LEAK	plase check the hose came off brake air line - I tied a rag on it		fit 2 clamps to hose at front tank	03/11/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Susp\SUSPENSION	borken wire cable on front axle		removed broken axle cable	03/11/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		
T277	Albury - Workshop	Brakes\BRAKE ADJ	adjust brakes		adjusted brakes	03/11/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER		

			hub cap missing LR. Multiple cap bolts missing organised parts removed, inspected and replaced bearings and seals replaced cap															
T277	Albury - Workshop	Chassis\WHEEL BRGS	replaced bolts			31/10/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\MUDGUARDS	tiehtened euards			31/10/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\SPAREWHEEL	repaired sensor mounts			31/10/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	Service	VehService\.DS		30/10/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Elect\ELECT P&W	trailer plug is broken to the B Trailer			30/10/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
					picked up parts. Replaced broken LHF spring . Replaced alignment dowel										
T277	Albury - Workshop	DrivLine\WHL HUB	hubo u/s		replaced lights plug	30/10/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Comp\Truck Safe	Trucksafe sticker exoired			30/10/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Susp\AIR BAG	RF airbag replace when time available			30/10/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Body\LIGHTS	no work lights			30/10/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			30/10/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		30/10/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\AIR LEAK	air leak		reolaced/resaired air hoses at 1st middle axles	13/10/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Tyres\DRV TYRES	PO FOR SPARE TYRE MOUNT BRACKET-AWAITING WO			01/10/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\AIR LEAK	maxi leak			30/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	Trailer Service	VehService\.DS		30/09/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To this Job			20/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		20/09/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\WINCH/STRP	tightened winch mount			03/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Susp\AIR BAG	RF airbag replace when time available			03/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			03/09/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		03/09/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		22/08/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\AIR LEAK	repained/replaced b/booster hoses (rubbed)			22/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			22/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			11/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		11/08/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			05/08/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		05/08/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Body\CHN/RLR/MN	PO FOR CATCH STRAP checked abs codes no dtc's			11/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\ABS	downloaded ecm			11/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Workshop\TRAINING	trained driver			11/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\CONSUMABLE	RHM axle cable			10/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To this Job			10/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		10/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\EBS FAULTS	trailer abs very sensitive got to tip toe around every thing			10/07/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\AS	due for A Service			10/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\ABS	checked ABS codes. No DTC's			03/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Susp\SHOCK ABS	tiehtened shocks			03/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			03/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		03/07/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Body\LIGHTS	no work lights T/table top, trunion bushes/feet and alter base			02/07/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\FIFTH WHEE	replaced RHF z-spring and wrap			25/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\FIFTH WHEE	Turntable trunions worn out reolace ball race and foot oins & bushes as well as doe bones		sublet to TCTC	24/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Albury - Workshop	Susp\AIR BAG	RHR spring eye bush order bush and wrapper			19/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Albury - Workshop	Susp\SPRNG PACK	broken z spring			19/06/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			06/06/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\.DS	Replaced grease nipple on jaws	06/06/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Air Con\FIFTH WHEE	adiusted iaws			31/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			31/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		31/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BOOSTER	PO FOR BRAKE BOOSTER			27/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			27/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		27/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\BOOSTER	replace brake booster L/H rear axle - adjust brake		replaced broken booster removed left over damaged components. Replaced fittings	23/05/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\ABS	ABS light on			23/05/2020	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			19/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Elect\WORK LIGHT	Repaired RHS work light wiring			19/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\.DS		19/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			14/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\FIFTH WHEE	Turntable trunions worn out			14/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Comp\Truck Safe	Trucksafe sticker expired			14/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\.DS		14/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\BRK RELINE	sub bit to TCTC to carry out brake reline 6 wheel ends			13/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			03/05/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		03/05/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			21/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		21/04/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			16/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		16/04/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			05/04/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		05/04/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Elect\TRL LIGHTS	repaired wiring to 2nd bolster lights			31/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			31/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		31/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			25/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		25/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Elect\ELECT P&W	clean out trailer plug			19/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\EBS FAULTS	EBS check one			19/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			19/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	Carry out trailer Service	VehService\.DS		19/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\BOLSTER	replaced LHF bolster light and repaired wiring			15/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Elect\ELECT P&W	plug trailer cable			14/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Albury - Workshop	Body\ELECT P&W	reoair cum to B trailer			14/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			14/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	trailer service	VehService\.DS		14/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\AS	A Service replace EBS and 7 pin elec plugs remount			12/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Body\ELECT P&W	made holder for lines/looms to take weight			06/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			06/03/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	carry out trailer service	VehService\.DS		06/03/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		27/02/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job D Service			15/02/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	tightened RHF and LHM sebolts	VehService\.DS		15/02/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			08/02/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		08/02/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\WINCH/STRP	reolaced handle. straiehtened bracket 2nd winch			06/02/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\BOLSTER	turn bolster pags			02/02/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\CROSS MBR	tension cross member bolts			02/02/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			02/02/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	Carry out trailer service	VehService\.DS		02/02/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\DAMAGE	weld s-cam tubes to keepers			24/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\FIFTH WHEE	adjust T/table jaws			23/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			23/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service replace following s cam tube s cam kit cam slack adj washer axle tab	VehService\.DS		23/01/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes\BRK O/HAUL	seal grease			08/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Albury - Workshop	Chassis\WHL HUB	jack ip and check all wheel bearings. Adjust as required LH cam not in position. Tube and cam worn out			08/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\SUSPENSION	replaced cam, tube and kit			04/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\WHL HUB	adjusted wheel bearings			04/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\HOUSEKEEP	reolaced missing lock washers			04/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\HOUSEKEEP	replaced missing, loose bolster bolts			04/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Chassis\SUSPENSION	tightened LF booster			04/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			04/01/2020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		04/01/2020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D Service	VehService\.DS		14/12/2019	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			14/12/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	TEST RESULTS			08/12/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D SERVICE	VehService\.DS		08/12/2019	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes	TEST RESULTS			03/12/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D SERVICE	VehService\.DS		03/12/2019	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Elect\ELECT P&W	DIAGNOSED & REPAIRED PLUG FOR B/TRAILER SCALES			28/11/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	Brakes				15/11/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Albury - Workshop	VehService\DS	D SERVICE	VehService\.DS		15/11/2019	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Albury Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	check lights			18/09/2019 169855	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\WORK LIGHT	no work liehts			17/09/2019	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	left hand center mudguard crack			03/09/2019 178066	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\PANELS	one bolt missing on checked plate LHS			03/09/2019 178066	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/08/2019 169854	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\.DS		28/08/2019 169854	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER

T277	Myrtleford - Workshop	Body\AIR LEAK	possible air leak				17/08/2019	165760	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	front airwinch is hard to wind up				09/08/2019	164056	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/08/2019	164058	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced air lines		09/08/2019	164058	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\SHOCK ABS	Replace RHR Shocker				02/08/2019	164058	Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHR Shocker Bush				02/08/2019	164058	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				31/07/2019	160537	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			31/07/2019	160537	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/07/2019	154436	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	rewire RH tail liaht bar		20/07/2019	154436	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/07/2019	147094	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	ONETRAK-3	TRAILER
			D Service As Per Attached Checklist														
T277	Myrtleford - Workshop	VehService\DS	Order # 16585	VehService\DS			05/07/2019	147094	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	ONETRAK-3	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/06/2019		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
					trailer service												
			D Service As Per Attached Checklist		guard												
T277	Myrtleford - Workshop	VehService\DS	Order # 6458	VehService\DS	check lights		21/06/2019		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	BARRY MANEY - 3	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/06/2019	129259	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/06/2019	129259	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	front winch strap needs replacing and winch very stiff to turn				04/06/2019	122080	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/06/2019	125989	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/06/2019	125989	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes				28/05/2019	122084	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
			wash hubs & wheels														
			crack test and reline all wheels														
T277	Myrtleford - Workshop	Brakes\BRK RELINE	hook up/drop tools in workshop				22/05/2019	122083	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				16/05/2019	121396	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			16/05/2019	121396	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/05/2019	117175	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	reoair leakine brake hose		11/05/2019	117175	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/05/2019	112210	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/05/2019	112210	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/05/2019	109058	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/05/2019	109058	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/04/2019	105971	Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/04/2019	105971	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/04/2019	99516	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/04/2019	99516	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				16/04/2019	95848	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	reolaced LHF mudeuard		16/04/2019	95848	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/04/2019	90309	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/04/2019	90309	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				04/04/2019	87030	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			04/04/2019	87030	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	check liahts				03/04/2019	86519	Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\HOUSEKEEP	check over				03/04/2019	86519	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRK O/HAUL	fit 40% run out brake shoes to RHF & RHM wheels				03/04/2019	86519	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\FIFTH WHEE	check and grease ball race				03/04/2019	86519	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\SLACK ADJ	Replace RHM slack adjuster				27/03/2019	83930	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				26/03/2019	83151	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			26/03/2019	83151	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/03/2019	77516	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/03/2019	77516	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/03/2019	73533	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/03/2019	73533	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/03/2019	68618	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/03/2019	68618	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/03/2019	64242	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/03/2019	64242	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				26/02/2019	59566	Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replace RH inner LED tail light		26/02/2019	59566	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/02/2019	54770	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/02/2019	54770	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\HOUSEKEEP	check over trailers				09/02/2019	50677	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes				09/02/2019	50677	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	fit new RH mudflap and repair m/flap retainers L&R				09/02/2019	50677	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\CHAS CRACK	Repair LH skid plate crack				08/02/2019	50677	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/02/2019	50087	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/02/2019	50087	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\INDICATORS	risht hand side rear indicator needs new rubber				06/02/2019	48915	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				02/02/2019	46227	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/02/2019	46227	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/01/2019	40276	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	repair reverse light wiring		25/01/2019	40276	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				18/01/2019	35905	Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			18/01/2019	35905	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
			L/hand back mudguard broken														
			L/H blinker and tail light not working														
T277	Myrtleford - Workshop	Tyres\DAMAGE	mudflap missing		repaired tyre damage		16/01/2019	33999	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/01/2019	30622	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/01/2019	30622	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\DAMAGE	Repair crack in LH bottom U Bolt saddle		replaced saddle		04/01/2019	28694	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
					replaced spring												
T277	Myrtleford - Workshop	Susp\SUSPENSION	Replace spring wrap		had to get seized spring off		04/01/2019	28694	Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/01/2019	2564	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tighten LHF outrigger		03/01/2019	2564	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	pull cord to release winch straps broken - front RHS				19/12/2018	20656	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				16/12/2018	4	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Wodonga Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/12/2018	19366	Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/12/2018	19366	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/12/2018	14956	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/12/2018	14956	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
			inspect all brake %														
T277	Myrtleford - Workshop	Brakes\BRK RELINE	Fit runouts to RHF & RHM & check bearings		all brake % are 50/60%		07/12/2018		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/12/2018	9278	Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/12/2018	9278	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/11/2018	4209	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/11/2018	4209	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres	Job Added From Invoice				27/11/2018	93444	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\CASE STOCK	Job Added From Invoice				27/11/2018	93444	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				27/11/2018	93444	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				27/11/2018	93444	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\Punct	Job Added From Invoice				27/11/2018	93444	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				27/11/2018		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist														
T277	Myrtleford - Workshop	VehService\DS	fit new hubo meter	VehService\DS	reolaced hubo		27/11/2018		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\CASE STOCK	Job Added From Invoice				27/11/2018	91599	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				27/11/2018	91599	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				27/11/2018	91599	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/11/2018	101595	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/11/2018	101595	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/11/2018	97148	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/11/2018	97148	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/11/2018	91595	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/11/2018	91595	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/10/2018	86990	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/10/2018	86990	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				27/10/2018	83832	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				27/10/2018	83832	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\FIFTH WHEE	hook up to 957				20/10/2018	81891	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
					move 2nd bolster forward												
					fit 2nd bolster clamp												
					repair winch cable												
					fit nego label												
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	Fit Air Winches				05/10/2018	81897	Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			05/10/2018	81897	PreventativeMai	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/10/2018	81891	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Check & Repair lights - Dan Borlovan		05/10/2018	81891	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				31/05/2018	77996	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/05/2018	78656	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/05/2018	78656	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	repair winch				18/05/2018		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				18/05/2018	73850	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			18/05/2018	73850	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/05/2018	69271	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/05/2018	69271	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				27/04/2018	64402	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			27/04/2018	64402	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	repair broken winch				21/04/2018	61869	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/04/2018	59361	Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/04/2018	59361	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/04/2018	55465	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/04/2018	55465	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	fit side light keepers				06/04/2018	55463	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	fit side

T277	Myrtleford - Workshop	Brakes\AIR LEAK	fit hose clamps to some airlines				06/04/2018	55463	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\FIFTH WHEE	fit front t/table lock pin				06/04/2018	55463	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	fit LHF mudflap				06/04/2018	55463	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	fit front winch strap				06/04/2018	55463	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Bodv\WHL HUB	tension wheel nuts				06/04/2018	55463	Reoair	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres	Job Added From Invoice				17/03/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				17/03/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				17/03/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
						replace all ram mounts on trailer and fit bolts											
T277	Myrtleford - Workshop	Hydraulics\RAM	Repair ram pin boss at cylinder end & replace ram eye ends(L4641)			repair rams also &repair cracks(L4640)	10/03/2018	1897	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Bodv\CHAS CRACK	Repair ram cross member cracks				10/03/2018	1897	Reoair	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\FIFTH WHEE	Repair ball race (L4077)				10/03/2018	1897	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\FIFTH WHEE	Check turn table feet bushes & pins& fit t/table hinge pins & bushes(L4194			wash trailer & ball race assembly	10/03/2018	1897	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels fit 2 x shockers & 8 x shocker bushes(L4159)				10/03/2018	1897	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/03/2018	54361	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/03/2018	54361	Service	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				05/03/2018	25840	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				05/03/2018	25840	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/02/2018	52158	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced LHR axle cable		28/02/2018	52158	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres	Job Added From Invoice				24/02/2018	0	Reoair	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				24/02/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				24/02/2018	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				17/02/2018	4962	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/02/2018	4962	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/02/2018	47492	Reoair	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/02/2018	47492	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Hydraulics\HYD LEAKS	hydraulic fittings broken off by loader driver				07/02/2018	47492	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	check all plugs				07/02/2018	47492	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\FIFTH WHEE	hook up trailer and grease turntable				03/02/2018		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Bodv\HOUSEKEEP	drop trailer T277 and solit off FL 848				01/02/2018		Reoair	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	winch handle broken off				24/01/2018	44668	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				24/01/2018	44668	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist														
T277	Myrtleford - Workshop	VehService\DS	repair hyd leak	VehService\DS			24/01/2018	44668	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
			2nd winch rod to hold strap broken off														
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	-weld back on				16/01/2018	42735	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	fit winch strap				13/01/2018	42464	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/01/2018	42154	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/01/2018	42154	Service	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				29/12/2017	39515	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			29/12/2017	39515	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRAKE ADJ	check and adjust brakes				20/12/2017	38468	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	repair RHR mudflap and hinge				14/12/2017	36732	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/12/2017	36732	Reoair	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
						no rego lable											
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	repair lights		14/12/2017	36732	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes				13/12/2017	36477	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes				06/12/2017	34255	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\FIFTH WHEE	gease turntable				24/11/2017	32267	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRAKE ADJ	adiust brakes				24/11/2017	32267	Fault	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\HCV	adjust ride height				24/11/2017	32267	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\AIR FITTIN	shorten supply and service airlines to B Trailer				24/11/2017	32267	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRK RELINE	Fit 40% Runout brake shoes to RHM & check bearings				23/11/2017	32267	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRK RELINE	Fit 40% Runout brake shoes to RHR & check bearings				23/11/2017	32267	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist														
T277	Myrtleford - Workshop	VehService\DS	fit new air bag	VehService\DS			21/11/2017	32264	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/11/2017	32264	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
			Fit correct axle cable to RHR														
T277	Myrtleford - Workshop	Susp\HOUSEKEEP	fit s/cam & s/cam tube				11/11/2017	33265	Reoair	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/11/2017	30517	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/11/2017	30517	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				27/10/2017	28419	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			27/10/2017	28419	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres	Job Added From Invoice				21/10/2017	26238	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice				21/10/2017	26238	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				21/10/2017	26238	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				18/10/2017	26550	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			18/10/2017	26550	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels				07/10/2017	24834	Reoair	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				05/10/2017	24362	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			05/10/2017	24362	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Hydraulics\HYD LEAKS	hyd couplings				28/09/2017	23631	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	fit light keepers				28/09/2017	23631	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Insp\INT INSP	fit srt stickers to oeas				28/09/2017	23631	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
			re-check all brake %														
T277	Myrtleford - Workshop	Brakes\CONSUMABLE	all ok 40%				26/09/2017	23631	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\HOUSEKEEP	fit cable straps to LHF and RHM axles				15/09/2017	21415	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/09/2017	21415	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/09/2017	21415	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/09/2017	19265	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/09/2017	19265	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	Replace broken mudflap				05/09/2017		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Insp\ANN INSP	Annual inspection As Per Checklist	Insp\ANN INSP			30/08/2017	16505	PreventativeMai	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/08/2017	16505	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/08/2017	16505	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/08/2017	13661	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			19/08/2017	13661	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/08/2017	1110	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/08/2017	1110	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	reolace R/H rear axle mudauard				05/08/2017	9980	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice				04/08/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/08/2017	9492	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/08/2017	9492	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				26/07/2017	6740	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			26/07/2017	6740	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres	Job Added From Invoice				21/07/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				21/07/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				21/07/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\FIFTH WHEE	make up and fit new T/table hinge pins and bushes and supply parts				20/07/2017	36202	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\HOUSEKEEP	Reolace LHF sorine clamo olate				20/07/2017	5924	Reoair	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\HOUSEKEEP	Weld LHF axle saddle crack		fit new LHF saddle clamp		20/07/2017	5924	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				19/07/2017	4523	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit new LHF slack adjuster		19/07/2017	4523	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				14/07/2017	551	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\HOUSEKEEP	Reolace LHM bottom sorine clamo olate				13/07/2017	5924	Reoair	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/07/2017	1764	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
						LHM bottom spring saddle u/s											
						repaired LH 2nd bolster light wiring											
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		repaired air leak at rear air tank	12/07/2017	1764	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\WHL HUB	Replace Hubo meter				07/07/2017		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/07/2017		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	needs new hubo		06/07/2017		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\SELECT P&W	reoair wirina in 7 oin olue				02/07/2017	36202	Repair	Completed	Greenfreiaht Loaaine NSW	Kennedv	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\PANELS	repair borkne bolt at front cover plate				02/07/2017	36202	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRAKE ADJ	adj brakes				02/07/2017	36202	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\HCV	adj ride height				02/07/2017	36202	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
			Fit EBS Kit to front & rear axles														
T277	Myrtleford - Workshop	Brakes\EBS Kit	check engineering on trl (jason underwood)		Complete		01/07/2017	36202	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
			Crack test & reline all wheels														
T277	Myrtleford - Workshop	Brakes\BRK RELINE	Fit 6 x Brake drums				29/06/2017	36201	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/06/2017	35838	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			23/06/2017	35838	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres	Job Added From Invoice				20/06/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				20/06/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				20/06/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/06/2017	33020	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/06/2017	33020	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	repair broken bolt to spring on winch				03/06/2017	31704	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice				30/05/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice				30/05/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				30/05/2017	30799	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/05/2017	30799	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\HOUSEKEEP	check over				24/05/2017	29152	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\CONSUMABLE	recheck RHM brake % = 30 not 20%				24/05/2017	29152	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				18/05/2017	28256	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			18/05/2017	28256	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\RUN OUT	Job Added From Invoice				12/05/2017	23754	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/05/2017	373365	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/05/2017	373365	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/04/2017	22290	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER

T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/04/2017	20153	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				29/03/2017	17991	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			29/03/2017	17991	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice				23/03/2017	16681	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\HOUSEKEEP	fit lav flat to brake hoses				18/03/2017	16683	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	R&R LH middle mudguard				18/03/2017	16683	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\FIFTH WHEE	R&R Ttable bushes and pins				18/03/2017	16683	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/03/2017	15967	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/03/2017	15967	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
					fit new relief valve to hyd ram												
T277	Myrtleford - Workshop	Hydraulics\RAM	Repair turn table lift ram seals		fit seal kit to t/table ram		01/03/2017	13987	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice				01/03/2017	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/02/2017	13762	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/02/2017	13762	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\AIR LEAK	replace R-12 relay valve				21/02/2017	12302	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	clean out A-brake valve - brakes wont release				21/02/2017	12302	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				16/02/2017	11829	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			16/02/2017	11829	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				03/02/2017	9751	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			03/02/2017	9751	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/01/2017	6969	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/01/2017	6969	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\HOUSEKEEP	check over trailer				05/01/2017	4758	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\HOUSEKEEP	repair chassis cracks at trailer hinge				05/01/2017	4758	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/12/2016	4757	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			23/12/2016	4757	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	lights - brake / indicator faulty				16/12/2016	3532	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\CROSS MBR	Tighten front cross member bolts		fit hyd clamp to cross member to hold has hoses		10/12/2016	4173	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\WORK LIGHT	Replace RH Work light				10/12/2016	4173	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/12/2016	2757	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/12/2016	2757	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				29/11/2016	555	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			29/11/2016	555	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\HOUSEKEEP	check LH hinge point above pin hole				26/11/2016		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\WHL HUB	Fit new hubo meter				19/11/2016		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
					need new hubbo #3												
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		w/o 36146 (P)		18/11/2016		Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			18/11/2016		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\AIR BAG	fit new air bag LHM axle				12/11/2016	24723	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/11/2016	23960	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/11/2016	23960	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\AIR LEAK	check LH centre airbae leakine when loaded				10/11/2016	23960	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	RH reverse light flickering				04/11/2016	2272	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP12	Job Added From Invoice				01/11/2016	28762	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\SHOCK ABS	Fit new shock absorber and bolt to LHR				28/10/2016	22328	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			27/10/2016	21192	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				27/10/2016	21192	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice				19/10/2016	18294	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\SUSPENSION	Weld crack in LHM spring saddle		remove spring saddle + send to rinatech for repair		18/10/2016	326108	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/10/2016	19159	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				15/10/2016	19159	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
					Fit new clearance light												
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair LHS No. 1 bolster light - not working		Complete		14/10/2016	19169	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				29/09/2016	16824	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			29/09/2016	16824	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice				22/09/2016	14410	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice				16/09/2016	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			14/09/2016	14410	PreventativeMai	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/09/2016	14410	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			14/09/2016	14410	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair RH inner indicator		Complete		13/09/2016	293651	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/09/2016	12396	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit LH tail light & rubber		01/09/2016	12396	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice				25/08/2016	9328	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				20/08/2016	9717	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			20/08/2016	9717	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
			Replace ball race														
			Replace turntable foot pins & jaw														
T277	Myrtleford - Workshop	Chassis\FIFTH WHEE	Grease nipples		replace all mount bolts & paint & grease also adj jaws		18/08/2016	13062	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/08/2016	7199	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/08/2016	7199	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Insp\RWC COMP	Replace Rego Label				02/08/2016	5659	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice				30/07/2016	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice				30/07/2016	4735	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice				30/07/2016	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice				30/07/2016	4735	Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\AIR LEAK	air leak when brakes applied				28/07/2016	4735	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\ELECT P&W	"A" Brake clicking on				28/07/2016	4735	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				27/07/2016	4448	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			27/07/2016	4448	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	Check winches. Reolace miscine air winches		Complete		26/07/2016		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body	replaced service air line coupling and fitting				26/07/2016		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\SPRNG PACK	Replace broken RHR spring pack & spring wrap		Complete		19/07/2016	2833	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				14/07/2016	1853	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			14/07/2016	1853	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Hydraulics\HYD LEAKS	Reoair leakine LH hydraulic lift ram		Complete		13/07/2016	1853	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	DriveLine\WHL HUB	Replace Hubo				05/07/2016		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				01/07/2016		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	DriveLine\WHL HUB	hubo u/s				01/07/2016		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			01/07/2016		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	LH mudflap fallen off				22/06/2016		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	refit mudflap LHS				22/06/2016		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/06/2016	262089	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			22/06/2016	262089	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\SHOCK ABS	back left upper shock bolt broken				09/06/2016	485022	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Hydraulics\RAM	Fit seal kit to turn table ram		fit new ram to turn table lift		08/06/2016	485624	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				06/06/2016	484319	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			06/06/2016	484319	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\HOUSEKEEP	check over trailers				24/05/2016		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\PANELS	replace bolts and washers on chassis cover				24/05/2016		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	check liehts + reoair				24/05/2016		Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				21/05/2016	481628	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			21/05/2016	481628	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRK RELINE	Crack Test & Reline all wheels				12/05/2016	481628	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace RHR Spring Eye Bush				12/05/2016	481628	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				11/05/2016	479146	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			11/05/2016	479146	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\AIR BAG	RHR spring eye bush				11/05/2016	479146	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				28/04/2016		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			28/04/2016		Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Chassis\WINCH/STRP	Check over Winches		complete		14/04/2016	238758	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Body\MUDGUARDS	Repair mudflap LHS		complete		14/04/2016	238758	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				07/04/2016	473972	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			07/04/2016	473972	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
			Replace LHR spring wrap														
T277	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace RHM & LHF shocker rubbers				25/03/2016	47459	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\SPRNG HANG	Repair LHM spring hanger crack				25/03/2016	47459	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\SHOCK ABS	Repace LHR shocker				25/03/2016	47459	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				23/03/2016	471165	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			23/03/2016	471165	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Hydraulics\RAM	Repair leaking turntable lift ram				11/03/2016	474589	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace LHF & RHF Spring eye bushes				11/03/2016	474589	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/03/2016	468476	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/03/2016	468476	Reapir	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	Replace R/H front bolster light. R/H front bolster light u/s				09/03/2016	468476	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	repair RH inner indicator wiring				09/03/2016	468476	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Tyres\TP51	Job Added From Invoice				01/03/2016	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/02/2016	466015	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/02/2016	466015	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRK O/HAUL	check brake %		completed		10/02/2016	465453	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\AIR LEAK	check for air leaks		completed		10/02/2016	465453	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Susp\HOUSEKEEP	check spring eye bushes		completed		10/02/2016	465453	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\BRK RELINE	fit run out brake shoes to RHF & RHM		Completed		10/02/2016	465453	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes\SLACK ADJ	reolace slack adiusuter on RHM		completed		10/02/2016	465453	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
			check ball race														
T277	Myrtleford - Workshop	Chassis\FIFTH WHEE	check turn table bushes & top		completed		10/02/2016	465453	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				29/01/2016	463660	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			29/01/2016	463660	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	436485	Myrtleford Workshop	TRAILER
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	1st pge RH side light LED		completed		29/01/2016	218766	Fault	Completed	Greenfreight Logging NSW

			fit nw RHR airbag																		
T277	Myrtleford - Workshop	Susp\AIR BAG	replace RHF airbag bell & bolts			completed	18/01/2016	462500	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		completed	08/01/2016	461002	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			completed	08/01/2016	461002	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Body\HOUSEKEEP	re-hang power air lead			completed	08/01/2016	461002	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Brakes\BRAKE ADJ	adiust brakes			completed	08/01/2016	461002	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Chassis\HOUSEKEEP	check over			completed	05/01/2016	460428	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Brakes\AIR LEAK	replace lhr brake booster hoses				17/12/2015		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Chassis\AIR LEAK	check for air leaks			completed	12/12/2015	458324	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
			fit 50% brake shoes to rhr + lhm axles																		
T277	Myrtleford - Workshop	Brakes\BRK RELINE	check wheel bearings			completed	12/12/2015	45833	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Brakes\BRK RELINE	brake oarts + 2 axles			coomoleted	12/12/2015		Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Elect\TRL LIGHTS	replace rh side light led peg no 2			completed	10/12/2015	45832	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			completed	09/12/2015	45832	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		completed	09/12/2015	45832	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Chassis\MUDGUARDS	replace lh mudflap			completed	26/11/2015		Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			completed	26/11/2015	455825	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		completed	26/11/2015	455825	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			completed	13/11/2015	452961	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		completed	13/11/2015	452961	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice				11/11/2015	450949	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice				11/11/2015	450949	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice				11/11/2015	450949	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
			check electric brakes operation																		
T277	Myrtleford - Workshop	Brakes\BRK O/HAUL	Lube u inflate+deflate valve			completed	05/11/2015	450947	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		completed	28/10/2015	449859	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			completed	28/10/2015	449859	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		completed	14/10/2015	447254	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			completed	14/10/2015	447254	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
			replace front binder strap																		
			tighten hoses hanging down																		
			replace can of spray for winches																		
T277	Myrtleford - Workshop	Tyres\DAMAGE	change middle axle outside flat tyre			completed	30/09/2015	444632	Fault	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			completed	30/09/2015	444632	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		completed	30/09/2015	444632	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Tyres\TP22	Job Added From Invoice				24/09/2015	0	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			completed	18/09/2015	292244	Repair	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		completed	18/09/2015	292244	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
						completed															
						repair top rail near pivot point rhs															
T277	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		replaced rhm shocker bush	02/09/2015	439734	PreventativeMai	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			
						completed															
						repaired top rail near pivot point rhs															
T277	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		replaced rhm shocker bush	02/09/2015	439734	Service	Completed	Greenfreight Logging NSW	Kennedy	Mt Gambier	STK	43648S	Myrtleford Workshop	TRAILER			