



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A318835

Station #: 71709	Station Name: Redhead Equipment
Technician #: 87734	Technician Name: Cale Boehm
Signing Officer #: 92422	Signing Officer Name: Kassey Kohl

Customer Details:	
Name: ELDON AND LORI MARTENS	Address: P.O. Box 28, Rabbit Lake, Saskatchewan, S0M 2L0

Inspection Completed Date: 13Mar2026	Inspection Expiry Date: 30Sep2026
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 1XP5PB9X91N547042	Odometer Reading: 464857 km
Year: 2001	Vehicle Make/Model: PETERBILT/HEAVY VEHICLE
Plate: 568KXX	Jurisdiction: Saskatchewan
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71709

Station Name: Redhead Equipment

Technician #: 87734

Technician Name: Cale Boehm

Signing Officer #: 92422

Signing Officer Name: Kassey Kohl

Customer Details:

Name: ELDON AND LORI MARTENS

Address: P.O. Box 28, Rabbit Lake, Saskatchewan, S0M 2L0

Vehicle Details:

VIN: 1XP5PB9X91N547042

Odometer Reading: 464857 km

Year: 2001

Vehicle Make/Model: PETERBILT HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
		x		Mirrors (8)	PASSENGER CONVEX MIRROR CRACKED
		x		Windshield Wipers/Washers (8)	DRIVER'S WINDSHIELD WASHER INOP
x				Windshield Defroster/Heater (8)	
		x		Windshield/Other Glass (8)	DRIVER'S WINDSHIELD ROCK CHIP
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
		x		Speedometer/Odometer (5)	SPEEDOMETER GAUGE BACKLIGHT POOR
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	RH SIDE SIGNAL POOR CONNECTIONS
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
		x		Retro Reflective Markings (6)	CAB REFLECTIVE TAPE PEELING OFF
		x		Body/Bumpers (8)	BUMPER BENT
		x		Trailer Hitch (10)	5TH WHEEL SLIDE MOUNT RUST JACKED PASSED 10MM
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
		x		Power Steering System (4)	STEERING SHAFT ROTATIONAL PLAY AT SLIP YOKE EXCEEDS 1MM
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	AIR LINES RUBBING FITTING AT REAR OF AIRTANK, AIR LEAK IN CAB WITH BRAKE APP
x				Wheel Bearings (9)	
		x		King Pins/Ball Joints (4)	KINGPIN PLAY PASSED 3/16 LIMIT
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
		x		Frame/Crossmembers/Mounts (8)	FRAME CATWALK LOOSE
		x		Suspension/Axles (2)	ALL AIRBAGS RUST JACKED
x				Drive Shaft/Universal Joints (1)	
		x		Exhaust/Emission System (1)	HOLES IN EXHAUST UNDER CAB

Brake/Tire Measurements

Axle 1-Pass

Wheel1-Off : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13 mm • Brake Drum/Rotor: 15.075 in • Brake Stroke: 33 mm

Wheel2-Off : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13 mm • Brake Drum/Rotor: 15.083 in • Brake Stroke: 32 mm

Axle 2-Pass

Wheel1 : Tire Tread Depth: 15 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 17 mm • Cam Rotation: 67.0 degrees • Brake Stroke: 41 mm

Wheel3-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 15 mm • Cam Rotation: 75.0 degrees • Brake Stroke: 43 mm

Wheel4 : Tire Tread Depth: 13 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 15 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 17 mm • Cam Rotation: 65.0 degrees • Brake Stroke: 42 mm

Wheel3-On : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 13 mm • Cam Rotation: 92.0 degrees • Brake Stroke: 42 mm

Wheel4 : Tire Tread Depth: 14 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A318835

Inspection Completed Date: 13Mar2026

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km.
Failure to do so may result in damage or serious injury.