EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T270	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		29/08/2023	35700	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/08/2023	35700	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/08/2023	35700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			12/07/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Albury Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/06/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/06/2023		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\DAMAGE	Repairs to smashed up cab guard including materials.			10/06/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	RINLATECH ENGINEERING-3	TRAILER
T270	Myrtleford - Workshop	Elect\TAIL LIGHT	replace rear tail lights			10/06/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP5+6	runouts			07/06/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Albury Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	replace 4th winch strap			03/06/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			31/05/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/05/2023		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/04/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	RHM brake booster	19/04/2023		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			12/04/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Albury Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP12	fix rear right os tyre		flat trailer tyre	06/04/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	fix winch release handle		winch handle	06/04/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			15/03/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Albury Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			02/03/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Albury Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	no tail lights		rubbed wiring	04/02/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP1A	runout			02/02/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Albury Workshop	TRAILER
T270	Wodonga - Workshop	Elect\TRL LIGHTS	NO LIGHTS ON TRAILER.		RESET BREAKER. CHECKED WIRING.	31/01/2023		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	REPAIR OR REPLACE FIRST AIR WINCH - LEAKING AIR			30/01/2023	35700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP08	runout			28/01/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Albury Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2023		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/01/2023		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/12/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Wodonga Workshop	TRAILER
T270	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/12/2022		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Wodonga Workshop	TRAILER
					LHR missing hub cap											
					*removed wheel bearing washed up and inspected not too bad											
			missing axle cap remove out bearing wash out		needs replacing but hub very dry not much grease											
T270	Myrtleford - Workshop	Body\WHL HUB	refit		need to remove all wheel and recheck	25/11/2022		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
					rear axle not tracking true											
					*inspected wheel bearing's all good											
T270	Myrtleford - Workshop	Susp\AXLES	rear axle not running true		*inspected all suspension part's all good unable to fault	23/11/2022	3868	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\FIFTH WHEE	hook up test lights			10/11/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	replace air winch			10/11/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	pulled apart winch, fixed problem			10/11/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace 3 winches			11/10/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\AIR LEAK	Repaired weight gauge not working			11/10/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	replace bolster reg bolts			07/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\HOUSEKEEP	wash trailer			07/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Albury - Workshop	Tyres\TP3+4	supply and fit 2tyres			07/09/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Albury Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2022	195480	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	change tyre RHS middle inner	02/09/2022	195480	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	REPLACE / REPAIR 2ND AIR WINCH		completed	19/08/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		17/08/2022	190663	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			17/08/2022	190663	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/08/2022	190663	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
			hook up													
T270	Myrtleford - Workshop	Body\FIFTH WHEE	lights			09/08/2022	188093	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	lube winches			12/07/2022	187223	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SPRNG HANG	replace RHF spring eye bolt			02/07/2022	187222	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SPRNG HANG	weld cracked RHF spring hanger			02/07/2022	187222	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SHOCK ABS	replace LHR shock bolt			02/07/2022	187222	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	POS 10, 11			26/05/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP01	supply and fit 1tyre			04/05/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/03/2022	182976	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	adjusted LHM & RHF wheel bearings	25/03/2022	182976	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	winches not working			17/03/2022	181559	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP5+6	supply and fit 2 tyres			12/03/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Wodonga - Workshop	Chassis\WINCH/STRP	REPAIR OR REPLACE 2ND ELPHINGSTONE WINCH		inspected all good	05/03/2022		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Wodonga Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	4th winch lubed etc			04/03/2022	180812	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/03/2022	180243	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Wodonga Workshop	TRAILER
					adjust RHM wheel bearing											
T270	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	adjust LHF wheel bearing	02/03/2022	180243	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Wodonga Workshop	TRAILER
T270	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/03/2022	180243	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Wodonga Workshop	TRAILER
T270	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	adjust RHM & LHF wheel bearings	01/03/2022	180243	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Wodonga Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/02/2022	35700	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/02/2022	35700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/01/2022	177777	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tighten bolsters	19/01/2022	177777	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/12/2021	175570	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Wodonga Workshop	TRAILER
T270	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/12/2021	175570	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Wodonga Workshop	TRAILER
T270	Myrtleford - Workshop	Body\HOUSEKEEP	check over T270			09/12/2021	174017	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/11/2021	173651	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tighten 2x shocker & 2x spring eye bolts	27/11/2021	173651	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/11/2021	35700	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/11/2021	35700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	front air winch not working		first winch not working as it should	25/11/2021	172494	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP10	puncture repair			24/11/2021	17277	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\FIFTH WHEE	hook up to T270			16/11/2021	170750	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	MOVE 2ND BOLSTER BACK TO SUIT LONGER LOGS			13/11/2021	170750	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP1+2	supply and fit 2 tyres			12/11/2021	170267	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/11/2021	170266	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
					repair trailer plug											
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced shocker strap	10/11/2021	170266	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\FIFTH WHEE	drop T134 and hook up to T270			28/10/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/10/2021	167670	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tighten RHF spring eye bolt	15/10/2021	167670	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\DAMAGE	REPLACE LHF TYRE			30/09/2021	16633	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\WHL HUB	REPLACE RHM WHEEL BEARING			30/09/2021	16633	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/09/2021	16633	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tigthen all spring eye bolts	29/09/2021	16633	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP9+10	supply and fit 2 tyres			29/09/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\BREAKDOWN	replaced flat tyre RHR outer			27/09/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\WHL HUB	adjust wheel bearing			27/09/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP12	fit runout			23/09/2021	165147	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\DAMAGE	CHANGE RHR TYRE			22/09/2021	165147	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres	Inflate tyres			21/09/2021	164800	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\HOUSEKEEP	Make up bracket for air lines			21/09/2021	164800	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\FIFTH WHEE	Hook 861 to T270			21/09/2021	164800	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	4th AIR WINCH HAS AIR LEAK			18/09/2021	165747	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\BREAKDOWN	breakdown replace 2 trailer tyres RH rear		replace two flat tyres RHR axle onsite	15/09/2021		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	shortened winch latch			14/09/2021	163575	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/09/2021	163201	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
					replaced LHF bolster light											
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	checked EBS	01/09/2021	163201	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\MOUNTS	MOUNT 4X ELPHINGSTONE AIR WINCHES		remove old winches	31/08/2021	163201	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\AIR FITTIN	CONNECT AIR LINES TO AIR WINCHES			31/08/2021	163201	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	check all winches for working order			27/08/2021	163207	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	check over 4x old elphinstone air winches to fit on T-270			26/08/2021		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SHOCK ABS	REPLACE RHR SHOCKER			15/04/2021	163206	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\HOUSEKEEP	REPLACE RHM SHOCKER STRAP			15/04/2021	163206	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\DAMAGE	REPLACE LHF INNER TYRE			15/04/2021	163210	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
					checked E.B.S - end of line test											
					repaired air lines to boosters											
					replaced air tank bolts											
					cleaned pulse wheels and sensor for E.B.S											
T270	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	hook up and unhook	14/04/2021	163209	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TPS1	FIT SPARE TYRE TO TYRE RACK			11/03/2021	163205	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/03/2021	163204	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER
T270	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replace RHR brake booster	10/03/2021	163204	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	431345	Myrtleford Workshop	TRAILER

T270	Myrtleford - Workshop	Chassis\BOLSTER	reposition front bolster			12/02/2021	163203	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	reposition front winch			12/02/2021	163203	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/02/2021	163203	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	weld rear bolster cracks	12/02/2021	163203	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/12/2020	163202	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/12/2020	163202	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Unknown - Unknown	Susp\DAMAGE	Replace RHF Spring Eye Bush			02/10/2020	162920	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	cables to quick release 3 broken			26/09/2020		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/09/2020	159895	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	EBS faults - reset front axle sensor and clean pulse wheel - test ok	19/09/2020	159895	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	removed bolsters move to 2900, welded stay blocks on redid wiring			01/09/2020	159330	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	replaced 1x winch strap			01/09/2020	159330	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			18/08/2020	159205	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/08/2020	159205	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\HOUSEKEEP	Fit cab guard			05/05/2020	159035	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\HOUSEKEEP	Fit winch bar & boom		fit rake hoe mounts	05/05/2020	159035	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			05/05/2020	159035	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	weld cracks	05/05/2020	159035	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	remove 2x bolsters			25/04/2020	159035	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\HOUSEKEEP	fit cab guard			25/04/2020	159035	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	fit 3rd winch and cable to rear bay			25/04/2020	159035	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
					rewired bolster lights											
					replaced reverse lights											
					adjust wheel bearings											
					weld cracks											
					replaced RHM bearing											
T270	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	shock strap - serial number 126934 - A50025/4540	11/03/2020	159033	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/03/2020	159033	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	hook up to S line	11/03/2020	159033	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\CHAS CRACK	crack lower chassis rail behind skid plate mount			11/03/2020	159033	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	repair bolster cracked inside mounting plate			11/03/2020	159033	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SHOCK ABS	LHF top shocker mount broken			11/03/2020	159033	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHR shocker			03/09/2019	159032	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			31/08/2019	157634	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tighten RHP spring eye bolt	31/08/2019	157634	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\STCH GUARD	Replace front stretch guard			29/08/2019	156032	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	no lights			28/08/2019	156005	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	tighten bolster bolts			06/08/2019	158890	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	fit release cable			06/08/2019	158890	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\STCH GUARD	fit chassis mat springs			06/08/2019	158890	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SUSPENSION	check and tighten spring, eye bolts, u bolts, nuts and shocker bolts and nuts			06/08/2019	158890	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SUSPENSION	Replace RHF Shocker Strap			03/08/2019	154890	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
					fit spring eye bushes to R&LH springs											
T270	Myrtleford - Workshop	Susp\SUSPENSION	Replace RHR Spring Wrap & FIT 2 X SPRING EYE BUSHES		fit spring wrap to RH spring	03/08/2019	154890	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/08/2019	153848	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tightened up spring eye bolts	02/08/2019	153848	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\DAMAGE	Repair or Replace Cab Guard Mounts At Front Of Trailer			31/07/2019	154891	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\WORK LIGHT	reverse lights not working			30/07/2019		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	light playing up still			30/07/2019		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/07/2019	147389	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	Order # L6685	VehService\DS	complete	20/07/2019	147389	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/07/2019	142706	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	Order # L6641	VehService\DS	completed trailer D Service	12/07/2019	142706	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/07/2019	137408	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	Order # L6604	VehService\DS	trailer service complete	06/07/2019	137408	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/06/2019	130521	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	Order # L6537	VehService\DS	completed D Service to attached checklist	29/06/2019	130521	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		recorded brake percentages	21/06/2019	122033	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	Order # L6467	VehService\DS	completed Service as per job	21/06/2019	122033	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	15/06/2019	115196	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	Order # L6417\6449	VehService\DS	completed	15/06/2019	115196	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		complete	08/06/2019	205439	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	Order # L6378	VehService\DS	complete	08/06/2019	205439	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/06/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	Order # L6301	VehService\DS		01/06/2019		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T270	Myrtleford - Workshop	Chassis\CHAS CRACK	repair skid plate cracks			30/05/2019	99866	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Wodonga - Workshop	Workshop\MOVE ASSET	drop trailer at Aldonga			30/05/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Wodonga Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		carry out brake check as per sheet	25/05/2019	212223	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	Order # L6264	VehService\DS	carry our D Service as per sheet	25/05/2019	212223	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T270	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice			19/05/2019	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Wodonga Workshop	TRAILER
T270	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			19/05/2019	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Wodonga Workshop	TRAILER
T270	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			19/05/2019	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Wodonga Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		complete	17/05/2019	86785	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	Order # L 6179	VehService\DS	complete	17/05/2019	86785	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed	10/05/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	L6136	VehService\DS	completed	10/05/2019		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			04/05/2019		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	Order # L6085	VehService\DS		04/05/2019		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	TWIN CITY TRUCK CENTRE - 3 - OLD	TRAILER
T270	Albury - Workshop	Chassis\CHAS CRACK	crack lower chassis rail behind skid plate mount			02/05/2019	66839	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Albury Workshop	TRAILER
T270	Albury - Workshop	Chassis\BOLSTER	repair bolster cracked inside mounting plate			02/05/2019	66839	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Albury Workshop	TRAILER
T270	Albury - Workshop	Brakes	Record Check Results As Attached To This Job			02/05/2019	66839	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Albury Workshop	TRAILER
T270	Albury - Workshop	VehService\DS	D Service	VehService\DS		02/05/2019	66839	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Albury Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/04/2019	61355	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/04/2019	61355	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SUSPENSION	RHF Spring Eye Bush			13/04/2019	57936	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/04/2019	56992	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/04/2019	56992	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\AIR LEAK	Air Fitting Leak			11/04/2019		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	broken peg			03/04/2019	52724	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			28/03/2019	51019	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit LHR top shocker bolt	28/03/2019	51019	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
					repair no plate wiring											
T270	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP	tighten RHM and LHM s/eye bolts	20/03/2019	50323	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace RHM spring eye bush			14/03/2019	47860	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/03/2019	46357	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/03/2019	46357	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/02/2019	41582	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/02/2019	41582	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\AIR BAG	middle LH airbag has a leak			12/02/2019	39834	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\HOUSEKEEP	LF shocker strap			06/02/2019	36570	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/02/2019	36570	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/02/2019	36570	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/01/2019	31465	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit new bolster clearance light	19/01/2019	31465	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/12/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/12/2018		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\CASE STOCK	Job Added From Invoice			11/12/2018	22429	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			11/12/2018	22429	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			11/12/2018	22429	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels			04/12/2018	22532	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/12/2018	22126	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/12/2018	22126	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER

T270	Myrtleford - Workshop	Susp\HOUSEKEEP	Repair LHF top spring saddle crack			27/11/2018	31465	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	DrCabElect\SCALES	Make up 600mm long scale extension cable			27/11/2018	20100	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			27/11/2018	14367	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\FIFTH WHEE	unhook from 861 and hook to 942, test lights/ETC			24/11/2018	19973	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/11/2018	19973	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	hook up to 942	24/11/2018	19973	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/11/2018	15802	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/11/2018	15802	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres	Job Added From Invoice			24/10/2018	12326	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			24/10/2018	12326	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			24/10/2018	12326	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			10/10/2018	8172	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			10/10/2018	8172	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			10/10/2018	10513	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/10/2018	10513	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	tyres fitted Orbost			20/09/2018	2486	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	tyres fitted Orbost			20/09/2018	2486	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			12/09/2018	5712	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	replace bolts in air tanks	VehService\DS		12/09/2018	5712	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	replace damaged trailer tyre			31/08/2018	2486	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	DrCabElect\SCALES	calibrate scales at CHH mill			24/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\REFLECTORS	remove and refit reflectors on the bolster and rear bumper			23/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
			check lights and repair													
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	FIT 2 X NEW LED TAIL LIGHT ASM			21/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\HOSES	extend air lines and tidy up hoses from t/table			21/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\PAINT/REST	paint bolsters and pegs and tail light bar			21/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\BRAKE ADJ	check brakes stuck on T270			21/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\STCH GUARD	refit stretch guard			21/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\HOUSEKEEP	Remove cab guard			17/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\AIR BAG	Replace 2 x airbags			17/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SHOCK ABS	Replace 2 x shocker straps			17/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\HOUSEKEEP	Wash trailer			17/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\MUDGUARDS	replace 2x mudguards			16/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\MUDGUARDS	repair and straighten outriggers			16/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\WHL HUB	fit new hubometer			16/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tightened RHM spring eye bolt	16/08/2018		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\TRL LEGS	Replace wind down legs			08/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	Move bolsters to 2.6mt spacings & add a third bay		replaced and painted bolster peg's	04/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\LELECT P&W	Wire in bolster lights			04/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
					make bracket for female socket											
T270	Myrtleford - Workshop	DrCabElect\SCALES	Fit Elphinstone scales to trailer		repair bark mat	04/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	Move winches to suit new bay spacings			04/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	Fit air winches to middle bay		fit x6 winches	04/08/2018		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	pin broken in back bolster		Fit new bolster bolt	20/07/2018	2371	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			20/07/2018	2370	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SHOCK ABS	LHF top shocker mount broken			20/07/2018	2370	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
					r&R tail light assembly x2											
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit bolt rear RH bolster	20/07/2018	2370	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\MOUNTS	L/H rear mudguard mount broken needs welding		repair LHR m/guard mount	06/07/2018		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			03/07/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\AIR BAG	Replace RHR air bag			27/06/2018	2351	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/06/2018	2349	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
					tighten RHM s/eye bolt											
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replace RHR clearance light on last bolster	26/06/2018	2349	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\MUDGUARDS	replace RHF mudguard			19/06/2018	493243	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
			repair bolster light plug in front bolsters													
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	check tralier			13/06/2018	492592	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/06/2018	490633	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/06/2018	490633	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/05/2018	485546	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tighten RHM s/eye bolt	15/05/2018	485546	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/04/2018	477671	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/04/2018	477671	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres	Job Added From Invoice			10/04/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			10/04/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			10/04/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	repair bolster wiring			28/03/2018	414948	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\MUDGUARDS	replace 2x mudguards after blown tyre			28/03/2018	414948	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\MOUNTS	replace outriggers x4			28/03/2018	414948	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\MUDGUARDS	fit new LHR mudguard and 4x brackets			28/03/2018	414948	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	replace front two straps old ones are frayed			27/03/2018	474517	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres	Job Added From Invoice			24/03/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			24/03/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			24/03/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			23/03/2018	473884	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	(RHM) missing spring eye nut (replaced)	23/03/2018	473884	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\STCH GUARD	Replace chassis cover mat & springs			17/03/2018	414948	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\WGHT GAUGE	Texta mark on trailer scales wrong		Driver to monitor	15/03/2018	470915	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\MUDGUARDS	Guard on RH5 loose		Fit mudguard tube & fit guard	15/03/2018	470915	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Hydraulics\WHEEL HUB	Fit weight gauge to LHS of trailer			07/03/2018	414948	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			06/03/2018	468621	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/03/2018	468621	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\HOUSEKEEP	need new broom or old one fixed			06/03/2018	468621	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	need to winch hook back on			06/03/2018	468621	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres	Job Added From Invoice			05/03/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			05/03/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			05/03/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres	Job Added From Invoice			14/02/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			14/02/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			14/02/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHF top shocker mount			09/02/2018	464000	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SHOCK ABS	LHF top shocker mount broken			08/02/2018	463343	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes			08/02/2018	463343	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP15	change tyres on middle axle		remove LHM rims from hub and fit 2x tyres	06/02/2018	462358	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels			01/02/2018	464000	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			31/01/2018	460585	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/01/2018	460585	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres	Job Added From Invoice			24/01/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			24/01/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			24/01/2018	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP18	change RHM outer tyre			16/01/2018	456043	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/01/2018	456290	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
			D Service As Per Attached Checklist													
T270	Myrtleford - Workshop	VehService\DS	fit log strap to front winch	VehService\DS		16/01/2018	456290	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	Test lights & check over			05/01/2018		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/12/2017	226056	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/12/2017	226056	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\BRAKE ADJ	adjust brakes			06/12/2017	447818	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\CROSS MBR	Repair crack in RHF cross member		hook up behind 835	22/11/2017	453271	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
			when pulled hand lever													
T270	Myrtleford - Workshop	Body\AIR LEAK	air comed out from trailer			21/11/2017	81138	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\HCV	Hcontrol rod and rubber worn & 90 deg. Bracket			21/11/2017	81138	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\HOUSEKEEP	replace broken ubolt LHM axle			21/11/2017	81138	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			21/11/2017	811138	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/11/2017	811138	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
			middle winch at rear													
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	hard to use- sticky, looks damaged			18/11/2017	80565	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	Drill out all bolster & peg mount bolts to 5/8"		repair bolster wiring	10/11/2017	445459	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\HOUSEKEEP	Repair crack			10/11/2017	445459	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\EBS Kit	check for EBS faults			09/11/2017	445459	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	bolt missing 2nd upright R/H/S			01/11/2017	443533	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\DAMAGE	weld cracks			01/11/2017	443533	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER

T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/11/2017	443533	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/11/2017	443533	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\CHAS CRACK	weld crack in LH bottom chassis rail behind skid plate			11/10/2017	438599	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection per the attached checklist			07/10/2017	438068	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			07/10/2017	438068	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/10/2017	438068	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SHOCK ABS	Replace RHF top shocker bush			20/09/2017	435453	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			19/09/2017	433005	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/09/2017	433005	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres	Job Added From Invoice			14/09/2017	430299	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres	Job Added From Invoice			14/09/2017	429804	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\CHAS CRACK	L/H/S crack in chassis			08/09/2017	42980	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2017	427991	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/09/2017	427991	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\EBS Kit	check trailer ebs system			31/08/2017	426753	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	fit (srt) tape to bolster pegs			31/08/2017	426753	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\PANELS	sign at back of trailer falling off			26/08/2017	424923	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
					check bolster bolts											
T270	Myrtleford - Workshop	Chassis\BOLSTER	front R/H/S bolt missing from upright		replace missing bolt	24/08/2017	423976	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			22/08/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/08/2017	422975	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/08/2017	422975	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\WORK LIGHT	Wire up rear reverse lights			15/08/2017	42120	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	no pin in rear upright pegs			08/08/2017	417525	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			08/08/2017	417525	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/08/2017	417525	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\EBS Kit	program EBS			22/07/2017	413855	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\EBS Kit	check and engineer trailer			22/07/2017	413855	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			11/07/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			24/06/2017	409787	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/06/2017	409787	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	RHS bolster needs nut & bolt so it doesn't pull out back one			22/06/2017	407762	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\BACK PLATE	Replace LHR top backing plate			16/06/2017	412855	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SHOCK ABS	Replace LHF shocker bush			16/06/2017	412855	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace LHF spring eye bush			16/06/2017	412855	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\EBS Kit	FIT EBS KIT TO FRONT & REAR AXLES			15/06/2017	412855	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/06/2017	404462	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
					tighten RHM s/eye bolt											
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tighten LHR shocker bolt	15/06/2017	404462	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\PRES CHECK	Job Added From Invoice			07/06/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\ELECT P&W	reverse lights do not work			27/05/2017	398370	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\HOUSEKEEP	broom handle broken/splintering			27/05/2017	398370	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/05/2017	398370	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/05/2017	398370	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres	Job Added From Invoice			19/05/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			19/05/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			19/05/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			13/05/2017	393359	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/05/2017	393359	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	rear most strap worn badly			11/05/2017	392111	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	front strap starting to fray			11/05/2017	392111	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres	Job Added From Invoice			10/05/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\FITMENT	Job Added From Invoice			10/05/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\RETREAD	Job Added From Invoice			10/05/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	no left side brake light and trail light			02/05/2017	388692	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	replace broken peg bolt 3rd RHS			02/05/2017	388692	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\HOUSEKEEP	fit new broom and handle			28/04/2017	388187	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\FIFTH WHEE	hook up to T270			28/04/2017	388187	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	test lights			28/04/2017	388187	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			27/04/2017	387828	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/04/2017	387828	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	Fit new winch strap to Middle rear		Complete	26/04/2017		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice			14/04/2017	38276	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP12	Job Added From Invoice			07/04/2017	382289	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\MUDGUARDS	repair LHR outrigger			01/04/2017		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	fit new clearance light			01/04/2017		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/04/2017	382289	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/04/2017	382289	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP16	Job Added From Invoice			29/03/2017	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	fit new strap - front strap on back bay			23/03/2017	3795	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\HOUSEKEEP	Replace LHM spring eye bush		weld in 2x new spring eye bushes and fit eye bolt and bush	17/03/2017	380364	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			16/03/2017	377442	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	(front bolster) L&R peg bolts broken (replaced)	16/03/2017	377442	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TRANS OIL	Job Added From Invoice			10/03/2017	375832	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			25/02/2017	372971	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/02/2017	372971	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			02/02/2017	368171	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/02/2017	368171	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice			01/02/2017	367516	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice			31/01/2017	365049	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	need a new strap on back bay and hock to be welded on middle strap as well			31/01/2017	365453	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/01/2017	365846	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
					fit alignment plate to LH side spring & weld to position											
					repair no plate wiring & weld logs for wiring											
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	weld cracks to LHF + RHF axle	11/01/2017	365846	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SPRNG HANG	Repair LH & RHF spring saddle cracks			16/12/2016	364650	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/12/2016	362238	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/12/2016	362238	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit 4 chassis mat springs	01/12/2016	359133	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			01/12/2016	359133	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			26/11/2016	356688	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/11/2016	355649	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			15/11/2016	355649	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
			check R/H taillight (plug)													
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	fit new plugs to wiring			04/11/2016		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\MUDGUARDS	weld outriggers			22/10/2016	350150	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\SPAREWHEEL	weld spare wheel carrier			22/10/2016	350150	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	rotate LHR bolster peg			22/10/2016	350150	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		21/10/2016	350150	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels			15/10/2016	350150	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	DrivLine\SPRNG HANG	Weld LHM spring saddle cracks			12/10/2016	35700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/10/2016	347008	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/10/2016	347008	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			22/09/2016	341650	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/09/2016	341650	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
					+bushes											
T270	Myrtleford - Workshop	Susp\SHOCK ABS	Replace RHF shocker strap		replace bolster peg bolts	10/09/2016	35700	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/09/2016	337411	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/09/2016	337411	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice			01/09/2016	332676	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice			01/09/2016	332427	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/08/2016	332246	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/08/2016	332246	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	replace peg bolts L/H bolster 2,3+4			25/08/2016	331873	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			09/08/2016		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
					repair LHF backing plate											
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	tighten LHR top shocker bolt	09/08/2016		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			30/07/2016	322928	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			30/07/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice			30/07/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			26/07/2016	322921	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/07/2016	322921	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\WORK LIGHT	Check RH Reverse light		Complete	22/07/2016	3219	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\STCH GUARD	Replace springs on stretch guard. Replace springs on stretech guard		Complete	22/07/2016	3219	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER

T270	Myrtleford - Workshop	Tyres\TP14	Job Added From Invoice				22/07/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP17	Job Added From Invoice				22/07/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	Replace 4 x bolster peg bolts				19/07/2016	320418	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace load strap no. 5				19/07/2016	320418	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				12/07/2016	317589	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			12/07/2016	317589	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\STCH GUARD	replace missing tarp spring				08/07/2016	316658	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TPS1	Job Added From Invoice				05/07/2016	315536	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	Repair broken peg bolt LHR Repair mudguard		Complete		22/06/2016	315240	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\MUDGUARDS	Replace mudflap LHR		Complete		22/06/2016	315240	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	Repair light bracket		Complete		22/06/2016	315240	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Insp\INT INSP	srt measurements				21/06/2016		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				09/06/2016	313006	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			09/06/2016	313006	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\PANELS	Missing spring on corner of bark tarp between chassis		Replace tarp spring Complete		03/06/2016	311785	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice				28/05/2016	308443	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice				28/05/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP19	Job Added From Invoice				28/05/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/05/2016	309033	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/05/2016	309033	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				04/05/2016	304759	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			04/05/2016	304759	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	broken winch				03/05/2016	304213	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	LHR bolster peg bolt broken				22/04/2016	302028	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\AIR FITTIN	repair air leak - fit 3/8' airline fitting to LHR airbag				22/04/2016	302028	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		weld in cracks in x-member in front hangers L+R sides + L+R side at legs on chassis		15/04/2016	301084	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			15/04/2016	301084	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	2nd bolster LHS upright needs a bolt		reline middle & rear axles only front axle ok		04/04/2016	297791	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\BRK RELINE	Crack test & reline all wheels		fit 2nd hand landing leg feet		30/03/2016	297139	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				25/03/2016	296790	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			25/03/2016	296790	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				10/03/2016	293708	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			10/03/2016	293708	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	replace 3 broken bolts 2nd 3rd & last bolster pegs LH side. replace 3 broken bolts 2nd 3rd & last bolster pegs LH side on bolste				02/03/2016	289705	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				29/02/2016	288712	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			29/02/2016	288712	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice				26/02/2016	892582	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice				26/02/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice				26/02/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				18/02/2016	286698	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Removed rims, inspected Hubs and spacers Re-fitted wheels evenly		18/02/2016	286698	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TRA	Rear axle tyres need re-truing		COMPLETED		12/02/2016	283672	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SUSPENSION	replace LHM spring eye bush				09/02/2016	282322	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			08/02/2016	282232	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				08/02/2016	282232	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	Replace centre rear winch		Completed		08/02/2016	282322	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice				06/02/2016	280399	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice				06/02/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP13	Job Added From Invoice				06/02/2016	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job				22/01/2016	279163	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replace broken bolt		22/01/2016	279163	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	repair rear LHS bolster peg		completed		21/01/2016	278710	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	supply parts		completed		15/01/2016		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\MOUNTS	RHM outrigger needs lifting up		completed		13/01/2016	275928	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\ELECT P&W	rewire trailer front to rear		complete		08/01/2016	275582	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\AIR LEAK	air tube / rubber		completed		08/01/2016		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\PAINT/REST	steel for repairs steel for repairs				06/01/2016		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\PANELS	brankos plug+side marker+cable				25/12/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\ELECT P&W	mae parts		completed		24/12/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Body\DAMAGE	rinlatech		completed		19/12/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\WINCH/STRP	replace 2nd hold down strap		completed		17/12/2015	275032	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed		09/12/2015	272627	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist supply 6 pegs	VehService\DS	completed		09/12/2015	272627	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	rinlatech remove & crack test all bolster pegs		completed		08/12/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\BOLSTER	replace 3 x pegs - 2nd, 3rd & 4th pegs on RHS		completed		08/12/2015	272626	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\ELECT P&W	glue rh indicator in place		completed		01/12/2015	271289	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed		25/11/2015		Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed		25/11/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect\TRL LIGHTS	repair/replace rhs clearance light		completed		24/11/2015	268564	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice				21/11/2015	267058	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice				21/11/2015	267058	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP21	Job Added From Invoice				21/11/2015	267058	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\FIFTH WHEE	repair cracked bottom flange on skid plate		completed		12/11/2015	26458	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed		12/11/2015	265300	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed		12/11/2015	265300	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice				11/11/2015	167036	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP11	Job Added From Invoice				11/11/2015	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Tyres\TP15	Job Added From Invoice repair cracks				11/11/2015	167036	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\CROSS MBR	rinl		completed		06/11/2015		Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\AIR FITTIN	replace air line on trailer		completed		06/11/2015	262052	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\MUDGUARDS	straighten lhs front mudguard pipe		completed		31/10/2015	59092	Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		completed		29/10/2015	260053	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed		29/10/2015	260053	Service	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Chassis\SUSPENSION	Job Added From Invoice				23/10/2015	0	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Brakes\BRK RELINE	crack test + reline front axle		completed		17/10/2015	257931	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SHOCK ABS	replace rhf top shocker mount		completed		17/10/2015	257931	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist replace slack adj to rhr	Insp\ANN INSP	completed		16/10/2015	257931	PreventativeMaintenance	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp	fit new broom		completed		16/09/2015		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Elect	repair short in taillights + sidelights		completed		05/09/2015		Fault	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER
T270	Myrtleford - Workshop	Susp\SHOCK ABS	reweld lhf shocker shield		completed		02/09/2015	257931	Repair	Completed	Greenfreight Logging Vic	KennedyBPW	Myrtleford	MTK	43134S	Myrtleford Workshop	TRAILER