EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T393	Albury - Workshop	VehService\DS	D Service	VehService\DS		08/09/2025	13243	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes\EBS FAULTS	LF WHEEL SPEED SENSOR CONTINUITY FAULT.			19/04/2024		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			19/04/2024		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/04/2024		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			05/08/2022		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/08/2022		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Body\STRAPS	Air leak at rear winch			26/01/2022		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\EXTE TU	AIR WINCH LEAKS AIR			26/01/2022		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			22/01/2022		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/01/2022		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP5+6	supply and fit 2 tyres			15/01/2022		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		CARRIED OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 13/1/21	12/01/2022		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/01/2022		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			08/01/2022		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/01/2022		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			25/12/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Rosewood Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/12/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Rosewood Workshop	TRAILER
T393	Wodonga - Workshop	Brakes\AIR LEAK	LOOSING AIR TOO QUICKLY		DIAGNOSED AND REPLACED BOOSTER HOSE CLAMPS.	21/12/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			18/12/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/12/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP11	puncture repair			17/12/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	Body	REAR BUMPER NEEDS PULLING OUT BECAUSE THE MUDFLAP BOLTS ARE RUBBING ON THE TYRES		MADE ADJUSTMENTS TO REAR BAR SO THAT THE MUDFLAP BOLTS DON'T RUB TYRES.	16/12/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		ADJUSTED SUSPENSION HEIGHT	11/12/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/12/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes\AIR LEAK	LEAKS AIR			11/12/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAKS			11/12/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Unknown	SERVICE.			11/12/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Unknown	SERVICE			11/12/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 3/12/21	04/12/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/12/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			26/11/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/11/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes\AIR LEAK	TRAILER LEAKS AIR.		TIGHTENED CLAMPS	26/11/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Unknown	SERVICE			26/11/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			19/11/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/11/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 5/11/21			06/11/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			27/10/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/10/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP11+12	supply and fit 2 tyres			22/10/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP9+10	supply and fit 2 tyres			14/10/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			14/10/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			14/10/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			09/10/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			09/10/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\BOLSTER	LNR Bolster pivot broken.			09/10/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Body\MUDGUARDS	REPAIRED LHF GUARD BENT IN TOWARDS TYRES AND REPLACED MUD FLAP BOLTS WITH SHORTER BOLTS TO PREVENT GOUGING TYRES. ATTEMPTED TO BEND RHR OUT TO S			30/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP1+2	supply and fit 2 tyres			30/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			29/09/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			29/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Body\MUDGUARDS	FIT SECOND HAND RHF MUDFLAP			18/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Drivline\WHEEL BRGS	ADJUSTED LHM WHEEL BEARING.			18/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Tyres\TP01	supply and fit 1tyre Perform laser wheel alignment			18/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Steering\WHEEL ALGN	Repair two aligning plates			18/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	Body\MUDGUARDS	CUT MUDGUARD OUT RIGGER OUT OF CHASSIS. CLEANED RAILS. MADE MOUNT BRACKET. WELDED. ADJUSTED GUARD AND RE-ATTACHED STRETCH GUARD.		Repaired Damage, replaced damaged/worn pivot arms, mounts and bushes. Removed LH guard for repairs(Damaged)	15/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\DAMAGE	Damaged Mudgaurds and Brackets. Angle required for repair. Don Sparks Steel		Adjusted Altered RH Stretch guard.	14/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\DAMAGE	PO# WW067111			14/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Body\DAMAGE	Check over Damage. Check over			10/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Insp\INT INSP	Write list of jobs required.			10/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Tyres\TP5+6	supply and fit 2 tyres			09/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist		CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 31/8/21	01/09/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		* Raised & supported middle & rear axle * Removed required wheel equipment * Removed/replaced brake linings as required * Inspected & found all wheel bearings to have wear * Removed/replaced all wheel bearings for axles * Found L/H front stub had some wear * Reinstalled all wheel equipment * Adjusted wheel bearings & brakes * Lowered down axles & tensioned wheels * Road tested trailer then reinspected	01/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRK RELINE	CARRY OUT BRAKE RELINE ON MIDDLE & REAR AXLE		* Repair complete	01/09/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\BOLSTER	Removed and replaced LH bolster pivot ram.			29/08/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			27/08/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/08/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\BOLSTER	LNR Bolster pivot broken.			27/08/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			19/08/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/08/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP3+4	Supply and fit 4 tyres			13/08/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			13/08/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			12/08/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/08/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Workshop\CLEAN	CLEAN WORKSHOP			12/08/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			06/08/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/08/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\WINCH/STRP	Remote release cable is broken.		Doesn't get used (back Bay in the middle)	06/08/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\MUDGUARDS	L/H Mudguard is push back.			06/08/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Unknown	Service due.		Refer job# 348924	06/08/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\MUDGUARDS	L/H Mudguard is push back.			30/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			30/07/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\WINCH/STRP	Remote release cable is broken.			30/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\WINCH/STRP	Lubricte winches		DISMANTLED AND LUBRICATED ALL WINCHES	30/07/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\EXTE TU	Service winches.		#348262	30/07/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			27/07/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\WINCH/STRP	Remote release cable is broken.			27/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\WINCH/STRP	Lubricte winches			27/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\MUDGUARDS	L/H Mudguard is push back.			27/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\EXTE TU	Service winches.			27/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Unknown	Service due.		Refer Job# 347771	27/07/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\AIR LEAK	Repaired air leak in chassis rail.			27/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes\AIR TANKS	Replaced 2nd air tank drain cock valve.			27/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP1+2	Supply and fit 1 tyre			24/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 20/7/21	21/07/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Unknown	Service way overdue.			21/07/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Unknown	Service due			21/07/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP7+8	replace 2 tyres			16/07/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Susp\AIR LEAK	Air leak at HCV		Replaced height control valve.	30/06/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Susp\AIR LEAK	Air leak appears to be coming from height control valve. Service As Per Attached Checklist Repaired Air leaks at 1st air tank. Replaced hose clamps x 2 at 1st tank.			30/06/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Replaced damaged air hoses left hand side chassis rail.			24/06/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		REPAIR AIR LEAKS AS REQUIRED. * Inspected & diagnosed air leaks * Found fitting leaking above front axle * Removed fitting & replaced o-ring inside * Reinstalled fitting with sealant * Tested for anymore leaks/all ok	24/06/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Susp\AIR LEAK	air leak Attempt to change RHF 30K. Nut seized refered to TCTC.		* Repair complete Repaired Air leaks at 1st air tank. Replaced hose clamps x 2 at 1st tank.	24/06/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\AIR LEAK	Air leaks.		Replaced damaged air hoses left hand side chassis rail.	24/06/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Unknown	Service due.			24/06/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP9+10	Supply and fit 2 tyres			19/06/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist			13/06/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/06/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service air leak		Refer Job # 342763	13/06/2021		Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Susp\AIR LEAK	Attempt to change RHF 30K. Nut seized refered to TCTC. called out to Tumbarumba, airbags flat diagnosed blown RHF airbag			13/06/2021		Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Rosewood - Workshop	Susp\BREAKDOWN	used temporary glue to stop air flow to blown bag only and inflate			12/06/2021		Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Rosewood Workshop	TRAILER

T393	Rosewood - Workshop	Susp\AIR BAG	contacted Chris Jones (Wodonga workhsop not answering) to advise replacement of bag needed before truck goes to work next week	REPLACE RHF AIR BAG . * Inspected & diagnosed leaking air bag * Drained air from air system * Supported chassis * Removed air lines & fittings * Removed/replaced air bag * Reinstalled fittings & air lines * Removed supports from chassis * Tested for air leaks/all ok * Repair complete	12/06/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Rosewood Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		05/06/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		05/06/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Unknown	Service Due.		05/06/2021	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		03/06/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		03/06/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Rosewood - Workshop	Chassis\BOLSTER	front left bolster pin	turn LHF bolster following poor unloading at Hyne	27/05/2021	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Rosewood Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		25/05/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		25/05/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service Due.		19/05/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Body\STRAPS	Lubricate winches.		19/05/2021	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Body\AIR LEAK	air leaks		19/05/2021	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
				Carried out trailer service as per service sheet.											
				* During service found loose RH 2nd bolster bolt and cracked bolster bolt tightened and crack weld.											
				* Loose LH front bracket for stretch guard – tightened loose bolt.											
				* LH side 2nd bolster cracked & loose bolts x2 – tightened bolts, crack weld.											
				* LH side 1st bolster cracked weld.											
				* 2nd axle LH booster hose cracked – replaced booster hose with new clamps.											
				* 1st axle LH shock loose – tightened.											
			Service	* Found a bubble inner tyre.											
				* LHM axle wheel bearing lock nut replaced to remove wheel movement.											
T393	Wodonga - Workshop	VehService\DS	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 19/5/2021.	* Found a broken reflector – reelaced.	19/05/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
				Tightened loose bolsters											
T393	Wodonga - Workshop	Body\BOLSTER	REPAIR LOOSE BOLSTERS & TIGHTEN LOOSE BOLTS IN STRETCH GUARD AS REQUIRED	* Tightened loose bolts in guards	19/05/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes\BOOSTER	REPLACE CRACKED BOOSTER HOSES	Replaced cracked booster hose on L/H 2nd axle	19/05/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Susp\SHOCK ABS	REPAIR LOOSE L/H FRONT SHOCKER AS REQUIRED	Tightened loose shocker as required	19/05/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
				1GREENLOGTRAILER											
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET - 1/5/21	02/05/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		02/05/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Chassis\STRAPS	Back two winches getting hard to wind up		02/05/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Unknown	Service Due.		02/05/2021	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Unknown	Service due.		02/05/2021	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP13+12	Supply and fit 2 tyres		01/05/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		24/04/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record check Results As Attached To This Job		24/04/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		16/04/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		16/04/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRAKE ADJ	brake adjustment	adjusted brakes	13/04/2021	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	Service As Per Attached Checklist		10/04/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		10/04/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Susp\AIR BAG	Replace Right hand Rear 30K Airbag		10/04/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP9+10	Supply and fit 2 tyres		08/04/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\AIR BAG	TCTC Supply Airbag	Replace 30K airbag	01/04/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	Susp\AIR BAG	replace 30K airbag		31/03/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Workshop\CLEAN	clean up		31/03/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
				TCTC											
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist	CARRY OUT GREENFREIGHT LOG TRAILER D-SERVICE AS PER ATTACHED SERVICE SHEET 30/3/2021	27/03/2021	Service	Completed	Greenfreight Loggine NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job	Grease	27/03/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Trailer Service		14/03/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	bolster pegs		14/03/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		14/03/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist		07/03/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		07/03/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	Tyres\TP5+6	Supply and fit 2 tyres		04/03/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP04	Fit Run out		02/03/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\STRAPS	Supply Strap 75mm x 9m		02/03/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist	repaired 2nd bolster lights	28/02/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		28/02/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\STRAPS	move to another position the on/off valve on the back air winch	relocate rear winch tap	25/02/2021	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\STRAPS	re-fitted 4th winch tap to better access point. Replaced air lines		25/02/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\AIR LEAK	repaired air leaks at rtr valve		25/02/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
				replaced maxi- valve and fittings											
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist	replaced bolster wear pads and pivot bushes	17/02/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		17/02/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP06	fit run out		12/02/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
				replaced 1st and 3rd straps											
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist	reolaced no. olate (returned to DS)	10/02/2021	Service	Completed	Greenfreight Loggine NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/02/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\CONSUMABLE	Supply Non Hydraulic Pivot Arm, Wearing Bush & Spacer Washer		05/02/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
				dismantled, cleaned lubed and reassembled rear winch											
T393	Albury - Workshop	Chassis\WINCH/STRP	replace rear winch	test ok	04/02/2021	Fault	Completed	Greenfreight Loggine NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
				replaced RHR outer bolster pivot											
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist	tightened tail bar	04/02/2021	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		04/02/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\MUDGUARDS	Supply Shield-Mudflap and warning plates		30/01/2021	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
				unhook from A											
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist	tightened LHF sebolt	13/12/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		13/12/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	Brakes\AIR LEAK	replaced/repaired booster lines		08/12/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist		08/12/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		08/12/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist	tightened LHM sebolt	20/11/2020 13243	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		20/11/2020 13243	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist		13/11/2020 13243	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		13/11/2020 13243	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	please replace rear winch (no good). plase replace rear winch (no good)		05/11/2020 13243	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		05/11/2020 13243	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\MUDGUARDS	bolts missing rear mudflaps		05/11/2020 13243	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
				lubed and repaired rear winch											
				secured rear mudflaps											
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist	repaired 2nd bolster light wiring	05/11/2020 13243	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		05/11/2020 13243	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\ABS	ABS codes		05/11/2020 13243	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\AIR BAG	LH airbag		05/11/2020 13243	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
			Gordo at Rosewood Depot												
T393	Rosewood - Workshop	Tyres\BREAKDOWN	fitted 2x new cao tvres to R/H rear axle	chanae tvre	29/10/2020 13243	Fault	Completed	Greenfreight Loggine NSW	ElpsBPW	Albury	ATK	YV49IX	Rosewood Workshop	TRAILER
T393	Rosewood - Workshop	Tyres\DAMAGE	Gordo at Rosewood Depot fitted 2x new cup tyres to R/H rear axle		29/10/2020 13243	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Rosewood Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		27/10/2020 13243	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		27/10/2020 13243	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service As Per Attached Checklist		21/10/2020 13243	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		21/10/2020 13243	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\ABS	ABS codes		21/10/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\AIR BAG	LH airbag		21/10/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	PO FOR BOLSTER-AWAITING FOR WO		15/10/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\HOUSEKEEP	PO FOR MULTIPLE PARTS AWAITING ON WO		15/10/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	trailer service		14/10/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	replace 3rd bolster (complete unit)		14/10/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		14/10/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
				repaired RH outrigger											
T393	Albury - Workshop	Chassis\MUDGUARDS	please replace right side stretch guard	reolaced damaed stretch auard	11/10/2020	Fault	Completed	Greenfreight Loggine NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Workshop\CLEAN	cleaned up after job completion		11/10/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Trailer Service		29/09/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\MUDGUARDS	tension stretch guard		29/09/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		29/09/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	Body\REFLECTORS	Job Added From Invoice		27/09/2020 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		20/09/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		20/09/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\CHN/RUB/MN	fit new tie down chain		12/09/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		11/09/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\AIR LEAK	repaired air leak at middle axle		11/09/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		11/09/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		06/09/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\TRL LIGHTS	repaired 4th bolster light wiring		06/09/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		06/09/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BOOSTER	check air line booster front axle	repaired booster lines	05/09/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\WORK LIGHT	rear bolster lights out		05/09/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
			replaced rear axle												
T393	Albury - Workshop	Susp\AXLES	replaced alainment plates. u-bolts. shocks and bolts		01/09/2020	Repair	Completed	Greenfreight Loggine NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\WORK LIGHT	replaced rear bolster lights		01/09/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
			removed x-member, repaired and refit												
T393	Albury - Workshop	Chassis\CROSS MBR	(damaged hold down eyelet)		30/08/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Drivline\WHEEL ALGN	WHEEL ALIGNMENT AT HTT		29/08/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
			assembled abs system for rear axle												
T393	Albury - Workshop	Brakes\ABS	checked for function. Cleared codes		28/08/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\CROSS MBR	repaired crossmember		28/08/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\TRL LIGHTS	replaced rear bolster lights		28/08/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\HOUSEKEEP	manufactured cable mounts		22/08/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\AXLES	removed rear axle		19/08/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\AIR LEAK	repaired air leaks		19/08/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER

T393	Albury - Workshop	Brakes\AIR FITTIN	hooked up. Diagnosed and replaced service relay valve		18/08/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\AIR FITTIN	replaced maxi valve		18/08/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\HOUSEKEEP	washed out chassis		18/08/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		29/07/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		29/07/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		23/07/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		23/07/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		23/07/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\WORK LIGHT	repaired wiring to work lights		18/07/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\AIR LEAK	air leak	locate air loss replace centre axle	14/07/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Carry out trailer Service		09/07/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\MUDGUARDS	straighten RH guard assembly		09/07/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\AIR LEAK	repaired air leak at front tank		09/07/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		09/07/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		25/06/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	dismantled and lubed rear winch		25/06/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\AIR BAG	LH airbag		25/06/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		25/06/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\TRL LIGHTS	side lights and rear park lights out		21/06/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	DrivLine\WHEEL ALGN	laser wheel alignment		10/06/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	DrivLine\WHEEL ALGN	laser wheel alignment completed at HTT		10/06/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	DrivLine\WHEEL ALGN	perform laser wheel alignment		06/06/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Brakes\BOOSTER	PO FOR BOOSTER		03/06/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SUSPENSION	PO FOR PARTS		28/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	DrivLine\AXLE REPLC	refit new axle		26/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WHEEL BRGS	removed seized wheel bearing		23/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
				ordered replacement axle										
T393	Albury - Workshop	DrivLine\AXLE REPLC	found axle journals too worn and machined	removed axle resaired lines	23/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		15/05/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		15/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
				Checked codes, Attemted to repair fault in RHF hub sensor. Found bearing failed & seized. Unable to remove in time frame, suspect damaged axle.										
T393	Albury - Workshop	Brakes\ABS	ABS codes	Unhooked trailers from prime mover & hooked it up to T400/401	15/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	PO FOR STRAPS		15/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\TAIL LIGHT	replaced LH reverse light		09/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\MUDGUARDS	PO FOR MUDFLAP		08/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		07/05/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	lubed all winches		07/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		07/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\TRL LIGHTS	PO FOR TRAILER LIGHTS		07/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
				diagnosed and repair open circuits in wiring										
T393	Albury - Workshop	Elect\TAIL LIGHT	no tails rear bumper lights	reolaced marker. marker holder. liehts rubbers and reverse. brake/tail liehts	03/05/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\AIR FITTIN	repaired leaks in suspension lines & FITTINGS		01/05/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		24/04/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		24/04/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\ABS	checked ABS codes		22/04/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
			re-fitted sensor and adjusted. Cleaned plugs											
T393	Albury - Workshop	Brakes\ABS	tested and cleared codes		22/04/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		19/04/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\ABS	removed LHF wheel and replaced ABS sensor		19/04/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		19/04/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	trailer service		10/04/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\EBS FAULTS	EBS - wheel bearings		10/04/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/04/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		03/04/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		03/04/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	back bay rear winch hard to turn		02/04/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		02/04/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		26/03/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		26/03/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRK RELINE	Reline 3 hubs		14/03/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Chassis\AIR LEAK	air leak near back axle back button in	air leak	13/03/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service	trailer service	13/03/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		13/03/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\ELECT P&W	repaired wiring at tail bar		10/03/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\TRL FLOOR	no rear tail lights		10/03/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\TRL REPS	check rear bumper plug I cleaned it		10/03/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Trailer Service		05/03/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		05/03/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		05/03/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		28/02/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	lubricated winches		28/02/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Engine\HOUSEKEEP	tightened cross member		28/02/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		28/02/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	back bay rear winch need lube if time		27/02/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		27/02/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		19/02/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		19/02/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\ABS	Service check abs please trailers not trailing true		19/02/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SUSPENSION	olease check a/c sorine eve bushes		19/02/2020	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	replace strap	ordered new strap	08/02/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	carry out trailer service		08/02/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		08/02/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		24/01/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		24/01/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Body\STRAPS	raise PO for 75mm strap 3rd winch		24/01/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Elect\TAIL LIGHT	Repaired Wiring To RH Tail Light		21/01/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\SUSPENSION	tightened RR bottom airbag bolts		17/01/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		17/01/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		17/01/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	carry out trailer service		03/01/2020	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\HCV	re-set ride height		03/01/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	turn bolster pegs		03/01/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\AIR FITTIN	replace various lines		03/01/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		03/01/2020	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		15/12/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	lubed rear winch		15/12/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		15/12/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		08/12/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	TEST RESULTS		08/12/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		01/12/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	TEST RESULTS		01/12/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		29/11/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\WHEEL BRGS	R/H front wheel bearing runnig hotter than all other bearings		29/11/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		22/11/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	TEST RESULTS		22/11/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	TURNED LEFT 3RD & 4TH PEGS		22/11/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		21/11/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	TEST RESULTS		21/11/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	TURNED LEFT 3RD & 4TH PEGS		21/11/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\STCH GUARD	REPLACED LH STRTCHED GUARD		20/11/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		15/11/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes			15/11/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\TRL LIGHTS	REPAIRED FRONT BOLSTER LIGHT EIERING		15/11/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		08/11/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes			08/11/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		30/10/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		30/10/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\TRL ROLLBK	replaced quick release cable and cable eyelet		30/10/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		25/10/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes			25/10/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		22/10/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		09/10/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes			09/10/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Engine\FAULT CODE	CHECKED FOR ABS CODES ;; NIL		09/10/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\ABS	ABS TRAILER LIGHT COMING ON		04/10/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Engine\FAULT CODE	HOOK UP LAP TOP	CHECK FOR CODES	04/10/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	LUBRICATED WINCHES		01/10/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		28/09/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes			28/09/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SHOCK ABS	REMOVED BROKEN SHOCKER STRAP		28/09/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes			21/09/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		21/09/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		14/09/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BOOSTER	replaced LHR B/booster		14/09/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		14/09/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Wodonga - Workshop	VehService\DS	D SERVIES		08/09/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Wodonga - Workshop	Brakes			08/09/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	please lube winches		04/09/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\INDICATORS	R/H blinker globe out somewhere		04/09/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		31/08/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\TAIL LIGHT	repaired tail lights wiring		31/08/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	turned bolster pegs		31/08/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		31/08/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRK RELINE	reline	Previously completed	30/08/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRK RELINE	brake reline	Previously completed	30/08/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRK RELINE	brake reline	Previously completed	30/08/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	Fit winch extension to 2nd and 3rd winches		30/08/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49IX	Albury Workshop	TRAILER

T393	Albury - Workshop	Body	fit winch extensions 2nd & 3rd winch	Previously completed	30/08/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\WHEEL ALGN	Wheel alignment	previously completed	30/08/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Steering\WHEEL ALGN	wheel alignment	Previously completed	30/08/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\HOUSEKEEP	PAINT TRAILERS	Driver request	30/08/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\WORK LIGHT	clearance light R/H rear	Previously completed	30/08/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\ELECT P&W	RH rear clearance light broken	previously completed	30/08/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\BRAKE ADJ	brakes coming on unnecessarily	previously completed	30/08/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\DRV TYRES	L/H outside middle axle tyre worn on outside only premature and uneven wear	previously completed	30/08/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\HOUSEKEEP	all air winches hard to wind up	Previously completed	30/08/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\WINCH/STRP	both winches very tight		22/08/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		22/08/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		22/08/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\WINCH/STRP	lube rear bay winches		22/08/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		22/08/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Wodonga - Workshop	Brakes	Brake test resuts attached		13/08/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER			
T393	Wodonga - Workshop	VehService\DS	D Service wheel bearings seized removed failed hub. Clean up axle		13/08/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER			
T393	Albury - Workshop	DrivLine\WHEEL BRGS	replaced hub, drum, studs, nut and wheel bearings		07/08/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		07/08/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	DrivLine\WHEEL BRGS	check wheel bearings		07/08/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		07/08/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	Service		03/08/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		28/07/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\WGHT GAUGE	checked for codes		28/07/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\BOLSTER	turned LHR bolster peg		28/07/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		28/07/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Wodonga - Workshop	VehService\DS	D Service		21/07/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER			
T393	Wodonga - Workshop	Brakes			21/07/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER			
T393	Wodonga - Workshop	Brakes\EBS FAULTS	Checked & cleared EBS faults		21/07/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER			
T393	Wodonga - Workshop	DrivLine\WHEEL BRGS	Adjusted RHF wheel bearings		21/07/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		10/07/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\HOUSEKEEP	tightened LHM and LHR sebolts		10/07/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SHOCK ABS	tightened RHF & LHM shockers		10/07/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/07/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Wodonga - Workshop	Chassis\CHAS CRACK	Crossmember broken from tiedown chain.	Removed crossmember from out of service trailer, modified & fitted to trailer	03/07/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		26/06/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\CONSUMABLE	replaced 3rd NXP and bush		26/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\BOLSTER	replaced loose bolster clamp bolts		26/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\ABS	checked ABS codes		26/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\BOLSTER	checked wheel bearings		26/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	DrivLine\WHEEL BRGS	adjusted LR		26/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		26/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		16/06/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		16/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SPRING PACK	please replace broken spring R/H/rear		13/06/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SPRING PACK	removed and replaced broken spring RHR		13/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\CONSUMABLE	fitted new u-bolts, nuts, washers		13/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	DrCabElect\INST/GAUGE	volt meter globe not working and as per previous R&R116095		12/06/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\EBS FAULTS	EBS erratic in L/H comes when loaded		12/06/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\MIRRORS	mirror heaters not working a, hazzard report will be entered for this as it is a safety issue on night shift		12/06/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\MIRRORS	mirror heaters not working		12/06/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\EBS FAULTS	EBS comes on heavy on L/H corners (when loaded inconsistently) only relined RHR-LHR	diagnosed and replaced faulty wheel sensors - cleaned codes and tested	12/06/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\BRK RELINE	removed and replaced RH-LH cam's		12/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	DrivLine\WHEEL BRGS	replaced LH bearing's		12/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\BRK ROTOR	replaced RH drum		12/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	DrivLine\WHL HUB	tensioned wheel nut's		12/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\AXLE CT	crack tested axle and inspected hub's		12/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		07/06/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		07/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\HCV	Height Level Valve	replaced damaged suspension control valve	01/06/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		30/05/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		30/05/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		24/05/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\BOLSTER	repaired wiring to rear bolster		24/05/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		24/05/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/05/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		10/05/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SUSPENSION	tightened RHF, LHM and RHM sebolts		10/05/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SUSPENSION	tightened LHF & RHM ubolts		10/05/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\AIR LEAK	repaired airleak at rear axle		10/05/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		05/05/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		05/05/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\BOLSTER	turn 3rd bolster pegs		04/05/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		28/04/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SHOCK ABS	Replaced R/R lower shocker post		28/04/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		28/04/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		17/04/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		17/04/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Insp\ANN INSP	D Service		12/04/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		12/04/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SHOCK ABS	tightened top shocker bolts		04/04/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SHOCK ABS	replaced RHR shocker		04/04/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	D Service		04/04/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		04/04/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		26/03/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SPRING HANG	replaced broken 2 spring - LHR		26/03/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		26/03/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		17/03/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\STCH GUARD	replaced LH stretch guard		17/03/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		17/03/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	Service		15/03/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\DRV TYRES	L/H outside middle axle tyre worn on outside only premature and uneven wear		15/03/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\STCH GUARD	L/H stretcher guard R/S		15/03/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		10/03/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\BOLSTER	Rht 2nd bolster light		10/03/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\CHN/RLR/MN	replaced hold down chain		10/03/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/03/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		02/03/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job	straightened LH stretch guard outrigger and mounts	02/03/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\DAMAGE	kangaroo damage LHS	damaaed by Kangaroo hit	26/02/2019	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	Service		21/02/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		21/02/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	Service		13/02/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	Service		13/02/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job middle axle cracked replaced complete axle repaired centre mat and fitted replaced boosters, alignment plates and u-bolts		13/02/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	DrivLine\AXLE REPLC	hooked up. fitted baltrace block		06/02/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	DrivLine\AXLE REPLC	REPLACE CRACKED AXLE		05/02/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\FIFTH WHEE	removed protective cover over skid plate, make template and then fit to T324		20/01/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		19/01/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		19/01/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		11/01/2019	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\BOLSTER	replaced bolster pivot bushes		11/01/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\BOLSTER	weld crack in 2nd bolster and chassis stiffner		11/01/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		11/01/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\WINCH/STRP	Winches & Straps	fitted air winches	11/01/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Workshop\MOVE ASSET	Move Assets	hook up- shift on to workshop	11/01/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\WINCH/STRP	fit exte winches		04/01/2019	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		21/12/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		21/12/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service	d service completed	13/12/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\TAIL LIGHT	plase replace L/H brake light	fit out new stop/tail assy.	08/12/2018	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\BRK LIGHT	inoperable stop light		08/12/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service	D service completed cracked skin to rail at ramp	07/12/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\BOLSTER	Bolster	tightened bolster bolts	07/12/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\DRV TYRES	Drive Tyres	removed and replaced tyres	06/12/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Wodonga - Workshop	Tyres\DRV TYRES	Drive Tyres	removed and replaced tyres	06/12/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		30/11/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\BOLSTER	repaired wiring to 3rd to 4th bolster lights		30/11/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SHOCK ABS	tightened shocker bolts		30/11/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		30/11/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body	Job Added From Invoice no marker lights on bolsters		29/11/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\TRL LIGHTS	clearance lights on bolsters 2,3,4 not working replaced service relay valve and fittings	repaired wiring at 1st bolster	28/11/2018	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\AIR FITTIN	repaired air lines		25/11/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Wodonga - Workshop	Hydraulics\VALVES	please replace/repair service valve on front unknown tank		24/11/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER			
T393	Rosewood - Workshop	Hydraulics\VALVES	broken service valve	cut off abit off the valve and out back on the front air tank with white oaste and re-tighten valve build up air with full air pressure to see if it will hol	24/11/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Rosewood Workshop	TRAILER			
T393	Rosewood - Workshop	VehService\DS	D Service	D service completed	24/11/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Rosewood Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service	D service completed	23/11/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\BOLSTER	Bolster	Replaced HUD, replaced hydraulic ram mount bolts 2nd Bolster	23/11/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SHOCK ABS	Shock Absorber	tightened loose shockers	23/11/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			

T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		16/11/2018 2	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\CLEANSKIN	Job Added From Invoice		16/11/2018 2	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service	D service completed- see attached	16/11/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SUSPENSION	Suspension	replcaed RHF sebolt and nut (broken) (completed during the service)	06/11/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service	D service completed	06/11/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\Re-Tor	Job Added From Invoice		03/11/2018 1	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	repaired 1st bolster lights		01/11/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\MUDGUARDS	replaced front mudflaps, straightened guard		01/11/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\REFLECTORS	replaced peg load light height stickers		01/11/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SUSPENSION	REPLACE BROKEN AXLE STRAP		27/10/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		26/10/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	DrivLine\DAMAGE	LHR axle cable		26/10/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SUSPENSION	tightened LHM & RHR sebolts		26/10/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		26/10/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SUSPENSION	fit seb's		24/10/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		24/10/2018 3	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		19/10/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
			replaced 1st and 3rd winch strap											
T393	Albury - Workshop	Chassis\WINCH/STRP	free up #3 winch		19/10/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BOOSTER	replaced RM booster		19/10/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		19/10/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\MUDGUARDS	L/H stretcher guard needs to be repaired or replaced	removed stretch guard, repaired cracked mounts and bracket	14/10/2018	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		10/10/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/10/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Workshop	Job Added From Invoice		09/10/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		05/10/2018 1	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		05/10/2018 1	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\DRV TYRES	changed tyres (LHR axle)		03/10/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\TP51	fit spare to T505		03/10/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		28/09/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		28/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		26/09/2018 20	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		26/09/2018 20	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		21/09/2018 20	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		21/09/2018 20	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		19/09/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\DAMAGE	replaced skid plate gussets		19/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		19/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	dismantle damaged bolstar		18/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	assemble new bolster and fit to T395		18/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\ELECT P&W	rewire bolstar		18/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\FIFTH WHEE	2nd quick release needs replacing	replaced 2nd quick release cable and eyelets	18/09/2018	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\CHN/RLR/MN	replaced hold down chain		18/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\MUDGUARDS	tightened guard bolts		18/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	Prep and paint bolster		14/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		13/09/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SHOCK ABS	Tightened top shocker bolts		13/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		13/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		07/09/2018 10	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		07/09/2018 10	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		07/09/2018 10	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		04/09/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	removed rear bolster assembly from T395 and fitted to rear		04/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		04/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	REPLACE DAMAGED BOLSTER	Removed damaged rear bolster	01/09/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		29/08/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		29/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SHOCK ABS	REPLACE SHOCKER STRAP		29/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		24/08/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SHOCK ABS	bottom shocker mount (RHM)		24/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	1st bolster ram		24/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	rear bolster LH ram		24/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SUSPENSION	adjusted suspension		24/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\INST/GAUGE	replaced broken/worn reflectors and clean side light		24/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SHOCK ABS	fitted shocker to RHM axle		24/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		24/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Hydraulics\HYD LEAKS	hydraulic leak first bolster ram L/H side		18/08/2018	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		16/08/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	LH NKP 3rd Bolster		16/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SHOCK ABS	RHM Bottom Shocker mount		16/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	LHR Bolster Cylinder		16/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	LHF Bolster Cylinder		16/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		16/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SUSPENSION	REPLACE SEB AND WRAP.		12/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		12/08/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SUSPENSION	LHM SEB		12/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		12/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		01/08/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		01/08/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		21/07/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		21/07/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		21/07/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		21/07/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		21/07/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		19/07/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		19/07/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		19/07/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		15/07/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		15/07/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Rosewood - Workshop	Body\CHN/RLR/MN	replace dog chain	replace hold down chain. Driver broke it	13/07/2018	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Rosewood Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		12/07/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		12/07/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\ROTATION	Job Added From Invoice		12/07/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		12/07/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	DrivLine\WHEEL BRGS	please check bearings on lead axle	checked RH and LH wheel bearings	07/07/2018	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\AIR LEAK	repaired air leak		07/07/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	DrivLine\AXLE REPLC	remove front axle		03/07/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Workshop\MOVE ASSET	drop off at w.e.c		03/07/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Workshop\MOVE ASSET	pick up from wec		03/07/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	DrivLine\AXLE REPLC	rebuild axle		03/07/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
				RELINE										
T393	Albury - Workshop	DrivLine\WHEEL BRGS	RHF wheel bearings removed wheel chained up axle	AXLE REPAIRED BY WEC	01/07/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		30/06/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		30/06/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		28/06/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		28/06/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		28/06/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
			checked for ABS codes 2 codes: first 1B - adjusted wheel bearings second 2B - reset ABS wheel sensor											
T393	Albury - Workshop	Brakes\ABS	cleared stored codes and reset - ok		28/06/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
				check ABS/EBS faults as per attached photos										
T393	Rosewood - Workshop	Brakes\ABS	check ABS - EBS codes	cleared codes and returned to Service	27/06/2018	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Rosewood Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE	forwarded photo's to Alb to check	24/06/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		24/06/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
				replaced fittings at scales and RTR valve with steel fittings.										
T393	Albury - Workshop	Susp\AIR FITTIN	please repair broken all links on trailer	Re-route suspension lines	21/06/2018	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		20/06/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Hydraulics\HYD LEAKS	please fix hydraulics leak om front bolster RAM LH	tightened gland nut on hydraulics cylinder fittings	19/06/2018	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		17/06/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	replaced 1st bolster ram & repair 3 x bolster rams		17/06/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SHOCK ABS	tightened top shocker bolts		17/06/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		17/06/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		14/06/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\AIR LEAK	repaired air leak		12/06/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		07/06/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		07/06/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
			checked ABS codes and suspension pressures											
T393	Albury - Workshop	Engine\FAULT CODE	downloaded ECM data for BPN enaineers		31/05/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SUSPENSION	press S.E.B		31/05/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\AXLE CT	reline and crack tested rear axle		26/05/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		26/05/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
			checked for codes - 2B (RHR)											
T393	Albury - Workshop	Engine\FAULT CODE	removed wheel for reline, replaced sensor and reset (no codes)		26/05/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		26/05/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		25/05/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		25/05/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		25/05/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		20/05/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		20/05/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\ABS	checked ABS codes		17/05/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	DrivLine\WHEEL BRGS	adjusted rear wheel bearings		17/05/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\ELECT P&W	checked RTR valve wiring and operation. Cleaned and fitted plug to solenoid		17/05/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		13/05/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		13/05/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\CHN/RLR/MN	Replaced hold down chain		13/05/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	Replaced brown winch handle		13/05/2018	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		09/05/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		09/05/2018 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		08/05/2018	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER

T393	Albury - Workshop	Susp\SUSPENSION	tightened LHM and RHR sebolt		08/05/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		08/05/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		25/04/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		25/04/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Elect\ELECT P&W	Replaced RHR axle cable		25/04/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		18/04/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		18/04/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		18/04/2018	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		10/04/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/04/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		04/04/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		04/04/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		24/03/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		24/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		18/03/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SUSPENSION	tightened RHF sebolt		18/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job please repair airline to height central valve		18/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\HCV	needs replacing	repaired damaged airline to HCV	14/03/2018		Fault	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service repaired broken chassis skin repaired broken hanger welds		10/03/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\CHAS CRACK	repaired broken cross members		10/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\MUDGUARDS	repaired bent mudguards		10/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SHOCK ABS	tightened seb's and shocks		10/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		09/03/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp	Job Added From Invoice		08/03/2018	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\CHAS CRACK	Weld up crack replaced RHR b/booster		06/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BOOSTER	reolaced LHM bottom shock mount fitted shock		03/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\AIR LEAK	repaired air leak		03/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	tightened bolster bolts		03/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRK RELINE	cleaned up after reline work		03/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		03/03/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		03/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\AXLE CT	crack test and reline LHF axle		03/03/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		24/02/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		24/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		17/02/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		17/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRK RELINE	brake reline		17/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		11/02/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	repaired wiring for 3rd and 4th bolsters		11/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	DrivLine\WHEEL BRGS	checked and adjusted all wheel bearings		11/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\CROSS MBR	replaced required cross member bolts		11/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\HOSES	tightened bolster mounts		11/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		11/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice fit lights and wear pads to bolster		08/02/2018	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	mount bolster onto trailer		03/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\SUSPENSION	replaced spring eye bushes in springs		03/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		02/02/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		02/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRK RELINE	reline		02/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	prepare and paint bolster		02/02/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\AS	A Service		25/01/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\AIR LEAK	check for air leak		25/01/2018		Fault	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		25/01/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		25/01/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRK RELINE	brake reline		25/01/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\BOLSTER	order parts for bolster repairs		17/01/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Wodonga Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		16/01/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	2ND AND 3RD WINCHES ARE JAMMED UP.	repaired 2nd & 3rd winches	16/01/2018		Fault	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	front bolster u/s large crack	replaced 1st bolster pivot mounts and bushes front bolster u/s, unhooked and hook up to alternate trailers	16/01/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		16/01/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\FIFTH WHEE	REPLACED KING PIN	replaced kingpin. Greased. Adjusted. Tested	12/01/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Hydraulics\RAM	LEAKING BOLSTER RAM		07/01/2018		Fault	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		07/01/2018		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Hydraulics\HYD LEAKS	replaced 2nd bolster hyd. Cylinder		07/01/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		07/01/2018		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service please		23/12/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE	REPLACED RHF SEB, WRAP AND ALINGMENT PLATE	23/12/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		23/12/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		17/12/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		17/12/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\WINCH/STRP	replaced 3rd winch strap		17/12/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SHOCK ABS	tightened loose shocker bolts		17/12/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Rosewood - Workshop	Chassis\WINCH/STRP	replaced 3rd winch strap		16/12/2017		Fault	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Rosewood Workshop	TRAILER
T393	Rosewood - Workshop	VehService\DS	T Service		16/12/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Rosewood Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		15/12/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		15/12/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		15/12/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\LIGHTS	please fix rear R/H clearance light		13/12/2017		Fault	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D Service		10/12/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		10/12/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		05/12/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		05/12/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRAKE ADJ	brake adjust and check over	checked axle for seb and alignment plate movement. Checked wheel bearings. Measured axle from spring eye bosses	03/12/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\AXLES	please check front axle due to tyre wear/change inside R/H inside tyre	all was ok	30/11/2017		Fault	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\DRV TYRES	changed RHF inner tyre		30/11/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		29/11/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\LIGHTS	replaced RHR marker light		29/11/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		29/11/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		25/11/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		22/11/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		22/11/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		22/11/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		22/11/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job check trailer ABS light on		22/11/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\ABS	codes for T393 rear sensors output level. Checked sensors and wheel bearing free play. Cleared codes		19/11/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		15/11/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		15/11/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		15/11/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		15/11/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		15/11/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRAKE ADJ	BRAKE ADJUST		10/11/2017		Fault	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\REFLECTORS	fit reflective tape to pegs		03/11/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		03/11/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		03/11/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE	adj. front axle & rear axle wheel bearing	27/10/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		27/10/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE replaced air lines running to RTR valve	replaced l/R seb/wrap reolaced airline asine to RFR HCV	22/10/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\AIR FITTIN	tie up all airlines at valve		22/10/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	DrivLine\WHEEL BRGS	replaced seb/bolts/wrap L/R	replaced seb	22/10/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		22/10/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		21/10/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		15/10/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\STCH GUARD	MAKE CENTRE BARK MAT SIT FLAT		15/10/2017		Fault	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Chassis\BOLSTER	REPLACE BENT BOLSTER 2ND LAST RHS.	turned 180° and fit new bolt	15/10/2017		Fault	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		15/10/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRAKE ADJ	BRAKE ADJ.		12/10/2017		Fault	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		10/10/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		10/10/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		10/10/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	Service		30/09/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		30/09/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Body\HOUSEKEEP	CENTRE MAT REQUIRED 3.8MTS		24/09/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres	Job Added From Invoice		22/09/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		22/09/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		22/09/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		22/09/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		20/09/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		20/09/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		19/09/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		19/09/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		19/09/2017	0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE		17/09/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\DAMAGE	REPLACE BROKEN RTR HCV.	replaced suspension controller (damaged)	14/09/2017		Fault	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Susp\SHOCK ABS	REMOVED SHOCKER AS TOP MOUNT IS BROKEN	CUT OUT OLD BOSS. WELD IN NEW TUBE.	06/09/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	Brakes\BRK RELINE	RELINE MIDDLE AXLE		06/09/2017		Repair	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER
T393	Albury - Workshop	VehService\DS	D SERVICE	replaced R/F shocker strap replaced missing shocker nut RM soring wraa L/R	06/09/2017		Service	Completed	Greenfreight Logging NSW	ElpsBPW		Albury	ATK	YV49JX	Albury Workshop	TRAILER

T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		06/09/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\MUDGUARDS	straightened RH guard bracket		30/08/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\MUDGUARDS	replaced RH stretch guard		30/08/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\WORK LIGHT	NO WORK LIGHTS breakdown at Shelley		29/08/2017	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\BREAKDOWN	Travel to Shelley repair airline to serv valve damaged by loe		26/08/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		25/08/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE		18/08/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\AIR BAG	REPLACED REAR AXLE AIR BAGS		18/08/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		18/08/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\ELECT P&W	SCALES NOT WORKING ON CH. 3	REPAIRED WIRING AT PLUGS	12/08/2017	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE		11/08/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		11/08/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\WINCH/STRP	PLEASE REPLACE REAR STRAP	REPLACED STRAP	09/08/2017	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\ABS	checked ABS DTC's		08/08/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	Service		03/08/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\TAIL LIGHT	SHORT IN TAIL LIGHTS down load EBS found airbag pressure air line not connected	CLEAN OUT PAVE OF TRUCK AND TRAILER - TEST OK	03/08/2017	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\ABS	fit air line - send to work		28/07/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE		27/07/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		27/07/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres	Job Added From Invoice		25/07/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\FITMENT	Job Added From Invoice		25/07/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\RETREAD	Job Added From Invoice		25/07/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\RUN OUT	Job Added From Invoice		25/07/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	service	If shock mount top req	21/07/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SHOCK ABS	REMOVED SHOCKER AS TOP POST IS BROKEN		18/07/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE		16/07/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		16/07/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\EBS Kit	Fit new conformance plate		10/07/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE		09/07/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	DrCabElect\SCALES	INVESTAGATE WHY THERE ARE NO SCALES.		08/07/2017	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\ELECT P&W	SCALES NOT WORKING		08/07/2017	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	DrCabElect	Please replace air trandsuter for scales		08/07/2017	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\DAMAGE	PLEASE CHANGE FLAT TRYE. EBS EOLT.		04/07/2017	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\EBS Kit	CERIFY EBS BRAKE MOD.		02/07/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\BRK RELINE	BRAKE RELINES DONE @ COROWA TRUCK AND TRAILER		16/06/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\EBS Kit	SUPPLY EBS KIT		07/06/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP11	Job Added From Invoice		08/04/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE		06/04/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SHOCK ABS	RHM SHOCKER U/S.	REPLACED SHOCKER, STRAP, RETAINERS AND RUBBERS	06/04/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	Record Check Results		06/04/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE		30/03/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP21	Job Added From Invoice		24/03/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE		21/03/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\CHN/RLR/MN	REPLACE HOLD DOWN CHAIN		21/03/2017	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP11	Job Added From Invoice		17/03/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP17	Job Added From Invoice		17/03/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP21	Job Added From Invoice		17/03/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE		12/03/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE		03/03/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP22	Job Added From Invoice		27/02/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE		23/02/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP13	Job Added From Invoice		15/02/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE	REPAIRED SHOT IN "A" TRAILER TAIL LIGHT BAR	08/02/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\INDICATORS	INDICATORS NOT WORKING	as per job entry #45974	08/02/2017	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\WINCH/STRP	please replace 2nd strap		31/01/2017	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D SERVICE		29/01/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\BRK RELINE	Reline RF brake.	cleaned up after job	26/01/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP11	Job Added From Invoice		21/01/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP12	Job Added From Invoice		21/01/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	DrivLine\WHEEL BRGS	Adj wheel bearings	Adj RHF wheel bearing	19/01/2017	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		15/01/2017	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP21	Job Added From Invoice		12/01/2017 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis\BOLSTER	Replace broken NKP.	LHF NKP	05/01/2017	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	Dservice		30/12/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service	as per attached	14/12/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	service please		14/12/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP15	Job Added From Invoice		13/12/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP18	Job Added From Invoice		13/12/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\INDICATORS	Fault in LH indicators	Fault in T392	08/12/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service	repaired park lights	04/12/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP11	Job Added From Invoice		01/12/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		27/11/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Steering\WHEEL ALGN	wheel alignment		20/11/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D Service		20/11/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service	replace 3rd bolster pivot	20/11/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service	replaced LHF airbag	13/11/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\WORK LIGHT	Back up lights not working. Flashing on/off when unloading	Fault was in T 392	07/11/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		02/11/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP15	Job Added From Invoice		26/10/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP13	Job Added From Invoice		26/10/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		23/10/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes		23/10/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\CHN/RLR/MN	replace hold down chain		20/10/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP21	Job Added From Invoice		18/10/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP11	Job Added From Invoice		18/10/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		16/10/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes	replaced RM bush check wheel alignment	16/10/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SUSPENSION	RM spring eye bush	adiusted wheel bearinas	16/10/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes Bolster lights not working.		09/10/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\TRL LIGHTS	LR bolster light needs raplacing		09/10/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		09/10/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres	change worn tyre. Pos 22	Bandag repaired short. But requires new light in LR bolster repaired wiring 3rd bolster	09/10/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\TRL LIGHTS	Bolster lights not working	requires LR bolster marker liaht	01/10/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Body\STCH GUARD	Replaced missing stretch guard		29/09/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		28/09/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes		28/09/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP17	Job Added From Invoice		21/09/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		20/09/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes		20/09/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Susp\SPRING PACK	Broken spring RHR	Replaced RR spring	13/09/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		11/09/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes		11/09/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\BRK RELINE	Reline LF and RR brakes	as per reline sheet	04/09/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		01/09/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes		01/09/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP15	Job Added From Invoice		27/08/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP15	Job Added From Invoice		27/08/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP15	Job Added From Invoice		27/08/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP14	Job Added From Invoice		27/08/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		21/08/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes		21/08/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service	as above	12/08/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes		12/08/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP11	Job Added From Invoice		06/08/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP18	Job Added From Invoice		06/08/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP21	Job Added From Invoice		06/08/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service	as above tightened shockers	05/08/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes		05/08/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\TRL LIGHTS	indicator lights shorting	cleaned out plugs and sockets	03/08/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service		28/07/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Elect\TAIL LIGHT	no bolster lights	repaired on T392	28/07/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes		28/07/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService	A Service		28/07/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Chassis	no bolster lights		28/07/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\AIR LEAK	air leak with maxi's off	replaced rubbed booster hoses as above	27/07/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service	tightened loose shockers	20/07/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes		20/07/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP16	Job Added From Invoice		13/07/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes\BRK RELINE	LM reline	as per attached reline sheet tightened loose shockers	12/07/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service	replaced rear bolster bolts for pegs	09/07/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Brakes	check and record brakes		09/07/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Tyres\TP12	Job Added From Invoice		06/07/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Hydraulics\RAM	bolster tilt ram leaking	replaced cylinder which was fitted in job # 25791. had to fit new spacer	03/07/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	Hydraulics\RAM	1st tilt cylinder leaking.	fit c/o cylinder. Sent leaking cylinder away for repair.	01/07/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			
T393	Albury - Workshop	VehService\DS	D service	c/o 1st bolster tilt cylinder #25791	01/07/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER			

T393	Albury - Workshop	Brakes	check and record brakes		01/07/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D service		26/06/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	check and record brakes		26/06/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D service		17/06/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Susp\SUSPENSION	Check locator plates. Alignment plates.		17/06/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes\AIR LEAK	air leak.	replaced rubbed air hose at front axle.	15/06/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP16	Job Added From Invoice		10/06/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Elect\TRL LIGHTS	replace LH 3rd bolster light	as above	08/06/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes\AIR LEAK	repair air leak	replaced fitting on relay valve	08/06/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D service	As above	07/06/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	check and record brakes		07/06/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP17	Job Added From Invoice		28/05/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP17	Job Added From Invoice		28/05/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D service	as above	27/05/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	check and record brakes		27/05/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D service	as above	18/05/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	check and record brakes		18/05/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP11	Job Added From Invoice		11/05/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP11	Job Added From Invoice		11/05/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP11	Job Added From Invoice		11/05/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
				as above removed bar sent to Aldonga eng. For repair paint & refit												
T393	Albury - Workshop	Chassis\MUDGUARDS	repair mud guard where it was damaged by the dozer pushing out 894 when it had the fan fail and damaged the radiator.	reseained bolster	10/05/2016	Reapir	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		30/04/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		30/04/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Chassis\WINCH/STRP	repair winch	lube winch and replace strap	28/04/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP13	Job Added From Invoice		23/04/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP13	Job Added From Invoice		23/04/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP13	Job Added From Invoice		23/04/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D service		16/04/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	check and record brakes		16/04/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Elect\BRK LIGHT	no brake lights	reset circuit breaker	15/04/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP21	Job Added From Invoice		12/04/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP21	Job Added From Invoice		12/04/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP21	Job Added From Invoice		12/04/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes\BRK RELINE	Reline LH rear brake	As per reline sheet	12/04/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Insp\ANN INSP	Annual inspection		12/04/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes\BRK RELINE	Reline RM wheel.	as above. Reline sheet attatched.	10/04/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D service.		10/04/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D service	as above	31/03/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	check and record brakes		31/03/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Chassis\WINCH/STRP	2nd and 4th winches are tight. Lube does not work.	adjusted winch mounts	15/03/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D service		15/03/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	check and record brakes		15/03/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes\BRK RELINE	Crack test and reline LF wheel	As above	12/03/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Body\STCH GUARD	Replace/repair stretch guard	repaired stretch guard	10/03/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes\AIR LEAK	air leak	repair air leak at valve	03/03/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP17	Job Added From Invoice		01/03/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP17	Job Added From Invoice		01/03/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP17	Job Added From Invoice		01/03/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP19	Job Added From Invoice		01/03/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP19	Job Added From Invoice		01/03/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP19	Job Added From Invoice		01/03/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D service		23/02/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D service		16/02/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D service as per attached check list		07/02/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Chassis\BOLSTER	Cracked NKP. Hydraulic pivot arm	replaced NKP	07/02/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP11	Job Added From Invoice		23/01/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP11	Job Added From Invoice		23/01/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP11	Job Added From Invoice		23/01/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP19	Job Added From Invoice		23/01/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP19	Job Added From Invoice		23/01/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP19	Job Added From Invoice		23/01/2016 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		21/01/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		21/01/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	adjust brakes		19/01/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Susp\SPRING PACK	spring/wrap	completed	19/01/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Wodonga - Workshop	Susp\SUSPENSION	lhr 2-spring broken	replace spring	16/01/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		07/01/2016	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		07/01/2016	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Susp	air bags not pumping up	adjusted HCV	01/01/2016	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Rosewood - Workshop	Chassis	centre right air bag input hose broken	repair broken fitting	31/12/2015	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		18/12/2015	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job u bolts+bush		18/12/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Susp\SUSPENSION	albu t & t	comoleted	09/12/2015	Reapir	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		05/12/2015	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		05/12/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP17	Job Added From Invoice		28/11/2015 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP17	Job Added From Invoice		28/11/2015 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP17	Job Added From Invoice		28/11/2015 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		18/11/2015	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		18/11/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Tyres\TP16	Job Added From Invoice switch		14/11/2015 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Elect\ELECT P&W	tctc brake parts	completed	12/11/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes\BRK O/HAUL	tctc bolster	comoleted	12/11/2015	Reapir	Completed	Greenfreight Logging NSW	ElosBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Chassis\BOLSTER	aldonga eng	completed	10/11/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		07/11/2015	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER		
T393	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		07/11/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER		
T393	Wodonga - Workshop	Susp	replace HCV rod rubbers		07/11/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER		
T393	Wodonga - Workshop	Brakes	crack test and reline rhf axle, wash and inspect bearings and hubs		07/11/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER		
T393	Wodonga - Workshop	Steering\WHEEL BRGS	right front wheel hub running hot	check all steering components, bearings and equalise tyre pressures	07/11/2015	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Wodonga Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		28/10/2015	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		28/10/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Body\LIGHTS	replace lh indicator insert air bag		28/10/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Susp\AIR BAG	tctc inv 1334003	completed	20/10/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		20/10/2015	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		20/10/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Susp\AIR BAG	lhm air bag cracked on top	replace lhm air bag	16/10/2015	Fault	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		09/10/2015	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job		09/10/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Susp\SPRING HANG	Job Added From Invoice		26/09/2015 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	VehService\DS	D Service As Per Attached Checklist		25/09/2015	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Brakes	Record Check Results As Attached To This Job	replace maxi relay valve	25/09/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Susp\SUSPENSION	tighten lhr spring eye bolt		25/09/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Albury - Workshop	Body\AIR LEAK	check for air leaks		15/09/2015 0	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Albury Workshop	TRAILER		
T393	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	completed	08/09/2015	Service	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Myrtleford Workshop	TRAILER		
T393	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job		08/09/2015	Repair	Completed	Greenfreight Logging NSW	ElpsBPW	Albury	ATK	YV49JX	Myrtleford Workshop	TRAILER		