



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A254093

Station #: 70997

Station Name: M & N Repair

Technician #: 89445

Technician Name: Randy Nahorney

Signing Officer #: 84671

Signing Officer Name: Darlene Nahorney

Customer Details:

Name: CMS HOLDINGS

Address: BOX 101, LANDIS, Saskatchewan, S0K2K0

Inspection Completed Date: 12Jan2026

Inspection Expiry Date: 31Jul2026

Vehicle Details:

VIN: 2WKEDCXH5VK945444

Odometer Reading: 425727 km

Year: 1997

Vehicle Make/Model: WESTERN STAR/HEAVY VEHICLE

Plate: 870HGJ

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70997

Station Name: M & N Repair

Technician #: 89445

Technician Name: Randy Nahorney

Signing Officer #: 84671

Signing Officer Name: Darlene Nahorney

Customer Details:

Name: CMS HOLDINGS

Address: BOX 101, LANDIS, Saskatchewan, S0K2K0

Vehicle Details:

VIN: 2WKEDCXH5VK945444

Odometer Reading: 425727 km

Year: 1997

Vehicle Make/Model: WESTERN STAR HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
		x		Horn Operation (5)	ELECTRIC HORN NOT WORKING
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	CAB LIGHT DRIVER SIDE, REAR TAILLIGHT DRIVER SIDE
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
		x		Trailer Power Cord (7)	TRAILER POWER PLUG FULL OF DIRT
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
		x		Power Steering System (4)	POWER STEERING HOSE NEEDS REPLACEMENT (BADLY WORN).
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

x			Hyd Brake System/Components (3.1)	
x			Air Brake System/Components (3.2)	
x			Wheel Bearings (9)	
x			King Pins/Ball Joints (4)	
x			Steering Linkage (4)	
x			Tires/Wheels (9)	
x			Self-Steering Axle (4)	
x			Engine/Transmission Mounts (1)	
x			Frame/Crossmembers/Mounts (8)	
x			Suspension/Axles (2)	
x			Drive Shaft/Universal Joints (1)	
x			Exhaust/Emission System (1)	

Brake/Tire Measurements

axle 1-Pass

Wheel1-Off : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 5/8 in • Brake Drum/Rotor: 15.1 in • Brake Stroke: 1 1/4 in

Wheel2-Off : Tire Tread Depth: 14 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 5/8 in • Brake Drum/Rotor: 15.1 in • Brake Stroke: 1 1/4 in

axle 2-Pass

Wheel1 : Tire Tread Depth: 17 mm

Brake(1): No Brake

I/A

Wheel2-Off : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 5/8 in • Brake Drum/Rotor: 16.525 in • Brake Stroke: 1 1/4 in

Wheel3-Off : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 11/16 in • Brake Drum/Rotor: 16.525 in • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 12 mm

Brake(1): No Brake

I/A

axle 3-Pass

Wheel1 : Tire Tread Depth: 17 mm

Brake(1): No Brake

I/A

Wheel2-Off : Tire Tread Depth: 18 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 9/16 in • Brake Drum/Rotor: 16.525 in • Brake Stroke: 1 1/4 in

Wheel3-Off : Tire Tread Depth: 17 mm

Brake(1): S-CAM Brake

Min Brake Lining/Pad: 5/8 in • Brake Drum/Rotor: 16.525 in • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 17 mm

Brake(1): No Brake

...

PASS - vehicle passes inspection

Decal # A254093

Inspection Completed Date: 12Jan2026

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be RE-TORQUED within 100-150 km.
Failure to do so may result in damage or serious injury.