



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A336790

Station #: 70956	Station Name: E Bourassa & Sons Partnership
Technician #: [REDACTED]	Technician Name: [REDACTED]
Signing Officer #: 92606	Signing Officer Name: [REDACTED]

Customer Details:
[REDACTED]

Inspection Completed Date: 09Jun2026 Inspection Expiry Date: 31Dec2026

Vehicle Details:

VIN: 1XP5DB9X95D857311	Odometer Reading: 992831 km
Year: 2005	Vehicle Make/Model: PETERBILT/HEAVY VEHICLE
Plate:	Jurisdiction:
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

Inspection Item	Pass	Fail	Notes
Windshield/Other Glass (1)			
Low Fluids Indicator & Maintenance			
Instrument Lamps (1)			
Seatbelts/Fasteners (1)			
Auxiliary Masters (5)			
Auxiliary Drive Controls (1)			
Emergency Exit (1)			
Power/Step Well Controls (1)			
General Exit Doors (1)			
Interior Lamps (1)			
Exterior Lamps (1)			
Exhaust (1)			
Brakes (1)			
Steering (1)			
Wipers (1)			
Other (1)			

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	

x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 11 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 56 degrees • Brake Stroke: 1 in

Wheel2-On : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 72 degrees • Brake Stroke: 1 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 16 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 15 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 44 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 12 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 41 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 14 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 10 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 10 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 58 degrees • Brake Stroke: 1 1/4 in

Wheel3-On : Tire Tread Depth: 8 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 39 degrees • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 8 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A336790

Inspection Completed Date: 09Jun2026