SGI

Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A374144

Station #: 70925

Station Name: Keep on Truckin Mechanical

Technician #: 83082

Technician Name: Ryley Parchoma

Signing Officer #: 80601

Signing Officer Name: Cora Manson

Customer Details:

Name: Beamish Farms Ltd

Address: Box 2127, Lloydminster, Saskatchewan, S9V1R6

Inspection Completed Date: 03Nov2026

Inspection Expiry Date: 31May2027

Vehicle Details:

VIN: 2HSFBJXR3GCA15586

Odometer Reading: 50787 km

Year: 1986

Vehicle Make/Model: INTERNATIONAL/HEAVY VEHICLE

Plate: 185KNA

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

SGI

Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70925

Station Name: Keep on Truckin Mechanical

Technician #: 83082

Technician Name: Ryley Parchoma

Signing Officer #: 80601

Signing Officer Name: Cora Manson

Customer Details:

Name: Beamish Farms Ltd

Address: Box 2127, Lloydminster, Saskatchewan, S9V1R6

Vehicle Details:

VIN: 2HSFBJXR3GCA15586

Odometer Reading: 50787 km

Year: 1986

Vehicle Make/Model: INTERNATIONAL HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
		x		Instruments/Gauges (5)	Gauge back lights out
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	Reverse lamp out, rh hood marker light out, roof light out, lh mirror light out
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments

x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	#1 rh clevis pin/bushing worn, #2 lh/rh clevis pins/bushings worn. #3 rh brake anchor spring broken
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
		x		Frame/Crossmembers/Mounts (8)	Frame crossmember bolt missing behind cab
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 13 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 12.2 mm • Cam Rotation: 45.0 degrees • Brake Stroke: 35 mm
Wheel2-On : Tire Tread Depth: 13 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 12.2 mm • Cam Rotation: 46.0 degrees • Brake Stroke: 35 mm

Axle 2-Pass

Wheel1 : Tire Tread Depth: 22 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 22 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 14.9 mm • Cam Rotation: 62.0 degrees • Brake Stroke: 35 mm
Wheel3-On : Tire Tread Depth: 22 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 14.6 mm • Cam Rotation: 65.0 degrees • Brake Stroke: 35 mm
Wheel4 : Tire Tread Depth: 22 mm
Brake(1): No Brake
N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 21 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 21 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 14 mm • Cam Rotation: 73.0 degrees • Brake Stroke: 35 mm
Wheel3-Off : Tire Tread Depth: 21 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 18 mm • Brake Drum/Rotor: 419.1 mm • Brake Stroke: 35 mm
Wheel4 : Tire Tread Depth: 21 mm
Brake(1): No Brake
N/A

PASS - vehicle passes inspection	Decal # A374144	Inspection Completed Date: 03Nov2026

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km.
Failure to do so may result in damage or serious injury.