



Vehicle Standards and Inspection

Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A374117

Station #: 70925

Station Name: Keep on Truckin Mechanical

Technician #: 91262

Technician Name: Steven Stahl

Signing Officer #: 80601

Signing Officer Name: Cora Manson

Customer Details:

Name: Beamish Farms Ltd

Address: Box 2127, Lloydminster, Saskatchewan, S9V1R6

Inspection Completed Date: 09Oct2026

Inspection Expiry Date: 31Oct2027

Vehicle Details:

VIN: 2LDAH4532GV062062

Hubometer Reading:

Year: 2016

Vehicle Make/Model: LOAD KING/TRAILER

Plate: 808JZR

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 70925

Station Name: Keep on Truckin Mechanical

Technician #: 91262

Technician Name: Steven Stahl

Signing Officer #: 80601

Signing Officer Name: Cora Manson

Customer Details:

Name: Beamish Farms Ltd

Address: Box 2127, Lloydminster, Saskatchewan, S9V1R6

Vehicle Details:

VIN: 2LDAH4532GV062062

Hubometer Reading:

Year: 2016

Vehicle Make/Model: LOAD KING TRAILER

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	No push rod indicators, several clevis pins seized
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
		x		Suspension/Axles (2)	All shocks leaking
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1 : Tire Tread Depth: 5 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 5 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 36.0 degrees • Brake Stroke: 35 mm

Wheel3-On : Tire Tread Depth: 4 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20.1 mm • Cam Rotation: 35.0 degrees • Brake Stroke: 35 mm

Wheel4 : Tire Tread Depth: 5 mm

Brake(1): No Brake

N/A

Axle 2-Pass

Wheel1 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 8 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20.3 mm • Cam Rotation: 33.0 degrees • Brake Stroke: 35 mm

Wheel3-On : Tire Tread Depth: 7 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20.1 mm • Cam Rotation: 35.0 degrees • Brake Stroke: 35 mm

Wheel4 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 4 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 4 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 20 mm • Cam Rotation: 35.0 degrees • Brake Stroke: 35 mm

Wheel3-On : Tire Tread Depth: 5 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 19.8 mm • Cam Rotation: 37.0 degrees • Brake Stroke: 35 mm