



Vehicle Standards and Inspection

Heavy Truck Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A358982

Station #: 72033

Station Name: Fab-All Welding

Technician #: 92457

Technician Name: Austin Walker

Signing Officer #: 89020

Signing Officer Name: Blaine Klein

Customer Details:

Name: LORNE HOFER

Address: BOX 746, WILKIE, Saskatchewan, S0K4W0

Inspection Completed Date: 25Aug2026

Inspection Expiry Date: 31Aug2027

Vehicle Details:

VIN: 1FVHCYCY0FHFZ3161

Odometer Reading: 27972 km

Year: 2015

Vehicle Make/Model: FREIGHTLINER/HEAVY VEHICLE

Plate:

Jurisdiction:

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

Heavy Truck Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 72033

Station Name: Fab-All Welding

Technician #: 92457

Technician Name: Austin Walker

Signing Officer #: 89020

Signing Officer Name: Blaine Klein

Customer Details:

Name: LORNE HOFER

Address: BOX 746, WILKIE, Saskatchewan, S0K4W0

Vehicle Details:

VIN: 1FVHCYCY0FHFZ3161

Odometer Reading: 27972 km

Year: 2015

Vehicle Make/Model: FREIGHTLINER HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
		x		Mud Flaps/Fenders (8)	FRONT RIGHT FENDER HARDWARE LOOSE
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
------	----------	-----------	----------	---------	----------

x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	-REAR SERVICE GLADHAND RUBBER TORN/BLUE -3RD AXLE RIGHT SLACK ADJUSTER MISSING SMALL CLEVIS PIN -3RD AXLE RIGHT BRAKE STROKED OUT -ALL BRAKE POTS MISSING STROKE INDICATORS
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
		x		Exhaust/Emission System (1)	-LOWER EXHAUST STACK BUSHING WORN OUT

Brake/Tire Measurements

Axle 1-Pass

Wheel1-Off : Tire Tread Depth: 9/16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Brake Drum/Rotor: 16.515 in • Brake Stroke: 1 1/4 in

Wheel2-Off : Tire Tread Depth: 9/16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 21 mm • Brake Drum/Rotor: 16.515 in • Brake Stroke: 1 1/4 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 9/16 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 9/16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Brake Drum/Rotor: 16.520 in • Brake Stroke: 1 1/2 in

Wheel3-Off : Tire Tread Depth: 19/32 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Brake Drum/Rotor: 16.520 in • Brake Stroke: 1 9/16 in

Wheel4 : Tire Tread Depth: 5/8 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 9/16 in

Brake(1): No Brake

N/A

Wheel2-Off : Tire Tread Depth: 1/2 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Brake Drum/Rotor: 16.520 in • Brake Stroke: 1 1/2 in

Wheel3-Off : Tire Tread Depth: 1/2 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Brake Drum/Rotor: 16.515 in • Brake Stroke: 1 1/4 in

Wheel4 : Tire Tread Depth: 1/2 in

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A358982

Inspection Completed Date: 25Aug2026

One or more wheels were removed for inspection. Warning: Wheel nuts **MUST** be **RE-TORQUED** within 100-150 km.
Failure to do so may result in damage or serious injury.