

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Station #: 71533

Decal # A296371

Technician #: 88585

Station Name: D-CAN AG REPAIR LTD.

Signing Officer #: 89323

Technician Name: Darrell Kraft

Signing Officer Name: Jason Thrun

Customer Details:

Name: HEX HOLDINGS LTD

Address: BOX 374, LUSELAND, Saskatchewan, S0L2A0

Inspection Completed Date: 18Mar2026

Inspection Expiry Date: 30Sep2026

Vehicle Details:

VIN: 2HSCHAERXYC064318

Odometer Reading: 407020 km

Year: 2000

Vehicle Make/Model: INTERNATIONAL/HEAVY VEHICLE

Plate: 864FLZ

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71533
 Technician #: 88585
 Signing Officer #: 89323

Station Name: D-CAN AG REPAIR LTD.
 Technician Name: Darrell Kraft
 Signing Officer Name: Jason Thrun

Customer Details:
 Name: HEX HOLDINGS LTD
 Address: BOX 374, LUSELAND, Saskatchewan, S0L2A0

Vehicle Details:
 VIN: 2HSCHAERXYC064318
 Year: 2000

Odometer Reading: 407020 km
 Vehicle Make/Model: INTERNATIONAL HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
		x		Windshield Wipers/Washers (8)	NO WIPERS
x				Windshield Defroster/Heater (8)	
		x		Windshield/Other Glass (8)	LEFT WINDSHIELD
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	BEACONS, WORK LIGHTS, SIDE CAB LIGHTS, LEFT MIRROR LIGHT, NO REVERSE LIGHT
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
		x		Body/Bumpers (8)	BOTTOM BUMPER CRACKS
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
		x		Drive Belts (1)	ALT BELT

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
------	----------	-----------	----------	---------	----------

x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
		x		Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	BOTH REAR TORQUE ARMS
x				Drive Shaft/Universal Joints (1)	
				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 6 in
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .708 in • Cam Rotation: 60.0 degrees • Brake Stroke: 1.50 in
 Wheel2-On : Tire Tread Depth: 14 in
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .710 in • Cam Rotation: 58.0 degrees • Brake Stroke: 1.50 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 9 in
 Brake(1): No Brake
 N/A
 Wheel2-On : Tire Tread Depth: 11 in
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .630 in • Cam Rotation: 68.0 degrees • Brake Stroke: 1.25 in
 Wheel3-On : Tire Tread Depth: 13 in
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .486 in • Cam Rotation: 100.0 degrees • Brake Stroke: 1.50 in
 Wheel4 : Tire Tread Depth: 12 in
 Brake(1): No Brake
 N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 9 in
 Brake(1): No Brake
 N/A
 Wheel2-On : Tire Tread Depth: 8 in
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .630 in • Cam Rotation: 76.0 degrees • Brake Stroke: 1.25 in
 Wheel3-On : Tire Tread Depth: 6 in
 Brake(1): S-CAM Brake
 • Min Brake Lining/Pad: .628 in • Cam Rotation: 74.0 degrees • Brake Stroke: 1.25 in
 Wheel4 : Tire Tread Depth: 8 in
 Brake(1): No Brake
 N/A

PASS - vehicle passes inspection

Decal # A296371

Inspection Completed Date: 18Mar2026