SGI

Vehicle Standards and Inspection

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #:	Station Name:
Technician #:	Technician Name:
Signing Officer #:	Signing Officer Name:

Customer Details:

Name: Beamish Farms Ltd. Address: Box 2127, Lloydminster, Saskatchewan, S9V1R6

Vehicle Details:

VIN: 1XP5DB9X6YN518133 Odometer Reading: 582862 km

Year: 2000 Vehicle Make/Model: PETERBILT HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
x				Windshield/Other Glass (8)	
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

x				Fire Extinguisher/Hazard Kit (5)	
		x		Seats/Seat Belts/SRS (8)	Drivers seat belt not retracting properly
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	Four lh air cleaner lights 50% out
x				Headlamp Aim (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Body/Bumpers (8)	
x				Trailer Hitch (10)	
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
x				Mud Flaps/Fenders (8)	
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
x				Power Steering System (4)	
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments

x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	No pushrod indicators
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
x				Exhaust/Emission System (1)	

Brake/Tire Measurements

Axle 1-Pass

Wheel1-On : Tire Tread Depth: 8 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 19.9 mm • Cam Rotation: 36.0 degrees • Brake Stroke: 35 mm
Wheel2-On : Tire Tread Depth: 10 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 20.7 mm • Cam Rotation: 28.0 degrees • Brake Stroke: 35 mm

Axle 2-Pass

Wheel1 : Tire Tread Depth: 15 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 14 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 17.8 mm • Cam Rotation: 56.0 degrees • Brake Stroke: 35 mm
Wheel3-On : Tire Tread Depth: 13 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 18.9 mm • Cam Rotation: 45.0 degrees • Brake Stroke: 35 mm
Wheel4 : Tire Tread Depth: 15 mm
Brake(1): No Brake
N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 13 mm
Brake(1): No Brake
N/A
Wheel2-On : Tire Tread Depth: 12 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 18.5 mm • Cam Rotation: 49.0 degrees • Brake Stroke: 35 mm
Wheel3-On : Tire Tread Depth: 14 mm
Brake(1): S-CAM Brake
• Min Brake Lining/Pad: 18.8 mm • Cam Rotation: 46.0 degrees • Brake Stroke: 35 mm
Wheel4 : Tire Tread Depth: 14 mm
Brake(1): No Brake
N/A

PASS - vehicle passes inspection	Decal # A374150	Inspection Completed Date: 05Nov2026