EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Jamie on service	06/10/2026	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Jamie and cheyne on service	13/07/2026	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		20/06/2026	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP08	Tyres\TP08 (28)			24/04/2026	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	BORDER BANDAG PTY LTD	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		24/04/2026	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	John	25/03/2026	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 32			07/03/2026	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	BORDER BANDAG PTY LTD	TRAILER
T259	Wodonga - Workshop	Body\DAMAGE	left curtain binds in runner when pulled back			24/02/2026	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Both Curtain's are Falling Apart and beyond Repair.		Pending	24/02/2026	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Both Curtain's are Falling Apart.		Pending	24/02/2026	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\STRAPS	several straps due for reolacement			24/02/2026	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		24/02/2026	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL GATES	Body\upright broken			24/02/2026	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\DAMAGE	curtains are falling apart		Pending	24/02/2026	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL WALL	left rear support post out of runner			17/02/2026	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		17/02/2026	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	L/H Rear Upright is out of runner.			17/02/2026	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	L/R Upright out of trailer.			17/02/2026	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)			14/01/2026	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	BORDER BANDAG PTY LTD	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		06/01/2026	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		04/12/2025	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Rear Left Upright is mostly off track only one wheel is still in track			04/12/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Insp\ANN INSP	Annual inspection	Insp\ANN INSP		04/12/2025	239389	PreventativeMaintenance	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)			07/11/2025	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	BORDER BANDAG PTY LTD	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		01/11/2025	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	DOORS BROKEN		Pendina	01/11/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Right rear curtain pole keep's coming out at top.			01/11/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Tear IN RHS Curtain.			01/11/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	CURTAIN WON'T SLIDE.			24/09/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Repair right rear curtain pole.			24/09/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT 23-24			23/08/2025	239389	Reapir	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	BORDER BANDAG PTY LTD	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		19/08/2025	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\MUDGUARDS	missing driver side rear mudflap			05/08/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	curtain track needs lubrication			05/08/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Post not locking at top		Pending	05/08/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	curtain ratchet handle rounded cant tiehten curtain			05/08/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRAKE ADJ	Brakes\BRAKE ADJ / CHECK			05/08/2025	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\HCV	ride control valve failing			05/08/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\MUDGUARDS	RHS mud flap missing.			23/07/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TRL LIGHTS	TRAILER PLUG PIN DAMAGED. REPLACE/ REPAIR PLUG.			23/07/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		23/07/2025	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)			26/06/2025	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	BORDER BANDAG PTY LTD	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		25/06/2025	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP11	Tyres\TP11			23/05/2025	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	BEAUREPAIRES	TRAILER
T259	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT TYRE POS 12			23/05/2025	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	BEAUREPAIRES	TRAILER
T259	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10			23/05/2025	239389	Reapir	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	BEAUREPAIRES	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		14/05/2025	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	R/H back upright is only hanging by one bearing. worried about it falling			03/04/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		03/04/2025	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRK RELINE	Full Brake Reline.			05/03/2025	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		30/01/2025	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Middle left and middle right need a reline asap,as they are at 3mm	11/12/2024	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\DAMAGE	Front Elec, Plug had to be Replaced But we didn"t have any screws to secure the cover in place. left it under the first str		"	05/12/2024	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		08/11/2024	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT 9 + 10			11/10/2024	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	BEAUREPAIRES	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	MI will need a new break oad soon	04/10/2024	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BREAKDOWN	Waste time checking brakes, because of a Doug Callout and Driver incompetence, both of which if brains where gunpow			23/08/2024	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		22/08/2024	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		19/07/2024	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	CUTAIN HAS A HUGE RIP ON THE L/H SIDE.			19/07/2024	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\INDICATORS	L/H REAR INDICATOR A BIT IFFY.			19/07/2024	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Repair Left Side Curtain Tear.			10/07/2024	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/04/2024	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	CURTAINS NEED REPLACING.			20/04/2024		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	REPLACE REAR DOORS			20/04/2024		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\HCV	REPLACE HCV AND BRACKET.			20/04/2024	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	REPLACE ALL HINGES AND LOCKS ON REAR DOORS.			20/04/2024	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE SHOCK MOUNTS.		CHECKED. OK. REPLACED REAR SHOCKS.	20/04/2024	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/04/2024	239389	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Insp\ANN INSP	Annual inspection As Per Checklist	Insp\ANN INSP		20/04/2024	239389	PreventativeMaintenance	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\MUDGUARDS	R/H/S REAR MUDFLAP MISSING.			09/04/2024		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRAKE ADJ	R/H/S REAR AXLE LOCKING UP ON BRAKING.			09/04/2024		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	R/H/S FRONT RATCHET FOR CURTAINS BROKEN.			09/04/2024		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\HCV	REPLACE HCV AND BRACKET.			16/03/2024		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	REPLACE ALL HINGES AND LOCKS ON REAR DOORS.			16/03/2024		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE SHOCK MOUNTS.			16/03/2024		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/03/2024	41718	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/03/2024	41718	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	REPLACE REAR DOORS			07/03/2024	41718	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	CURTAINS NEED REPLACING.			07/03/2024	41718	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRAKE ADJ	Adiust Brakes			10/02/2024	31267	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body	Strap Rollers Missing Winding Handles		Maxiparts supply HANDLE BENT TENSIONER CASTING FACET	23/01/2024	239389	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Albury Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	REPAIRED UPRIGHTS.			06/12/2023		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/11/2023	14004	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body	Strap Rollers Missing Winding Handles			24/11/2023	14004	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/11/2023	14004	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
			RIPS AND HOLES IN CURTAINS.													
T259	Albury - Workshop	Body\TRL REPS	AT END OF LIFE. NEED REPLACEMENT.			11/11/2023		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Albury Workshop	TRAILER
T259	Albury - Workshop	Body	Rios In Curtain's Both Sides			11/11/2023		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Albury Workshop	TRAILER
T259	Albury - Workshop	Body	Missing Buckles			11/11/2023		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Albury Workshop	TRAILER
			Repair Torn Curtain (Tape Up) (Elite Diesel)													
T259	Wodonga - Workshop	Body\TRL REPS	Purchase Order Number: WWO81852			24/10/2023	239389	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	REPLACED LF CURTAIN RATCHET.			21/10/2023	9996	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/10/2023	5579	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	NEED NEW HARDWARE AT BACK DOORS. SOME MISSING AND SOME WORN.			07/10/2023	5579	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	RIPS AND HOLES IN CURTAINS.			07/10/2023	5579	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Uprights need new rollers. Need new pelmet rubber.			07/10/2023	5579	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	REAR DOOR LATCHES NEED REPLACING.			07/10/2023	5579	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	MISSING STRAPS. DAMAGED CURTAINS.			07/10/2023	5579	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPAIRED LM CAM & SLACK ADJUSTER.	07/10/2023	5579	Service	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	DrivLine\WHEEL BRGS	REPLACE BEARINGS IN 6 HUBS.			06/09/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
			Check Brake & Wheel Bearing Adjustment (Bayswater Truck Centre)													
T259	Wodonga - Workshop	Brakes\BRAKE ADJ	Purchase Order Number: WWO80347			16/08/2023	239389	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			11/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Albury Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			11/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Albury Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			11/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Albury Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			11/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Albury Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			10/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Albury Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			10/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Albury Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	NEED NEW HARDWARE AT BACK DOORS. SOME MISSING AND SOME WORN.			10/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	RIPS AND HOLES IN CURTAINS.			10/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Uprights need new rollers. Need new pelmet rubber.			10/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	REAR DOOR LATCHES NEED REPLACING.			10/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRK RELINE	RELINES REQUIRED.			10/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\ELECT P&W	2 LIGHTS NEED REPLACING.			10/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	MISSING STRAPS. DAMAGED CURTAINS.			10/08/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Wodonga Workshop	TRAILER
			D Service As Per Attached Checklist													
T259	Wodonga - Workshop	VehService\DS	Not used since last service	VehService\DS		10/08/2023		Service	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
			CALLOUT AFTER HOURS													
			TRAVEL OUT TO BLUE METAL REST AREA PARKING BAY													
			CHECK LIGHTS NW- LOCATE SHORTING LIGHTS													
			TRACE WIRING - LOCATE BURNT OUT WIRING TO LHS NO PLATE LIGHT													
			DISCONNECT LIGHT- DRILL HOLE BIGGER FOR WIRING													
			REFIT AND REWIRE AND REPAIR BURNT WIRING													
T259	Wodonga - Workshop	Elect\BREAKDOWN	HAGANS PO# WWO79520			05/07/2023		Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/06/2023	12990	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	NEED NEW HARDWARE AT BACK DOORS. SOME MISSING AND SOME WORN.			10/06/2023	12990	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	RIPS AND HOLES IN CURTAINS.			10/06/2023	12990	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Uprights need new rollers. Need new pelmet rubber.			10/06/2023	12990	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	REAR DOOR LATCHES NEED REPLACING.			10/06/2023	12990	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRK RELINE	RELINES REQUIRED.			10/06/2023	12990	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/06/2023	12990	Service	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\ELECT P&W	2 LIGHTS NEED REPLACING.			10/06/2023	12990	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	MISSING STRAPS. DAMAGED CURTAINS.			10/06/2023	12990	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/03/2023	112365	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Uprights need new rollers. Need new pelmet rubber.			15/03/2023	112365	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	REAR DOOR LATCHES NEED REPLACING.			15/03/2023	112365	Reapir	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED LF WHEEL BEARING. REPLACED LR MUDFLAP.	15/03/2023	112365	Service	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRK RELINE	RELINES REQUIRED.			15/03/2023	112365	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Insp\ANN INSP	Annual inspection As Per Checklist	Insp\ANN INSP		15/03/2023	112365	PreventativeMaintenance	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/10/2022	97432	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Uprights need new rollers. Need new pelmet rubber.			25/10/2022	97432	Repair	Completed	FL Green Distribution	Chiller	Woodonga	LHS	711065	Woodonga Workshop	TRAILER

T259	Wodonga - Workshop	Body\STRAPS	RHR CURTAIN STRAP WHOLE ASSEMBLY BROKEN		OK.	25/10/2022	97432	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	NEED NEW HARDWARE AT BACK DOORS. SOME MISSING AND SOME WORN.			25/10/2022	97432	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\FITMENT	REPLACE RF LR INNER TYRES.			25/10/2022	97432	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	REAR DOOR LATCHES NEED REPLACING.			25/10/2022	97432	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	RIPS AND HOLES IN CURTAINS.			25/10/2022	97432	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/10/2022	97432	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/08/2022	88708	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\TRL LEGS	cross bar of lending legs has crack again, already checked with Andrew			27/08/2022	88708	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRNG HANG	Left front starting to crack again.			27/08/2022	88708	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Uprights need new rollers. Need new pelmet rubber.			27/08/2022	88708	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\STRAPS	RHR CURTAIN STRAP WHOLE ASSEMBLY BROKEN			27/08/2022	88708	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	UPRIGHT LHS FEET BROKEN.		REPAIRED UPRIGHTS. REPLACED MUDFLAP AND LH INDICATOR.	27/08/2022	88708	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	NEED NEW HARDWARE AT BACK DOORS. SOME MISSING AND SOME WORN.			27/08/2022	88708	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/08/2022	88708	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\FITMENT	REPLACE RF LR INNER TYRES.			27/08/2022	88708	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	REAR DOOR LATCHES NEED REPLACING.			27/08/2022	88708	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	RIPS AND HOLES IN CURTAINS.			27/08/2022	88708	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP3+4	SUIPPLY AND FIT 2TYRES			27/08/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\VALVES	Valves			31/05/2022	239389	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	WODONGA SPRING WORKS-4	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	Rear doors U/S - not sealing		#782522	28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Holes & rips, missing straps, RHR pelmet rubber broken poor condition Rips and holes missing straps		REPLACED STRAPS.	28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Tagged out aswell		#382512	28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	multiple soot curtain needs oatchine		#382512	28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\TRL LEGS	cross bar of lending legs has crack again, already checked with Andrew			28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRNG HANG	Left front starting to crack again.			28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	REAR DOORS NEED NEW BUSHES OF HARDWARE AND OUTER RUBBER		#382522	28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	Rear doors need hardware		#382522	28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Uprights need new rollers. Need new pelmet rubber.			28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\STRAPS	RHR CURTAIN STRAP WHOLE ASSEMBLY BROKEN			28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	UPRIGHT LHS FEET BROKEN.			28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	NEED NEW HARDWARE AT BACK DOORS. SOME MISSING AND SOME WORN.			28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	MULTIPLE STAPS MISSING. RR STRAP BROKEN.			28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	RIPS AND HOLES IN CURTAINS.		#382512	28/05/2022	6965	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP3+4	MIDDLE LEFT TYRE NEEDS A LOOK AT. SLIGHT DAMAGE TO CENTRE OF TREAD. (WHITE SHOWING)			28/05/2022	6965	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/05/2022	6965	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/04/2022	64819	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
					Carried out D Service											
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Issues found - Chassis cracks - marked with paint pen, 1 x loose shock	22/04/2022	64819	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/03/2022	59635	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/03/2022	59635	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	RIPS AND HOLES IN CURTAINS.			19/03/2022	59635	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/02/2022	53355	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\MUDGUARDS	LR GUARD, MUDFLAP AND OUTRIGGER BROKEN			05/02/2022	53355	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED RM WHEEL BEARINGS.	05/02/2022	53355	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	UPRIGHT LHS FEET BROKEN.			05/02/2022	53355	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	MULTIPLE STAPS MISSING. RR STRAP BROKEN.			05/02/2022	53355	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	NEED NEW HARDWARE AT BACK DOORS. SOME MISSING AND SOME WORN.			05/02/2022	53355	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/12/2021	48951	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\STRAPS	RHR CURTAIN STRAP WHOLE ASSEMBLY BROKEN			17/12/2021	48951	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP9+10	BLOWN TYRE REAR AXLE, LEFT SIDE BENT REAR GUARD ON TRAILER. TYRE IN RACK.			17/12/2021	48951	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/12/2021	48951	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\MUDGUARDS	LR GUARD, MUDFLAP AND OUTRIGGER BROKEN			17/12/2021	48951	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RUN OUT	fit runout to spare			01/12/2021	46638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP10	fit runout			27/11/2021		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/11/2021	42198	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL GATES	2nd gate from left front has crack in it.		CHECKED.	05/11/2021	42198	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\STRAPS	RHR CURTAIN STRAP WHOLE ASSEMBLY BROKEN			05/11/2021	42198	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	RR curtain strap broken.		#359715	05/11/2021	42198	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Uprights need new rollers. Need new pelmet rubber.			05/11/2021	42198	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
					ADJUSTED RF LF WHEEL BEARINGS.											
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	PICK UP. DROP OFF.	05/11/2021	42198	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP3+4	supply and fit 4 tyres			28/10/2021	42197	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			28/10/2021	42197	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/10/2021	40238	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/10/2021	40238	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	RR curtain strap broken.			06/10/2021	40238	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	Rear doors need hardware			06/10/2021	40238	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL WALL	Right wall upright broken from bottom.			06/10/2021	40238	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BOOSTER	LR Booster has loose nuts and bolts.			06/10/2021	40238	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Uprights need new rollers.			06/10/2021	40238	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Insp\ANN INSP	Annual inspection As Per Checklist	Insp\ANN INSP		06/10/2021	40238	PreventativeMaintenance	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\PRES CHECK	oressure maintenance POS 1-12			28/08/2021	36475	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP02	runout fitted			14/08/2021	35745	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/07/2021	35745	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP1+2	Left front both has cracks need to replace.			30/07/2021	35745	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TRL LIGHTS	Left front clearance lights is dull needs to be replaced. Left rear strap has to be replaced.			30/07/2021	35745	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Could not change as was restraining load.			30/07/2021	35745	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/07/2021	35745	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\STRAPS	CURTAIN PATCHING. PARK ON THE TOP AFTER THE JOB.			30/07/2021	35745	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	REAR DOORS NEED NEW BUSHES OF HARDWARE AND OUTER RUBBER			30/07/2021	35745	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\STRAPS	RHR CURTAIN STRAP WHOLE ASSEMBLY BROKEN			30/07/2021	35745	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Maintenance POS 1 -12 Valve Extension			22/07/2021	35744	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/06/2021	33407	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/06/2021	33407	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP1+2	Left front both has cracks need to replace.		Supply and fit 2 tyres	12/06/2021	33407	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TRL LIGHTS	Left front clearance lights is dull needs to be replaced.			12/06/2021	33407	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRNG HANG	Left front startine to crack aeain.			12/06/2021	33407	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL GATES	2nd gate from left front has crack in it. Left rear strap has to be replaced.			12/06/2021	33407	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Could not change as was restraining load.			12/06/2021	33407	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/06/2021		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\ANN INSP	Annual Inspection As Per Checklist			05/06/2021		PreventativeMaintenance	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/06/2021		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			14/05/2021	27913	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/05/2021	27913	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\AIR LEAK	air hose clamp was loose			14/05/2021	27913	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/03/2021		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	trailer has been parked in Albury depot since last service	27/03/2021		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
			Rapid Hydraulics Dis-assembled cylinder.													
			Found scoring on the chrome surfaces.													
			Linished all chrome surfaces to remove high spots.													
			Replaced all seals and O-Rings.													
			Assembled cylinder.													
T259	Wodonga - Workshop	Hydraulics\RAM	Non-Warranty repair due to chrome surfaces.			24/03/2021		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/02/2021		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	trailer has been parked in Albury depot since last service	15/02/2021		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	check trailer is empty and has gates for Dean. Hook up to with 1028 and park behind workshop			16/01/2021	23625	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/01/2021	23624	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	includine smoke time	15/01/2021	23624	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	multiple spot curtain needs patching			15/01/2021	23624	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	multiple strap is missing			15/01/2021	23624	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\TRL LEGS	cross bar of lending legs has crack again, already checked with Andrew			15/01/2021	23624	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/12/2020	19391	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\LIGHTS	LH too clearance liaht n/w			08/12/2020	19391	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRNG HANG	hanger support cracks		also had to weld holes on deck plate/floor and underside	08/12/2020	19391	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\LIGHTS	LH top clearance light n/w monitor R/L brake shoe - check next service		316924 job no. related with it	08/12/2020	19391	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\SLACK ADJ	LHR brake shoes not contacting with drum - possible worn 's' cam		checked	08/12/2020	19391	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/12/2020	19391	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres	spare tyre needs reolace			08/12/2020	19391	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\ELECT P&W	R.side wall clearance light and base plug run out		replaced l/duty elec base plug	08/12/2020	19391	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\LIGHTS	replaced R/hand c/lamp (inc L/hand duties)			08/12/2020	19391	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL LEGS	replace landing legs			18/11/2020	15916	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers			18/11/2020	15916	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\TRL LEGS	inspect trailer lea and aearbox function			18/11/2020	15916	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\TRL LEGS	replace legs			18/11/2020	15916	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL LEGS	PO FOR TRAILER LANDING LEGS			17/11/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
					inspect and repairs to scams											
T259	Wodonga - Workshop	Brakes\CONSUMABLE	weld S cam tubes		clean and weld s-cams	05/11/2020	14557	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\CLEAN	clean up from job			05/11/2020	14557	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRNG HANG	hanger support cracks			04/11/2020	14456	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		Carry Out D Service	04/11/2020	14456	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Carry out D Service	04/11/2020	14456	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\LIGHTS	LH top clearance light n/w			04/11/2020	14456	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Woodonga Workshop	TRAILER

T259	Wodonga - Workshop	Brakes\AIR LEAK	brake valve venting			04/11/2020	14456	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\LIGHTS	LH top clearance light n/w			04/11/2020	14456	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
			brake valve venting air - caused by faulty LHR booster													
T259	Wodonga - Workshop	Brakes\BOOSTER	L/H booster u/s			04/11/2020	14456	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
			monitor R/L brake shoe - check next service													
T259	Wodonga - Workshop	Brakes\SLACK ADJ	LHR brake shoes not contacting with drum - possible worn 's' cam		inspected boosters and relay valve - faulty LHR booster. Replaced. Noticed brakes weren't greased during service. Re-adjusted and greased brakes. Noticed LHR brake sh	04/11/2020	14456	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer			04/11/2020	14456	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\CLEAN	clean w/shop			04/11/2020	14456	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/09/2020	8470	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	REPLACE 1 BUCKLE LEFT HAND SIDE			30/09/2020	8470	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	move trailers	30/09/2020	8470	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
			poor condition													
			Rips and holes missing straps													
T259	Wodonga - Workshop	Body\TRL REPS	Tagged out aswell			30/09/2020	8470	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\LIGHTS	elec repairs RH side blinker side marker wirina			29/09/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\CLEAN	clean up from job			29/09/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/09/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL FLOOR	Floor lifting at front			03/09/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	Small gusset cracks			03/09/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Holes & rips. missine straps. RHR pelmet rubber broken			03/09/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Clean up included	03/09/2020		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TRL LIGHTS	LH tail light repairs			03/09/2020	4475	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/08/2020	2337	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
					Replaced mudflap											
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Welded airbag base	06/08/2020	2337	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL FLOOR	Floor lifting at front			06/08/2020	2337	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	Small gusset cracks			06/08/2020	2337	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TAIL LIGHT	RHR tail/brake lights missing LED's		Previously completed	06/08/2020	2337	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Holes & rips, missing straps, RHR pelmet rubber broken			06/08/2020	2337	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	Rear doors U/S - not sealing			06/08/2020	2337	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	LHM Shock mount cracked		Previously comoleted	06/08/2020	2337	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\CROSS MBR	Crossmember cracked		Previously completed	06/08/2020	2337	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SUSPENSION	RHR trailing arm has crack at airbag		Welded by M Watt	06/08/2020	2337	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\MUDGUARDS	RHR mudflap		Replaced	06/08/2020	2337	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\HCV	check for airleaks adjust and test ride height			17/07/2020	700	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\ELECT P&W	Job Added From Invoice			17/07/2020	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	DrivLine\WHL HUB	Job Added From Invoice			17/07/2020	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/07/2020	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SUSPENSION	RHR trailing arm has crack at airbag			10/07/2020	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/07/2020	0	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\MUDGUARDS	RHR mudflap			10/07/2020	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\WHL HUB	Fitted new hubbo		Fit light duty electrical base	10/07/2020	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\CLEAN	Clean up			10/07/2020	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer from beer shed			16/06/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Engine	Job Added From Invoice			10/06/2020	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/06/2020	83998	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TAIL LIGHT	RHR tail/brake lights missing LED's			05/06/2020	83998	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Holes & rips, missing straps, RHR pelmet rubber broken			05/06/2020	83998	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	Rear doors U/S - not sealing			05/06/2020	83998	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	LHM Shock mount cracked			05/06/2020	83998	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\CROSS MBR	Crossmember cracked			05/06/2020	83998	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SUSPENSION	RHR trailing arm has crack at airbag		As per #289498	05/06/2020	83998	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SUSPENSION	RHR trailing arm has crack at airbag			05/06/2020	83998	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/06/2020	83998	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	move set & drop get next set of trailers for repairs			04/06/2020	83998	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TAIL LIGHT	reolace RHR stoo tail laht			04/06/2020	83998	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\ELECT P&W	repairs to wires		notify to not hold water in all rear lights and mounts	04/06/2020	83998	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/05/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRING HANG	Hanger, hanger crossmember & base plate cracked			27/05/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	major cracks upper shock mounts			27/05/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CROSS MBR	cracks in cross supports underneath			27/05/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	curtains need replacing			27/05/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	Top & bottom shock mounts cracked			27/05/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	Top door locks loose			27/05/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\AIR BAG	Some bottom mounts cracked			27/05/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/05/2020		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			27/05/2020	183397	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			27/05/2020	183397	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/05/2020	182038	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	uprights need rollers and gates		Checked operation - ok	01/05/2020	182038	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\TRL LEGS	Occasionally jumpine out of gear		Couldn't fault	01/05/2020	182038	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/05/2020	182038	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Weld upright & straighten			01/05/2020	182038	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	Take trailer out of shed with S-Line			01/05/2020	182038	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	Top & bottom shock mounts cracked			01/05/2020	182038	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	Too door locks loose			01/05/2020	182038	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\AIR BAG	Some bottom mounts cracked			01/05/2020	182038	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\CLEAN	clam up			30/04/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			25/04/2020	165375	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			25/04/2020	165375	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/04/2020	166162	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	curtains need replacing			01/04/2020	166162	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	Small gusset cracks			01/04/2020	166162	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\TRL LEGS	Occasionally jumping out of gear			01/04/2020	166162	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRING HANG	Hanger, hanger crossmember & base plate cracked			01/04/2020	166162	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	uprights need rollers and gates			01/04/2020	166162	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	major cracks upper shock mounts			01/04/2020	166162	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CROSS MBR	cracks in cross supports underneath			01/04/2020	166162	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/04/2020	166162	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\ELECT P&W	change clearance light			01/04/2020	166152	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\REFLECTORS	reolace reflectors			01/04/2020	166152	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\REFLECTORS	repair uprights			01/04/2020	166152	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/03/2020	162493	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	curtains need replacing			04/03/2020	162493	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	DrivLine\WHEEL BRGS	all bearing need adjusting on LHS		Completed during service	04/03/2020	162493	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/03/2020	162493	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	Small gusset cracks			04/03/2020	162493	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\TRL LEGS	Occasionally jumping out of gear			04/03/2020	162493	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRING HANG	Hanger, hanger crossmember & base plate cracked			04/03/2020	162493	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	DrCabElect\SUZI COIL	change trailer plug & fix fuses for lights on trailetr			14/02/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	curtain rollers needed to be reolaced			01/02/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	repair uprights replace/weld new rollers weld cracks and fix base plates			29/01/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TRL LIGHTS	broken light bracket-replace reflector			29/01/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	re-do up-right repairs, after repairs had been told to do in a incorrect way		rollers and locks	18/01/2020	154888	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	L/H rear post roller comint out of track when moving post			18/01/2020	154888	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/01/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/01/2020		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/01/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/01/2020		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/01/2020	154888	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
					Rollers all ok											
T259	Wodonga - Workshop	Body\TRL REPS	curtains need replacing		All buckle strap holes U/S	18/01/2020	154888	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	DrivLine\WHEEL BRGS	all bearing need adjusting on LHS			18/01/2020	154888	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL LEGS	winding handle cracked needs welding		Reoairs comoleted	18/01/2020	154888	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\AIR BAG	RH front airbag and LH rear perishing		Not leaking - ok	18/01/2020	154888	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL LEGS	replaced landing lag under winder - 18/10/19		Ok, thanks	18/01/2020	154888	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TRL LIGHTS	Replaced RHS clearance light & LHS indicator			18/01/2020	154888	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	Move trailers, park & close up shed			18/01/2020	154888	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/01/2020	154888	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			25/12/2019	149578	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			25/12/2019	149578	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		carried out D Service	19/12/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL LEGS	needs new legs - gearbox u/s		inspected legs - operate perfectly fine - only thing wrong is the landing leg handle is cracked needs welding	19/12/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Carried out D Service	19/12/2019		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	DrivLine\WHEEL BRGS	all bearing need adjusting on LHS			19/12/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL LEGS	winding handle cracked needs welding			19/12/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL LEGS	replaced landing lag under winder - 18/10/19			19/12/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\AIR BAG	RH front airbag and LH rear perishing			19/12/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Insp\ANN INSP	carry out Annual Inspection			20/11/2019	146952	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/11/2019		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/11/2019	146952	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/11/2019	146952	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	curtains need reolacine			20/11/2019	146952	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL LEGS	needs new legs - gearbox u/s			20/11/2019	146952	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SUSPENSION	bushes worn			20/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL FLOOR	floor fitting			20/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\AIR LEAK	2 arms have small cracks around airbags mounts			20/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	chassis/susset cracks			20/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL GATES	Repair broken gates			04/11/2019	143859	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RUN OUT	Job Added From Invoice			17/10/2019	728161	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice			17/10/2019	728161	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\CHN/RLR/MN	curtain rollers L side need lookine out			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Woodonga Workshop	TRAILER

T259	Wodonga - Workshop	Body\TOOLBOX	toolbox is bent at the front			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	RM cross member at welded is cracked		previously completed	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	crack on RHM x-member		previously completed	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	curtain strap and buckle missing some holes in curtains as rollers need replacing LH shoe has 5mm kick LH shoe has 3mm kick			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRK RELINE	all axles need reline		previously completed	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\AIR FITTIN	need Hduty plug and reverse lights fitted number plate lights out			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\PANELS	nose cone need attention		inspected - cant find anything wrong with nose cone	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	missing straps some holes also missing buckle straps bent poles rollers need replacing			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	DrivLine\WHL HUB	resack in reline			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SUSPENSION	trailer arm cracked RHM RHR		previously completed	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SUSPENSION	bushes worn 6mm kick reline 3mm kick reline		trailing arm bush's	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRK RELINE	all axles		previously completed	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL FLOOR	rear bar cracks		previously completed	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Insp\BRK RELINE	recommend reline soon		previously completed	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	rips holes strap missing			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar bent		previously completed	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL FLOOR	floor fitting			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\AIR LEAK	2 arms have small cracks around airbaes mounts kicking 5mm on RH kicking 3mm on RH			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BOOSTER	needs full reline		previously completed	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\MUDGUARDS	front mudflap bracket bent		previously completed	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	strap broken/rips and tears			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	chassis/gusset cracks			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\DAMAGE	Damaged Equipment			03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	curtains need oiline			03/10/2019	139123	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\DAMAGE	Broken rear bumper on RHS		previously completed	03/10/2019	139123	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/10/2019	139123	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SUSPENSION	scam was incorectly mounted to axle mount ,cuasing the scam to lock on and drag wheels		removed wheels and brakes to inspect ,found problem and readjusted the scam mount to correct the problem and reassembled parts	03/10/2019	139123	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			01/09/2019	135242	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			01/09/2019	135242	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Steering\WHEEL SEAL	Job Added From Invoice			30/08/2019	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Job Added From Invoice			30/08/2019	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRK RELINE	Job Added From Invoice			30/08/2019	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	DrivLine\WHEEL BRGS	Job Added From Invoice			30/08/2019	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRK RELINE	oreo hubs for reline. out brakes toeether			30/08/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRK RELINE	Reline			30/08/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	finish off rear bar welding paint rear bar and structure, prep and clean			10/08/2019	135242	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\HOUSEKEEP	let paint set			10/08/2019	135242	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\ELECT P&W	start rewiring lights and mounting them			10/08/2019	135242	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	curtain repairs/rehane curtains			09/08/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\CLEAN	cleaning			09/08/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	check trailer over and move trailer			09/08/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CROSS MBR	rear bar bent bent cracks in cross members			09/08/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\DAMAGE	Start on rear bar repairs while assisting Adon on 553 deck repairs			08/08/2019	135242	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\DAMAGE	Cut rear bar off. oreo & weld new bar on.		Reaositioned bumo stoos & liahts	08/08/2019	135242	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes			#Requires reline	20/07/2019	132746	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\ELECT P&W	Replaced number plate light			20/07/2019	132746	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\DAMAGE	Rear bar broken			20/07/2019	132746	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		20/07/2019	132746	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/06/2019	129061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	shocky bushes need replacing		previously completed	19/06/2019	129061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\AIR BAG	RHF airbag leaking		previously completed	19/06/2019	129061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP01	1 middle inner tyre		previously completed	19/06/2019	129061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\HOSES	leaking hoses		previously completed	19/06/2019	129061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\AIR BAG	IT!7CAS 1x airbae		previously completed	19/06/2019	129061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL GATES	right pole to be fix at back trailer		previously done	19/06/2019	129061	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\MUDGUARDS	front mudflap bracket bent			19/06/2019	129061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	strap broken/rips and tears			19/06/2019	129061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	chassis/gusset cracks			19/06/2019	129061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/06/2019	129061	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TRL LIGHTS	no left side indicator		replace and rewire plug and fuses	18/06/2019		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	service moving trailers			08/05/2019	124884	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\AIR LEAK	repairs air leaks			08/05/2019	124884	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\CLEAN	cleaning			08/05/2019	124884	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	rips holes strap missine			08/05/2019	124884	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BOOSTER	booster lines leaking			08/05/2019	124884	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar bent			08/05/2019	124884	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL FLOOR	floor fitting			08/05/2019	124884	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\AIR LEAK	2 arms have small cracks around airbags mounts			08/05/2019	124884	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\AIR BAG	IT!7CAS 1x airbae kicking 5mm on RH kicking 3mm on RH			08/05/2019	124884	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BOOSTER	needs full reline			08/05/2019	124884	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/05/2019	124884	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		08/05/2019	124884	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			03/05/2019	10	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			03/05/2019	10	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/04/2019	124203	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	repair damaged curtain pole			30/04/2019	124203	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer to beer shed for them			30/04/2019	124203	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\TP01	1 middle inner tyre			30/04/2019	124203	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL FLOOR	rear bar cracks			30/04/2019	124203	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TOOLBOX	rear toolbox bent			30/04/2019	124203	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\HOSES	leaking hoses			30/04/2019	124203	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Insp\BRK RELINE	recommend reline soon			30/04/2019	124203	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/04/2019	124203	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TRL LIGHTS	too 3 lights art rear of trailer out		previously done	14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	the uprights need wedding bits on the bottom of then see that will stay in place. Also the uprights are bent out			14/03/2019	117192	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	I tightened booster lines but all need replacing all repairs to be carried out in in reline	14/03/2019	117192	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\AIR FITTIN	need Hduty plug and reverse lights fitted number plate lights out			14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\PANELS	nose cone need attention			14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	missine straps some holes also missine buckle straps bent poles rollers need reolacine booster lines leaking			14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BOOSTER	replace booster lines			14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	DrivLine\WHL HUB	repack in reline			14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SUSPENSION	trailer arm cracked RHM RHR			14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SUSPENSION	bushes worn			14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	shocky bushes need reolacine			14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\AIR BAG	RHF airbag leaking 6mm kick reline 3mm kick reline			14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRK RELINE	all axles			14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	repairs moving trailers			14/03/2019	117192	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/02/2019	112200	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	rolls off cur are fuck		the rollers in curtains are as described talk to workshop supervisor	05/02/2019	112200	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	the uprights need wedding bits on the bottom of then see that will stay in place. Also the uprights are bent out		job pending till all repairs are to be completed ref Dean	05/02/2019	112200	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TRL LIGHTS	top 3 lights art rear of trailer out			05/02/2019	112200	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	curtain strap and buckle missing some holes in curtains as rollers need replacing			05/02/2019	112200	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CROSS MBR	rear bar bent bent cracks in cross members LH shoe has 5mm kick LH shoe has 3mm kick			05/02/2019	112200	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes\BRK RELINE	all axles need reline			05/02/2019	112200	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		05/02/2019	112200	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			16/01/2019	10	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			16/01/2019	10	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer			22/12/2018	105949	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\CLEAN	clean workshop			22/12/2018	105949	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/12/2018	105949	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	service	VehService\DS		22/12/2018	105949	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/12/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	RHS curtain winder is stripped cant tighten curtains			22/12/2018		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/12/2018		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\WINCH/STRP	Job Added From Invoice			13/11/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Trailer (Tautliner) Repairs		started on RNRs pulled apart RH curtain rackle and looked for parts need but could not find. Could not put ratchet back together because I believe it was unsafe order pa	06/11/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL GATES	make and fit starps to hold gates in rack			03/11/2018	96419	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\TRL LIGHTS	Job Added From Invoice			24/10/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/10/2018	93194	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	RHS curtain winder is stripped cant tighten curtains LH clearance light move trailer			16/10/2018	93194	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	clean up curtains are really hard to pull and jerky it is a hazard needs to be fixed curtain poles bent needs to be fixed	16/10/2018	93194	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL GATES	repair damaged trailer gates		moving trailers	29/08/2018	85763	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Job Added From Invoice			29/08/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/08/2018	84813	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	rolls off cur are fuck			23/08/2018	84813	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	RHS curtain winder is stripped cant tighten curtains			23/08/2018	84813	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	7110GS	Wodonga Workshop	TRAILER

T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/08/2018	84813	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	DrivLine\WHEEL BRGS	Inspect & repack outer bearings			23/08/2018	84813	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Replace RHF curtain handle		refer to job no. 184994	23/08/2018	84813	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	Ratchet handle on driver side is broken		Replace RHF curtain handle	23/08/2018	84813	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/07/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRNG HANG	bushes u/s			26/07/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRNG HANG	all bushs worn u/s			26/07/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	all bushs's on rear door poles & locks u/s both dors have excessive movement needs new hand ratchet on front at curtain on front R/Hand side. I have reportoed this on the 22.06.18 was supposed to be fixed but wasn't?			26/07/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\CHN/RLR/MN	Gate that's been welded will need new tabs on it as well			26/07/2018		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/07/2018		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		26/07/2018		PreventativeMaintenance	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			22/06/2018	16857	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/06/2018	76857	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	curtains tensioner both sides		oreviously done	20/06/2018	76857	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/06/2018	76857	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	DrivLine\WHL HUB	remove hub caps and check nuts/locking nuts for proper installation and tightness			20/06/2018	76857	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	replace RHF & RHM shocks			20/06/2018	76857	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\AIR FITTIN	repalce pressure valve			20/06/2018	76857	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	air up trailer - check brakes and oark in vard			20/06/2018	76857	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/05/2018	69988	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/05/2018	69988	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Elect\ELECT P&W	replaced 2x c/lamps			18/05/2018	69988	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\CHN/RLR/MN	replace RHF ratchet handle			11/05/2018	68655	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres	Job Added From Invoice			03/05/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			27/04/2018	65086	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/03/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	Service Trailer	VehService\DS		28/03/2018		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			24/02/2018	55970	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		adiusted	23/01/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\DRV TYRES	monitor LHF set and R/H/R inner		replaced previously	23/01/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\HOUSEKEEP	signage RHS of crash bar u/s		signs replaced leave till next service	23/01/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	front right top shock bush worn		safe to use	23/01/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp	no shockie straps		trailer nut fitted for shocker straps	23/01/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/01/2018		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			11/01/2018	92341	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			11/01/2018	92341	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		complete during service	22/12/2017	46815	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/12/2017	46815	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\DRV TYRES	monitor LHF set and R/H/R inner			22/12/2017	46815	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\HOUSEKEEP	signage RHS of crash bar u/s			22/12/2017	46815	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	missing strap, curtain damage			22/12/2017	46815	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	DrivLine\WHEEL BRGS	adjust front and middle axle bearings			22/12/2017	46815	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRNG HANG	monitor left front spring eye bush			22/12/2017	46815	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	front riaht top shock bush worn			22/12/2017	46815	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp	no shockie straps			22/12/2017	46815	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	took to trailer shed for service had already been done (service stick not changed) took back to yard did quick visual insp			23/11/2017		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			23/11/2017	39642	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			23/11/2017	39642	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/11/2017	40344	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRNG HANG	all bushs worn u/s			21/11/2017	40344	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL DOORS	all bushs's on rear door poles & locks u/s both dors have excessive movement			21/11/2017	40344	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	Service "B" Trailer	VehService\DS		21/11/2017	40344	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\AIR FITTIN	replace air line connection			07/11/2017		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SPRNG HANG	bushes u/s			20/10/2017	35475	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/10/2017	35475	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/10/2017	35475	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/09/2017	32050	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	RM cross member at welded is cracked			28/09/2017	32050	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Susp\SHOCK ABS	LF RM shocker weesine			28/09/2017	32050	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/09/2017	32050	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Chassis\CHAS CRACK	crack on RHM x-member			28/09/2017	32050	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL REPS	repair curtain ratchet handle			28/09/2017	32050	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			27/09/2017	31299	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			27/09/2017	31299	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			26/09/2017	29086	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Tyres\RUN OUT	Job Added From Invoice			26/09/2017	29086	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Workshop\MOVE ASSET	moved trailer for bar shed			22/09/2017		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/08/2017	26974	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	Body\TRL LEGS	gearbox on lees u/s			30/08/2017	26974	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER
T259	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/08/2017	26974	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHS	711065	Wodonga Workshop	TRAILER