EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T201	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Jamie and cheyne on service	08/07/2026	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		12/05/2026	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		16/04/2026	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	John ,,, Corey	18/03/2026	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		18/03/2026	8370	PreventativeMaintenance	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			28/02/2026	8370	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	BORDER BANDAG PTY LTD	TRAILER
T201	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)			20/02/2026	8370	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	BORDER BANDAG PTY LTD	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		14/02/2026	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	-service -painted rear bar -needs right hand side caution decal ((none in yard)) -full lights check conducted	13/12/2025	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\ELECT P&W	Replace right rear clearance light,.		-marker lights replaced as required	24/10/2025	8370	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Reline needed and s cams replaced asap after unloading Mr airbag needs to be replaced	24/10/2025	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\INDICATORS	No L/H Indicator		-indicator lights not working due to faulty trailer plug -B trailer combination lights should be swapped out for red/amber -didnt have enough time to replace A trailer combination light	28/07/2025	8370	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 28			21/07/2025	8370	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	BORDER BANDAG PTY LTD	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		18/07/2025	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	Replace left middle shockabsorber.			13/06/2025	8370	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		13/06/2025	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4			02/06/2025	8370	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	BEAUREPAIRES	TRAILER
T201	Wodonga - Workshop	Brakes\BOOSTER	REPLACED LM BOOSTER.			02/05/2025	8370	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Weilding repairs	04/04/2025	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BREAKDOWN	GRAHAM THOMPSON MOTORS- RF BRAKE LOCKING ON WHEN GOING FORWARD.		DIAGNOSED AND REPLACED BOOSTER.	03/04/2025	8370	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			21/03/2025	8370	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	BEAUREPAIRES	TRAILER
T201	Wodonga - Workshop	Elect\BRK LIGHT	NO BRAKE LIGHTS. TRAILER LIGHTS FLICKERING		REPAIRED ON WO#195112	14/03/2025	8370	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Reline needed asap,,,,,, pad slap mr	07/03/2025	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\AIR LEAK	Losing too much air whilst braking.		Found two incorrect boosters front right and middle right relay valve needs replacing and a full reline to be carried out Rebuild hubs for reline	20/12/2024	8370	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		12/12/2024	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\Punct	Repair Tyre Puncture Position 7. (Wodonga Tyre & Auto P/O: WW090163)			16/11/2024	8370	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	BEAUREPAIRES	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		05/11/2024	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		20/09/2024	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		20/09/2024	8370	PreventativeMaintenance	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		22/08/2024	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	Replace middle left lower shocker mount, and replace middle left and rear left shockabsorbers.			21/06/2024	8370	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\HCV	TRAILER GEIGHT VALVE NOT WORKING. TRAILER WILL BE IN THE YARD ALL DAY TUESDAY.			21/06/2024	8370	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP10	Tyre Position 10			25/04/2024	8370	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Albury Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			25/04/2024	8370	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Albury Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/04/2024	34393	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	Brake Re-line			25/04/2024	34393	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\RWC COMP	VEHICLE SIGN ON REAR RHS FALLEN OFF.			25/04/2024	34393	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED 2 LIGHTS.	25/04/2024	34393	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\PAINT/REST	TONY WANTS BACK OF TRAILER PAINTED.			22/03/2024		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Unknown	TRAILERS WILL BE HOME ALL DAY WEDNESDAY. TRAILERS NEED A SERVICE.			22/03/2024		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP09	Tyre Position 9			01/02/2024		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Albury Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/11/2023	10226	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/11/2023	10226	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	FULL RELINE.			04/11/2023	10226	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\PAINT/REST	TONY WANTS BACK OF TRAILER PAINTED.			04/11/2023	10226	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	NEW GUARDS REAR LHS.			04/11/2023	10226	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\MUDGUARDS	Replace Damaged Guards			04/11/2023	10226	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2023	2064	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\BRK LIGHT	BRAKE LIGHT ISSUE.			02/09/2023	2064	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/09/2023	2064	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	FULL RELINE.			02/09/2023	2064	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			26/08/2023		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Albury Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/07/2023	45070	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	BOTH FRONT HANGERS CRACKED.		To be done at next reline.	15/07/2023	45070	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE RR SHOCK.			15/07/2023	45070	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/07/2023	45070	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		15/07/2023	45070	PreventativeMaintenance	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/07/2023	8370	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			14/07/2023	8370	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKE ADJUSTMENT.			23/06/2023		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			09/05/2023		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Albury Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			03/05/2023		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Albury Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/03/2023	27063	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\INDICATORS	REPAIR LR INDICATOR.			21/03/2023	27063	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\CLEAN	CLEAN UP.			21/03/2023	27063	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED RR WHEEL BEARING.	21/03/2023	27063	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	BOTH FRONT HANGERS CRACKED.			21/03/2023	27063	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	REPLACE RR SHOCK.			21/03/2023	27063	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			17/03/2023		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Albury Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/11/2022	9526	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Myrtleford Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED LF AIRBAG.	26/11/2022	9526	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Myrtleford Workshop	TRAILER
T201	Wodonga - Workshop	Elect\INDICATORS	REPAIR LR INDICATOR.			26/11/2022	9526	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Myrtleford Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\CLEAN	CLEAN UP.			26/11/2022	9526	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Myrtleford Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\TRL LEGS	REPAIR LEG BRACES.			07/10/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	RELINES DUE.			07/10/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/10/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\STRAPS	I NEED 2x BOXES OF 11METRE BINDER STRAPS. I NOTE THAT THERE ARE RATCHET AND STRAPS IN THE TOOLBOX OF THE 'A'. BUT THEY ARE 9METRE STRAPS AND TOO SHORT TO REACH OVER P/			07/10/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\ELECT P&W	REPAIR LF CLEARANCE LIGHT.		REPLACED 2 FRONT AND 1 RH CLEARANCE LIGHTS.	07/10/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	REPAIR CRACKED FRONT HANGER.			07/10/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/10/2022		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\TAIL LIGHT	LHS REAR TAIL LIGHT NOT WORKING.			07/10/2022		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Unknown	OVERDUE FOR SERVICE.			07/10/2022		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP9+10	supply and fit 4 tyres			06/10/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			06/10/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Albury - Workshop	Brakes\BRAKE ADJ	BRAKE ADJUSTMENT.			05/10/2022		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Albury Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	carry out full brake reline		TCTC supply partS REPAIRED AIR LEAKS AND SIGN. CLEANED UP.	01/10/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BOOSTER	Air leak Travel to green wattle gap turnoff discovered RHF booster leaking replace booster, start and check RHS centre let go Get booster dropped off and fit Adiust brakes and check			29/09/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/08/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\STRAPS	I NEED 2x BOXES OF 11METRE BINDER STRAPS. I NOTE THAT THERE ARE RATCHET AND STRAPS IN THE TOOLBOX OF THE 'A'. BUT THEY ARE 9METRE STRAPS AND TOO SHORT TO REACH OVER P/			10/08/2022		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/08/2022		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\ELECT P&W	REPAIR LF CLEARANCE LIGHT.			10/08/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	REPAIR CRACKED FRONT HANGER.			10/08/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\TRL LEGS	REPAIR LEG BRACES.			10/08/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	RELINES DUE.			10/08/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP09	puncture repair			29/07/2022		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKE ADJUSTMENT.			13/07/2022	739985	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/06/2022	367586	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/06/2022	367586	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\DAMAGE	rear bar needs replacing			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SUSPENSION	Front SEB bushes to be replaced			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SUSPENSION	Trailing arm hangers cracked			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\WHL HUB	poor condition			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\SLACK ADJ	front hangers cracked, LF, RM scam tubes need welding			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	RM shock mount broken			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\TP06	small body cracks			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\SKID PLATE	skid plate has mark, check with Andrew, Adon as well			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	RHF hangers got crack			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	both middle one shocks mount has broken			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SUSPENSION	Both front hangers have cracks.			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	LM LOWER SHOCK MOUNT BROKEN.			04/05/2022	361902	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/05/2022	361902	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/03/2022	354074	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	Both lower shock mounts U/S Middle axle.			18/03/2022	354074	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/03/2022	354074	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	Right front hanger cracked.			18/03/2022	354074	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	RF HANGER CRACKED NEAR BOLT			18/03/2022	354074	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	FRONT HANGERS CRACKED BOTH SIDES.			18/03/2022	354074	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	RF HANGER CRACKED BELOW BOSS			18/03/2022	354074	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRAKE ADJ	Brales dragging.			18/03/2022	354074	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\STRAPS	2 x BOXES OF 11 METRE BINDER STRAPS NEEDED.			18/03/2022	354074	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\STRAPS	2 x BOXES 11 METRE BINDER STRAPS. Please let me know when they're in.			18/03/2022	354074	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\STRAPS	2 x BOX OF 11 METRE BINDER STRAPS NEEDED.			18/03/2022	354074	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\STRAPS	STILL NEED 2 x BOX'S OF NEW 11 METRE BINDER STRAPS			18/03/2022	354074	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	LM LOWER SHOCK MOUNT BROKEN.			18/03/2022	354074	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP9+10	supply and fit 2tyres			18/02/2022	348505	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2022	343230	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/01/2022	343230	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	RF HANGER CRACKED BELOW BOSS			25/01/2022	343230	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/12/2021	340653	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\TAIL LIGHT	Rego globe not working.			23/12/2021	340653	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\AIR LEAK	Trailer dumping all its air.			23/12/2021	340653	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED RR LF WHEEL BEARINGS	23/12/2021	340653	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP1+2	supply and fit 2 tyres			24/11/2021	334325	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/11/2021	333317	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP04	flat tyre rhs front axle outside			19/11/2021	333317	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED FL RR WHEEL BEARINGS. REPAIRED RH CLEARANCE LIGHT.	19/11/2021	333317	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER

T201	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		19/11/2021	333317	PreventativeMaintenance	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRING HANG	FRONT HANGERS CRACKED BOTH SIDES.			19/11/2021	333317	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\INDICATORS	LH BLINKER NOT WORKING		REPAIRED TRAILER PLUG PINS CLOSED UP	17/11/2021	332818	Fault	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP04	puncture repair			02/11/2021	330248	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			05/10/2021	324429	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\AIR LEAK	Trailer dumps all its air intermittently when Maxi's applied			05/10/2021	324429	Fault	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED LF RF WHEEL BEARINGS	05/10/2021	324429	Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\TRL LIGHTS	REPLACED NUMBER PLATE LIGHT GLOBE. REWIRED LH SIDEWALL CLEARANCE LIGHT. PARKED IN YARD			05/10/2021	324429	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRING HANG	RF HANGER CRACKED NEAR BOLT			05/10/2021	324429	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BOOSTER	Replace right rear booster.		REPLACED RR BOOSTER IN FREIGHT SHED	02/10/2021		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP3+4	Supply and fit 2 tyres			14/08/2021	316294	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/08/2021	316294	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP03	Right Front inner tyre replaced			13/08/2021	316294	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\TAIL LIGHT	Rego globe not working.			13/08/2021	316294	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRING HANG	Right front hanger cracked.			13/08/2021	316294	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	Right middle shock mount broken.		Replaced middle axle bottom shock mounts.	13/08/2021	316294	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/08/2021	316294	Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRAKE ADJ	Brake Adjustment.			29/07/2021		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\AIR LEAK	check for air leaks			29/07/2021		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRAKE ADJ	Brake Adjustment.		Refer Job# 348093	29/07/2021		Fault	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\AIR LEAK	Rear tris loosing air when Maxi's applied.		Refer Job# 348094	29/07/2021		Fault	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
					RE-LINE ALL BRAKES, CHECK ALL BEARINGS ETC													
					FULL RE-LINE, CHECK BEARINGS ETC.													
					JACKED UP ALL AXLES AND SUPPORT ON STANDS.													
					REMOVED ALL WHEELS AND BRAKE DRUMS.													
					REMOVED ALL HUBS AND BEARINGS.													
					REMOVED ALL BRAKE SHOES AND S-CAMS.													
					CUT OUT OLD S-CAM TUBES.													
					INSTALLED ALL NEW S-CAM TUBES AND PLATES AND WELD INTO POSITION.													
					INSTALLED NEW S-CAMS.													
					REMOVED AND REPLACED ALL ANCOR PINS.													
					CLEANED ALL BEARINGS AND HUBS AND INSPECTED BEARINGS.													
					RE-PACKED ALL WHEEL BEARINGS AND INSTALLED.													
					INSTALLED NEW HUB SEALS AND RE-FITTED HUBS.													
					ADJUSTED WHEEL BEARINGS.													
					INSTALLED NEW BRAKE SHOES AND FITTED NEW DRUMS.													
					RE-FITTED ALL WHEELS AND TENSIONED ALL WHEEL NUTS TO SPEC.													
					GREASED AND ADJUSTED ALL BRAKES.													
T201	Wodonga - Workshop	Brakes\BRK RELINE	Full reline done by Daimler.		REMOVED STANDS AND LOWER AXLES ON GROUND.	20/07/2021		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
			Record Check Results As Attached To This Job															
T201	Wodonga - Workshop	Brakes	Needs Reline ASAP!		Refer Job# 346729	20/07/2021		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP3+4	Supply and fit 2 tyres			24/06/2021	310692	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
			Record Check Results As Attached To This Job															
T201	Wodonga - Workshop	Brakes	Needs Reline ASAP!			24/06/2021	310692	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\LIGHTS	R clearance, number plate light			24/06/2021	310692	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\LIGHTS	L rear number plate light			24/06/2021	310692	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\HOUSEKEEP	Housekeeping			24/06/2021	310692	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres	RHF inner		Changed by Tyre Fitter	24/06/2021	310692	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\TRL LIGHTS	Rh clearance mount u/s			24/06/2021	310692	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
			Rh kicking 4mm															
T201	Wodonga - Workshop	Brakes\BRK RELINE	Rh kickina out 8mm		Refer Job# 343306	24/06/2021	310692	Repair	Comoleted	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\LIGHTS	rego globes, R.H clearance light hanging			24/06/2021	310692	Repair	Comoleted	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	guards need replacing			24/06/2021	310692	Repair	Comoleted	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
			need reline around 3mm															
T201	Wodonga - Workshop	Brakes\BRK RELINE	RHR around 4mm. Kickine out drum		Refer Job# 343306	24/06/2021	310692	Repair	Comoleted	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshoo	TRAILER
			Left hand side rear blinker very dull.															
T201	Wodonga - Workshop	Elect\INDICATORS	Cant be seen that well in daviliht as well.			24/06/2021	310692	Fault	Comoleted	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshoo	TRAILER
			Brakes staying on.															
T201	Wodonga - Workshop	Brakes\BRAKE ADJ	Brakrne not oulline truck ue aood enouah.		Refer Job# 343306	24/06/2021	310692	Fault	Comoleted	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonea Workshoo	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		24/06/2021	310692	Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SUSPENSION	Both front hangers have cracks.			24/06/2021	310692	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	Both lower shock mounts L/S. Middle axle.			24/06/2021	310692	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/05/2021	302415	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/05/2021	302415	Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	guards need replacing			13/05/2021	302415	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\LIGHTS	rego globes, R.H clearance light hanging			13/05/2021	302415	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Comp\Truck Safe	replaced with new one			13/05/2021	302415	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\SKID PLATE	skid plate has mark, check with Andrew, Adon as well			13/05/2021	302415	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRING HANG	RHF hangers got crack			13/05/2021	302415	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	both middle one shocks mount has broken			13/05/2021	302415	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
			need reline around 3mm kick out															
T201	Wodonga - Workshop	Brakes\BRK RELINE	RHR around 4mm. Kicking out drum			13/05/2021	302415	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\STRAPS	Job Added From Invoice			07/04/2021	0	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/03/2021	291156	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	welded cracks and shocker mounts	11/03/2021	291156	Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres	RHF inner			11/03/2021	291156	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\TRL LIGHTS	Rh clearance mount u/s			11/03/2021	291156	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\TP06	small body cracks			11/03/2021	291156	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRING HANG	both front hangers cracked			11/03/2021	291156	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SUSPENSION	middle scam broken			11/03/2021	291156	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	LH & RH shock mounts broken			11/03/2021	291156	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
			RH kicking 4mm															
T201	Wodonga - Workshop	Brakes\BRK RELINE	RH kickina out 8mm			11/03/2021	291156	Repair	Comoleted	FL Green Distribution	Chiller		Wodonea	LHB	529285	Wodonea Workshoo	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/02/2021	888527	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/02/2021	888527	Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\LIGHTS	L rear number plate light			04/02/2021	888527	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\SLACK ADJ	front hangers cracked, LF, RM scam tubes need welding			04/02/2021	888527	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	RM shock mount broken			04/02/2021	888527	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\HOUSEKEEP	Housekeeping			04/02/2021	888527	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\No Show	D Service As Per Attached Checklist			29/01/2021	8370	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			29/01/2021	8370	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Comp\Truck Safe	MYIR sticker needs replacing			29/01/2021	8370	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\HOUSEKEEP	LM lower shocky mount broken, left side coaming rail major dent			29/01/2021	8370	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	L/centre bottom mount			29/01/2021	8370	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\SHOCK ABS	L. middle axle shock need replace			29/01/2021	8370	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\VALVES	maxi valve			29/01/2021	8370	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	mount snapped MR			29/01/2021	8370	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\AIR LEAK	brakes sticking on			29/01/2021	8370	Fault	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\AIR LEAK	brakes sticking on			29/01/2021	8370	Fault	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP5+6	replace 2 tyres			24/12/2020	279361	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/12/2020		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	yard check, move trailers	24/12/2020		Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\LIGHTS	R clearance, number plate light			24/12/2020		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\WHEEL BRGS	adjusted RR and repack outer bearing			24/12/2020		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\WHL HUB	poor condition			24/12/2020		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRING PACK	front hangers, FL axle saddle			24/12/2020		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	mount snapped MR			24/12/2020		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/11/2020	273820	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SUSPENSION	Front SEB bushes to be replaced		Andrew checked it, need 1/2 day off the road	25/11/2020	273820	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SUSPENSION	Trailing arm hangers cracked			25/11/2020	273820	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\VALVES	maxi valve			25/11/2020	273820	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\HOUSEKEEP	LM lower shocky mount broken, left side coaming rail major dent		315414 job releated with this	25/11/2020	273820	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	L/centre bottom mount		315414 job no. related with this	25/11/2020	273820	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\AIR LEAK	brakes sticking on			25/11/2020	273820	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\AIR LEAK	brakes sticking on		315419 job no. related with this	25/11/2020	273820	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/11/2020	273820	Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\TP06	crack in back bad, need replace			25/11/2020	273820	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\WHEEL BRGS	adjusted L.R			25/11/2020	273820	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\SHOCK ABS	L. middle axle shock need replace			25/11/2020	273820	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/10/2020	266279	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	welded spare wheel carrier frame	13/10/2020	266279	Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\VALVES	maxi valve			13/10/2020	266279	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\HOUSEKEEP	LM lower shocky mount broken, left side coaming rail major dent			13/10/2020	266279	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	L/centre bottom mount			13/10/2020	266279	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\STRAPS	change last binder			18/09/2020		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp	Repair R/Centre bottom shock mount and weld cracks in x members			15/09/2020	261259	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/09/2020	261259	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRAKE ADJ	L kicking out 2mm		previously done	15/09/2020	261259	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/09/2020	261259	Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\MUDGUARDS	r/rear marker			15/09/2020	261259	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\AIR FITTIN	r/centre bottom mount			15/09/2020	261259	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/08/2020		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/08/2020		Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Comp\Truck Safe	need to order			18/08/2020	25615	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\SLACK ADJ	inspect brakes			18/08/2020	25615	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/08/2020	25615	Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/08/2020	25615	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	RtHM shock mount broken			18/08/2020	25615	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\BRK LIGHT	Rh brake light faulty		Previously completed	18/08/2020	25615	Fault	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
			inspect suspension															
T201	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock mount broken			18/08/2020	25615	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	RHM shock mount broken			18/08/2020	25615	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SUSPENSION	Trailing arm hangers cracked			18/08/2020	25615	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BOOSTER	replace booster cage and pin			15/08/2020		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\SLACK ADJ	inspect brakes		all brakes kicking out D washers need replacing	14/08/2020	255910	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
			inspect suspension															
T201	Wodonga - Workshop	Susp\SHOCK ABS	LHM shock mount broken			14/08/2020	255910	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\BRK LIGHT	replace R/H stop tail light and indicator			31/07/2020		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	RtHM shock mount broken			31/07/2020		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			09/07/2020	248774	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	repair R/H Lower shock mount			02/07/2020	248760	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/07/2020	248760	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/07/2020	248760	Service	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	RtHM shock mount broken			02/07/2020	248760	Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\SPAREWHEEL	fit rear gate			19/06/2020		Repair	Completed	FL Green Distribution	Chiller		Wodonga	LHB	529285	Wodonga Workshop	TRAILER

T201	Wodonga - Workshop	Workshop\MOVE ASSET	load tank on trailer and strapped down for transport			16/06/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\CLEAN	move assets cleaning		finished repairs	14/06/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\FIFTH WHEE	skid plate worn		don sparks for 30+30+2mm POww055384	13/06/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\FIFTH WHEE	help fit new skid plate			11/06/2020	246721	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\FIFTH WHEE	Skid plate U/S			05/06/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/06/2020	245968	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/06/2020	245968	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\FIFTH WHEE	Skid plate U/S			02/06/2020	245968	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SUSPENSION	Front SEB bushes to be replaced		As per #288716	02/06/2020	245968	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SUSPENSION	Front SEB bushes to be replaced			02/06/2020	245968	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	RHM shock mount broken		Replaced shock mount & repaired spare wheel carrier	02/06/2020	245968	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\FIFTH WHEE	skid plate worn		don sprarks for metal Poww054993 Bring trailers up from yard, access skid plate job & order steel	02/06/2020	245966	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			20/05/2020	240852	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			20/05/2020	240852	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/05/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	service not completed trailers taken (came back for service)	08/05/2020		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\DRV TYRES	L/rear changed			08/05/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRAKE ADJ	L kicking out 2mm			08/05/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\WINCH/STRP	replaced all straps		fix strap housings	19/04/2020	237310	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\WINCH/STRP	2 box of new binder straps			19/04/2020	237310	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\SHOCK ABS	repair left right lower shocky mount			31/03/2020	234303	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\SUSPENSION	replaced swing arm bushes			31/03/2020	39344	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\CLEAN	clean up			31/03/2020	39344	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers for servicing			28/03/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHL HUB	hub seals leaking		previously done	28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	LH-M outrigger broken			28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\FIFTH WHEE	skid plate worn			28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	Middle axle shock mounts		previously done	28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Comp\Truck Safe	need to order			28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\DAMAGE	rear bar needs replacing			28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	both middle u/s - mounts u/s and wrong bolts		previously done	28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\TRL LEGS	legs bent rearwards		previously done	28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\TRL LIGHTS	L/rear c/lamp		replaced L/rear c/lamp	28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\RWC COMP	long vehicle sign to be fixed to trailer			28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\WHEEL BRGS	adjusted l/rear			28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	r/rear shock mount			28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Comp\Truck Safe	NHVR sticker needs replacing			28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\ELECT P&W	repaired wiring			28/03/2020	234061	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	complete service fit rear marker	28/03/2020	234061	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\TRL LIGHTS	Rear LHS clearance light not working		Completed by Darren Bishop on 27/3/2020	28/03/2020		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/02/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\TRL LEGS	legs bent rearwards			06/02/2020		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/02/2020		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TOOLBOX	Tyre rack broken repair spare wheel rack and weld hanger cracks			05/02/2020	223962	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/01/2020	219817	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/01/2020	219817	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Comp\Truck Safe	need to order			08/01/2020	219817	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\DAMAGE	rear bar needs replacing			08/01/2020	219817	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	both middle u/s - mounts u/s and wrong bolts			08/01/2020	219817	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\INDICATORS	replaced LH side blinker and repairs to wires under side of deck			08/01/2020	219817	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\MOVE ASSET	organized work and missing paperwork for trailers and cleaning			08/01/2020	219817	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Insp\ANN INSP	As per checklist			23/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TOOLBOX	Tyre rack broken			23/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	Middle axle shock mounts			23/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	shocky mounts broken		Previously completed	23/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK O/HAUL	r/hand dock rubber		Previously completed	23/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\MUDGUARDS	Mudguards & Mudflaps		Previously done	23/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\FIFTH WHEE	skid plate worn			23/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\LIGHTS	LHR tail light n/w		Previously completed	23/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	r/r top c/r broken mount		Previously completed	23/11/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	repair/weld broken shocky mount			26/10/2019	208712	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\HOUSEKEEP	spare wheel rack			26/10/2019	208712	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/10/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/10/2019		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		26/10/2019	208712	PreventativeMaintenance	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\MUDGUARDS	small crack tail light outrigger			26/10/2019	208712	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHEEL BRGS	adjust bearings			26/10/2019	208712	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	r/r top c/r broken mount			26/10/2019	208712	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres	Job Added From Invoice			18/10/2019	202139	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice			18/10/2019	202139	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			18/10/2019	202139	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			18/10/2019	202139	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			18/10/2019	202139	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		Carried out D Service	04/10/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\WHL HUB	Inner hub seals leaking		previously completed	04/10/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	RHF shock		previously completed	04/10/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	Front hangers/LM hanger		previously completed	04/10/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\MUDGUARDS	LHF guard needs replacing		previously completed	04/10/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\RWC COMP	need to order new one		specify??	04/10/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearing adjustments		previously completed	04/10/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\TRL LEGS	bent leg		previously completed	04/10/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	RHM shocky mount broken		refer job no. 252478	04/10/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\REFLECTORS	long vehicle sign has fallen out		previously completed	04/10/2019		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	carried out D Service replaced LHR tail lamp	04/10/2019		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\LIGHTS	LHR tail light n/w			04/10/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\REFLECTORS	Job Added From Invoice			28/09/2019	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Insp\RWC COMP	fabricat mounting brackets for long vehicle sign , weld new mounts to trailer and mount sign		completed move trailers	24/09/2019	202138	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\MUDGUARDS	LHF guard needs replacing			02/09/2019	197546	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\RWC COMP	need to order new one			02/09/2019	197546	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearing adjustments			02/09/2019	197546	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\FIFTH WHEE	skid plate worn			02/09/2019	197546	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\TRL LEGS	bent leg			02/09/2019	197546	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	RHM shocky mount broken			02/09/2019	197546	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2019	197546	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	Service	VehService\DS		02/09/2019	197546	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL FLOOR	modify hand rail ractchets - barrol rolls obstructed		rails cut and modified cleaned up from job and move trailers	27/08/2019	196290	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\WINCH/STRP	load binders, straps and cooming rail			22/08/2019	194500	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TAIL LIGHT	tail lights may not be working properly		replaced both brake/tail lights	15/08/2019		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHL HUB	hub seals leaking			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\DAMAGE	spare wheel carrier rear bar bent			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL LEGS	leg bracing needs to be replaced			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/07/2019	186638	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	shocky mounts broken		Shock mounts not broken, but have wrong size bolts	27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\MOUNTS	both rear bottom shocky mounts need replacing		Job previously completed	27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	LH-M outrigger broken			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	keg trailer/cracks on gates		Repairs completed	27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SUSPENSION	front hangers cracked			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	LHM loose, RH broken rear shocks loose		Job previously completed	27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	2x mudflaps missing L/H side			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK O/HAUL	r/hand dock rubber			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	2x front hangers cracked		As per job #239319	27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\REFLECTORS	"don't overtake turning vehicle" sign need to be attached properly			27/07/2019	186638	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	several gates need repair (joiners and strap/bars)			27/07/2019	186638	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\ELECT P&W	LH side wires been pulled			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\MUDGUARDS	Dock rubbers & rear signs			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\WHL HUB	Inner hub seals leaking			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	Front hangers/LM hanger			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	RHF shock			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\TRL LIGHTS	Fixed LHF clearance light			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\CHAS CRACK	R&R repairs		Prep for & clean up after welding Remount signage on rear	27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	Repair hanger cracks on front axle			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\MOVE ASSET	Move trailers			27/07/2019	186638	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/07/2019	176887	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/07/2019	176887	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	Repair shock			28/06/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP01	LF/outer tyre worn			28/06/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\RWC COMP	NHVAS sticker needs replacing			28/06/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Chassis\FIFTH WHEE	Worn skid plate, recommend replacement			28/06/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		28/06/2019		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Insp\RWC COMP	Job Added From Invoice			24/05/2019	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/05/2019	163069	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	gate joiner on left side bars on 2 gates on left need welding			23/05/2019	163069	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	several gates need repair (joiners and strap/bars)			23/05/2019	163069	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/05/2019	163069	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	2x mudflaps missing L/H side			23/05/2019	163069	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK O/HAUL	r/hand dock rubber			23/05/2019	163069	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SPRNG HANG	2x front hangers cracked			23/05/2019	163069	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK O/HAUL	refit cirslips to l/centre r/rear s-cams			23/05/2019	163069	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice			03/05/2019	93738	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\Punct	Job Added From Invoice			03/05/2019	93738	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TP01	blown tyre			27/04/2019	151290	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	rear marker signs need to be mounted properly mudflaps LHS 2x guards		previously done	30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL REPS	binder straps need replacing		done	30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	52928S	Wodonga Workshop	TRAILER

						replaced RHM bottom													
						shocky mount bracket													
T201	Wodonga - Workshop	Susp\SHOCK ABS	loose LHR shock mount			tahtened shocky's movina trailer	30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	needs reline				30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\TRL LIGHTS	2 clearance lights need replacing			previously done	30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	missing 2 mudflaps			done	30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHEEL BRGS	to be replaced in reline			previously done	30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	loose shocky			multiple shock's loose	30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	needs reline			previously done	30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHEEL SEAL	weaping oil around hubs			replaced on reline	30/03/2019	141253	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	Two gates on left side missing / damaged metal straps (Joint between vertaer bars)			previously done	30/03/2019	141253	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	Almost all gates on left side have been bent outwards , making it difficult to back into narrow docks.			replaced previously	30/03/2019	141253	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
						bearing adjustments													
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	move trailers	30/03/2019	141253	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	LH-M outrigger broken				30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	keg trailer/cracks on gates				30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SUSPENSION	front hangers cracked				30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	LHM loose, RH broken rear shocks loose				30/03/2019	141253	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice				10/03/2019	10	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				10/03/2019	10	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice				10/03/2019	10	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Engine	Job Added From Invoice				09/03/2019	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp	Job Added From Invoice				09/03/2019	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\CLEAN	parts list from reline				06/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\CLEAN	clean up from reline				06/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL REPS	replace all trailer straps				06/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\CLEAN	clean up from job/move trailer for greasing. Greased				06/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine	poor condition				05/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\SCALES	weight gauge needs replacing			fitted new weight gauge	05/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
						done as per reline													
T201	Wodonga - Workshop	DrivLine\WHL HUB	2x weeping hub seals			job#214851	05/03/2019	133072	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
						done as per reline													
T201	Wodonga - Workshop	DrivLine\WHL HUB	rear right hub seal weaping			job#214851	05/03/2019	133072	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\REFLECTORS	"don't overtake turning vehicle" sign need to be attached properly				05/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	repair broken shock mounts				05/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\CHN/RLR/MN	weld chail loops onto front and rear gates				05/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	reline				05/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL REPS	replaced 7x binder straps				05/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	brake re-line				02/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\HOSES	replaced 2x c/clamps				02/03/2019	133072	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	cleaning meeting	26/02/2019	131088	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\ELECT P&W	clearance lights out			2x clearance lights out	26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	rear marker signs need to be mounted properly mudflaps LHS 2x guards			job pending for run change to pellets	26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TPS1	spare wheel corner broken gate locks broken x2			checked "ok"	26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MOUNTS	leg mounts cracked				26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHL HUB	hub seals leaking			to be done after getting unloaded reline booked in	26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL REPS	binder straps need replacing			to be done during reline	26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	loose LHR shock mount			broken will get done when reline is getting done	26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	needs reline			to be done after getting unloaded	26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHEEL SEAL	weaping oil around hubs			to be done in reline	26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	1x gate joiners (hinges) needs re-welding (currently between gate #3&4 on right side)			checked "Ok"	26/02/2019	131088	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	reweld brace joiner L/H gate 3				26/02/2019	131088	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	needs reline				26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\TRL LIGHTS	2 clearance lights need replacing				26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	missing 2 mudflaps				26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\DAMAGE	spare wheel carrier rear bar bent				26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHEEL BRGS	to be replaced in reline				26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL LEGS	leg bracing needs to be replaced				26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	shocky mounts broken				26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	loose shocky				26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\MOUNTS	both rear bottom shocky mounts need replacing				26/02/2019	131088	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHL HUB	2x weeping hub seals				20/02/2019		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\W/S MAINT	1x broken gate strap/bar last gate left hand side				20/02/2019		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	1x weld broken on hinged gate joiner 4th gate left side				20/02/2019		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHEEL SEAL	weaping oil around hubs			all hubs o/s	25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHEEL SEAL	weaping oil around hubs			#2019307	25/01/2019	120244	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\AIR LEAK	major air leak - looses most air in 20mins			sticking valve but not extremely bad	25/01/2019	120244	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	1x gate joiners (hinges) needs re-welding (currently between gate #3&4 on right side)				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	mudflaps from between left side tyres missing due to hitting kangaroo			does not need or have any	25/01/2019	120244	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		25/01/2019	120244	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\ELECT P&W	clearance lights out				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MUDGUARDS	rear marker signs need to be mounted properly mudflaps LHS 2x guards				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\TPS1	spare wheel corner broken gate locks broken x2				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\MOUNTS	leg mounts cracked				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHL HUB	hub seals leaking				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL REPS	binder straps need replacing				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\SCALES	weight gauge needs replacing				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
						replaced lower LH-R shock bolt and tightened													
T201	Wodonga - Workshop	Susp\SHOCK ABS	loose LHR shock mount			RHR & LHF	25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRK RELINE	needs reline				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\DOOR LOCK	repairs made to broken gate locks				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\MOVE ASSET	moved trailers				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\CLEAN	clean up from job				25/01/2019	120244	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	Trailer Gates			fabricate and repai gates	06/11/2018	88218	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer				21/09/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\CLEAN	clean w/s				21/09/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/09/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	service		VehService\DS		21/09/2018		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Steering\WHEEL SEAL	Job Added From Invoice				20/09/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Steering	Job Added From Invoice				19/09/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Steering\WHEEL SEAL	Job Added From Invoice				19/09/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHEEL BRGS	Job Added From Invoice				19/09/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				18/09/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\TRL LIGHTS	left hand tail light not working				18/09/2018		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
			R/H don't overtake turn wh sign wired on																
T201	Wodonga - Workshop	Body\REFLECTORS	-needs to be reattached croosely				18/09/2018		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\HOUSEKEEP	Wash Trailer				18/09/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS		18/09/2018		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	DrivLine\WHEEL BRGS	repack bearings/full bearing inspection				15/09/2018	65604	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer				15/09/2018	65604	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				15/09/2018	65604	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	Service		VehService\DS		15/09/2018	65604	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				09/08/2018	48402	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	Service		VehService\DS		09/08/2018	48402	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	repair gate latch L/H side				14/07/2018	38733	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				14/07/2018	38733	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	Service		VehService\DS		14/07/2018	38733	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\AIR BAG	middle and front airbags on left side don't appear to be inflating properly			inspection of airbags - ok could not fault, even after dumping all air and re supply tanks and bags	30/05/2018	19466	Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\DAMAGE	Repairs				29/05/2018	18745	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				29/05/2018	18745	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	VehService\DS	Service		VehService\DS		29/05/2018	18745	Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				26/05/2018	17363	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice				26/05/2018	17363	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\AIR BAG	drive to get airbags				24/05/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\SHOCK ABS	weld bottom left shockie bracket back to axle				24/05/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Susp\AIR BAG	replace both middle and left front air bag				24/05/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\BREAKDOWN	breakdown in depot for flat tyre				24/05/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\DAMAGE	found other repairs needed to be done while changing tyre				24/05/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres	Job Added From Invoice				02/05/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice				02/05/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice				02/05/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\ROTATION	Job Added From Invoice				02/05/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice				02/05/2018	0	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL REPS	repair broken gate latches				21/04/2018	6270	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\ELECT P&W	rewired base plug				17/04/2018	3469	Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Body\TRL GATES	modify to suit kegs and repair gates			extended 4x gates and fit latches to 10 gates fabricated	07/04/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Elect\ELECT P&W	rewire - base plug				05/04/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRAKE ADJ	brake adjustment				05/04/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\CLEAN	pack up from job/shut shed				05/04/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				04/04/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
						hubbo fitted													
						replaced binder ratchet and strap													
						replaced LHF orange reflector													
						replaced rear signs													
T201	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist		VehService\DS	diamrose service line blockaee	04/04/2018		Service	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Brakes\BRAKE ADJ	adjustment			went to move trailer but keeped moving after brake test after inspection off air line found service line melted and blocked replaced air line	04/04/2018		Fault	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Workshop\CLEAN	inspected paperwork done check started repairs				04/04/2018		Repair	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER
T201	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist		Insp\ANN INSP		04/04/2018		PreventativeMaintenance	Completed	FL Green Distribution	Chiller	Wodonga	LHB	529285	Wodonga Workshop	TRAILER