EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T015	Wodonga - Workshop	Body\TRL GATES	Gate pockets cracked			26/05/2026	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Front and middle Axel will need reline shoe damaged and kicking out	14/05/2026	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	L/H & R/H turning sign's are about to fall off, L/H Gate pocket is broken/cracked, L/H front gate Bent/Broken.			14/05/2026	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		15/04/2026	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		03/03/2026	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	COREY V ALSO ON JOB	06/02/2026	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		08/01/2026	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		10/12/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\RWC COMP	LEFT SIDE "DON'T OVERTAKE" SIGN FELL OFF.			04/11/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Fr trading arm bush needs replacing and reline needed brek pads falling apart	04/11/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK O/HAUL	S-CAMS/ BUSHES WORN OUT		Pending	04/11/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		24/09/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRAKE ADJ	REPOSITION BRAKE SHOES.			24/09/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	CRACKED GATES PASSENGER SIDE			19/08/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP	Pending	19/08/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		19/08/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		22/07/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		14/05/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			02/04/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	BEAUREPAIRES	TRAILER
T015	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12			02/04/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	BEAUREPAIRES	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		13/03/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	Fabricate new gate latch.			28/02/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		11/02/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\PRES CHECK	Tyres\PRES CHECK 1-12			29/01/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	BEAUREPAIRES	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		15/01/2025	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		16/12/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	I	16/11/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			24/10/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	BEAUREPAIRES	TRAILER
T015	Wodonga - Workshop	Tyres\TP01	Replace 2x Tyres L/H Front Axle.		Job Done By Tyre fitter JAMES.14/10/24	15/10/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\DAMAGE	Repair Broken Gates			15/10/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		14/10/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		29/08/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL LEGS	Replace landing leg handle bolt.			27/08/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		29/07/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\STRAPS	NEW WINCH STRAPS. (DRIVER TO SORT OUT)			29/07/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP09	WORN TYRE L/HAND- REAR AXLE OUTER. CHECK REST OF TYRES.			26/07/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	BEAUREPAIRES	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		28/05/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		28/05/2024	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			12/04/2024	384680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Albury Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/04/2024	384680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\STRAPS	Repair Broken Gates.			11/04/2024	384680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/04/2024	384680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	WELD GATES.			11/04/2024	384680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	REPLACE TYRES.			11/04/2024	384680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\TRL LEGS	REPAIRED LEG HANDLE BRACKET.			16/03/2024		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			14/02/2024	368953	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	GATES & COMBING RAIL BENT OUT.		STRAIGHTENED ALL GATES, HEAD BOARD AND COAMING RAIL.	14/02/2024	368953	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\INDICATORS	TRAILER LIGHT PLUG "LEFT INDICATOR"			14/02/2024	368953	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\STRAPS	FRONT HEAD BOARD BENT BACK.			14/02/2024	368953	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRAKE ADJ	BRAKES LOCK UP?			14/02/2024	368953	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	FLAT SPOTS MOST TYRES. FRONT GATES AND FRONT GATE BENT DUE TO RAPID STOP WITH FULL LOAD. NO BROKEN WELDS BUT WILL NEED TO BE STRAIGHTENED BEFORE IT'S USED OR AT LEAST CHECKED.			14/02/2024	368953	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	THE TRAILER WORK IS IMPORTANT.			14/02/2024	368953	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/02/2024	368953	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			09/01/2024	363907	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	REAR LEFT GATE CRACKED TAG (CHECK ALL GATES)			09/01/2024	363907	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\RWC COMP	TURNING SIGN BROKEN LOOSE.			09/01/2024	363907	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP04	TYRES. (AT LEAST FRONT RIGHT OUTER)			09/01/2024	363907	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\HOUSEKEEP	GENERAL CHECK OVER. PLZ.			09/01/2024	363907	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\STRAPS	REPLACE DAMAGED BOARDS.		BEER SHED JOB.	09/01/2024	363907	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/01/2024	363907	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		27/09/2023	179678	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/09/2023	339300	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/09/2023	339300	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/08/2023		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/08/2023		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\SUSPENSION	Replace Rocker Box Bushes		WELD CRACKS.	29/08/2023		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/07/2023	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/07/2023	337654	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/05/2023	323292	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\SUSPENSION	BACK END MAY BE SITTING TOO LOW.			31/05/2023	323292	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\Torque Rod	CHECK ROCKER BUSH L/H FRONT.			31/05/2023	323292	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	TOOLBOX NO LONGER STAYS LOCKED.			31/05/2023	323292	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/05/2023	323292	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	FABRICATED NEW GATE LATCHES.			31/01/2023		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRAKE ADJ	NO BRAKES @ ALL ON TRAILERS.		FOUND BRAKES BACKED OFF. ADJUSTED.	15/01/2023		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/01/2023	279212	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/01/2023	279212	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Myrtleford - Workshop	Elect\ELECT P&W	replace 7 pin female plug			07/01/2023	278590	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Myrtleford Workshop	TRAILER
T015	Myrtleford - Workshop	Body\MUDGUARDS	replaced LHR mudflap			07/01/2023	278590	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Myrtleford Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			13/12/2022		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Albury Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			13/12/2022		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Albury Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			13/12/2022		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Albury Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			13/12/2022		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Albury Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/12/2022	271715	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	DrivLine\KING PIN	King Pin Replace		OK.	06/12/2022	271715	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\SPRNG PACK	Leaf Springs Replace		INSPECTED. OK.	06/12/2022	271715	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	DrivLine\WHEEL ALGN	Wheel Alignment		N/A.	06/12/2022	271715	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	Repair gates and Replace all bolts for gate latches. URGENT. T15 SPRINGS WORN OUT!			06/12/2022	271715	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp	TYRES DRAGGING ON CHASSIS AND ROPE RAIL.> DAMAGED MULTIPLE TYRES.		INSPECTED. OK.	06/12/2022	271715	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	RELINED TRAILER.		CLEANED UP.	06/12/2022	271715	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/12/2022	271715	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			29/09/2022	250634	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Myrtleford Workshop	TRAILER
T015	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/09/2022	250634	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Myrtleford Workshop	TRAILER
T015	Myrtleford - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		29/09/2022	250634	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Myrtleford Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL REPS	GATES NEED REPAIR.			24/07/2022	232162	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL REPS	COAMING RAIL CRACKED.			24/07/2022	232162	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	Front head board broken			24/07/2022	232162	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			09/07/2022	229545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.			09/07/2022	229545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	REPLACE TOOLBOX LOCKS.			09/07/2022	229545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL REPS	GATES NEED REPAIR.			09/07/2022	229545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL REPS	COAMING RAIL CRACKED.			09/07/2022	229545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	CLEANED UP.	09/07/2022	229545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/05/2022	220054	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\DAMAGE	Rear bar is badly damaged.			17/05/2022	220054	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\SUSPENSION	REPLACE BUSHES IN REAR AXLE. JACK UP AND CHECK ALL.			17/05/2022	220054	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\SUSPENSION	SUSPENSION BUSHES, SAGGING L/HHAND REAR AXLE SPRINGS (TRACKING TO RIGHT 6 INCHES0		REPLACED REAR ROCKER BUSHES.	17/05/2022	220054	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\VALVES	BRAKEE RELAY VALVE OR BBOOSTER FAULTY (SLOW TO RELEASE SERVICE SIDE)		REPLACED BOTH RELAY VALVES.	17/05/2022	220054	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\PANELS	BUMMPER BAR/ TAIL LIGHT SUPPORTS NEED REBUILD.			17/05/2022	220054	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	CHECK GATES FOR CONDITION.			17/05/2022	220054	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WINCH/STRP	REPLACE WINCH DRUMS OR REMOVE.			17/05/2022	220054	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Comp\Truck Safe	REPLACE NHVAS STICKER.			17/05/2022	220054	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	REPLACE TOOLBOX LOCKS.			17/05/2022	220054	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED H/DUTY LIGHT SOCKET. Inspected and found brakes not releasing due to stick valve Removed airlines, spray CRC in all lines Refit lines & test multiple times	17/05/2022	220054	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\AIR TANKS	Brakes not releasing		Repair complete	22/04/2022		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\AIR TANKS	AIR ISSUE.			22/04/2022		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER

T015	Wodonga - Workshop	Tyres\TP7+8	supply and fit 4 tyres			20/04/2022		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			20/04/2022		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/04/2022	214194	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\DAMAGE	Rear bar is badly damaged.			15/04/2022	214194	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\DAMAGE	Rear bar damaged needs replacing.			15/04/2022	214194	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\DAMAGE	REAR BAR DAMAGED, NEED NEW ONE.			15/04/2022	214194	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL WALL	FRONT HEAD WALL/GATE NEEDS TO BE REPLACED.			15/04/2022	214194	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\PANELS	REPLACE/ REPAIR BENT REAR BAR.			15/04/2022	214194	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\DAMAGE	Damage to rear bar of trailer caused by object left at back of finger dock.			15/04/2022	214194	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\SUSPENSION	REPLACE BUSHES IN REAR AXLE. JACK UP AND CHECK ALL T/ROD AND R/BOX XBUSHES U/S.			15/04/2022	214194	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/04/2022	214194	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\ELECT P&W	REPLACED CLEARANCE LIGHTS.			15/04/2022	214194	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/03/2022	207826	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\TRL LIGHTS	Please repair all U/S trailer lights.			18/03/2022	207826	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/03/2022	207826	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\PANELS	REPLACE/ REPAIR BENT REAR BAR.			18/03/2022	207826	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP9+10	supply and fit 2tyres			05/03/2022		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP9+10	supply and fit 2 tyres			18/02/2022		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/01/2022	193832	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\DAMAGE	Rear bar is badly damaged.			22/01/2022	193832	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\DAMAGE	Rear bar damaged needs replacing.			22/01/2022	193832	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\DAMAGE	REAR BAR DAMAGED, NEED NEW ONE.			22/01/2022	193832	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL WALL	FRONT HEAD WALL/GATE NEEDS TO BE REPLACED.			22/01/2022	193832	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\DAMAGE	Damage to rear bar of trailer caused by object left at back of finger dock.			22/01/2022	193832	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\TRL LIGHTS	Please repair all U/S trailer lights.		REPAIRED RH INDICATOR. 2 LH, 2 RH CLEARANCE LIGHTS STILL NOT WORKING.	22/01/2022	193832	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/01/2022	193832	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\SUSPENSION	Track rod bushes perished.			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Gusset/chassis cracks.			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\AXLES	Axle hangers cracked from rear.			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\DAMAGE	Rear bar is badly damaged.			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL WALL	Right side of wall has a crack.			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\REFLECTORS	Rear markers damaged.			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\DAMAGE	Rear bar damaged needs replacing.			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\DAMAGE	REAR BAR DAMAGED, NEED NEW ONE. Steel plate at left rear corner fell off because of impact.			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\DAMAGE	Needs re-attaching/welding on (Part in toolbox)			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\DAMAGE	Damage to rear bar of trailer caused by object left at back of finger dock.			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	Front Gate/Rack Bent and Cracked			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	Back left hand gate has cracked a tag off.			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL WALL	FRONT HEAD WALL/GATE NEEDS TO BE REPLACED.			10/12/2021	187844	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			09/11/2021	179444	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	Load gates cracked.			09/11/2021	179444	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\TRL LIGHTS	damaged pin in trailer socket (light duty) Think it's LH indicators			09/11/2021	179444	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/11/2021	179444	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\DAMAGE	REAR BAR DAMAGED, NEED NEW ONE.			09/11/2021	179444	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			14/10/2021		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP03	supply and fit 2 tyres			16/09/2021	166185	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/09/2021	166185	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FITMENT	LR outter and LM inner need replacing.			16/09/2021	166185	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/09/2021	166185	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		16/09/2021	166185	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	Load gates cracked.			16/09/2021	166185	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BOOSTER	LHR Booster needs replacing.		Repairs to booster.	16/09/2021	166185	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\DAMAGE	Rear bar damaged needs replacing.			16/09/2021	166185	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\REFLECTORS	Rear markers damaged.			16/09/2021	166185	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP5+6	Supply and fit 4 tyres			13/08/2021	164811	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			13/08/2021	164811	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/08/2021	164810	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/08/2021	164810	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FITMENT	LR outter and LM inner need replacing.			12/08/2021	164810	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\DAMAGE	Rear bar is badly damaged.			12/08/2021	164810	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL WALL	Right side of wall has a crack.			12/08/2021	164810	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	DrivLine\WHEEL STUD	Left middle axle wheel stud has snapped.			12/08/2021	164810	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Workshop\MOVE ASSET	Yard check and hook up trailer.			12/08/2021	164810	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP09	replace damaged tyre			04/07/2021	196792	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\TP11+12	Supply and fit 2 tyes			26/06/2021	147346	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/06/2021	147346	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	LM inner and RR outter require attention.			26/06/2021	147346	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FAILURE	RR and RF duals bald			26/06/2021	147346	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FITMENT	Tyres have flat spots and low tread.			26/06/2021	147346	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/06/2021	147346	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\SUZI COIL	Trailer plug broken.		Completed. Replaced trailer base plug.	26/06/2021	147346	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	DrivLine\WHEEL BRGS	LM, RM, Bearings need adjustment.		Adjusted wheel bearings.	26/06/2021	147346	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Workshop\MOVE ASSET	Hook up and drop off trailer as well.			26/06/2021	147346	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	LM inner and RR outter require attention.			26/06/2021		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FAILURE	RR and RF duals bald			26/06/2021		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FITMENT	Tyres have flat spots and low tread.			26/06/2021		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	Tool box door left hand side missing.		Remove old door less toolbox, fit new toolbox modify mounting holes.	13/06/2021	142684	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/05/2021	136777	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/05/2021	136777	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	LM inner and RR outter require attention.			27/05/2021	136777	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FAILURE	RR and RF duals bald			27/05/2021		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/04/2021	123550	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/04/2021	123550	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FAILURE	RR and RF duals bald			27/04/2021	123550	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL REPS	5 x barrel straps and 2 x ratchet straps.			27/04/2021	123550	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\SUSPENSION	Track rod bushes perished.			27/04/2021	123550	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Gusset/chassis cracks.			27/04/2021	123550	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\AXLES	Axle hangers cracked from rear.			27/04/2021	123550	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/04/2021		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/04/2021		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/03/2021	117652	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	R.F. outer tyre need replace			11/03/2021	117652	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	completed	11/03/2021	117652	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\STRAPS	Repair L/Rear gate latch			02/02/2021	105519	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/02/2021	105519	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/02/2021	105519	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	R.F. outer tyre need replace			02/02/2021	105519	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/12/2020	95310	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	including smoke time	08/12/2020	95310	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/10/2020	89965	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/10/2020	89965	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			17/09/2020	83086	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			17/09/2020	83086	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/09/2020	83088	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\SUSPENSION	Trail arm bush's u/s		checked during service and found no fault in bushes	15/09/2020	83088	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Deck rail cracking			15/09/2020	83088	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL WALL	Head board cracking			15/09/2020	83088	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	normal wear and tear, back and front		welded rear bar	15/09/2020	83088	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	toolbox cover has normal bent RR inner tyre needs replace front axle right outer tyre needs replacing			15/09/2020	83088	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\DRV TYRES	middle axle inner tyre			15/09/2020	83088	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/09/2020	83088	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		13/08/2020	17589	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/08/2020	17589	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/08/2020	17589	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	normal wear and tear, back and front			13/08/2020	17589	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	toolbox cover has normal bent			13/08/2020	17589	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER

			RR inner tyre needs replace															
			front axle right outer tyre needs replacing															
			middle axle inner tyre															
T015	Wodonga - Workshop	Tyres\DRV TYRES	R front axle outer tyre needs replacing						13/08/2020	17589	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						15/07/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\SUSPENSION	Trail arm bush's u/s						15/07/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Gusset cracks						15/07/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CROSS MBR	Crossmember cracks						15/07/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Steering\WHEEL ALGN	Wheel not running true						15/07/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	Gates in poor condition			New gates			15/07/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Deck rail cracking						15/07/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\DAMAGE	Coaming rail cracking						15/07/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL WALL	Head board cracking						15/07/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL FLOOR	Floor in very poor condition			Checked okay			15/07/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					15/07/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice						03/07/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\SUSPENSION	Trail arm bush's u/s						17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Gusset cracks						17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CROSS MBR	Crossmember cracks						17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Steering\WHEEL ALGN	Wheel not running true						17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Some cracks refer to Adon						17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\TRL LIGHTS	replace LH clearance light						17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WINCH/STRP	chain in toolbox still needs fixing/replacement binder/dog is damaged bent and damaged threads			Previously completed			17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	Gates in poor condition						17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Deck rail cracking						17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\DAMAGE	Coaming rail cracking						17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL WALL	Head board cracking						17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL FLOOR	Floor in very poor condition						17/06/2020	68084	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Workshop\MOVE ASSET	put away stock						16/06/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Workshop\CLEAN	clean up						16/06/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	inspect and repair load gates						16/06/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						20/05/2020	66681	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					20/05/2020	66681	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\TRL LIGHTS	replace LH clearance light						20/05/2020	66681	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WINCH/STRP	crill and fit strap bolt for load binder						20/05/2020	66681	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\TRL LIGHTS	re-wire 2 core wire from main loom and pit new clearance light						20/05/2020	66681	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Workshop\MOVE ASSET	take out park up						20/05/2020	66681	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						23/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					23/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
			Rope rails need attention															
T015	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar has cracks - tyre carrier/gate with cracks			replaced worst parts pf rope rails, clean up and move trailers			23/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Gusset cracks			pending			23/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CROSS MBR	Crossmember cracks			pending			23/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	Toolbox door lock loose			repaired			23/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Steering\WHEEL ALGN	Wheel not running true			need more information			23/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\MUDGUARDS	Guards need straightening			guards ok still roadworthy			23/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL FLOOR	Coaming rails need reairs or replacing			crack on coming rails welded crack in webbing welded			23/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WINCH/STRP	chain in toolbox still needs fixing/replacement binder/dog is damaged bent and damaged threads						23/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	some cracks refer to Adon						23/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\PAINT/REST	paint legs						22/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	refit toolbox door latch						22/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\PAINT/REST	prepare & paint tool box						22/04/2020	66680	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\ELECT P&W	change electrical socket						22/04/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice						07/04/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice						07/04/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WINCH/STRP	Ratchets and straps						26/03/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\HOUSEKEEP	Rust everywhere						26/03/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	Needs reline						26/03/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Insp\ANN INSP	Annual inspection As Per Checklist	Insp\ANN INSP					26/03/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\SUSPENSION	Trail arm bush's u/s						26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
			Rope rails need attention															
T015	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar has cracks - tyre carrier/gate with cracks						26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Gusset cracks						26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CROSS MBR	Crossmember cracks						26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	Toolbox door lock loose						26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Steering\WHEEL ALGN	wheel not running true						26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar, crossmembers and gussets cracked						26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	Tyres scalloped						26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WINCH/STRP	Chain in toolbox still needs fixing/replacement, Binder/dog is damaged and has damaged threads						26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\MUDGUARDS	Guards need straightening						26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL FLOOR	Coaming rails need reairs or replacing						26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					26/03/2020	66679	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						07/02/2020	50870	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
			rope rails need attention															
T015	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar has cracks - tyre carrier/gate with cracks						07/02/2020	50870	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	Gates			Previously completed			07/02/2020	50870	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Gusset cracks						07/02/2020	50870	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CROSS MBR	Crossmember cracks						07/02/2020	50870	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	Toolbox door lock loose						07/02/2020	50870	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Steering\WHEEL ALGN	wheel not running true						07/02/2020	50870	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\ELECT P&W	LH & RH side marker out			Previously completed			07/02/2020	50870	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar, crossmembers and gussets cracked						07/02/2020	50870	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WINCH/STRP	chain in toolbox still needs fixing/replacement binder/dog is damaged bent and damaged threads						07/02/2020	50870	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					07/02/2020	50870	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	Tyres scalloped						07/02/2020	50870	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers to service service had already been done drop trailers back						15/01/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						11/01/2020	45377	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Steering\WHEEL ALGN	wheel not running true						11/01/2020	45377	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\ELECT P&W	LH & RH side marker out						11/01/2020	45377	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar, crossmembers and gussets cracked						11/01/2020	45377	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	DrivLine\WHEEL BRGS	RHF, LHM						11/01/2020	45377	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL FLOOR	loaded, underside checked						11/01/2020	45377	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\SUSPENSION	trail arm bush's u/s						11/01/2020	45377	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					11/01/2020	45377	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\ELECT P&W	repira to trailer to lights and wiring- large section of rubbed wire and removed 3 leads. 3x lights and wire replaced						11/01/2020		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						10/12/2019	35275	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\TRL LIGHTS	RH 2 in line clearance light						10/12/2019	35275	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Steering\WHEEL ALGN	recommend wheel alignment			Inspected ok			10/12/2019	35275	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
			rope rails need attention															
T015	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar has cracks - tyre carrier/gate with cracks						10/12/2019	35275	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\SUSPENSION	rear axle mount cracked			Previously completed			10/12/2019	35275	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	Gates						10/12/2019	35275	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Gusset cracks						10/12/2019	35275	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CROSS MBR	Crossmember cracks						10/12/2019	35275	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	Toolbox door lock loose						10/12/2019	35275	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WINCH/STRP	Load straps frayed			Replaced all			10/12/2019	35275	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					10/12/2019	35275	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						19/11/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\TAIL LIGHT	number plate light need replacing			Replaced			19/11/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\TRL LIGHTS	RH 2 in line clearance light			x1 Only - RHF not working			19/11/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	coming rail sid rail needs replacing bent and cracked rear bar bent webing cracked			Still managable			19/11/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	door bent on toolbox			Repairs completed			19/11/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					19/11/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\TRL LIGHTS	light repairs						15/10/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WINCH/STRP	changed binder straps						15/10/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\PAINT/REST	paint legs						15/10/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			Repair Matt			15/10/2019	13881	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\TAIL LIGHT	number plate light need replacing						15/10/2019	13881	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\TRL LIGHTS	RH 2 in line clearance light						15/10/2019	13881	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WINCH/STRP	binder straps need replacing						15/10/2019	13881	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	coming rail sid rail needs replacing bent and cracked rear bar bent webing cracked						15/10/2019	13881	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER

T015	Wodonga - Workshop	Chassis\TRL LEGS	loose leg bracing			15/10/2019	13881	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	door bent on toolbox			15/10/2019	13881	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/10/2019	13881	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\LIGHTS	2nd side light (from front) on right side dim/not working		replace clearance light	02/10/2019	9693	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\MUDGUARDS	left hand mudflap missing		left side mudflap	02/10/2019	9693	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	DrivLine\WHL HUB	Job Added From Invoice			19/09/2019	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/09/2019	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/09/2019	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WINCH/STRP	Replace load straps			07/09/2019	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\RWC COMP	Fix up rear signs & make them secure			07/09/2019	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	reline all axles			09/08/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WHL HUB	Replaced wheel nut covers			09/08/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Steering\WHEEL ALGN	recommend wheel alignment			03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL FLOOR	side timbers u/s, coamings bend			03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	reline needed			03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	change next service		As per #240592	03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	DrivLine\WHEEL SEAL	both front hub seals starting to leak (monitor)		Done on reline	03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	DrivLine\WHL HUB	rear hub seals weeping		Done on reline	03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	reline		As per #240592	03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK O/HAUL	brakes low		As per #540592	03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Steering\WHEEL HUB	RHR hub seal leaks reline		As per #540595	03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	LH Drum oversize		As per #540592	03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL LEGS	front/rear gate with cracks rope rails need attention		Previously done	03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar has cracks - tyre carrier/gate with cracks			03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	toolbox has cracks			03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\SUSPENSION	rear axle mount cracked			03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Crossmembers & gaskets			03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL REPS	Trailer (Tautliner) Repairs			03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\HOUSEKEEP	Rust everywhere			03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	Needs reline		As per #240592	03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/08/2019	84545	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/06/2019	78471	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Crossmembers & gaskets			25/06/2019	78471	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/06/2019	78471	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	reline needed			09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	change next service		as per job #224086	09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	DrivLine\WHEEL SEAL	both front hub seals starting to leak (monitor)			09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	DrivLine\WHL HUB	rear hub seals weeping			09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	reline		as per job#224086	09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK O/HAUL	brakes low		as per job #224086	09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Steering\WHEEL HUB	RHR hub seal leaks reline			09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	LH Drum oversize		as per job#224086	09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL LEGS	front/rear gate with cracks			09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	needs reline rope rails need attention			09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar has cracks - tyre carrier/gate with cracks			09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	toolbox has cracks			09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\SUSPENSION	rear axle mount cracked			09/05/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Workshop\CLEAN	cleaning			22/03/2019	49510	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer			22/03/2019	49510	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\CHN/RLR/MN	weld side rail pocket crack's			22/03/2019	49510	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL REPS	gates and holders			22/03/2019	49510	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	multiple chassis cracks and gusset cracks, cracks in side of deck rails			22/03/2019	49510	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Steering\WHEEL HUB	RHR hub seal leaks reline			22/03/2019	49510	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	LH Drum oversize			22/03/2019	49510	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/03/2019	49510	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	Service	VehService\DS		22/03/2019	49510	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL REPS	(2nd or 3rd from front) roll strap needs replacing			07/03/2019		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice			23/02/2019	42427	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			23/02/2019	42427	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			23/02/2019	42427	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			09/01/2019	39528	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		09/01/2019	39528	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK O/HAUL	brakes low			09/01/2019	39528	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Workshop\CLEAN	clean up			09/01/2019	39528	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Insp\RWC COMP	Job Added From Invoice			07/12/2018	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/12/2018	32955	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/12/2018	32955	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	DrivLine\WHL HUB	rear hub seals weeping			04/12/2018	32955	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Steering\WHEEL ALGN	recommend wheel alignment			04/12/2018	32955	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	reline			04/12/2018	32955	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	fit gate latches			04/12/2018	32955	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Workshop\MOVE ASSET	Move Assets		check yard for trailer 15 not in the yard	16/11/2018		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\WINCH/STRP	Job Added From Invoice			13/11/2018	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL LEGS	legs bent			06/11/2018		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL FLOOR	side timbers u/s, coamings bend			06/11/2018		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL GATES	modify gates to suit.		pick up steel from ben sparks fabricate gate hatches	06/11/2018		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/11/2018	27394	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	DrivLine\WHEEL SEAL	both front hub seals starting to leak (monitor)		continue to monitor	02/11/2018	27394	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/11/2018	27394	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	Job Added From Invoice			21/10/2018	26792	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			21/10/2018	26792	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			21/10/2018	26792	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/09/2018		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\HOUSEKEEP	Wash trailer			18/09/2018		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/09/2018		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	change next service			01/09/2018	24350	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/09/2018	24350	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/09/2018	24350	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\AIR LEAK	replace air coupling			01/09/2018	24350	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer			01/09/2018	24350	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	Job Added From Invoice			06/07/2018	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			06/07/2018	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			06/07/2018	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			06/07/2018	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/07/2018	20968	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Service and clean up	03/07/2018	20968	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		03/07/2018	20968	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Workshop\CLEAN	clean, tidy and finalise paperwork			23/05/2018	19232	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/05/2018	19232	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	"Service" as per Greenfreight check list	VehService\DS		23/05/2018	19232	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/04/2018		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/04/2018		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/04/2018		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/02/2018	14034	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	change next service			23/02/2018	14034	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	Service "B" Trailer	VehService\DS		23/02/2018	14034	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	Job Added From Invoice			23/02/2018	13124	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	Job Added From Invoice			20/01/2018	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			20/01/2018	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			20/01/2018	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\TRL LEGS	legs have cracks in them		as per job #147781	17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	L side gut holers have cracks		as per job#147781	17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	multiple body & structural cracks			17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL LEGS	mounts u/s and bracing u/s		as per job#147781	17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	toolbox mounts cracked, hinges bend			17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	032465	Wodonga Workshop	TRAILER

T015	Wodonga - Workshop	Brakes\BOOSTER	cracks/rear boosters at diff stokes LHF booster clicks when air supplied/air tank cocks u/s		as per job#147781	17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\MUDGUARDS	RHR bent			17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	tyre rack is crack		as per job#147781	17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Front & rear gates developing cracks. LHMI neary completely delaminated		checked "ok"	17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\LIGHTS	RHM mix matched tlrs		previously done	17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CROSS MBR	crossmembers and gussets		as per job#147781	17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\AXLES	sadle wels cracked & rocker box's worn		as per job#147781	17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\MUDGUARDS	straightened front guards		straightened front 1/4 guards	17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BOOSTER	r/front booster u/s		replaced r/front booster	17/01/2018	10730	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Comp\INT INSP	Internal Inspection			07/12/2017		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Elect\ELECT P&W	tidy up wiring		zip tie wiring	07/12/2017		Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job LHMI neary completely delaminated			07/12/2017	7786	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\LIGHTS	RHM mix matched tlrs			07/12/2017	7786	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CROSS MBR	crossmembers and gussets			07/12/2017	7786	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Susp\AXLES	sadle wels cracked & rocker box's worn			07/12/2017	7786	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
					Service Trailer as per checklist										
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Service Not Finish	07/12/2017	7786	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			14/11/2017	6251	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/11/2017	6251	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\LIGHTS	RH clearance light u/s			14/11/2017	6251	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	Front & rear gates developing cracks.			14/11/2017	6251	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			13/10/2017	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			13/10/2017	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/10/2017	4316	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\DAMAGE	LH-M set u/s			12/10/2017	4316	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\MUDGUARDS	RHR bent			12/10/2017	4316	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\AIR LEAK	drain cox on mid tank u/s		air cox is ok just need one cable	12/10/2017	4316	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/10/2017	4316	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	tyre rack is crack			12/10/2017	4316	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\DAMAGE	LH-M set u/s			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\TRL LEGS	legs have crack and both side of trailer frame is bent		mounts and cross members supports u/s	15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\TRL LEGS	legs have cracks in them			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	L side gut holers have cracks			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL LEGS	legs bent			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\MUDGUARDS	RHR bent			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\AIR LEAK	drain cox on mid tank u/s			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Chassis\CHAS CRACK	multiple body & structural cracks			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL FLOOR	side timbers u/s, coamings bend			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TRL LEGS	mounts u/s and bracing u/s			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Body\TOOLBOX	toolbox mounts cracked, hinges bend			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BOOSTER	cracks/rear boosters at diff stokes LHF booster clicks when air supplied/air tank cocks u/s			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Brakes\BRK RELINE	reline needed			15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/09/2017	2824	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres	Job Added From Invoice			02/09/2017	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			02/09/2017	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER
T015	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			02/09/2017	0	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	03246S	Wodonga Workshop	TRAILER