EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Jamie on service	06/10/2026	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Jamie and cheyne on service	18/07/2026	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Brakes\BRAKE ADJ	Check Brake's, apparently the brakes are not releasing. Maybe Brake Adjustment or R12 Valve???			24/06/2026	321028	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		19/06/2026	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Susp\Torque Rod	R/H rear rocker box Bush to be inspected and replace if need's be.			19/06/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Susp\SUSPENSION	R/H Rear Rocker Box Bush [maybe shot Reported by Driver]			19/06/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\RWC COMP	L HAND TURNING SIGN LOOSE			19/06/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Susp\SPRING HANG	Right front hanger to be repaired,		Repairs to hangers completed small cracks on front hangers	19/05/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4		23-24	02/05/2026	321028	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	BORDER BANDAG PTY LTD	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		28/04/2026	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\MOUNTS	Left hand light bar broken/loose [cable tied up]			28/04/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		02/03/2026	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	Replace all Gates, and repair guards.			11/02/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Tyres\Punct	Tyres\Punct POS 31			09/02/2026	321028	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	BORDER BANDAG PTY LTD	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	Repair gates and gate latches.			02/02/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\DAMAGE	have another go at gates			02/02/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Elect\TAIL LIGHT	Repair Tail lights.			02/02/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		02/02/2026	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 30			14/01/2026	321028	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	BORDER BANDAG PTY LTD	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	Front Rack Gate Bent Replace/Repair			12/01/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		12/01/2026	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	Repair Gate Latch on R/H side ,last post.			12/01/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Elect\TAIL LIGHT	LEFT HAND CLEARANCE LIGHT AT BACK POPPING OUT.			12/01/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
					-lights check, all working.											
					-right hand side marker light secured.											
					-left hand side combination light bracket rewelded in place to resecure.											
					-assisted with service.											
T076	Woodonga - Workshop	Body\ELECT P&W	L/H Tail light is loose.		-gates welded as required	12/01/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\MUDGUARDS	REAR PASSENGER MUDGUARD LOOSE.			12/01/2026	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			06/01/2026	321028	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	BORDER BANDAG PTY LTD	TRAILER
T076	Woodonga - Workshop	Elect\TRL LIGHTS	Rear Left Hand Light Cluster Loose (Falling Off)			02/12/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\OH&S	Rear Turn Signs Loose - Falling Off			02/12/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		02/12/2025	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Chassis\MUDGUARDS	Rear Left Hand Guard Still Loose! (Needs Bracing)		Pending	02/12/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Chassis\RWC COMP	Trailer Needs A Proper Sort Out Top To Bottom!!		Pending	02/12/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Brakes\AIR FITTIN	Brake Hose Joined (Rub Through) Over Second Axle			02/12/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			16/10/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	BORDER BANDAG PTY LTD	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	-CHECK GATES			15/10/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\MUDGUARDS	-GUARD L/H REAR LOOSE			15/10/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		15/10/2025	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	HEAD GATE NOT FITTING IN SLOTS/ SHORT POLES & BENT. LS GATE BROKEN STRAPPING.			15/10/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VService\ab	-SERVICE			15/10/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Insp\ANN INSP	Insp\ANN INSP	Insp\ANN INSP		15/10/2025	321028	PreventativeMaintenance	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		25/07/2025	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	HEAD GATE NOT FITTING IN SLOTS/ SHORT POLES & BENT. LS GATE BROKEN STRAPPING.		Created a new pending job because: not completed	17/07/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		11/06/2025	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	Front Loading Rack Crooked (Needs Attention)		Pending	11/06/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Chassis\MUDGUARDS	L/Hand Rear Guard Loose			11/06/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\HOUSEKEEP	L/Hand Turning Sign Loose			11/06/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Chassis\TRL LEGS	WINDER STILL NEEDS WORK.			12/05/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		12/05/2025	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Chassis\MUDGUARDS	LH rear guard loose			12/05/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\HOUSEKEEP	LH turning sign loose			12/05/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Chassis\WINCH/STRP	SECOND STRAP HAS BROKEN. NEEDS REPLACEMENT. (RIGHT SIDE)			12/05/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Chassis\TRL LEGS	LEG WINDER COULD USE MAINTENANCE, MISSING A WASHER (WORN THROUGH) MAY NEED GREASE? DOESN'T SOUNT RIGHT AT FULL EXTENSION.			12/05/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\HOUSEKEEP	Front loading rack is crooked (needs attention)		Pending	12/05/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\MUDGUARDS	REPAIR WELD HAS FAILED. NEEDS TO BE RE-ATTACHED. -TEMP FIXED WITH CABLE TIE.			12/05/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\MUDGUARDS	RIGHT SIDE REAR WHEEL GUARD.			12/05/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT 1-2			06/05/2025	321028	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	BEAUREPAIRES	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		08/04/2025	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
			* Ballast trailer & removed wheel equipment													
			* Inspect all axle braking components to diagnose repair													
			* Attempt to removed drums, scam seals, shoes, bushes, bearings, linings & component													
			* Removed drums, scam seals, shoes, bushes, bearings, linings & component													
			* Clean all components complete													
			* Check all parts for possible re-use													
			* Installed drums, s-cam, bushes, seals, shoe/lining kit & components													
			* Shim s-cams as required													
			* Install slack adjusters & shim to specification													
			* Adjust, grease, bearings, hubs & components													
			* Grease all s-cam tubes													
			* Installed wheel equipment & remaining components													
			* Re torque all fittings & fixtures													
			* Adjust all braking to specification													
T076	Woodonga - Workshop	Brakes\BRK RELINE	* Removed trailer ballast			07/04/2025	321028	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	PACCAR PARTS FLEET SERVICES	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		13/03/2025	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	Repair Damaged Gate/s.			06/03/2025	321028	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Tyres\TP01	Tyres\TP01			18/02/2025	321028	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	BEAUREPAIRES	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		08/02/2025	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\DAMAGE	Front Right Post/Upright Needs Welding			08/01/2025	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		08/01/2025	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Brakes\AIR TANKS	Weld Air Tank Bracket Back On.			03/12/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		02/12/2024	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Chassis\CHAS CRACK	Crack in webbing		Pending	01/11/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Susp\WHEEL ALGN	WHEEL ALIGNMENT "MIDDLE AXLE" BAD.		Pending	01/11/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Susp\SUSPENSION	-ALL ROCKER BUSHES SHOWING WEAR.		Pending	01/11/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Susp\SUSPENSION	-L HAND FORWARD ROCKER BUSH COLLAPSED.		Pending	01/11/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Reline asap	01/11/2024	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Elect\INDICATORS	L/Hand Mid Chassis Indicator VERY Dim.			15/10/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\MUDGUARDS	-R HAND REAR GUARD BRACKET BROKEN.			15/10/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
					* Inspected bush & confirmed to be buildging											
					* Unbolted & removed RHM mudguard											
					* Ballast axle as required											
					* Unbolted & removed bolt / pivot											
					* Fabricated removal of bush as required											
					* Lubricated & installed replacement rocker box bush											
					* Installed replacement pin											
					* Refit all components											
					* Aligned & tensioned all components											
T076	Woodonga - Workshop	Susp\SUSPENSION	Replace R/H Front Rocker Box Bush. (TCTC P/O: WW089152)		* Test ooerations - All ok. fault no lonaer oresent.	05/10/2024	321028	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	TWIN CITY TRUCK CENTRE - OLD	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS	VehService\DS	Will need reline asap	04/10/2024	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Susp\SUSPENSION	Replace left front rocker box bushes.		Rh rockerbox bush needs replacing trailer loaded with full kegs can not be done with the weight	27/09/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\MUDGUARDS	Lr out rigger loose			25/09/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\MUDGUARDS	Lr out rigger loose			25/09/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			20/09/2024	321028	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	BEAUREPAIRES	TRAILER
T076	Woodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			20/09/2024	321028	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	BEAUREPAIRES	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		23/08/2024	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	WELD GATES AND CROSS STRAPS.			22/07/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\MUDGUARDS	TIGHTEN REAR LEFT OUTRIGGER "GUARD" STRAPS.			22/07/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
			SLIGHT DAMAGE TO WHEEL GUARD SUPPORT. LEFT SIDE FRONT GUARD SHOULD BE REPAIRED BEFORE IT'S ON THE ROAD AGAIN.													
T076	Woodonga - Workshop	Body\MUDGUARDS	SCRATCHED PAINT SAME LOCATION ON SIDE RAILS.			22/07/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\TRL WALL	REPAIR CRACKS AT FRONT WALL AND GATES.		1	22/07/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\TRL WALL	REPAIR CRACKS AT FRONT WALL AND GATES.			22/07/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		16/07/2024	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\MUDGUARDS	REPLACED GUARDS AND OUTRIGGERS.			14/06/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	D Service	VehService\DS		14/06/2024	321028	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\MUDGUARDS	L/HAND FRONT GUARD OUTRIGGER BENT AND BRACKETS BROKEN.			14/06/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Elect\TRL LIGHTS	7 PIN PLUG STUFFED.			14/06/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	BROKEN GATE L/HAND REAR.			14/06/2024	321028	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	REPAIRED BROKEN GATES x 3.			17/04/2024	135434	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/03/2024	132717	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Susp\SUSPENSION	CRACKS IN CROSSBAR FOR TRACK RODS.			28/03/2024	132717	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/03/2024	132717	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Elect\TRL LIGHTS	Anv Chance We Can Get A Heavv Plug Attached This Kee Trailer. Just So We Don't Have To Relv On Adaptors Given That Most Of Them Already Have Both Pluas A			23/03/2024		Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\TRL GATES	REPAIRED GATE.			06/02/2024		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/01/2024		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/01/2024		Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			13/12/2023		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Albury Workshop	TRAILER
T076	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/10/2023	91798	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/10/2023	91798	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Susp\SUSPENSION	CRACKS IN CROSSBAR FOR TRACK RODS.			04/10/2023	91798	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		04/10/2023	91798	PreventativeMaintenance	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Myrtleford - Workshop	Body\TRL GATES	WELDED LOAD GATES.			11/08/2023	76997	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Myrtleford Workshop	TRAILER
T076	Myrtleford - Workshop	Body\MUDGUARDS	RIGHT SIDE WHEEL GUARD FALLING OFF. FAILED WELD.		REPAIRED LHS. RHS STILL OK.	11/08/2023	76997	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Myrtleford Workshop	TRAILER
T076	Myrtleford - Workshop	Brakes	Record Check Results As Attached To This Job			11/08/2023	76997	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Myrtleford Workshop	TRAILER
T076	Myrtleford - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/08/2023	76997	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Myrtleford Workshop	TRAILER
T076	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/07/2023		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Body\DAMAGE	L/HAND REAR AXLE RETREAD DAMAGE GUARD & BOTH TYRES.			13/07/2023		Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Elect\INDICATORS	L/HAND MID TRAILER INDICATOR NOT WORKING.			13/07/2023		Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/07/2023		Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Tyres\TP09	Tyre Position 9			13/07/2023		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Albury Workshop	TRAILER
T076	Woodonga - Workshop	Tyres\TP1+2	Tyre Position 1 + 2			01/07/2023		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Albury Workshop	TRAILER
T076	Woodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/07/2023	68766	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	Susp\WHEEL ALGN	WHEEL ALIGNMENT.			01/07/2023	68766	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Woodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/07/2023	68766	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
			Whilst checking bearing during service, on close inspection of front left hub assembly.													
			It was found that the lock washer was missing from hub assembly.													
T076	Woodonga - Workshop	DriveLine\WHEEL BRGS	All hubs were inspected and 5 washers missing, all were replaced.			01/07/2023	68766	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER

T076	Woolonga - Workshop	Body\TRL GATES	Repair broken load gates.			01/07/2023	68766	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			30/06/2023		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Albury Workshop	TRAILER
T076	Woolonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			30/06/2023		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Albury Workshop	TRAILER
T076	Woolonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			30/06/2023		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Albury Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/02/2023	31450	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL GATES	WELD GATES THAT ARE CRACKED.			16/02/2023	31450	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\WHEEL ALIGN	WHEEL ALIGNMENT.			16/02/2023	31450	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes\AIR LEAK	AIR LEAK AT BACK AXLE.		CHECKED. COULDN'T FAULT.	16/02/2023	31450	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL GATES	CRACKED GATE (TOP) L/HAND THIRD FROM FRONT. CHECK REST OF GATES PLZ.			16/02/2023	31450	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Elect\TRL LIGHTS	7 PIN SOCKET REPLACE.		PLUG OK. REPLACED 2 REAR LIGHTS.	16/02/2023	31450	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Unknown	CHECK SERVICE STATUS- SERVICE AS REQUIRED.			16/02/2023	31450	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/02/2023	31450	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/12/2022	115511	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
					fit side indicator light fit front clearance light														
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	adjusted all wheel bearings	13/12/2022	115511	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Tyres\Re-Tor	Re-Torque			29/10/2022		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job REPLACE LR GUARD.			25/10/2022		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\MUDGUARDS	Also replaced Left centre.right rear and right centre.			25/10/2022		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\SUSPENSION	SUSPENSION BUSHES.			25/10/2022		Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\SPRING PACK	REPLACE LEAF PACKS AS THEY'RE WORN OUT.			25/10/2022		Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL GATES	WELD GATES THAT ARE CRACKED.			25/10/2022		Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\WHEEL ALIGN	WHEEL ALIGNMENT.			25/10/2022		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
					No fault found with either king pin or light plug.														
T076	Woolonga - Workshop	Chassis\KING PIN	KING PIN & 7 PIN TRAILER PLUG.		Changed king pin as instructed by Wayne.	25/10/2022		Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/10/2022		Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\Torque Rod	Replaced Torque rod bushes - centre axle + Right Rear. Rocker bushes left front replaced.	VehService\DS		25/10/2022		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\SPRING HANG	Left rear rocker box + bushes and right rear rocker & bushes.			25/10/2022		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\SPRING PACK	6 x new spring packs.			25/10/2022		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Workshop\CLEAN	Clean up workshop.			25/10/2022		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/08/2022	362950	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL GATES	Repair broken gates			21/08/2022	362950	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/08/2022	362950	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Myrtleford - Workshop	Body\MUDGUARDS	RHR mudflap			07/08/2022	359510	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Myrtleford Workshop	TRAILER
T076	Myrtleford - Workshop	Body\ELECT P&W	RHR side light			07/08/2022	359510	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Myrtleford Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			14/07/2022	354428	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	BRAKES LOCK UP WITH MINIMAL PRESSURE ON BRAKE PEDAL.		ADJUSTED BRAKES.	14/07/2022	354428	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes\VALVES	TRAILER LOCKS WHEELS ANYTIME BRAKES ARE APPLIED- EVEN AUTO BRAKE IN TRAFFIC- LEES PROBLEMATIC WITH FULL KEGS. BUT ALMOST ALWAYS WITH FULL U			14/07/2022	354428	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\STRAPS	OIL FOR DOGS?			14/07/2022	354428	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		14/07/2022	354428	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\MUDGUARDS	REPLACE LR GUARD.			14/07/2022	354428	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Steering\WHEEL ALGN	Perform laser wheel alignment			04/06/2022		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Workshop\CLEAN	CLEANED WORKSHOP.			03/06/2022	164655	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Tyres\TP1+2	fit 4 runouts			03/06/2022		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			03/06/2022		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes\BRK O/HAUL	Brake Overhaul			30/05/2022	321028	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/05/2022	342048	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL WALL	FRONT OF TRAILER TWO MAIN POLES HAVE CRACKS BOTH SIDES			27/05/2022	342048	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\MUDGUARDS	HOLES IN GUARDS.		Not required	27/05/2022	342048	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	DRUMS OVERSIZE.		Completed during reline	27/05/2022	342048	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	BRAKES LOCKING UP WITH MINIMAL PRESSURE TO PEDLE- MAY BE ONLY FRONT TRAILER AXLE- OCCURS WITH AUTO BRAKES AS WELL. POSSIBLE IT'S JUDT THE TR		Monitor	27/05/2022	342048	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Tagged out for brake drums and bearings	27/05/2022	342048	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
			Stripped L/front hub to check bearings, found axle to be U/S - Removed axle. After a discussion with Ashley, decided it would be a better idea to fully reline the middle and rear axle seeing as though the hubs were to be stripped for bearing and drum replacement. Fit axle																
T076	Woolonga - Workshop	Brakes\BRK RELINE	Comolete axle fittine. mount slack adiusters. remove trailer from shed clean up.			27/05/2022	342048	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\SUSPENSION	Repair Rocker box left middle			27/05/2022	342048	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Drivline\AXLE REPLC	Refurbish new front axle and fit tio trailer			27/05/2022	342048	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Elect\INDICATORS	LEFT REAR INDICATOR FAULTY.		REPLACED INDICATOR AND WIRING.	20/05/2022	340346	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/03/2022	323805	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/03/2022	323805	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\MUDGUARDS	HOLES IN GUARDS.			20/03/2022	323805	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	DRUMS OVERSIZE.			20/03/2022	323805	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/02/2022	317589	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\CHAS CRACK	Gusset cracks and front chanel cracks. All gussets need replacing.			17/02/2022	317589	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\CHAS CRACK	Head board needs weldine.			17/02/2022	317589	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL WALL	FRONT OF TRAILER TWO MAIN POLES HAVE CRACKS BOTH SIDES			17/02/2022	317589	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL WALL	LF CORNER CRACKED IN BODY STRUCTURE			17/02/2022	317589	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/02/2022	317589	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\STRAPS	Make new gate locks up as required.			09/02/2022		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/01/2022	309954	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\CHAS CRACK	Gusset cracks and front chanel cracks. All gussets need replacing.			18/01/2022	309954	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\CHAS CRACK	Head board needs weldine.			18/01/2022	309954	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL WALL	FRONT OF TRAILER TWO MAIN POLES HAVE CRACKS BOTH SIDES			18/01/2022	309954	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL WALL	LF CORNER CRACKED IN BODY STRUCTURE			18/01/2022	309954	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL GATES	gates on left hand side badly bent			18/01/2022	309954	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL GATES	gates all need to be straightened badly			18/01/2022	309954	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/01/2022	309954	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Workshop\CLEAN	CLEAN WASHBAY			04/12/2021	297472	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL FLOOR	Gussets don't have any strength to hold floor.			04/12/2021	297422	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\CONSUMABLE	Not all U-Bolts have same thickness.			04/12/2021	297422	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes\BRK O/HAUL	Brake drums oversize all axles.			04/12/2021	297422	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\MUDGUARDS	Holes in Guards.			04/12/2021	297422	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job All gussets need replacing.			02/12/2021	297471	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\CHAS CRACK	Head board needs welding.		NEED UNLOADED	02/12/2021	297471	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL WALL	FRONT OF TRAILER TWO MAIN POLES HAVE CRACKS BOTH SIDES			02/12/2021	297471	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL GATES	gates on left hand side badly bent			02/12/2021	297471	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL GATES	gates all need to be straightened badly			02/12/2021	297471	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/12/2021	297471	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL WALL	LF CORNER CRACKED IN BODY STRUCTURE			02/12/2021	297471	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\STRAPS	FABRICATE NEW UPRIGHT			16/11/2021		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Tyres\TP3+4	supply and fit 2 tyres			12/11/2021		Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes\VALVES	BRAKE RELAY VALVE. BRAKES ONLY WORK AT HARD PRESSURE.		CHECKED BRAKING. REPLACED CA700 VALVE. TESTED BRAKE APPLICATION.	09/11/2021	290385	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/10/2021	287335	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	PARKED AFTER SERVICE. CLEANUP.	23/10/2021	287335	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\STRAPS	REPLACED STRAP.			23/10/2021	287335	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL WALL	FRONT OF TRAILER TWO MAIN POLES HAVE CRACKS BOTH SIDES			23/10/2021	287335	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/09/2021	278354	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/09/2021	278354	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\MUDGUARDS	Holes in Guards.			16/09/2021	278354	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\CHAS CRACK	Gusset cracks and front chanel cracks.			16/09/2021	278354	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Drivline\WHEEL BRGS	Wheel bearing adjustments.			16/09/2021	278354	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		16/09/2021	278354	PreventativeMaintenance	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/08/2021	278353	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL REPS	post 1 on right hand needs straightening			12/08/2021	278353	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL REPS	post need straightening and shims in holes		Refer Job# 348870	12/08/2021	278353	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/08/2021	278353	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\AIR TANKS	Rear air tank was loose.			12/08/2021	278353	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL GATES	Left second rear gate needed welding.			12/08/2021	278353	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/07/2021	271123	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\MUDGUARDS	Guards need replacing.		Tightened loose outriggers.	02/07/2021	271123	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/07/2021	271123	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/05/2021	269118	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/05/2021	269118	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\MUDGUARDS	Guards need replacing. All gussets need replacing.			26/05/2021	269118	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\CHAS CRACK	Head board needs welding.			26/05/2021	269118	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL FLOOR	Gussets don't have any strength to hold floor.			26/05/2021	269118	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\CONSUMABLE	Not all U-Bolts have same thickness.			26/05/2021	269118	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes\BRK O/HAUL	Brake drums oversize all axles.			26/05/2021	269118	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/04/2021	262934	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\LIGHTS	three clearance light runout			27/04/2021	262934	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\TP06	small crack back bar, it is normal			27/04/2021	262934	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\AXLES	axel saddles cracked			27/04/2021	262934	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL REPS	rear restraint strap in poor condition small gusset cracks		Changed 7 Straps.	27/04/2021	262934	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\TP06	cracks on front of trailer at chassis points			27/04/2021	262934	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\WHEEL ALIGN	wheels not running true			27/04/2021	262934	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/04/2021	262934	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes\BRAKE ADJ	Trailer Has no Brakes		previously done 17/3/21	18/03/2021	253211	Fault	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/03/2021	253211	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL GATES	gates on left hand side badly bent			17/03/2021	253211	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL REPS	post 1 on right hand needs straightening			17/03/2021	253211	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL GATES	gates all need to be straightened badly			17/03/2021	253211	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL REPS	post need straightening and shims in holes			17/03/2021	253211	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\WHEEL BRGS	replaced RHF bearings and cones			17/03/2021	253211	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Workshop\MOVE ASSET	move trailer			17/03/2021	253211	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/03/2021	253211	Service	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/02/2021	244064	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Body\TRL REPS	rear restraint strap in poor condition small gusset cracks			13/02/2021	244064	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Chassis\TP06	cracks on front of trailer at chassis points			13/02/2021	244064	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER
T076	Woolonga - Workshop	Susp\WHEEL ALIGN	wheels not running true			13/02/2021	244064	Repair	Completed	FL Green Distribution	FlatTop	Woolonga	LHS	069065	Woolonga Workshop	TRAILER

T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/02/2021	244064	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\STRAPS	Repair bent gate post			30/01/2021		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/12/2020	234993	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\WHEEL BRGS	adjusted LM			31/12/2020	234993	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\AXLES	axel saddles cracked			31/12/2020	234993	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/12/2020	234993	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\TRL LIGHTS	Job Added From Invoice			03/12/2020	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/11/2020	223363	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK O/HAUL	drums oversized		checked replaced 3x c/lamps	27/11/2020	223363	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\LIGHTS	three clearance light runout		replaced light lens	27/11/2020	223363	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\TP06	small crack back bar, it is normal			27/11/2020	223363	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\WHEEL BRGS	RH middle axle has adjusted			27/11/2020	223363	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\MOVE ASSET	park up			27/11/2020	223363	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/11/2020	223363	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	Job Added From Invoice			12/11/2020	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHL HUB	replace hubcap inspect all		organize parts to order	10/11/2020	215710	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	gates on left side need straightening			07/10/2020		Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL REPS	post 1 on right hand needs straightening			07/10/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/09/2020	198797	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/09/2020	198797	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\WHEEL BRGS	adjust R/R & F/R			22/09/2020	198797	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	Gate repairs			10/09/2020	197606	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer from beer shed and park			31/08/2020	195732	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/08/2020	194797	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	gates bent from loading			18/08/2020	194797	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK O/HAUL	drums oversized			18/08/2020	194797	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/08/2020	194797	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\INDICATORS	peplace LHB and wiring			18/08/2020	194797	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers/clean up			18/08/2020	194797	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/07/2020	193853	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	Lifting & cracking oversized drums rocker box worn gusset cracks		inspected ok	23/07/2020	193853	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\SUSPENSION	RHR outriggers cracked		inspected all previously done except drums are still oversized but werent replaced when reline was done	23/07/2020	193853	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	Body and Gusset cracks			23/07/2020	193853	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	Loaded, underside cracks			23/07/2020	193853	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	Cracks in saddles, boxes and cross boone			23/07/2020	193853	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	Bushes need doing			23/07/2020	193853	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\WHL HUB	put caps on guards send it			23/07/2020	193853	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\PANELS	Rust at back of trailer			23/07/2020	193853	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	gates bent from loading			23/07/2020	193853	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK O/HAUL	drums oversized			23/07/2020	193853	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/07/2020	193853	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\ELECT P&W	Change over electrical socket			22/07/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			03/07/2020	191020	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/06/2020	191946	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	RELINE		Previously completed	25/06/2020	191946	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\INDICATORS	L side blinker		Previously completed	25/06/2020	191946	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	Needs reline		As per #292199	25/06/2020	191946	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/06/2020	191946	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\PANELS	Rust at back of trailer			25/06/2020	191946	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		25/06/2020	191946	PreventativeMaintenance	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	Loaded, underside cracks			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	Body and Gusset cracks			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	needs alignment RHM rocker box u/s		ok	23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\DAMAGE	cracks everywhere			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	worn bushes			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks in gussets		ok	23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	Crossmember cracks		ok all comolete weldine R&R's one on this iob!!	23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	Lifting & cracking gusset crack body		pending trailer loaded	23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar cracks and bent		ok	23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	Needs reline oversized drums rocker box worn gusset cracks		pendning	23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\SUSPENSION	RHR outriaeers cracked		#ussett cracks and RHR outriaeer	23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL REPS	poor condition straps			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	Gussets, AHK, outrigger cracked, rear bar bent and chasis punched holes in it		ok	23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\WHL HUB	loaded underside ol, needs one after reline and suspension repairs. Pending			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\AXLES	LHM slight different unknown			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	RELINE			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/05/2020	191091	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\INDICATORS	L side blinker			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\CLEAN	clean up for servicing, pack away stock and clean benches			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	Cracks in saddles, boxes and cross boone			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	Bushes need doing			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	needs reline			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	all duals are just sitting on. Wasn't st sure if you had already booked out bearings, seals and nut kits so havent's ordered anything			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\WHL HUB	put caps on guards send it			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	reline			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\Torque Rod	t/rod bushes			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\CLEAN	clean up top w/shop			23/05/2020	191091	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\WHEEL BRGS	Adjusted new bearings			21/05/2020	191019	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\AXLES	LHM slight different unknown			23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		pending: brakes on F 3/3 M: 3/3 R: 2/3	23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	need reline		would reccoment looking at reline very soon	23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\WHEEL BRGS	poor oversized drums rocker box worn gusset cracks		to be done on reline- completed	23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\SUSPENSION	RHR outriaeers cracked		oendine: LH rocker box bolt loose. missine leads worn rocker boxes worn. cant and broken trailarm bushes and torque rod bushes	23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\SUSPENSION	LHM ubolts mismatched		one only slightly longer in threat-ok	23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	reline soon		ok	23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		23/04/2020	191018	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL REPS	poor condition straps			23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	Gussets, AHK, outrigger cracked, rear bar bent and chasis punched holes in it			23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\WHL HUB	loaded underside ol, needs one after reline and suspension repairs. Pending			23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK O/HAUL	all drums oversized, rocker box u/s a;; suspension bushs U/S-pening			23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BOOSTER	boost lines goal, air tank lines			23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	RELINE			23/04/2020	191018	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\SUSPENSION	LHM ubolts mismatched			31/03/2020	191017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	reline soon			31/03/2020	191017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		front = L5 R5 m-axle = L3 R3	31/03/2020	191017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	need reline		rear axle = L3 R4	31/03/2020	191017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	Landing leg bracing U/S		inspected by Andrew - ok	31/03/2020	191017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks in gussets			31/03/2020	191017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	Crossmember cracks			31/03/2020	191017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	Lifting & cracking			31/03/2020	191017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist gusset crack body	VehService\DS	drop trailer and do yard check at end	31/03/2020	191017	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	rear bar cracks and bent			31/03/2020	191017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\WHEEL BRGS	poor oversized drums rocker box worn gusset cracks			31/03/2020	191017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\SUSPENSION	RHR outriaeers cracked			31/03/2020	191017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect	Job Added From Invoice			28/02/2020	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\TAIL LIGHT	Job Added From Invoice			28/02/2020	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\LIGHTS	replace 3x clearance light 1x blinker & number plate light		cut out old wire & rewire rear bar	25/02/2020	188704	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/02/2020	188704	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/02/2020	188704	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	Landing leg bracing U/S			25/02/2020	188704	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	mid all cross sport is bent		As per #273657	25/02/2020	188704	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks in gussets & rails			25/02/2020	188704	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	Crossmember cracks			25/02/2020	188704	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	Lifting & cracking			25/02/2020	188704	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\MOVE ASSET	Hook up & bring in to shed for sevice		Move & drop trailers	25/02/2020	188704	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\ELECT P&W	Electrical repairs			25/02/2020	188704	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	needs alignment			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	cracks in floor			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	worn bushes			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	many cracks			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	floor bracket detached			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER

T076	Wodonga - Workshop	Body\TRL LEGS	mid all cross sport is bent			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	LM RM cross members cracked			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/01/2020		Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\DAMAGE	RHM rocker box u/s cracks everywhere			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	1 mudflap 2 guards		replace 3x guards straiten and tighten outriggers	30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	Trailer Floor Repairs			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	left hand guards need replacing			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	bracing U/S			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	need reline			30/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	support bar for gates bent and cracked on left front side			30/01/2020		Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\CLEAN	clean up after t076			30/01/2020	186444	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	adjust RHS wheel bearing			30/01/2020	186444	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL REPS	take out gate pole weld paint and replace			30/01/2020	186444	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	adjust LHS wheel bearing			30/01/2020	186444	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\MUDGUARDS	replace old guards adjust out riggers and refit			30/01/2020	186444	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\MOVE ASSET	yard check			29/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\CLEAN	clean			29/01/2020		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer			29/01/2020	186444	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	adjust wheel bearings			29/01/2020	186444	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\WINCH/STRP	replace binder straps			03/01/2020	182318	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/01/2020	182318	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	Service	VehService\DS		03/01/2020	182318	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	many cracks			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	floor bracket detached			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	mid all cross sport is bent			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	LM RM cross members cracked			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	needs alignment			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	cracks in floor			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\DAMAGE	RHM rocker box u/s cracks everywhere			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	worn bushes			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	1 mudflap 2 guards			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	Trailer Floor Repairs			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	left hand guards need replacing			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	bracing U/S			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	need reline			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	support bar for gates bent and cracked on left front side			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/11/2019		Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Steering\WHEEL BRGS	replace bearing front axle check and repack others			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\TRL LIGHTS	REPAIRE REAR LIGHT			13/11/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			23/10/2019	163497	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			23/10/2019	163497	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	service	VehService\DS		04/10/2019	162529	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\FIFTH WHEE	needs plate added between t/t and guid plate		modify lead in plate to skid plate	04/10/2019	163192	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/10/2019	162529	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\DAMAGE	repairs to broken up right			03/10/2019	162529	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/10/2019	162529	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\RUN OUT	Job Added From Invoice			15/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\AIR LEAK	fix leaks			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TOOLBOX	repairs to lid and box			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	many cracks			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	floor bracket detached			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	mid all cross sport is bent			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	cross braces bent			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	LM RM cross members cracked			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	all members cracked and front of trailer has cracks			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	gussets and gates cracking			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	needs alignment			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	crack at front of trailer in webing gussets and floor gates cracked			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	cracks in floor			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	rod bush's u/s			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\DAMAGE	RHM rocker box u/s cracks everywhere			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	cracks at front of trailer also nearly every gusset			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	worn bushes			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	1 mudflap 2 guards			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	Chassis Crack			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	Wheel Bearings			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	Trailer Floor Repairs			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/09/2019	156825	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	left hand guards need replacing			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL REPS	straps broken			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	bracing U/S			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	need reline			06/09/2019	156825	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\RWC COMP	Remount rear sinage			03/09/2019	156527	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres	Job Added From Invoice			11/08/2019	151063	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice			11/08/2019	151063	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			11/08/2019	151063	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			11/08/2019	151063	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			11/08/2019	151063	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\MOVE ASSET	move trailer from beer shed to tyre bay			06/08/2019	151063	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\MOVE ASSET	park trailer			06/08/2019	151063	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	Weld cracks as per service sheet			21/07/2019	148477	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\MUDGUARDS	Change left hand mudflap & anti-soil			21/07/2019	148477	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/07/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	guards			20/07/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	2 guards/mudflap		Previously completed	20/07/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/07/2019		Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	Major crossmember, gusset & chassis cracks Springs shifting			20/07/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	Will need adjusting next service			20/07/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	Underside of floor in very poor condition			20/07/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	1 mudflap 2 guards			22/06/2019	144832	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		22/06/2019	144832	PreventativeMaintenance	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/06/2019	144832	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	guards		job pending	22/06/2019	144832	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/06/2019	144832	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	2 guards/mudflap			22/06/2019	144832	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	paint gate latch's for keg trailer gates			19/04/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	remove old gate's from trailer			19/04/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	set up new gates to be installed			19/04/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/04/2019	132540	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\DRV TYRES	right front inner a bit low. Monitor			02/04/2019	132540	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\TRL LIGHTS	left hand parker light dull to right side			02/04/2019	132540	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL REPS	bent gates and broken weld's and uprights			02/04/2019	132540	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	rope rail's need replacing and minor chassis cracks			02/04/2019	132540	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	worn bushes			02/04/2019	132540	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/04/2019	132540	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	weld/repair broken gates			19/03/2019	129722	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Job Added From Invoice			21/02/2019	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\DAMAGE	reweld bracking bracket R/H/S back post		repair upright as per R&R	19/02/2019	126516	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		replaced RHF slack adjuster	19/02/2019	126516	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	1 guard broken monitor next service			19/02/2019	126516	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRAKE ADJ	RHF slack adjuster u/s			19/02/2019	126516	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	cracks at front of trailer also nearly every gusset			19/02/2019	126516	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	moving trailers	19/02/2019	126516	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/01/2019	119440	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Steering\WHEEL ALGN	steering is shaky at about 85-90/cm/par then goes away at about (100/cm/p/m)		issue not with trailer	12/01/2019	119440	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	gate post on drivers side R/H side with no 4 welded in it need grinding at bottom so it fits in square take on trailer properly takes 2 people to pull it out of trailer?			12/01/2019	119440	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/01/2019	119440	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	guards			12/01/2019	119440	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	crack at front of trailer in webing gussets and floor gates cracked			12/01/2019	119440	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL FLOOR	cracks in floor			12/01/2019	119440	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\DAMAGE	RHM rocker box u/s cracks everywhere			12/01/2019	119440	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	rod bush's u/s			12/01/2019	119440	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearing adjustments			12/01/2019	119440	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL REPS	binder straps and fitted new dog			12/01/2019	119440	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL REPS	Trailer (Tautliner) Repairs		INSPECT FOR RNRS, ANDREW TO DO LATER	11/01/2019	19440	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\MOVE ASSET	Move Assets		MOVE TRAILER	11/01/2019	19440	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL REPS	Trailer (Tautliner) Repairs		WELD GATES (STRAPS) UPRIGHT, REPLACE 2X STRAP RATCHET	11/01/2019	19440	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	repair gates and uprights			08/01/2019	118509	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	set up for 1500mm tall gates			05/01/2019		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	repair 2x gates			25/10/2018		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\WINCH/STRP	Job Added From Invoice			04/10/2018	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	measure gates for T076. 3 foot over all width 2200 in between feet 1020. measurement between uprights 2700			26/09/2018		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\TRL LIGHTS	Job Added From Invoice			30/08/2018	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/08/2018	87055	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	load gates cracked			28/08/2018	87055	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL REPS	Needs 6 new straps		new 11mtr strap placed in toolbox	28/08/2018	87055	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\ELECT P&W	Need new trailer clearance light on R/H side of trailer		all lights working RH clearance light replaced	28/08/2018	87055	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRAKE ADJ	rear gate on left hand side has a brace missing and 3rd gate on LH side badly bent need fixing		as per job#185207	28/08/2018	87055	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	gate post on drivers side R/H side with no 4 welded in it need grinding at bottom so it fits in square take on trailer properly takes 2 people to pull it out of trailer?			28/08/2018	87055	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/08/2018	87055	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER

T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/06/2018	76506	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	load gates cracked			28/06/2018	76506	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL REPS	Needs 6 new straps			28/06/2018	76506	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\ELECT P&W	Need new trailer clearance light on R/H side of trailer		light on order	28/06/2018	76506	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRAKE ADJ	rear gate on left hand side has a brace missing and 3rd gate on LH side badly bent need fixing			28/06/2018	76506	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\CHN/RLR/MN	needs spare tie down straps (2) and 2 ratchets (hand ones)		In toolbox	28/06/2018	76506	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/06/2018	76506	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/05/2018	71931	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	load gates cracked			31/05/2018	71931	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\HOUSEKEEP	missing load winch strap u/s			31/05/2018	71931	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	L/H rear upright has snapped		previously replaced	31/05/2018	71931	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	L/H rear gate needs straightening and the middle foot welded back on		previously done	31/05/2018	71931	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\DAMAGE	L/H side rear upright - weld cracked			31/05/2018	71931	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\CHN/RLR/MN	replace all frayed straps		all frayed straps replaced	31/05/2018	71931	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	replaced binder straps	31/05/2018	71931	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	repaired gates			22/05/2018		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body	Job Added From Invoice			24/03/2018	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	5 weld guard support & upright			09/03/2018	58723	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	repairs			09/03/2018	58723	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\CLEAN	cleaning			09/03/2018	58723	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\MOVE ASSET	drop trailer and look for service in yard			09/03/2018	58723	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\HOUSEKEEP	missing load winch strap u/s			09/03/2018	58723	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			09/03/2018	58723	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	Service	VehService\DS		09/03/2018	58723	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\CLEAN	clean up top shed			09/02/2018		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		completed during service	08/02/2018	53910	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRAKE ADJ	scams need shimming u/s			08/02/2018	53910	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	11 binged			08/02/2018	53910	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BOOSTER	middle booster at different strokes		levelled all booster arms so they run at the same strokes	08/02/2018	53910	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	rocker box's are worn		replaced L/front r/box and bushes new centre bolt l/front, replaced t/rod bushes where req complete suspension repairs	08/02/2018	53910	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/02/2018	53910	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	chassis cracks			08/02/2018	53910	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\AXLE CT	adjusted brakes where req			08/02/2018	53910	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	needs alignment			08/02/2018	53910	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\AXLE CT	L/front r/box			08/02/2018	53910	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\Torque Rod	t/rod bushes			08/02/2018	53910	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	gate repairs			08/02/2018	53910	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/12/2017	47583	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/12/2017	47583	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\DAMAGE	tyres to be checked			22/12/2017	47583	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	load gates cracked			22/12/2017	47583	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres	Job Added From Invoice			07/11/2017	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			07/11/2017	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			07/11/2017	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			07/11/2017	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/10/2017	38616	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\DAMAGE	tyres to be checked			31/10/2017	38616	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	gussets and gates cracking			31/10/2017	38616	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	rocker box's are worn			31/10/2017	38616	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	Service B Trailer	VehService\DS		31/10/2017	38616	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Air Con\ELECT P&W	LR light is dul			28/09/2017	34927	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/09/2017	34927	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	replace damaged mud guard			28/09/2017	34927	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	RB mudguard u/s			28/09/2017	34927	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BOOSTER	middle booster at different strokes			28/09/2017	34927	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	all members cracked and front of trailer has cracks			28/09/2017	34927	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		28/09/2017	34927	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	R/H front axle - mudguard needs replacing		see #124055	02/09/2017	29889	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\ELECT P&W	R/H side - 3rd light needs replacing - no amber 1/2		see #124056	02/09/2017	29889	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	R/H front axle - mudguard needs replacing		replaced mudguard	02/09/2017	29889	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\ELECT P&W	R/H side - 3rd light needs replacing - no amber 1/2		replaced 2 clearance lights	02/09/2017	29889	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/08/2017	2846	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp	needs weight gauge			25/08/2017	2846	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	guards u/s mudflap u/s		prev. done	25/08/2017	2846	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	gates u/s gussets u/s			25/08/2017	2846	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearings adjustments		Done as part of service	25/08/2017	2846	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\ELECT P&W	LR light is dul			25/08/2017	2846	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	LM RM cross members cracked			25/08/2017	2846	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	11 binged			25/08/2017	2846	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/08/2017	2846	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	floor bracket detached			01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	many cracks			01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	mid all cross sport is bent			01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	cross braces bent			01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Steering\SHOCK ABS	rocker bushes, t/rod bushes		previously done	01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	LR guard and ourtigger missing		previously done	01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SHOCK ABS	rocket box rubber on bolt u/s		previously done	01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	rocker bushes u/s		previously done	01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	needs reline		previously done	01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\AIR LEAK	brakes take a long time to release			01/08/2017	24485	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\SLACK ADJ	Removed LHF scam and inspected for damage, changed slack adjuster, put it back together			01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	guards u/s mudflap u/s			01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRAKE ADJ	scams need shimming u/s			01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	gates u/s gussets u/s			01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHEEL BRGS	bearings adjustments			01/08/2017	24485	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		01/08/2017	24485	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\CHN/RLR/MN	remove broken/bent chain dog/ratchet and replace			28/07/2017	24484	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\CLEAN	clean up work area and move trailer 76 down to service bay for grease			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	brake reline			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\AIR LEAK	brakes take a long time to release			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SPRNG HANG	LHF rocker box cracked			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	floor bracket detached			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	cosmetic cracks u/s			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp	needs weight gauge			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	Minor cracks everywhere			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	cracks in all gussets u/s			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SPRNG HANG	rocker bushes		replaced all 4 bushes	04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	reline			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	mid all cross sport is bent			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	all cross members wield coming way from wields			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	cross braces bent			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Steering\SHOCK ABS	rocker bushes, t/rod bushes			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	LR guard and ourtigger missing			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SHOCK ABS	rocket box rubber on bolt u/s			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	cracks in cross members u/s			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	front LH rocker box u/s			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	rocker bushes u/s			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	needs reline			04/07/2017	20429	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRAKE ADJ	had to back brakes right off to move trailer as would not release			01/07/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop\MOVE ASSET	move into shed and put on stands			01/07/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BREAKDOWN	brakes sticking		CTS to inspect	30/06/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			23/06/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CROSS MBR	cracks in cross members u/s			23/06/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	front LH rocker box u/s			23/06/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SUSPENSION	rocker bushes u/s			23/06/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	needs reline			23/06/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	Service	VehService\DS		23/06/2017		Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	replace L/R mud guard			27/05/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	attempted to fit guard but there is not enough space			18/05/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			06/05/2017	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\ROTATION	Job Added From Invoice			06/05/2017	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			06/05/2017	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres	Job Added From Invoice			03/05/2017	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/05/2017	8418	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\ELECT P&W	L/hand no plate light u/s		completed	02/05/2017	8418	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL GATES	some gates need repair			02/05/2017	8418	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\TAIL LIGHT	R/H tail light assembly needs fixing		replaced light assembly	02/05/2017	8418	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\DAMAGE	repair damage from tyre blow out		completed	02/05/2017	8418	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/05/2017	8418	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\MUDGUARDS	LR guard and ourtigger missing			02/05/2017	8418	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SHOCK ABS	rocket box rubber on bolt u/s			02/05/2017	8418	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres	Job Added From Invoice			22/04/2017	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			22/04/2017	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			22/04/2017	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/03/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\AIR LEAK	brakes take a long time to release			11/03/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	l/front rocker box u/s t/rod bushes u/s rocker box bushes u/s r/rear light assembly	11/03/2017		Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\ELECT P&W	L/hand no plate light u/s			11/03/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	all cross members wield coming way from wields			11/03/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	cross braces bent			11/03/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Steering\SHOCK ABS	rocker bushes, t/rod bushes			11/03/2017		Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Elect\ELECT P&W	Trailer plug - broken pin		Track rod bush's and replaced at front electrical plug	07/03/2017		Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice			14/02/2017	0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	06906S	Wodonga Workshop	TRAILER

T076	Wodonga - Workshop	Elect\ELECT P&W	test drove, major elec issues, engine cutting in & out majorly				02/02/2017 230525	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/01/2017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body\TRL LEGS	mid all cross sport is bent				21/01/2017	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			21/01/2017	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP			21/01/2017	PreventativeMaintenance	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice				22/12/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body	Job Added From Invoice				09/12/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\WHL HUB	Job Added From Invoice				07/12/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
						moving trailers										
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	looking for next service		06/12/2016	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonaa Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/12/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	DrivLine\AIR LEAK	bad air leak			previously done	06/12/2016	Fault	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\AIR LEAK	brakes take a long time to release				06/12/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	cracks in all gussets u/s				06/12/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SPRING HANG	rocker bushes				06/12/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	reline				06/12/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body	Job Added From Invoice				15/11/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body	Job Added From Invoice				15/11/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\TP19	Job Added From Invoice				15/11/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Put gates back in		11/11/2016	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				11/11/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\MUDGUARDS	LHF guard u/s both front mudflaps u/s				11/11/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres	LHR outer tyre u/s				11/11/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	Minor cracks everywhere				11/11/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Steering\WHEEL SEAL	Job Added From Invoice				19/10/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Steering\WHEEL SEAL	Job Added From Invoice				30/09/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BOOSTER	Job Added From Invoice				30/09/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes\BRK RELINE	Job Added From Invoice				30/09/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				13/09/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\MUDGUARDS	LHF guard u/s both front mudflaps u/s				13/09/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres	LHR outer tyre u/s				13/09/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			13/09/2016	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\TP21	Job Added From Invoice				11/08/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\TP21	Job Added From Invoice				11/08/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\TP21	Job Added From Invoice				11/08/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Workshop	went down to the loading bay to help pick up a loaded trailer that has sunk in the ground				26/07/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				02/07/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\MUDGUARDS	LHF guard & both front mudflaps need replacing				02/07/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	LHF booster 30/30 u/s				02/07/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			02/07/2016	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	floor bracket detached				02/07/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp	needs weight gauge				02/07/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				13/05/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	LHF booster 30/30 u/s				13/05/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis	many cracks				13/05/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			13/05/2016	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				13/05/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			13/05/2016	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice				01/04/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				30/03/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\MUDGUARDS	LHF guard & both front mudflaps need replacing				30/03/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\AIR LEAK	nylon service line rubbed through on crossmember				30/03/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\MUDGUARDS	LHF guard u/s both front mudflaps u/s				30/03/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\CHAS CRACK	cosmetic cracks u/s				30/03/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Susp\SPRING HANG	LHF rocker box cracked				30/03/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			30/03/2016	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\TP17	Job Added From Invoice				01/03/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\TP17	Job Added From Invoice				01/03/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				24/02/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\MUDGUARDS	LHF guard & both front mudflaps need replacing				24/02/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Chassis\AIR LEAK	nylon service line rubbed through on crossmember				24/02/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			24/02/2016	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Tyres\TP19	Job Added From Invoice				26/01/2016 0	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Body	repair all broken gates				21/01/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				17/01/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	Insp\ANN INSP	Roadworthy				17/01/2016	Repair	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER
T076	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS			17/01/2016	Service	Completed	FL Green Distribution	FlatTop	Wodonga	LHS	069065	Wodonga Workshop	TRAILER