

## Cross-Canada Vehicle Identification Number (VIN) report

## 2ATK06204GMCCP002

1986 SIEMENS TRAILER Semi Trailer

## Registration and inspection details

Eligible for Saskatchewan registry	ation:	Required Saskatchewan inspection(s):  Mechanical inspection
Most recently registered:	Jurisdiction	Status
	Saskatchewan	Unsafe-Inspection
Most recently registered:  Previous registration status:  Important information about this vehicle:  Jurisdiction search:	Jurisdiction	Status
	Alberta	Normal
•	This vehicle:  • is recorded as Unsafe-Inspection in Saskatchewan.  • has been recorded as Normal in Alberta.	
Jurisdiction search:	All provinces respon	nded.
Notes		
A01-42		

Claims:

No Saskatchewan damage claims reported to SGI.

## Saskatchewan VIN search results

Details:

02 February 2021

SK PST status:

SK registration expiry:

Payable

VIN status date:

18 February 2021

VIN status:

Unsafe - Inspection