EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
1068	Albury - Workshop	Brakes|BRAKE ADJ	BRAKES NOT HOLDING WHEN LOADING		Brought truck over pit, checked and adjusted brakes, applied park brake and checked brake linings made contact with brake drum, released park braked and tested service brake, all good, truck sent back to work.	######## 807146		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Brakes|BRAKE ADJ	brakes need checking		Brought truck over pit, checked and adjusted brakes, applied park brake and checked brake linings made contact with brake drum, released park braked and tested service brake, all good, truck sent back to work.	######## 807146		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Wodonga - Workshop	VehService|AS	VehService|AS A Service VehService|AS Svc B 1 Service, Jack up steer axle check bearings and king pins.	VehService|AS		######## 802441		Service	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	VehService|AS Svc	Replace cabin filter.	VehService|AS Svc		######## 802441	PreventativeMaintenance	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonas Workshop	P/MOVER
1068	Wodonga - Workshop	Engine|ADBLUE	derating bad , losing power		REPAIRED AFTER TREAT FAULTS	######## 802441		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Steering|HOSES	FOUND STEERING HOSE BLOWN. REMOVED AND HAD NEW ONE MADE AT RAPID HYDRAULICS. B Service Serviced @ 794,190 Kims			######## 802441		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	VehService|BS		VehService|BS		######## 793828		Service	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonas Workshop	P/MOVER
1068	Albury - Workshop	CTS|TS Drive	CTS Left Side Need Replacing gut wear			######## 793828		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	DrCabElect|NOT/GAUGE	Lights Not Working On Two Gauges		Two Blown Globes	######## 793828		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Brakes|ABS FAULTS	esc light is illuminated all the time when cornering light flashed and truck droppps back to idle			######## 793828		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Brakes|ABS	ESC Defer RMR (132415)			######## 793828		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Chassis|MUDGUARDS	Front Mud Flaps Missing			######## 793828		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	DrCabElect|NOT/GAUGE	Volt Meter Not Working		Wiring Issue Repaired As Required	######## 793828		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Driveline|CTCH PACK	Driveline|CTCH PACK		THE CLUTCH WAS REPLACED AT 774289 KMS	######## 793801		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - 4	P/MOVER
1068	Albury - Workshop	Engine|ADBLUE	After Treatment Light On Dash.		Traveled to workshop. connected comsuter to truck. checked for faults found two faults 1doser oumo not resoondne & doser oumo loss of orimel. removed todbua lid above R/H fuel tank. removed all oanels toe ean access to doser oumo. removed doser oumo from brackets. removed all adblue lines & fluid	######## 784546		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Brakes|BRAKE ADJ	Brakes On PM Not Holding When Loading		Checked & Adjusted Brakes	######## 774852		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	VehService|AS	A Service	VehService|AS	Serviced By Aaron R, Shane Mc & John S	######## 774684		Service	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	DriveLine|DIFF REPAIN	DISMANTLED AND INSPECTED POWER DIVIDER. REPLACED BULL GEAR AND REBUILT PUMP- WARRANTY - PARTS COVERED VehService|AS Svc B 1 Service, Jack up steer axle check bearings and king pins.	VehService|AS		######## 792801		Repair	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - 4	P/MOVER
1068	Albury - Workshop	VehService|BS Svc	Replace cabin filter.	VehService|BS Svc		######## 772855	PreventativeMaintenance	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonas Workshop	P/MOVER
1068	Albury - Workshop	DriveLine|CLUTCH	CLUTCH BRAKE NOT WORKING SOMETIMES.			######## 772855		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	DriveLine|DIFF LN SER	FRONT DIFF CLUNKING WHEN CROSS LOCKS ARE IN.			######## 772855		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	DriveLine|OIL LEAK	RRE seal seal leaking VehService|AS Svc B 1 Service, Jack up steer axle check bearings and king pins.			######## 772855		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	VehService|BS Svc	Replace cabin filter.	VehService|BS Svc		######## 771677	PreventativeMaintenance	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonas Workshop	P/MOVER
1068	Albury - Workshop	Insp|ANN INSP	Insp|ANN INSP Annual Inspection As Per Checklist	Insp|ANN INSP		######## 771277	PreventativeMaintenance	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Elect|ELECT P&W	Volt meter dropping to nothing.		inspected not faulting at time	######## 760549		Fault	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workhoo	P/MOVER
1068	Albury - Workshop	VehService|AS	VehService|AS A Service	VehService|AS	completed by SS AR JS	######## 759153		Service	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Air Con|HEATER	REPLACE HEATER FAN		REPLACED FAN AND TESTED ALL GOOD KLM AT TIME OF REPLACEMENT 717110	######## 757686		Repair	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Elect|ELECT P&W	REPAIR MAIN ALTERNATOR WIRING AT ALT SHORTING OUT ON CHASSIS BOLT		SHORTEN ALTERNATOR LEAD AT ALT ALTERNATOR TCTC T134502 -vehicle charging intermittently according to driver. -alternator checked over and loaded, charging at 14.8 volts, couldn't fault after multiple tests. -batteries inspected, all green and loading ok, terminals were dirty, all were checked over for breaks and cleaned. -truck voltage rechecked once back toaether. charging as intended.	######## 757686		Repair	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Elect|ALT	Check Charging System, Voltage Dropped Below 10 Volts While Driving			######## 756122		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Elect|WORK LIGHT	CAB GUARD LIGHTS NOT WORKING.			######## 756066		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Elect|WORK LIGHT	work light not working			######## 756066		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Myrtleford - Workshop	DriveLine|DRV LN SER	CHECK REAR DIFF ALIGMENT TO FRONT DIFF		FOUND REAR SWAY BAR MOUNTS TO BE NOT WELDED IN THE RIGHT SPOT MAKING REAR DIFF HANG OUT TO THE RIGHT NEEDS MORE INVESTIGATING (KLM AT TIME OF INSPECTION 756193)	######## 756066		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Myrtleford - Workshop	Elect|ELECT P&W	Rad Scales CH1 & 3 Not reading correctly.			######## 756011		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Myrtleford - Workshop	Body|FW WHEL	REMOVE AND FIT NEW FOOT BUSHES AND PINS TO T/TABLE TOP		KLM AT TIME OF REPLACEMENT 755967	######## 756028		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Susp|SUSPENSION	REPLACE TOP LEFT AND TOP RIGHT SUSPENSION GUSSETS		KLM AT TIME OF REPLACEMENT 755967	######## 756011		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Susp|SWAYBAR	REPLACE FRONT SWAY BAR BUSHES		KLM AT TIME OF REPLACEMENT 755967	######## 756011		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Myrtleford - Workshop	Susp|AIR LEAK	Air leak L/H front air tank.		TIGHTEN AIR DRYER MID BODY BOLTS	######## 756011		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Myrtleford - Workshop	DrCabElect|NOT/GAUGE	Ad-Blu gauge is going from full to empty, and after treat goes on and off, also check engine light is on.			######## 756011		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	VehService|AS	VehService|AS A Service RADIATOR LEAKING (AT SHELLEY) T134307 REMOVED AND FITTED RADIATOR	VehService|AS	completed by JS TOWED TO WODONGA DEPOT RADIATOR REPAIRED AT BORDER RADIATORS	######## 755090		Service	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Cooling|RADIATOR				######## 754521		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Body|BREAKDOWN	Body|BREAKDOWN		TOW FROM SHELLEY - WD DEPOT - AAA TOWING	######## 757271		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Tyres|TP's-6	Tyres|TP's-6			######## 754511		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1068	Albury - Workshop	Tyres|TP's-8	Tyres|TP's-8			######## 754511		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1068	Albury - Workshop	VehService|BS	VehService|AS B Service	VehService|BS	completed by SMc JS	######## 749591		Service	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	VehService|AS	VehService|AS A Service	VehService|AS	completed by JS SMc	######## 749591		Service	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Brakes|BRK RELINE	Brakes|BRK RELINE PURCHASE ORDER 116676/T133785 WAS FOR WOR205930			######## 754521		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	VehService|AS	VehService|AS A Service	VehService|AS	completed by JS	######## 749591		Service	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	DrCabReg|ELECT P&W	ESC/TC/After treat /check engine lights are on.		checked, Ok at time of service	######## 740066		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Engine|ADBLUE	AFTER TREAT LIGHT KEEPS COMING ON			######## 740066		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Engine|FAULT CODE	CHECK ENGINE ALWAYS ON!			######## 740066		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Body|CHAS	NO FIRE EXTINGUISHERS!			######## 740066		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Tyres|TP's-2	Tyres|TP's-2		MECHANIC IN MYRTLEFORD - CONTACT THEM FOR DETAILS BOLT ON 2 Y/SER	######## 741705		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - 4	P/MOVER
1068	Albury - Workshop	Cooling	Transfer tube cracked, radiator bottom hose p clamp snapped & leaking coolant		WARRANTY JOB DONE BY TCTC AT G/F M/FORD 27/4/26 AT 733372 KMS	######## 733372		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - 4	P/MOVER
1068	Albury - Workshop	DrCabReg|SEAT	*DRIVERS SEAT CUSHION NEEDS TO BE REPLACED Engine|ENG FAN FIT BEARING & SEAL KIT TO HORTON			######## 733372		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Engine|ENG FAN	REPLACE ENGINE FAN told fan was cracked		KLM AT TIME OF REBUILD 735011	######## 733372		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	DrCabReg|MOUNTS	REPLACE TOP BONNET STOPS & BONNET DICES RELINE REAR DRIVE AXLE REPLACE S/CAMS & TUBES REPLACE WHEEL BEARINGS ON BOTH SIDES			######## 734891		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Brakes|BRK RELINE	REPLACED REAR DIFF INPUT SHAFT SEAL & NUT			######## 735011		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	DriveLine|DRIVES	ADJUST END FLOAT IN POWER DIVIDER			######## 733372		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	DriveLine|SHOCK ABS	REPLACE WARN TOP DRIVE SHOCKER MOUNTS & REPLACE ALL TOP & BOTTOM DRIVE SHOCKER MOUNTS			######## 733372		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Body|MOUNTS	REPLACE LH & RH RADIATOR SIDE MOUNT RUBBERS			######## 733372		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Susp|Torque Rod	LHF REAR AND RHR FRONT TORQUE ROD BUSHES U/S			######## 733011		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Body|EXHAUST	REPLACE EXHAUST DUMP PIPE RUBBERS		REPLACED BYE T.C.T.C	######## 733372		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Susp|SHOCK ABS	REPLACE TOP & BOTTOM STEER SHOCKER RUBBERS			######## 733372		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Brakes|ABS FAULTS	*TRAILER ABS LIGHT COMES ON OCCASIONALLY			######## 740066		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Elect|ELECT P&W	REPLACE ENGINE EARTH CABLES FROM ENGINE TO CHASSIS			######## 740066		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Elect|HEAD LIGHT	REPAIR H/LIGHT WIRING IN CHASSIS (H/LIGHTS WERE STUCK ON)			######## 740066		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Engine|AIR LEAK	REPLACE LEAKING GOVENOR AIR LINES			######## 740066		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Engine|GOV VALVE	REPLACE LEAKING GOVENOR VALVE			######## 733372		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Elect|WORK LIGHT	WORK LIGHTS ON CAB GUARD NOT WORKING		REPLACED FUSE AND TESTED UNABLE TO FAULT	######## 733372		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	DriveLine|CLUTCH	REPLACE BOTTOM CLUTCH BELL CRANK BEARING Truck Won't Build Up Air (Replace Compressor) (TCTC P/O: T133546)			######## 735011		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER
1068	Albury - Workshop	Engine|COMPRESSOR				######## 741705		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - 4	P/MOVER
1068	Albury - Workshop	Tyres|STEER TYRE	FIT 2 X NEW STEER TYRES OUT OF MJFORD STOCKS			######## 733372		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	MYRTLEFORD MOTORS - 3	P/MOVER
1068	Wodonga - Workshop	DriveLine|OIL LEAK	Oil Leaking Rear Diff. (TCTC Reapirne Under Warranty. SS$315 Kims)			######## 733033		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonas Workshop	P/MOVER
1068	Albury - Workshop	Tyres|FITMENT	Worn Back Axle Drive Tyres VehService|AS Svc B 1 Service, Jack up steer axle check bearings and king pins.		DRIVER TYRES WERE CHAGED BY BOURDER BANDAG ON 17/4/26	######## 737064		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workhoo	P/MOVER
1068	Albury - Workshop	VehService|BS Svc	Replace cabin filter.	VehService|BS Svc	KLM AT TIME OF SERVICE 733372	######## 733372	PreventativeMaintenance	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Brakes|BRAKE ADJ	Brakes Need Adjusting		AS BELOW	######## 733372		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1068	Albury - Workshop	Brakes|BRAKE ADJ	Check Brakes Not As Good As Normal		COMPLETED ON B1 SERVICE JOB # (205922)	######## 733372		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - 4 - OLD	P/MOVER
1068	Albury - Workshop	Chassis|AIR LEAK	Check For Air Leaks & Repair			######## 733033		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Tyres|TP's-10	Tyres|TP's-10		TYRES WERE FLAT - SHAUN INSTRUCTED FITTER TO CHANGE THEM OUT - JC EMAIL	######## 727064		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1068	Albury - Workshop	Tyres|TP's1-12	Tyres|TP's1-12		TYRES WERE FLAT - SHAUN INSTRUCTED FITTER TO CHANGE THEM OUT - JC EMAIL	######## 727064		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1068	Albury - Workshop	VehService|AS	VehService|AS A Service	VehService|AS	completed by TP	######## 730647		Service	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Tyres|TP's-2	Tyres|TP's-2			######## 716175		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1068	Albury - Workshop	Tyres|TP's-8	Tyres|TP's-8			######## 716175		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1068	Albury - Workshop	Tyres|TP's-6	Tyres|TP's-6			######## 716175		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1068	Albury - Workshop	DriveLine	Power dividor has excessive movment, repaired		SMc	######## 709277		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DriveLine|DIFF OIL	DriveLine|DIFF OIL	DriveLine|DIFF OIL	PART OF C SERVICE	######## 709277	PreventativeMaintenance	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Elect	ALTINATOR N/S		SMc	######## 709277		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DrCabReg|DMMAGE	range selector not working		SMc	######## 709277		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Steering|WHEEL ALIGN	TRUCK PULLS TO THE LEFT		SMc	######## 709277		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Susp|Torque Rod	LHR torque rod bush's		SMc	######## 709277		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Susp|Torque Rod	LHR torque rod bush's		SMc service completed at 709,277 SMc	######## 709277		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	VehService|CS	VehService|CS C Service	VehService|CS		######## 709277		Service	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workhoo	P/MOVER
1068	Albury - Workshop	DrCabElect|NOT/GAUGE	Volt guage Not working		completed SMc	######## 709277		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DriveLine	Bell cranks and rose joints		SMc	######## 709277		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DrCabElect|NOT/GAUGE	colt meter not working		SMc	######## 709277		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DrCabElect|NOT/GAUGE	esc/check engine lights on		completed SMc	######## 709277		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	VehService|AS	VehService|AS A Service	VehService|AS	Add 1 ltr time	######## 698346		Service	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER
1068	Albury - Workshop	Tyres|TP's-10	Tyres|TP's-10		LOW	######## 690504		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1068	Albury - Workshop	Tyres|TP's1-12	Tyres|TP's1-12		LOW	######## 690504		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	BORDER BANDAG PTY LTD - 4	P/MOVER
1068	Albury - Workshop	VehService|BS	VehService|BS B Service	VehService|BS		######## 690504		Service	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Engine	Rear engine mounts cracked		Monitor	######## 686504		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Brakes|ABS FAULTS	ESC Light Still Comes On		Previously completed	######## 686504		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DrCabElect|ELECT P&W	Truck ESC light coming on and staying on.		Previously completed	######## 686504		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Brakes|ABS	Trailer ABS light on all the time. VehService|AS Svc B 1 Service, Jack up steer axle check bearings and king pins.		Previously completed	######## 686504		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	VehService|BS Svc	Replace cabin filter.	VehService|BS Svc	Ref Shane McCabe turn table	######## 686504	PreventativeMaintenance	Completed	Greenfreight Loanine NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workhoo	P/MOVER
1068	Albury - Workshop	VServeLab	*B SERVICE			######## 686504		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DrCabElect|NOT/GAUGE	ABS light on		Previously completed	######## 686504		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DrCabElect|NOT/GAUGE	alternator reading 12v or less			######## 686504		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DrCabElect|NOT/GAUGE	esc light on		Previously completed	######## 686504		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DrCabElect|NOT/GAUGE	abs trailer fault on dash unsure what trailer		Previously completed	######## 686504		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DrCabElect|NOT/GAUGE	failed light		Previously completed	######## 686504		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DrCabElect|NOT/GAUGE	ESC,After treat, check engine light comes on.			######## 686504		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	DrCabElect|NOT/GAUGE	engine light on Engine|ALT		Previously completed	######## 686504		Fault	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
1068	Albury - Workshop	Engine|ALT	NEW ALT HAS BEEN FITTED !!WDI		ALTERNATOR L/N: LGDA PAD MT PULLEY ALTERNATOR	######## 733033		Repair	Completed	Greenfreight Logging NSW	KWAYSLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - 4	P/MOVER
1068

| | | |

			Engine tune missed during C service ENGINE TUNE CUSTOMER REPORTS RATTLE PRESENT IN RH SIDE OF ENGINE * Test operations * Unable to fault rattle * Found slight top end rattle * Investigate history & found no history of engine tune * Report findings to Greenfreight who confirmed possible cause * Removed & check air intake for restrictions * Check radiator for oil indicating compression or oil leaks * Removed rocker cover to access internal components * Check top end components * Adjust valve clearance to specification * Set all parameters to specification * Install rocker cover & components complete * Check & adjust all belts * Pressure test CAC * Test, confirm & quality check engine operation																
1068	Albury - Workshop	Engine|ENG TUNE	* All okay. fault no longer present			######## 530419	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX PACCAR PARTS FLEET SERVICES - 6	P/MOVER				
			Brakes|BOOSTER AIR LEAK WHILST CARRYING OUT SERVICE, FOUND DRIVERS SIDE STEER BRAKE BOOSTER LINE LEAKING Disconnected & removed line * Found damaged section * Repaired as required * Refit line & secured in position * Aligned, adjusted & tensioned all components																
1068	Albury - Workshop	Brakes|BOOSTER	* Test operations - All ok. fault no longer present			######## 530419	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX PACCAR PARTS FLEET SERVICES - 6	P/MOVER				
			Driveline|DIFF DIFF WHILST CARRYING OUT SERVICE, FOUND FRONT DIFF INPUT TO HAVE MOVEMENT $300.00 * Unbolted & removed driveshaft * Removed retaining nut & removed yoke * Found seal to be leaking * Removed seal & adjusted preload to specifications Cleaned down all sealing surfaces * Installed replacement seal * Refit yoke with replacement retaining nut & tensioned to specifications * Refit driveshaft																
1068	Albury - Workshop	Driveline|DIFF REPAIN	* Aligned, adjusted & tensioned all components to specifications * Test operations - All ok. fault no longer screen			######## 530419	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX PACCAR PARTS FLEET SERVICES - 6	P/MOVER				
			VetService|All. Svc 8 1 Service, PO:#T085237 Jack up steer axle check bearings and king pins.															
1068	Albury - Workshop	VehService|All. Svc	Replace cabin filter.	VehService|All. Svc		######## 527463	PreventativeMaintenance	Completed	Greenfreight Loading NSW	KWIKSLOG	Albury	ATK	XW73GX PACCAR PARTS FLEET SERVICES - 6	P/MOVER				
1068	Albury - Workshop	VSerLab	SERVICE+B1			######## 527663	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX PACCAR PARTS FLEET SERVICES - 6	P/MOVER				
1068	Albury - Workshop	Elect|HOUSEKEEP	Not turning off		Completed by Blair Boswell	######## 517076	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Elect|ELECT P&W	DIAGNOSED AND REPLACED FAILED TURBO TIMER.			######## 517076	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Albury Workshop	P/MOVER				
1068	Albury - Workshop	VehService|CS	VehService|CS	VehService|CS		######## 526032	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	VehService|AS	VehService|AS	VehService|AS	506373km	######## 515819	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Engine|FAULT CODE	Aftertreat light on		Inspected. No active fault at time or stored flash codes	######## 509219	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	VehService|AS	VehService|AS A Service	VehService|AS		######## 505530	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	CTI|CTI Drive	CTI LOOSING AIR		1	######## 504335	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Albury Workshop	P/MOVER				
1068	Albury - Workshop	DrCabElect|INST/GAUGE	VOLT METRE NOT WORKING			######## 504335	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Albury Workshop	P/MOVER				
1068	Albury - Workshop	Susp|SHOCK ABS	UNHOOKED/ HOOKED UP TRAILERS. REPLACED LF SHOCK MOUNT AND RUBBERS. STRAIGHTENED BRACKET.			######## 490781	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Albury Workshop	P/MOVER				
1068	Albury - Workshop	VehService|AS	VehService|AS A Service	VehService|AS		######## 491120	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Susp|SHOCK ABS	Front drive shocks loose and rubber cracked			######## 491120	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Tyres|TPI+8	Tyres|TPI+8			######## 487517	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX BEAUREPAIRES - 4	P/MOVER				
1068	Albury - Workshop	Tyres|TPI+10	Tyres|TPI+10			######## 487517	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX BEAUREPAIRES - 4	P/MOVER				
1068	Albury - Workshop	Brakes|ARK RELINE	RELINE REAR DRIVERS.			######## 486063	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	DrCabElect|SCALES	CHANNEL 3 SCALES NOT WORKING. VehService|All. Svc 8 1 Service, Jack up steer axle check bearings and king pins.		REPAIRED SCALES LOOM IN T479.	######## 486063	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	VehService|All. Svc	Replace cabin filter.	VehService|All. Svc		######## 486063	PreventativeMaintenance	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonas Workshop	P/MOVER				
1068	Albury - Workshop	Chassis|SCALES	scales channel 3 not working		REPAIRED SCALES LOOM IN T479.	######## 486063	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonas Workshop	P/MOVER				
1068	Albury - Workshop	Insp|ANN INSP	Insp|ANN INSP	Insp|ANN INSP	fd 86362.	######## 486063	PreventativeMaintenance	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Tyres|TPI+6	Tyres|TPI+6			######## 484946	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX BEAUREPAIRES - 4	P/MOVER				
1068	Albury - Workshop	Tyres|TPI+4	Tyres|TPI+4			######## 484946	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX BEAUREPAIRES - 4	P/MOVER				
1068	Albury - Workshop	Tyres|Punct	CTI NOT WORKING AS SHOULD (SLOW LEAK IN ONE OF THE DRIVE TYRES)		Reseated during service	######## 485043	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	VSerLab	Service B1		Reseated air fitting on LHR drive during service	######## 486063	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	CTI|CTI Drive	CTI not holding pressure			######## 486063	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Body|MUDGUARDS	RH front guard			######## 479382	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	VehService|AS	VehService|AS A Service	VehService|AS	479618kms	######## 479618	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Albury Workshop	P/MOVER				
1068	Albury - Workshop	Driveline|CLUTCH	Adjust clutch brake		REPLACED ROSE JOINTS. ADJUSTED CLUTCH.	######## 479618	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Albury Workshop	P/MOVER				
1068	Albury - Workshop	Steering|WHEEL BRGS	FRONT LEFT STEER HAD PLAY WHEN DOING WHEEL NUTS UP.		INSPECTED STEERING COMPONENTS. DIAGNOSED MOVEMENT AND REPLACED RH TIE-ROD END.	######## 472384	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Albury Workshop	P/MOVER				
1068	Albury - Workshop	VehService|BS	VehService|All & Service	VehService|BS		######## 464206	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Tyres|TPI+2	Tyres|TPI+2			######## 466059	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX BEAUREPAIRES - 4	P/MOVER				
1068	Albury - Workshop	VehService|AS	VehService|AS A Service TCTC PO #T081641	VehService|AS	REPLACED BELTS. ADDED 4L ENGINE OIL.	######## 461297	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX PACCAR PARTS FLEET SERVICES - 6	P/MOVER				
1068	Albury - Workshop	Driveline|CLUTCH	no clutch (brake down start of running creek)		travelled to brake found free travel arm adjuster missing replaced and adjusted clutch tested all good													
1068	Albury - Workshop	Workshop|MOVE ASSET	PICKED UP TRUCK. VehService|AS A Service		KLM at time of reseir 461424 K.RYAN 1/2 HOUR LABOUR.	######## 462424 ######## 461081	Fault Repair	Completed Completed	Greenfreight Logging NSW Greenfreight Logging NSW	KWIKSLOG KWIKSLOG	Albury Albury	ATK ATK	XW73GX Albury Workshop XW73GX Albury Workshop	P/MOVER P/MOVER				
1068	Albury - Workshop	VehService|AS	TEST DIFF DIFFICULTY	VehService|AS	CHECKED DIFF OIL TOOK FOR TEST DRIVE. FRONT DIFF MAKING NOISE. TCTC TO REPAIR/ REPLACE.	######## 462591	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX PACCAR PARTS FLEET SERVICES - 6	P/MOVER				
1068	Albury - Workshop	Driveline|OIL LEAK	DIFF LEAKING OIL		K BRAKE SERVICE ADVISE	######## 462979	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Albury Workshop	P/MOVER				
1068	Albury - Workshop	CTI|CTI Drive	C.T.I. SLOW TO PUMP UP.		Replaced pressure reduction valve. Valve was completely blocked. Unplugged air hose to CTI system and had no air supply with tank full of air	######## 460016	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Workshop|MOVE ASSET	MOVED TO TYRE BAY FOR STEER REPLACEMENT. UNLOADED TRAILERS.			######## 457367	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Albury Workshop	P/MOVER				
1068	Albury - Workshop	Tyres|RUN OUT	Tyres|RUN OUT FITTING 4			######## 459677	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX BEAUREPAIRES - 4	P/MOVER				
1068	Albury - Workshop	Chassis|AIR LEAK	REPAIRED AIR LEAK.			######## 454121	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Albury Workshop	P/MOVER				
1068	Albury - Workshop	Driveline|CTI Drive	CTI slow to pump tyres VehService|All. Svc 8 1 Service, Jack up steer axle check bearings and king pins.		REPLACED CTI PRESSURE PROTECTION VALVE TO 85 PSI.	######## 451670	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	VehService|All. Svc	Replace cabin filter.	VehService|All. Svc		######## 451670	PreventativeMaintenance	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonas Workshop	P/MOVER				
1068	Albury - Workshop	Chassis|AIR TANKS	REPLACE DRAIN COCK FITTED TEMPORARILY IN AIR TANK WITH PRESSURE RELIEF VALVE.			######## 451670	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	VehService|BS	VehService|All & Service	VehService|BS		######## 451670	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Driveline|CTI Drive	LH CTI leaking		previously completed	######## 451670	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	VSerLab	SERVICE			######## 446226	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	CTI|CTI Drive	REPAIRED CTI HOSE/ ROTOR DAMAGE.		REPLACED LH CTI ROTORS AND TAP BLOCK. STRAIGHTENED CENTRE OUTRIGGER. REPLACED CTI HOSES TO ROTORS.	######## 443773	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Chassis|AIR TANKS	AIR FITTING BROKEN ON AIR TANK. VehService|All & Service		TRAVELLED TO AND FROM PINE ROAD, CHILTERN. REPLACED BROKEN PRESSURE RELIEF VALVE WITH DRAIN COCK TO STOP LEAK TEMPORARILY.	######## 462997	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	VehService|AS	created PO T0925560 not aiven to customer	VehService|AS		######## 441419	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX PACCAR PARTS FLEET SERVICES - 6	P/MOVER				
1068	Albury - Workshop	Driveline|OIL LEAK	Driveline|OIL LEAK THROUGH SHAFT SEAL VehService|AS A Service			######## 441419	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX PACCAR PARTS FLEET SERVICES - 6	P/MOVER				
1068	Albury - Workshop	VehService|AS	PO created TCTC #T0926319 not aiven to customer	VehService|AS		######## 437527	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX PACCAR PARTS FLEET SERVICES	P/MOVER				
1068	Wodonga - Workshop	CTI|CTI Drive	CTI,slow to pump up tyres.			######## 437565	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	CTI|CTI Drive	C.T.I. SLOW TO PUMP UP TYRES.		TESTED. DIAGNOSED AND REPLACED FAULTY PROTECTION VALVE. * Ballast axles * Removed wheel end equipment * Removed drum & hub assemblies - found drums also worn * Removed brake shoes * Cleaned down all components * Installed replacement brake shoes & hardware as required * Greased bearings & refit hub assemblies * Installed replacement drums * Refit wheel end equipment * Aligned, adjusted & tensioned all components	######## 427565	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Brakes|ARK RELINE	Brake Reline On Both Drive Axles. (TCTC P/O: T0925551)		* Test operations - All ok. no further faults	######## 436273	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	Brakes|BRAKE ADJ	will Not hold on hill's with block button in when loading. VehService|AS A Service		Adjusted brakes and checked where it was visible for glazed drums couldnt see enough to determine that driver to monitor the situation	######## 431146	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	VehService|AS	VehService|AS	VehService|AS		######## 431640	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonas Workshop	P/MOVER				
1068	Albury - Workshop	Engine|LEECT P&W	Check Engine light coming on randomly.		Connected Computer to truck checked faults, found no active faults, there were inactive faults for alternator check charge rate, tested alternator all good, sent truck to work and asked driver to monitor.	######## 431315	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Body|MUDGUARDS	REPLACED BROKEN GUARD BRACKET.			######## 431315	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Hydraulics|LOOSE/UNABLE	Need's Hydraulic Oil			######## 427644	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Body|MOUNTS	Tighten deck plate over Ad-Blu Tank.			######## 427643	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes|BRAKE ADJ	Check drive brakes, not holding on hill's the way they should.			######## 427643	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Body|MOUNTS	Tighten chassis deck plate.			######## 427643	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Chassis|BULLBAR	FIT COMPLIENCE PLATE TO BULLBAR.			######## 427642	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	VehService|All. Svc	VehService|All. Svc	VehService|All. Svc		######## 427642	PreventativeMaintenance	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonas Workshop	P/MOVER				
1068	Wodonga - Workshop	Driveline|OIL LEAK	R/H/S FRONT DRIVE AXLE GASKET STILL LEAKING.		Drained oil removed cap and replaced gasket	######## 427642	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes|BRAKE ADJ	Won't hold on hill's with Black button IN.			######## 427642	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	VehService|AS	VehService|AS	VehService|AS	421647ks	######## 421629	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Driveline|OIL LEAK	Tighten Axle front L/H/S Drive Leaking.			######## 420277	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	CTI|CTI Drive	CTI Slow To Pump Tyres Up			######## 420277	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Brakes|BRAKE ADJ	Drive Brakes Need Adjusting			######## 420277	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Tyres|TPI+2	Tyres|TPI+2			######## 417560	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX BEAUREPAIRES - 4	P/MOVER				
1068	Wodonga - Workshop	Elect|WORK LIGHT	Rear Work light Occasionally coming on with brake lights.		Duplicate job	######## 416368	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Elect|CONSUMABLE	Occasionally Tripping Circuit Breaker In Reverse.		Duplicatejob	######## 416268	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	DrCabElect|ELECT P&W	Trips Curcuit Braker in Reverse		Duplicate job	######## 416268	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Air Con|AIR CON	A/C condenser starting to block up (Reduced air flow)		Duplicate job	######## 416268	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	DrCabRep|ST Wheel	Leather on steering wheel worn through.		New steering wheel has been fitted Previously completed	######## 416368	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Engine|ADBLUE	After treat light on		After treatment fahl did not come on	######## 416268	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonas Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes|BRAKE ADJ	check adjustment / wear drive brakes		All brakes have been adjusted Previously completed	######## 416268	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Air Con|AIR CON	Check A/C Drain Leaking On Floor		Ran aircon and checked for leaks none found has good pressure and cold air. Aircon is working prooerly	######## 416268	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Elect|ELECT P&W	Reverse Lights Occasionally Tripping Circuit Breaker		Duplicate job	######## 416268	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	DrCabElect|ELECT P&W	Work Light come on with left indicator.		Checked worklight with hazards on and left indicator at no time did the worklight come on nor did any other light.	######## 416268	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Chassis|BULLBAR	FRUP LD Plate Missing From Bull Bar		Plate has been ordered from Mr bull bar 29 1 25 I'll be installed when it arrives	######## 397189	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Elect|ELECT P&W	FRONT SENSOR UNDER BULLBAR DAMAGE. REQUIRES NEW MOUNT.		The mount bracket has been damaged due to the bullbar locating bolt constantly bouncing up and down on top of the bracket	######## 416268	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Steering|WHEEL HUB	Left front drive needs new backing plate.		A new steering wheel has been fitted Attempted to trip Circuit breaker by putting truck in reverse multiple times it did not work This RMK was put in place 2 to 3 months ago	######## 416268	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Elect|ELECT P&W	Occasionally trips circuit breaker in reverse (Truck ball race)		Previously complete	######## 416268	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	VehService|AS	VehService|AS	VehService|AS		######## 415596	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Engine|EXHAUST	Exhaust Flex Leaking (Parts Supplied By TCTC P/O: T087053			######## 411481	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Wodonga - Workshop	DrCabElect|INST/GAUGE	Volt gauge stopped working.		Dropped bull-bar through over bonnet, started engine, checked alternator out-put, alternator out-put was 14.6 volts, found blown fuse for volt esuere. reolaced fuse. checked volt esuere was workine. all aood. pulled bonnet back over. lifted bull-bar back up. sent truck back to work.	######## 411772	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonas Workshop	P/MOVER				
1068	Wodonga - Workshop	VehService|BS	VehService|BS	VehService|BS		######## 408872	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	VehService|BS	B Service			######## 408872	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	DrCabElect|INST/GAUGE	Engine Temp Gauge Not Working		New gauge driver to monitor	######## 408872	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Susp|AIR LEAK	loassing Air.		Repaired airline	######## 408872	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Driveline|OIL LEAK	Oil Leaking From Input Shaft On Front Diff		Minimal weep check next service	######## 408872	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Elect|ELECT P&W	Temp Gauge Not Working.		Temp sensor replaced by TCTC	######## 404043	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	Elect|ELECT P&W	Temp Gauge Not Working.		temp sensor replaced by TCTC	######## 404043	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	VehService|AS	VehService|AS	VehService|AS	Completed by TCTC	######## 404076	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	DrCabElect|INST/GAUGE	Engine temp gauge not working again		Temp sensor replaced by TCTC	######## 404043	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	Elect|ELECT P&W	Temp Gauge Not Working.		temp sensor replaced by TCTC	######## 404043	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	VehService|AS	Service A		Completed by TCTC	######## 404043	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	VehService|AS	A Service. (TCTC P/O: T090875)	VehService|AS	Hinge mount on bullbar snapped off at weld	######## 404063	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	Tyres|TPI+10	Tyres|TPI+10			######## 398458	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX BEAUREPAIRES - 4	P/MOVER				
1068	Albury - Workshop	Tyres|TPI+8	Tyres|TPI+8			######## 398458	Repair	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX BEAUREPAIRES - 4	P/MOVER				
1068	Myrtleford - Workshop	CTI|CTI Drive	CTI not building up air (leaks or no air fault on display)		Carried out service on CTI unit breathers blocked and return filter from tyres / readjusted regulator for CTI.unit of truck air tank witch then got the unit working again tested unable to fault (KLM at time of repair 396704)	######## 396704	Fault	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Myrtleford Workshop	P/MOVER				
1068	Wodonga - Workshop	VehService|AS	VehService|AS	VehService|AS		######## 394883	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	VehService|BS	VehService|BS	VehService|BS		######## 394664	Service	Completed	Greenfreight Logging NSW	KWIKSLOG	Albury	ATK	XW73GX Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	VehService|AS	VehService|AS	VehService|AS		######## 386264	Service	Completed	Greenfreight

				Reverse light tripping circuit breaker -trailers7 (brake light on same circuit)		Travel to Greenfreight. Remove resettable fuse with standard fuse. Inspect reverse system. Ok.														
1068	Albury - Workshop	Elect\BRK LIGHT		ihrkon Auto Electrical P/O: TOB91161		Inspect wiring on both trailers and prime mover. Ok														
1068	Albury - Workshop	Elect\DRV LIGHT		still tripping circuit breaker with reverse light		Could not fault at time of diamosis.	######## 355884	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	ARKON AUTO ELECTRICAL - 4	P/MOVER				
1068	Albury - Workshop	Elect\ELECT P&W		TWO TERMINALS, BOTH ARE TOO LONG- CLOSE TO SHORTING OUT ON COVER.			######## 355884	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	ARKON AUTO ELECTRICAL - 4	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\B5		VehService\B5	VehService\B5	344311 ks	######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Engine\B5LTS/TDNS		EXCESSIVE BELT NOISE FRONT OF ENGINE.			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\AS		VehService\AS	VehService\AS	344311ks	######## 343976	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Driv\Unit\DRV LN S/R		Clunking in drivetrine with past divider engaged			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Drl\Cabin\ELECT P&W		T/C & ec light on all the time			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Chassis\Wnl\L HUB		Tighten CDn R-rear drive check hub bolts			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Tyres\STEER TYRE		Check hubs left and right on steers			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Drl\Cabin\TjNST/GAUGE		check temp gauge - reading erratic or not at all			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Body\WIPERS		Replace L/H/S upper blades			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Body\HOUSEKEEP		R/H/S toolbox cover/step needs to be replaced			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Engine\ELECT P&W		Engine Temp Guage NOT Working.			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Drl\Cabin\TjNST/GAUGE		Engine temp not working			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Drl\Cabin\TjNST/GAUGE		Engine Temp Gauge Not working (Replace)			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Elect\BRK LIGHT			Occasionally Tripping Brake Light Circuit Breaker			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Susp\SHOCK ABS		Shock bushes on rear diffs worn need replacing			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Drl\Cabin\TjNST/GAUGE		ENGINE TEMP GAUGE N/W CORRECTLY. (OFF & ON)			######## 343976	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Tyres\TP+8		Tyres(TP7+8+8+10			######## 169527	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	BEAUGRAINES - 4	P/MOVER				
1068	Myrtleford - Workshop	Steering\PWR STEER		power steering hose leaking		KLM at time of repair 336898	######## 327643	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Myrtleford Workshop	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\AS		VehService\AS	VehService\AS		######## 314473	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
						- -														
				VehService\B1 Svc		- -														
1068	Wodonga - Workshop	Veh\Service\B1 Svc		Serviced @ 327,522 Kms	VehService\B1 Svc	I	######## 327193	PreventativeMaintenance	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
				VehService\AS																
1068	Wodonga - Workshop	Veh\Service\AS		Serviced @ 327,522 Kms	VehService\AS		######## 327193	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\AS		VehService\AS	VehService\AS		######## 318522	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\AS		VehService\AS	VehService\AS		######## 316701	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\AS		A-B service			######## 316701	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Steering\DN LEAK		Check Hubs Left & Right On Steers			######## 310254	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Driv\Unit\LT/Drive		Tighten CDi Spindle R/H Front Drive Check Axle Bolts			######## 310254	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Veh\Service\C5		C Service			######## 370667	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	Drl\Cabin\THROTTLE		OCCASIONAL DEAD SPOT/ HESITATION IN ACC PEDAL.			######## 370667	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	Veh\Service\AS		A SERVICE.			######## 370667	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	Veh\Service\C5		C Service (TCTC P/O: TOB80381)	VehService\C5		######## 370667	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	Brakes\ABS FAULTS		TRACTION CONTROL/ ESC LIGHTS ON ALL THE TIME.			######## 370667	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	Elect\WORK LIGHT		WORK LIGHT ON THIS LIGHT BAR LOOSE.			######## 370667	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	Driv\Unit\DRIVES		Power Divider Clunking			######## 370667	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	TWIN CITY TRUCK CENTRE - OLD	P/MOVER				
1068	Albury - Workshop	Tyres\TP+6		Tyres(TP5+6			######## 294610	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	BEAUGRAINES - 4	P/MOVER				
1068	Albury - Workshop	Tyres\TP3+4		Tyres(TP3+4			######## 294610	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	BEAUGRAINES - 4	P/MOVER				
				AFTER TREAT ISSUES:																
1068	Wodonga - Workshop	Engine\ADBLUE		CHECKED CODES. FLUSHED SYSTEM. UNBLOCKED FITTING. REASSEMBLED. CLEARED CODES.			######## 276458	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Engine\ADBLUE		*AFTER TREAT			######## 276458	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Susp\CONSUMABLE		Tr/ESC Lights Constantly On			######## 275704	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Drl\Cabin\ELECT P&W		Speedo Reading Not Working			######## 275704	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
						273601ks														
1068	Wodonga - Workshop	Veh\Service\B5		VehService\B5	VehService\B5		######## 273261	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Tyres\TP3+2		Tyres(TP5+2			######## 269847	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	BEAUGRAINES - 4	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\AS		VehService\AS	VehService\AS	RUBY H ½ HOUR LABOUR.	######## 262611	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Elect\BRK LIGHT			Traction control light on occasionally			######## 327548	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS		TRACTION CONTROL/ ESC LIGHT COMING ON & STAYING ON.			######## 327548	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\B1 Svc		B 1 Service	VehService\B1 Svc	Rt: 256686	######## 327548	PreventativeMaintenance	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\AS		SERVICE.			######## 327548	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
						244545 km														
						Service done with Cody and Shane McCabe														
						Front diff leak at														
1068	Wodonga - Workshop	Veh\Service\AS		A Service	VehService\AS		######## 244101	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Air Con\AIR CON		Air Con\AIR CON			######## 213233	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	HAGANS AUTO ELECTRICAL SERVICE	P/MOVER				
1068	Albury - Workshop	Tyres\FAILURE		Breakdown			######## 224497	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	BEAUGRAINES - 4	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\AS		A SERVICE			######## 210663	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Body\FUEL TANK		TIGHTEN ADBLUE COVER.			######## 210663	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	CTL\TJ Elect		NO C.T.I. - "VALVE COMMS LOST" IN SCREEN. NO PRESSURES REGISTERING.			######## 210663	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\B5		B Service	VehService\B5		######## 210663	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Insp\ANN INSP		Annual inspection	Insp\ANN INSP		######## 210663	PreventativeMaintenance	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS		TRACTION CONTROL/ ESC LIGHTS OCCASIONALLY COMING ON & STAYING ON.			######## 210663	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Driv\Unit\DN LEAK		front diff banjo leakin			######## 269678	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Comp\Truck Safe		FIT TRUCKSAFE STICKER.			######## 269678	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes		Record Check Results As Attached To This Job			######## 269678	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Tyres		VIBRATION IN TRUCK.			######## 269678	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes		TRUCK BRAKE VERY SQUEAKEY.			######## 269678	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Susp\SUSPENSION		Knock From Front Of Truck In Bush			######## 269678	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS		TRACTION CONTROL/ ESC LIGHT ON ALL THE TIME.			######## 269678	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Unknown		B SERVICE.			######## 269678	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS		TRACTION CONTROL/ ESC LIGHTS COMING ON & STAYING ON.			######## 269678	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS FAULTS		TRAILER ABS LIGHT ON ALL THE TIME.			######## 269678	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS		TC/ESC LIGHTS STILL COMING ON & STAYING ON AT RANDOM TIMES.			######## 269678	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Drl\Cabin\HOUSEKEEP		NEED NEW R&R BOOK.			######## 269678	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\AS		Carry out A Service as per job card for T909 315	VehService\AS		######## 269678	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Hydraulics\OIL/FILTER		HOOKED UP- CHECKED AND TOPPED UP HYDRAULIC OIL.			######## 221700	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Susp\SUSPENSION		Knock From Front Of Truck In Bush			######## 213233	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS		TRACTION CONTROL/ ESC LIGHT ON ALL THE TIME.			######## 213233	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes		Record Check Results As Attached To This Job			######## 213233	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Driv\Unit\DN LEAK		front diff banjo leakin			######## 213233	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Body\TOOLBOX		Cant open either dog boxes			######## 213233	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Driv\Unit\DN LEAK		front diff banjo leaking			######## 213233	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\BRK RELINE		RELINE DRIVES.			######## 213233	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Tyres		VIBRATION IN TRUCK.			######## 213233	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes		TRUCK BRAKE VERY SQUEAKEY.			######## 213233	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\AS		Carry out A Service as per job card for T909 315	VehService\AS		######## 213233	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
				B 1 Service,																
				jack up steer axle check bearings and king pins.																
1068	Wodonga - Workshop	Veh\Service\B1 Svc		Replace cabin filter.	VehService\B1 Svc		######## 213233	PreventativeMaintenance	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Tyres\TP+2		Tyre Position 1 + 2			######## 220700	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER				
1068	Albury - Workshop	Tyres\Re-Tor		3-10			######## 220647	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes		Record Check Results As Attached To This Job			######## 200613	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Comp\Truck Safe		FIT TRUCKSAFE STICKER.			######## 200613	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Driv\Unit\DN LEAK		front diff banjo leakin			######## 200613	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Body\TOOLBOX		Cant open either dog boxes			######## 200613	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Body\HOSES		Air leak somewhere under truck			######## 200613	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Driv\Unit\DN LEAK		front diff banjo leaking			######## 200613	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Elect\WORK LIGHT			REAR WORK LIGHT NOT WORKING.			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS FAULTS		TRAILER ABS LIGHT ON ALL THE TIME.			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS FAULTS		Truck ABS To Switch			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS		Trailer ABS Light Came On About 3/4 Through The Day & Started Dragging Brakes Empty - Got Worse Onm Way Home Loaded			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS FAULTS		TRAILER ABS LIGHT COMING ON.			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS FAULTS		TRAILER ABS LIGHT ON.			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS FAULTS		TRAILER ABS LIGHT ON ALL THE TIME.			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Tyres		VIBRATION IN TRUCK.			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS FAULTS		TRAILER ABS LIGHT ON ALL THE TIME.			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS		ABS LIGHT ON.			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes		TRUCK BRAKE VERY SQUEAKEY.			######## 200613	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS FAULTS		TRAILER ABS LIGHT ON ALL THE TIME.			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\ABS FAULTS		*TRAILER ABS LIGHT ON ALL THE TIME			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Body\AIR LEAK		loossing air at idle			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	CTL\TJ Elect		C?r not working alarm is constantly going off.			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Engine\COMPRESSOR		Check air compessor operating, struggles to build air pressure from 600 PKA at fast idle			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	CTL\TJ Elect		C?r getting stuck on low air warning (see above)			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Drl\Cabin\TjNST/GAUGE		Trailer ABS light on all the time			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Elect\ELECT P&W		LANE SENSOR FELL OFF WINDSCREEN.		STUCK BACK ON WINDSCREEN.	######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Unknown		B service			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Hydraulics\HOSES		BLOWN HYDRAULIC HOSE.			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Susp\SUSPENSION		Knock From Front Of Truck In Bush			######## 200613	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Drl\Cabin\ELECT P&W		Lane Dectection Camera Fallen Off Windscreen			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes\BRK RELINE		RELINE DRIVES.			######## 200613	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Veh\Service\AS		Carry out A Service as per job card for T909 315	VehService\AS		######## 200613	Service	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Unknown		A Service			######## 200613	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	CTL\TJ Elect		C?I NOT WORKING. ALARM CONTANTLY GOING.		REPLACED PRESSURE PROTECTION VALVE AND AIR LINE.	######## 189228	Fault	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Albury - Workshop	Tyres\TP03		Tyre Position 1			########	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER				
1068	Albury - Workshop	Tyres\TP5+6		Tyre Position 5 + 6			########	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER				
1068	Wodonga - Workshop	Brakes		Record Check Results As Attached To This Job			######## 189174	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
				inspect green residue on passenger floor																
1068	Wodonga - Workshop	Drl\Cabin\HOUSEKEEP		*HAGANS TO REPAIR*		Ran truck with ac on for 1½ an hour found no evidence of a coolant leak on passenger floor	######## 189174	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Elect\WORK LIGHT		cab work lights N/W			######## 189174	Repair	Completed	Greenfreight Logging NSW	KWI\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER				
1068	Wodonga - Workshop	Driv\Unit

1068	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON ALL THE TIME.			########	Repair	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Tyres	VIBRATION IN TRUCK.			########	Repair	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Hydraulics\PUMP	trailers very slow to unfold		REPLACED HYDRAULIC FILTER. ADDED 15L HYDRAULIC OIL. OK.	########	Fault	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Unknown	SERVICE.			########	Fault	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 144858	Repair	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Brakes\EBS FAULTS	Truck EBS To Swotive			######## 144858	Repair	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Brakes\ABS	Trailer ABS Light Came On About 3/4 Through The Day & Started Dragging Brakes Empty - Got Worse Onm Way Home Loaded			######## 144858	Repair	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Air Con\AIR CON	A/C STILL NOT WORKING PROPERLY- POOR AIRFLOW- NOT COLD ENOUGH.			######## 144858	Fault	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Air Con\AIR CON	A/C STILL FREEZING UP REDUCING COOLING EFFECT & RESTRICTING AIR FLOW.			######## 144858	Fault	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT COMING ON.			######## 144858	Repair	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Engine	OCCASSIONAL RATTLE FROM FRONT OF ENGINE.			######## 144858	Repair	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Brakes\EBS FAULTS	TRAILER ABS LIGHT ON.			######## 144858	Repair	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Elect\ELECT F&W	RACK LIGHT NOT WORKING.			######## 144858	Repair	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Elect\ALT2 DR	RATTLE R/H/S FRONT OF ENGINE- CHECK ALTERNATOR.			######## 144858	Repair	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Unknown	SERVICE A			######## 144858	Fault	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	VehService\BS	Service As Per Attached Checklist	VehService\BS		######## 144858	Service	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 135804	Repair	Completed	Greenfreight Logging NSW	KWK91GLOG	Albury	ATK	KW73GA	Wodonga Workshop	P/MOVER
1068	Wodonga - Workshop	Comp\Truck Safe	FIT TRUCKSAFE STICKER.

1068	Albury - Workshop	Tyres\TP3+4	Tyre Position 3 + 4
1068	Albury - Workshop	Tyres\TP5+6	Tyre Position 5 + 6
1068	Albury - Workshop	Tyres\TP7+8	Tyre Position 7 + 8
1068	Albury - Workshop	Tyres\TP9+10	Tyre Position 9 + 10
1068	Wodonga - Workshop	Insp\Truck Pre	Carry Out Pre-Delivery

########		Repair	Completed	Greenfreight Logging NSW	KW19\SLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
########		Repair	Completed	Greenfreight Logging NSW	KW19\SLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
########		Repair	Completed	Greenfreight Logging NSW	KW19\SLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
########		Repair	Completed	Greenfreight Logging NSW	KW19\SLOG	Albury	ATK	XW73GX	Albury Workshop	P/MOVER
########	268150	Repair	Completed	Greenfreight Logging NSW	KW19\SLOG	Albury	ATK	XW73GX	Wodonga Workshop	P/MOVER