| EquipmentName | Workshop | CodeAndSubCode | Description | Schedule | CompletionComments | DateDone | DistanceDone | Worktype | Workstate | EquipmentOwner | MaintenanceGroup | Location | Division | Rego | Supplier | EquipmentType |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T078 | Wodonga - Workshop | Brakes\VALVES | replace service valve | | | 30/07/2026 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS D Service | VehService\DS | Jamie and cheyne on service | 14/07/2026 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | Fabricated rear mudflap mount | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Body\MUDGUARDS | Replace rear axle relocate saddles | | | 05/06/2026 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL WALL | REPAIR/REPLACE HEADBOARD | | | 05/06/2026 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP9+10 | Tyres\TP9+10 (29-30) | | | 03/06/2026 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BORDER BANDAG PTY LTD | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\AXLE REPLC | Remove rear axle, for replacement to be fitted. | | | 23/04/2026 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | | | Onsite call-out fee | | | | | | | | | | | |
| | | | | | Technician labour (0-3 hours) | | | | | | | | | | | |
| | | | | | Travel allowance (0-30 km) | | | | | | | | | | | |
| | | | | | Diagnostic scan if required | | | | | | | | | | | |
| | | | | | Please note: Any additional requirements outside the above—such as additional labour, parts, materials, or further repairs—will be charged separately. | | | | | | | | | | | |
| | | | | | Subtotal | | | | | | | | | | | |
| | | | | | GST | | | | | | | | | | | |
| | | | | | Total | | | | | | | | | | | |
| | | | | | $615.00 | | | | | | | | | | | |
| | | | | | $826.36 | | | | | | | | | | | |
| | | | | | $82.64 | | | | | | | | | | | |
| | | | | | $909.00 | | | | | | | | | | | |
| | | | | | Paid | | | | | | | | | | | |
| | | | | | Balance Due | | | | | | | | | | | |
| | | | | | Travel to Broadford weighbridge | | | | | | | | | | | |
| | | | | | Inspect & remove failed trailer p/s rear wheel & hub assy due to completely failed wheel bearing | | | | | | | | | | | |
| | | | | | Chain axle | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Steering\WHEEL BRGS | Steering\WHEEL BRGS FAILURE - BREAKDOWN CALL OUT | | Advise to send to nearest reoairer ASAP | 10/04/2026 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BOAG'S DIESEL MECHANICS | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | Left Rear Wheel Bearing Failure, Dismantle and Asses Damage before Repair. | | | 25/03/2026 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS D Service | VehService\DS | | 02/03/2026 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Gates to be replaced or repaired. | | | 05/02/2026 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\FAILURE | Replace R/H inner Tyre. | | | 05/02/2026 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\ELECT P&W | 7 Pin Elec plug, to be replaced. | | Pending | 05/02/2026 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS D Service | VehService\DS | | 05/02/2026 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS D Service | VehService\DS | | 14/01/2026 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\RUN OUT | Tyres\RUN OUT TO SPARE | | | 31/12/2025 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BORDER BANDAG PTY LTD | TRAILER |
| T078 | Wodonga - Workshop | Tyres\Punct | Tyres\Punct POS 22 | | | 04/11/2025 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BORDER BANDAG PTY LTD | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS D Service | VehService\DS | | 03/11/2025 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | Reolace Damaaed Trailer Liaht Socket | | | 03/11/2025 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Check & Reoair Gates As Needed | | | 03/11/2025 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | REPAIRED LIGHTS. | | | 06/09/2025 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS D Service | VehService\DS | | 06/09/2025 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Insp\ANN INSP | Annual Inspection | Insp\ANN INSP | Pending | 07/08/2025 | 279821 | PreventativeMaintenance | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS D Service | VehService\DS | | 07/08/2025 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP10 | Tyres\TP10 (30) | | CALL OUT - UNREPAIRABLE | 06/08/2025 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BORDER BANDAG PTY LTD | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | CHECKED WHEEL BEARINGS AND ADJUSTED. | | | 01/05/2025 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS D Service | VehService\DS | | 17/04/2025 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP9+10 | Tyres\TP9+10 | | | 26/03/2025 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BEAUREPAIRES | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP5+6 | Tyres\TP5+6 | | | 26/03/2025 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BEAUREPAIRES | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP3+4 | Tyres\TP3+4 | | | 26/03/2025 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BEAUREPAIRES | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP7+8 | Tyres\TP7+8 | | | 26/03/2025 | 279821 | Reoair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BEAUREPAIRES | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS D Service | VehService\DS | | 22/03/2025 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP9+10 | Tyres\TP9+10 | | | 04/03/2025 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BEAUREPAIRES | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP3+4 | Tyres\TP3+4 | | | 04/03/2025 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BEAUREPAIRES | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS | VehService\DS | | 27/02/2025 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\PRES CHECK | Tyres\PRES CHECK 1-12 | | | 30/01/2025 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BEAUREPAIRES | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | FRONT GATE COULD USE STRAIGHTENING. | | | 15/01/2025 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS | VehService\DS | | 15/01/2025 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\DAMAGE | R/Hand Front Gate POST Cracked & Gates Cracked. | | | 15/01/2025 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | gate post cracked at bottom L/hand side | | Completed by Cheyne O 30/11/2024 work order #192039 | 03/12/2024 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Gate post cracked at bottom L/H side , Rear load rack cracked at bottom | | | 30/11/2024 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Gate post cracked at bottom L/H side , Rear load rack cracked at bottom | | | 30/11/2024 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Fix Front Left Gate Pod | | | 30/11/2024 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes\BRK O/HAUL | Brakes Verv Noisev at low speed. sounds like metal to metal and verv sensitive on pedal and arabs easily. | | | 30/11/2024 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Weld Cracked Rear Head Board Post | | | 30/11/2024 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\STRAPS | Replace Damaged Straps | | | 30/11/2024 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Weld Passenger Side Gates | | | 30/11/2024 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS | VehService\DS | | 09/11/2024 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | R2 GATE MIDDLE TONG SNAPPED OFF. NEEDS NEW ONE WELDED ON. | | | 09/11/2024 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\PRES CHECK | Tyres\PRES CHECK 1-12 | | | 24/10/2024 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BEAUREPAIRES | TRAILER |
| T078 | Wodonga - Workshop | Tyres\RUN OUT | Tyres\RUN OUT 9-10 | | | 24/10/2024 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BEAUREPAIRES | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS | VehService\DS | | 17/10/2024 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS | VehService\DS | | 06/09/2024 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP11+12 | Tyres\TP11+12 | | | 16/08/2024 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BEAUREPAIRES - 3 | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP5+6 | Tyres\TP5+6 | | | 16/08/2024 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | BEAUREPAIRES - 3 | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Check Gates For Cracks | | | 29/07/2024 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\AIR FITTIN | Rear Load Rack Cracked/Rusted Throuah At L/Hand Base | | | 29/07/2024 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | VehService\DS | VehService\DS | | 29/07/2024 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Repair/weld cracks on rear load gate and check/Repair all other broken side gates as per R&Rs | | | 04/07/2024 | 279821 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service | VehService\DS | | 17/06/2024 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHL HUB | REPLACED HUBBO. | | | 25/04/2024 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 05/04/2024 | 289444 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | REPLACE TOOLBOX. | | FABRICATED MOUNTING BRACKETS. | 05/04/2024 | 289444 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | ADJUSTED LF ML LR WHEEL BEARINGS. | 05/04/2024 | 289444 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP9+10 | Tyre Position 9 + 10 | | | 09/03/2024 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Albury Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 09/03/2024 | 284278 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | Any Chance We Can Get A Heavy Plug Attached To This Trailer. Just So We Don't Have To Rely On Adaptors Given That Most Of Them Are | | | 09/03/2024 | 284278 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 09/03/2024 | 284278 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | REPLACE TOOLBOX. | | | 09/03/2024 | 284278 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 02/12/2023 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 02/12/2023 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | Any Chance We Can Get A Heavy Plug Attached To This Trailer. Just So We Don't Have To Rely On Adaptors Given That Most Of Them Are | | | 02/12/2023 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 04/11/2023 | 256601 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 04/11/2023 | 256601 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 23/10/2023 | 279821 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 23/10/2023 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP3+4 | Tyre Position 3 + 4 | | | 11/10/2023 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Albury Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 15/09/2023 | 242613 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 15/09/2023 | 242613 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Insp\ANN INSP | Annual Inspection As Per Checklist | Insp\ANN INSP | | 15/09/2023 | 242613 | PreventativeMaintenance | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 04/08/2023 | 231461 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL ALIGN | Wheel Alianment. | | | 04/08/2023 | 231461 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | L HAND GATE POST SERIOUS CRACK. SECOND FROM FRONT. | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Body\TRL GATES | CHECK GATES FOR CRACKS/ DAMAGE. | | | 04/08/2023 | 231461 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | FRONT GATE- SNAPPED LEFT SIDE OF GATE WELD DUE TO HEAVY BRAKING UNDER LOAD. | | | 04/08/2023 | 231461 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 04/08/2023 | 231461 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 21/06/2023 | 225101 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 21/06/2023 | 225101 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP09 | Tyre Position 9 | | | 21/06/2023 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Albury Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP9+10 | Tyre Position 9 + 10 | | | 24/05/2023 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Albury Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\RETREAD | spare | | | 29/04/2023 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Albury Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 19/04/2023 | 213206 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\STRAPS | REAR RIGHT DOG MAY NEED REPLACING - HANDLE BENT BY FORLIFT. STIL WORKS BUT PLEASE TAKE A LOOK. | | OK. | 19/04/2023 | 213206 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL ALIGN | Wheel Alignment. | | | 19/04/2023 | 213206 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | GATES CRACKING UP. | | | 19/04/2023 | 213206 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body | REPLACE BOARDS. | | | 19/04/2023 | 213206 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | CLEANED UP. | 19/04/2023 | 213206 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Unknown | CHECK SERVICE STATUS. | | | 19/04/2023 | 213206 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Suso\SUSPENSION | REPLACED T/ROD BUSHES WHERE REQUIRED. | | | 19/04/2023 | 213206 | Reoair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP04 | Tyre Position 4 | | | 11/03/2023 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Albury Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | WELD GATES THAT ARE CRACKED. | | | 17/01/2023 | 186238 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 17/01/2023 | 186238 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\WHEEL ALGN | WHEEL ALIGNMENT. | | | 17/01/2023 | 186238 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes\AIR LEAK | AIR LEAK AT BACK AXLE. | | | 17/01/2023 | 186238 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | REPLACED LF LR CLEARANCE LIGHTS. | 17/01/2023 | 186238 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP5+6 | Tyre Position 5 + 6 | | | 23/12/2022 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Albury Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP7+8 | Tyre Position 7 + 8 | | | 23/12/2022 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Albury Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP10 | Tyre Position 10 | | | 23/12/2022 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Albury Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 20/12/2022 | 183605 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Suso\SPRING HANG | Reolace worn out suspension bushes. | | #398991 | 20/12/2022 | 183605 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Suso\SPRING PACK | Reolace worn out leaf sprines. | | | 20/12/2022 | 183605 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Weld cracked gates. | | CLEANED UP. | 20/12/2022 | 183605 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL ALIGN | Wheel Alignment. | | | 20/12/2022 | 183605 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | Check and inspect all wheel bearings replace if needed | | | 20/12/2022 | 183605 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 20/12/2022 | 183605 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\PAINT/REST | PREP AND PAINT REAR BAR. ASSEMBLE. | | | 20/12/2022 | 183605 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | Failed Wheel Bearing AAA Towing Attending | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | Purchase Number: WW075657 | | | 09/12/2022 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |

| | | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | Failed Wheel Bearing | | | | | | | | | | | | | | | |
| | | | Boag's Diesel is doing the repairs | | | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | Purchase Order Number: WW075658 | | | 09/12/2022 | 279821 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 07/10/2022 | 166388 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 07/10/2022 | 166388 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Mvrtleford - Workshop | Elect\ELECT P&W | replaced trailer olues | | | 20/08/2022 | 154431 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Mvrtleford Workshop | TRAILER |
| T078 | Myrtleford - Workshop | Chassis\WHL HUB | adjust front and middle axle wheel bearings | | | 05/08/2022 | 151755 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Myrtleford Workshop | TRAILER |
| T078 | Myrtleford - Workshop | Brakes\BOOSTER | booster replace | | | 30/06/2022 | 136454 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Myrtleford Workshop | TRAILER |
| T078 | Myrtleford - Workshop | Body\AIR LEAK | air couplings | | | 30/06/2022 | 136454 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Myrtleford Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 18/05/2022 | 127152 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 18/05/2022 | 127152 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP09 | Tyre Position 9 | | | 30/04/2022 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Albury Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 24/03/2022 | 116632 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\MUDGUARDS | LM LR OUTRIGGERS LOOSE | | | 24/03/2022 | 116632 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | LAST 2 GATES (BACK) ON PASSENGER SIDE NEED THE CENTRE LOCATING TABS RE-WELDED ALMOST BROKEN OFF. | | | 24/03/2022 | 116632 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\KING PIN | replace king pin | | | 24/03/2022 | 116632 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 24/03/2022 | 116632 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 26/01/2022 | 99767 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | CHECKED AND ADJUSTED ALL WHEEL BEARINGS. | 26/01/2022 | 99767 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP11+12 | supply and fit 2tyres | | | 23/12/2021 | 97067 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 23/12/2021 | 97067 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 23/12/2021 | 97067 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WHL HUB | L.Rear hub cap bolt is snap | | DRILLED AND TAPPED. | 04/12/2021 | 99767 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\MUDGUARDS | LM LR OUTRIGGERS LOOSE | | | 04/12/2021 | 99767 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SWAYBAR | LR SWAY BAR BUSH BOLT RUBBING ON TYRE | | | 04/12/2021 | 99767 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\REFLECTORS | Fit big relectors next service on back. | | | 04/12/2021 | 99767 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 24/11/2021 | 85213 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 24/11/2021 | 85213 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\REFLECTORS | Fit bie relectors next service on back. | | | 24/11/2021 | 85213 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 29/10/2021 | 81910 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 29/10/2021 | 81910 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\MUDGUARDS | LM LR OUTRIGGERS LOOSE | | | 29/10/2021 | 81910 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SWAYBAR | LR SWAY BAR BUSH BOLT RUBBING ON TYRE | | | 29/10/2021 | 81910 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Insp\ANN INSP | Annual Inspection As Per Checklist | Insp\ANN INSP | | 29/10/2021 | 81910 | PreventativeMaintenance | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\MOVE ASSET | PICK UP TRAILER AND TAKE TO SERVICE BAY | | | 29/10/2021 | 87910 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP1+2 | supply and fit 2 tyres | | | 21/10/2021 | 80119 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 17/09/2021 | 75427 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | Adjusted RF & RR Bearings. | | | 17/09/2021 | 75427 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 17/09/2021 | 75427 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\Rims | Albury Truck & Trailer Supply Spacer Rim | | | 04/08/2021 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP3+4 | Supply and fit 2 tyres | | | 04/08/2021 | 71340 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP10 | Supply and fit 1 tyre | | | 04/08/2021 | 71339 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshoo\MOVE ASSET | MOVE FROM YARD TO SERVICE BAY. MOVE BACK TO YARD. | | | 31/07/2021 | 71338 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 02/07/2021 | 71339 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\MOVE ASSET | MOVE FROM TYRE BAY AND PARK INTO THE YARD. | | | 02/07/2021 | 71339 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | | | RHF SPIDER RIM CRACKED. LHR INNER TYRE MISSING RUBBER. REPLACED (BEAUREPAIRS) | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | CHANGE FIVE STRAP | 02/07/2021 | 71339 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshoo | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 11/06/2021 | 64799 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | toolbox lid (cover has some crack) | | | 11/06/2021 | 64799 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL DOORS | door bent need straightening | | | 11/06/2021 | 64799 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WHL HUB | L.Rear hub cap bolt is snap | | | 11/06/2021 | 64799 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL REPS | bent locking gate post's | | | 11/06/2021 | 64799 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | rear bar cracked | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Body\DAMAGE | Left Side inner side need welding. | | | 11/06/2021 | 64799 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | Cracks in Gate pockets | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Body\TRL GATES | Right rear gates has crack, needs welding. | | | 11/06/2021 | 64799 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 11/06/2021 | 64799 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\MOVE ASSET | drop at Heavy Mech | | | 10/06/2021 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\MOVE ASSET | pick up from Heavy mech | | | 10/06/2021 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | | | to be completed at Heavy mechanical | | | | | | | | | | | |
| | | | | | Rear springs L/H | | | | | | | | | | | |
| | | | LHR spring pack cracked | | Jack up trailer. Remove u-bolts, rocker bolt & spring pack. Fit new spring pack & u-bolts & | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | Has now snapped. | | tension. Re-fit rocker bolt. | 10/06/2021 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | LHR needs tightening | | | 10/06/2021 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 04/05/2021 | 58521 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WHL HUB | L.Rear hub cap bolt is snap | | | 04/05/2021 | 58521 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL REPS | bent locking gate post's | | | 04/05/2021 | 58521 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\STRAPS | needs new load binder straps | | | 04/05/2021 | 58521 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL REPS | 2x binder strap needs replacing | | | 04/05/2021 | 58521 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | rear bar cracked | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Body\DAMAGE | Left Side inner side need welding. | | | 04/05/2021 | 58521 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | LHR spring pack cracked | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | Has now snapped. | | | 04/05/2021 | 58521 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | | | Need to replace spring. | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | LHR needs tightening | | Refer Job # 335292 | 04/05/2021 | 58521 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshoo | TRAILER |
| T078 | Wodonga - Workshop | Body\STRAPS | Load Straps need replacing | | | 04/05/2021 | 58521 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | Cracks in Gate pockets | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Body\TRL GATES | Right rear gates has crack. needs welding. | | | 04/05/2021 | 58521 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshoo | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 04/05/2021 | 58521 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\MOVE ASSET | Park trailer up as is now grounded until repairs are done to springs. | | | 04/05/2021 | 58521 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 07/04/2021 | 57805 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 07/04/2021 | 57805 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\STRAPS | Load Straps need replacing | | | 07/04/2021 | 57805 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Cracks in Gate pockets | | | 07/04/2021 | 57805 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\MUDGUARDS | L. middle tyre guard hanger welding is crack | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | toolbox lid (cover has some crack) | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\HOUSEKEEP | crack back at tow bar that normal wear and tear | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WHL HUB | L.Rear hub cap bolt is snap | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL REPS | bent lockine aate post's | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\STRAPS | needs new load binder straps | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 10/03/2021 | 55500 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WHEEL BRGS | bearing adjustments | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | weld toolbox | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\CLEAN | clean up | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\ELECT P&W | electrical repairs | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | clearance light RHS | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL REPS | 2x binder strap needs replacing | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\DAMAGE | rear bar cracked | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL DOORS | door bent need straightening | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | LHR spring pack cracked | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | LHR needs tightening | | | 10/03/2021 | 55500 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP7+8 | replace 2 tyres | | | 13/01/2021 | 51849 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 12/01/2021 | 52931 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 12/01/2021 | 52931 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\MOVE ASSET | pull straps out, put back parts on order and move trailers 78, yard check and move 67, help on 570 | | | 12/01/2021 | 52931 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL REPS | bent locking gate post's | | | 12/01/2021 | 52931 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\STRAPS | needs new load binder straps | | | 12/01/2021 | 52931 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WHEEL BRGS | RHF adjusted. All hubs had gussets replaced as wash out | | | 12/01/2021 | 52931 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WHEEL BRGS | RF repacked | | | 12/01/2021 | 52931 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\CLEAN | clean up for service | | | 12/01/2021 | 52931 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\FITMENT | Job Added From invoice | | | 30/12/2020 | 47506 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\RETREAD | Job Added From invoice | | | 30/12/2020 | 47506 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\Punct | Job Added From invoice | | | 30/12/2020 | 47506 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 27/11/2020 | 47508 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 27/11/2020 | 47508 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\MUDGUARDS | L. middle tyre euard hanaer weldine is crack | | | 27/11/2020 | 47508 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | toolbox lid (cover has some crack) | | | 27/11/2020 | 47508 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\HOUSEKEEP | crack back at tow bar that normal wear and tear | | | 27/11/2020 | 47508 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WHL HUB | L.Rear hub cap bolt is snap | | | 27/11/2020 | 47508 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 07/10/2020 | 36388 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | | 07/10/2020 | 36388 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 05/09/2020 | 32893 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Steering\WHEEL ALGN | Axles out of alignment | | Axles tracking ok | 05/09/2020 | 32893 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | Spring pack, misaligned wearing out | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | Rocker bushes | | Normal wear for leaf spring packs - ok | 05/09/2020 | 32893 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | Damage to rocker boxes | | Normal wear - ok | 05/09/2020 | 32893 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CROSS MBR | Cracks in rear bar & crossmembers | | No cracks significant enough to be a problem | 05/09/2020 | 32893 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | Fatigue cracks Tri area | | As per #304093 | 05/09/2020 | 32893 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | Needs a new toolbox | | Toolbox is ok | 05/09/2020 | 32893 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Veh\Service\DS | D Service As Per Attached Checklist | VehService\DS | Includes replacing chevrons | 05/09/2020 | 32893 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\INDICATORS | right hand indicators not working | | Rewired trailer olue | 11/08/2020 | | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 23/07/2020 | 29009 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Steering\WHEEL ALGN | axles out of alignment | | | 23/07/2020 | 29009 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | spring pack, misaligned wearing out | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | Rocker bushes | | | 23/07/2020 | 29009 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | Damaae to rocker boxes | | | 23/07/2020 | 29009 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CROSS MBR | Cracks in rear bar & crossmembers | | | 23/07/2020 | 29009 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | fatigue cracks Tri area | | | 23/07/2020 | 29009 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |

| | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T078 | Wodonga - Workshop | Body\TRL LEGS | bent supoorts and cracks and bent lee | | ok ooerate correctlv | | 23/07/2020 | 29009 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | Needs a new toolbox | | | | 23/07/2020 | 29009 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | | 23/07/2020 | 29009 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\CLEAN | waiting for driver to collect trailers from shed as he was waiting on trailers | | | | 23/07/2020 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\MOVE ASSET | move trailers | | | | 23/07/2020 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\PRES CHECK | Job Added From Invoice | | | | 03/07/2020 | 21375 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | | 30/06/2020 | 28061 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | fatigue cracks Tri area | | | | 30/06/2020 | 28061 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL LEGS | bent supports and cracks and bent leg | | | | 30/06/2020 | 28061 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CROSS MBR | Cracks in rear bar & crossmembers | | | | 30/06/2020 | 28061 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | | 30/06/2020 | 28061 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | Needs a new toolbox | | | | 30/06/2020 | 28061 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Insp\ANN INSP | Annual Inspection As Per Checklist | Insp\ANN INSP | | | 30/06/2020 | 28061 | PreventativeMaintenance | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | | 30/05/2020 | 29278 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\TRL LEGS | Bit notchy - monitor | | OK | | 30/05/2020 | 29278 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | fatigue cracks Tri area | | | | 30/05/2020 | 29278 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Steering\WHEEL ALIGN | axles out of alignment | | | | 30/05/2020 | 29278 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | spring pack, misaligned wearing out | | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | Rocker bushes | | | | 30/05/2020 | 29278 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL LEGS | bent supports and cracks and bent leg | | | | 30/05/2020 | 29278 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CROSS MBR | Cracks in rear bar & crossmembers | | | | 30/05/2020 | 29278 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP09 | tyre replacement required | | Checked by Chris at beaurepairs - all good | | 30/05/2020 | 29278 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | | 30/05/2020 | 29278 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | Damage to rocker boxes | | | | 30/05/2020 | 29278 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | | 09/05/2020 | 27374 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | | 09/05/2020 | 27374 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | fatigue cracks Tri area-pending | | | | 09/05/2020 | 27374 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\LIGHTS | fit 8mm rod to comon rail to support light wiring | | Don sparks steel to supply rod P/O WW03353S3 | | 16/04/2020 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | | 16/04/2020 | 27373 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Gate latch missing | | Reolaced missing latch & straightened another one | | 16/04/2020 | 27373 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | | 16/04/2020 | 27373 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\TRL LEGS | Bit notchy - monitor | | | | 16/04/2020 | 27373 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\MOVE ASSET | Move trailer | | | | 16/04/2020 | 27373 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\ELECT P&W | Wiring caching & ripping out | | Made up rods to weld in between each crossmember on the RHS of the trailer to secure clearance light & indicator wires to. R | | 16/04/2020 | 27373 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\CLEAN | Cleaned workshop | | | | 16/04/2020 | 27373 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | repair upright gate latch | | | | 15/04/2020 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | keg trailer: gate latch missing | | | | 15/04/2020 | | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | | 17/03/2020 | 26703 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\TRL LEGS | LHS landing leg bracket broken off | | | | 17/03/2020 | 26703 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\DAMAGE | LHR light bar mount is cracked again - has been welded previously | | Previously completed | | 17/03/2020 | 26703 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | | 17/03/2020 | 26703 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\ELECT P&W | Locate & rectify electrical issue | | | | 17/03/2020 | 26703 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\TRL LEGS | REPAIR LANDING LEG. SUPPORT& bracket | | | | 16/03/2020 | 26703 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\ELECT P&W | repair wiring | | | | 16/03/2020 | 26703 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\HOUSEKEEP | anchor wiring | | | | 16/03/2020 | 26703 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\MOVE ASSET | take upto top shed shed for welding | | | | 16/03/2020 | 26703 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | | 13/02/2020 | 19411 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | | 13/02/2020 | 19411 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\TRL LEGS | LHS landing leg bracket broken off its mount | | | | 13/02/2020 | 19411 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\DAMAGE | LHR light bar mount is cracked again - has been welded previously | | | | 13/02/2020 | 19411 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\MOVE ASSET | move trailers & connect disconnect | | | | 13/02/2020 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | side lights turning on and off (bad earth/loose wire) rear lights ok | | | | 04/02/2020 | | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHL HUB | Job Added From Invoice | | | | 29/01/2020 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\CASE STOCK | Job Added From Invoice | | | | 24/01/2020 | 10 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\FITMENT | Job Added From Invoice | | | | 24/01/2020 | 10 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\RETREAD | Job Added From Invoice | | | | 24/01/2020 | 10 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Steering\WHEEL ALIGN | axles out of alignment | | | | 22/01/2020 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | spring pack, misaligned wearing out | | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | Rocker bushes | | | | 22/01/2020 | | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL LEGS | bent supoorts and cracks and bent lee | | | | 22/01/2020 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CROSS MBR | Cracks in rear bar & crossmembers | | | | 22/01/2020 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP09 | tyre replacement required | | | | 22/01/2020 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | | 17/01/2020 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | | 17/01/2020 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP09 | tyre replacement required | | | | 17/01/2020 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WINCH/STRP | Change load straps | | | | 03/01/2020 | 13822 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | | 13/12/2019 | 2058 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | Replaced RHS clearance & indicators | | | | 13/12/2019 | 2058 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | | 13/12/2019 | 2058 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CROSS MBR | Cracks in rear bar & crossmembers | | | | 13/12/2019 | 2058 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHL HUB | Job Added From Invoice | | | | 01/11/2019 | 0 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WHL HUB | Reolaced hubbo & clear lens | | | | 31/10/2019 | 0 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | repairs to load gates and straps | | | | 12/10/2019 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\MOVE ASSET | yard check | | | | 12/10/2019 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\INDICATORS | repairs to RH blinker | | | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | clearance light wiring | | | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\ELECT P&W | replace base plug and repairs to lights and wiring | | Trailer requires full rewire | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\ELECT P&W | replace base plug and fix wiring | | | | 12/10/2019 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | spring pack, misaligned wearing out | | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | Rocker bushes | | | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | rope rails need attention - rear bar cracked leg support's cracked - toolbox w/ cracked | | Previously completed | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | | | No cracks found | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Body\TRL LEGS | bent supports and cracks and bent leg | | Supports bent from excessive forward movement of trailer while legs down | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\DAMAGE | 2x cracks inside top rear bar | | | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres | RHR.O, FR / rear marker | | Previously done | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\MUDGUARDS | RHF guard u/s rear markers faded | | As per #253398 | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | cracks in toolbox | | Small cracks in hinges - ok for now | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\MUDGUARDS | RF guard | | Replaced | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | toolbox has cracks | | As per #253497 | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | worn | | | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\AIR FITTIN | booster line worn down to wire | | Previousdy completed | | 12/10/2019 | 147422 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | | 12/10/2019 | 147422 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\Punct | Job Added From Invoice | | | | 15/09/2019 | 138696 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\INDICATORS | no indicators on rear | | | | 04/09/2019 | | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\STCH GUARD | reposition guard | | cable tie electrical cables | | 31/08/2019 | 139367 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Steering\WHEEL ALIGN | axles out of alignment | | | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | spring pack, misaligned wearing out | | | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | rope rails need attention - rear bar cracked leg support's cracked - toolbox w/ cracked | | | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL LEGS | bent supports and cracks and bent leg | | | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | toolbox door hinges are cracked | | previously completed | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\DAMAGE | 2x cracks inside top rear bar | | | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\DAMAGE | R front inner tyre | | previously done | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres | RHR.O, FR / rear marker | | | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\MUDGUARDS | RHF guard u/s rear markers faded | | | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | cracks in toolbox | | | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | left clearance light | | replace clearance light | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\MUDGUARDS | RF guard | | | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | rear bar on inside where chassis meets chassis - underneath gross braces are | | weld cracks on x members | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | toolbox has cracks | | | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | worn | | | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\AIR FITTIN | booster line worn down to wire | | replaced air lines | | 15/08/2019 | 134274 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | | 15/08/2019 | 134274 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\CASE STOCK | Job Added From Invoice | | | | 11/08/2019 | 133598 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\FITMENT | Job Added From Invoice | | | | 11/08/2019 | 133598 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\RETREAD | Job Added From Invoice | | | | 11/08/2019 | 133598 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Repair gate uprisht | | | | 02/08/2019 | 133598 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Repair/ straighten damagged gates | | | | 25/07/2019 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | | 16/07/2019 | 130359 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\DAMAGE | R front inner tyre | | job pending | | 16/07/2019 | 130359 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TAIL LIGHT | clearance 2x number plate | | | | 16/07/2019 | 130359 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres | RHR.O, FR / rear marker | | | | 16/07/2019 | 130359 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | RHS clearance and indicator u/s | | replace clearance light | | 16/07/2019 | 130359 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\MUDGUARDS | RHF guard u/s rear markers faded | | | | 16/07/2019 | 130359 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | bearing adjustments | | | | 16/07/2019 | 130359 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | cracks in toolbox | | | | 16/07/2019 | 130359 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\INDICATORS | replace indicator | | | | 16/07/2019 | 130359 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | | 16/07/2019 | 130359 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\CASE STOCK | Job Added From Invoice | | | | 29/06/2019 | 10 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\FITMENT | Job Added From Invoice | | | | 29/06/2019 | 10 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\RETREAD | Job Added From Invoice | | | | 29/06/2019 | 10 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Insp\ANN INSP | Annual Inspection As Per Checklist | Insp\ANN INSP | | | 21/06/2019 | 126534 | PreventativeMaintenance | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\MUDGUARDS | mudguard bracket | | | | 21/06/2019 | 126534 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\DAMAGE | 2x cracks inside top rear bar | | | | 21/06/2019 | 126534 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | | 21/06/2019 | 126534 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\DAMAGE | LHM duels need replacing | | job still pending | | 21/06/2019 | 126534 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\DAMAGE | rear bar cracked and gate uprights need welding | | small cracks welded big cracks not welded | | 21/06/2019 | 126534 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\DAMAGE | R front inner tyre | | job still pending | | 21/06/2019 | 126534 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |

| | | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | park liahts not workina | | 2x rubber olate liahts and 1x clearance liaht | 21/06/2019 | 126534 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 21/06/2019 | 126534 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TAIL LIGHT | clearance 2x number plate | | | 21/06/2019 | 126534 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | adjusted as needed | | | 21/06/2019 | 126534 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\PAINT/REST | Job Added From Invoice | | | 09/05/2019 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 08/05/2019 | 121078 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\DAMAGE | LHM duels need replacing | | | 08/05/2019 | 121078 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\DAMAGE | rear bar cracked and gate uprights need welding | | | 08/05/2019 | 121078 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\CHN/RLR/MN | load straps need replacing | | | 08/05/2019 | 121078 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\DAMAGE | R front inner tyre | | | 08/05/2019 | 121078 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | park lights not working | | | 08/05/2019 | 121078 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | gate's need repairs/replaced straps | | | 08/05/2019 | 121078 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | rope rails need attention - rear bar cracked lee support's cracked - toolbox w/ cracked | | | 08/05/2019 | 121078 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL LEGS | bent supoorts and cracks and bent lee | | | 08/05/2019 | 121078 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | toolbox door hinges are cracked | | | 08/05/2019 | 121078 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | rewire and replace clearance lights | | | 08/05/2019 | 121078 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 08/05/2019 | 121078 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | gates, latches and uprights | | | 01/05/2019 | 121079 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\HOUSEKEEP | prep and paint | | | 01/05/2019 | 121079 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | repairs lights | | | 21/03/2019 | 114324 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Steering\WHEEL BRGS | bearing adjustments | | | 21/03/2019 | 114324 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\DAMAGE | LHM duels need replacing | | | 21/03/2019 | 114324 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | RH clearance light out exposed wires | | | 21/03/2019 | 114324 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\DAMAGE | rear bar cracked and gate uprights need welding | | | 21/03/2019 | 114324 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\CHN/RLR/MN | load straps need replacing | | | 21/03/2019 | 114324 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 21/03/2019 | 114324 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | Service | VehService\DS | | 21/03/2019 | 114324 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | repair broken gate | | | 20/03/2019 | 114324 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Insp\RWC COMP | Job Added From Invoice | | | 06/02/2019 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CROSS MBR | weld broken gates, rear bar and rear crossmember | | | 01/02/2019 | 104186 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\REFLECTORS | rear zebra signs faded | | | 01/02/2019 | 104186 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Steering\WHEEL ALIGN | axles out of alignment | | | 01/02/2019 | 104186 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | spring pack, misaligned wearing out | | | 01/02/2019 | 104186 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 01/02/2019 | 104186 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | trailer service | VehService\DS | | 01/02/2019 | 104186 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | | | replaced straps as required | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Body\CONSUMABLE | replace worn straps | | 2 spare placed in toolbox | 18/01/2019 | 101589 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\PANELS | repair cracked upright | | | 18/01/2019 | 101589 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | repair tail light | | replaced and rewired broken and messy wires to new light | 18/01/2019 | 101589 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | | | modify 4x upright's also fabricate new posts and latches | | | | | | | | | | | |
| | | | | | prep and paint uprights and latche's | | | | | | | | | | | |
| | | | | | modify new gate's | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Body\TRL GATES | set up for 5 foot gates | | | 03/01/2019 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 30/12/2018 | 97516 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | no running lights on R/H/side | | previously completed 15/12/18 | 30/12/2018 | 97516 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 30/12/2018 | 97516 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | weld axtes and damaaed upright | | | 30/12/2018 | 97516 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | Trailer Liahts | | repair wirina as per RNR | 06/12/2018 | 95080 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 04/12/2018 | 91969 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 04/12/2018 | 91969 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 03/12/2018 | 8895 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 03/12/2018 | 8895 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | repair broken gates | | | 29/11/2018 | 91969 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Trailer Gates | | repair gate upright for beer shed | 22/11/2018 | 91299 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\BREAKDOWN | Failed Leg | | | 15/09/2018 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | Job Added From Invoice | | | 12/09/2018 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 08/09/2018 | 75262 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | repaired gates, replaced worn straps and replaced clearance light and clean up and parking trailer | | | 08/09/2018 | 75262 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 08/09/2018 | 75262 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 02/08/2018 | 65526 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\CHN/RLR/MN | ratchet chain doas on riaht handside at trailer need unseizina cannot tiahten up chains needs one more strap and ratchet in toolbox olea | | | 02/08/2018 | 65526 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\CHN/RLR/MN | chain ratchets on R/hands side need unseizing on top | | #182105 | 02/08/2018 | 65526 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 02/08/2018 | 65526 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | threads will not tighten or loosen gate in middle of trailer needs strap welding on R/hand side | | completed at earlier date | 02/08/2018 | 65526 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | middle gate on L/hand side needs to be straightened as it is bent & out of shape | | | 02/08/2018 | 65526 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 04/07/2018 | 51298 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | Service | VehService\DS | | 04/07/2018 | 51298 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 27/06/2018 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\CHN/RLR/MN | ratchet chain dogs on right handside at trailer need unseizing cannot tighten up chains needs one more strap and ratchet in toolbox plea | | | 27/06/2018 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 27/06/2018 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\PRES CHECK | Job Added From Invoice | | | 15/06/2018 | 57788 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 31/05/2018 | 56831 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\CHN/RLR/MN | reolace load straps as required | | | 31/05/2018 | 56831 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 31/05/2018 | 56831 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\ELECT P&W | Repairs to lights | | | 31/05/2018 | 56831 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | repairs to load gates (welding) | | | 31/05/2018 | 56831 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | repaired gates | | | 25/05/2018 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 12/04/2018 | 50023 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | Service | VehService\DS | | 12/04/2018 | 50023 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | Job Added From Invoice | | | 07/03/2018 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | could not adjust stubs undersized u/s | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | replace axles | | | 21/02/2018 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | bearings not able to be adjusted, stub axles undersize, evidence of steel in grease. Spacer has been added to bearing nut assembly | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | bearing adjustments unserviceable | | | 21/02/2018 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\INDICATORS | blinkers on side's u/s | | | 21/02/2018 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | LHR saddle cracked, rear of main runners cracked | | | 21/02/2018 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\HOUSEKEEP | sub poor condition | | | 21/02/2018 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | LHR saddle cracked | | | 21/02/2018 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SPRNG HANG | rocker box's worn/track rod bush's | | | 21/02/2018 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | 2 gates need welding LHS | | | 21/02/2018 | 0 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Workshop\CLEAN | clean up after iob | | | 21/02/2018 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | service asa oer sheet | VehService\DS | | 21/02/2018 | 0 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 20/01/2018 | 43413 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | could not adjust stubs undersized u/s | | still under size | 20/01/2018 | 43413 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL DOORS | load gates u/s (cracked) | | previously done | 20/01/2018 | 43413 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | | | still as above description | | | | | | | | | | | |
| | | | | | trailer axles unroadworthy | | | | | | | | | | | |
| | | | bearings not able to be adjusted, stub axles undersize, evidence of steel in grease. Spacer has been added to bearing nut assembly | | trailer unrpadworthy, placed on fence tagged out, all axles to be replaced | | | | | | | | | | | |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | bearing adjustments unserviceable | | cleaned service bay after services | 20/01/2018 | 43413 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | | | still to do - LH & RH blinkers | | | | | | | | | | | |
| | | | | | cracks on hangers | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Elect\INDICATORS | blinkers on side's u/s | | and trailer gussets and crossmember | 20/01/2018 | 43413 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | LHR saddle cracked. rear of main runners cracked | | | 20/01/2018 | 43413 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\HOUSEKEEP | sub poor condition | | | 20/01/2018 | 43413 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | LHR saddle cracked | | | 20/01/2018 | 43413 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SPRNG HANG | rocker box's worn/track rod bush's | | | 20/01/2018 | 43413 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 20/01/2018 | 43413 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Insp\ANN INSP | Annual Inspection As Per Checklist | Insp\ANN INSP | | 20/01/2018 | 43413 | PreventativeMaintenance | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 20/01/2018 | 43143 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 20/01/2018 | 43143 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | repair broken gates | | | 19/01/2018 | 43143 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres | Job Added From Invoice | | | 16/12/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\PRES CHECK | Job Added From Invoice | | | 16/12/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 16/12/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 16/12/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | bearings not able to be adjusted, stub axles undersize, evidence of steel in grease. Spacer has been added to bearing nut assembly | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | bearing adjustments unserviceable | | | 07/11/2017 | 31315 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 07/11/2017 | 31315 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL DOORS | load gates u/s (cracked) | | | 07/11/2017 | 31315 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | could not adjust stubs undersized u/s | | | 07/11/2017 | 31315 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | Service B Trailer | VehService\DS | | 07/11/2017 | 31315 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\INDICATORS | L/H rear blinker not working | | replaced LHR indicator | 31/10/2017 | 30390 | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 06/10/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WINCH/STRP | all bolts need refastening | | | 06/10/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SPRNG PACK | both front spring packs missing keepers | | | 06/10/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SHOCK ABS | LHF & LHR stubs u/s | | | 06/10/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SHOCK ABS | middle acle track rod bushes u/s | | | 06/10/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | rear of chassis cracked | | | 06/10/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | welds to the floor is cracked | | | 06/10/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL FLOOR | floor is starting to warp | | | 06/10/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | R bumoer LB has lone crack | | | 06/10/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL SEAL | LHRe hub needs inspectine u/s | | | 06/10/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | rocker bushes oerished u/s | | | 06/10/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CROSS MBR | cracks on x members u/s | | | 06/10/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 06/10/2017 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 02/09/2017 | 21315 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 02/09/2017 | 21315 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL SEAL | adjust bearings | | | 02/09/2017 | 21315 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |

| | | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| T078 | Wodonga - Workshop | Chassis\CROSS MBR | cracks on x members u/s | | | 02/09/2017 | 21315 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 04/08/2017 | 15540 | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 04/08/2017 | 15540 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 11/07/2017 | 1129 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes\BOOSTER | L booster line u/s | | | 11/07/2017 | 1129 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 11/07/2017 | 1129 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 07/06/2017 | 6372 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | LHR LHF bearings wont adjust up u/s | | 110573 | 07/06/2017 | 6372 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | LHF water in hub grease u/s | | 110573 | 07/06/2017 | 6372 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | LHF/R bearings adjusted | | adjusted bearings but have grease must get back for further repairs | 07/06/2017 | 6372 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\ELECT P&W | repair rear light assy | | previously done | 07/06/2017 | 6372 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\MUDGUARDS | LHR guard bracket loose | | | 07/06/2017 | 6372 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 07/06/2017 | 6372 | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes\BOOSTER | L booster line u/s | | | 07/06/2017 | 6372 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | R bumper LB has long crack | | | 07/06/2017 | 6372 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL SEAL | LHRe hub needs inspecting u/s | | | 07/06/2017 | 6372 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | rocker bushes perished u/s | | | 07/06/2017 | 6372 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres | Job Added From Invoice | | | 01/06/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\PRES CHECK | Job Added From Invoice | | | 01/06/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\FITMENT | Job Added From Invoice | | | 01/06/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\RETREAD | Job Added From Invoice | | | 01/06/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | | | r/centre rear bushes u/s | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | l/rear rear bushes u/s | 27/04/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\SUSPENSION | LHR LHM outriggers loose u/s | | complete | 27/04/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\ELECT P&W | repair rear light assy | | | 27/04/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\MUDGUARDS | LHR guard bracket loose | | | 27/04/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\MUDGUARDS | LB outrigger is loose | | complete | 27/04/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | weld outriggers | 27/04/2017 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP15 | Job Added From Invoice | | | 14/04/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP16 | Job Added From Invoice | | | 14/04/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP01 | Job Added From Invoice | | | 31/03/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP18 | Job Added From Invoice | | | 31/03/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 25/03/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | 4th gate on RHS needs welding | | | 25/03/2017 | | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | Straighten gates and posts on LHS - if possible | | | 25/03/2017 | | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 25/03/2017 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\MUDGUARDS | LB outrigger is loose | | | 25/03/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | welds to the floor is cracked | | | 25/03/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL FLOOR | floor is starting to warp | | | 25/03/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP11 | Job Added From Invoice | | | 14/02/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 01/02/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\ELECT P&W | female connection leakine when hand oiece is used | | | 01/02/2017 | | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | some broken eates | 01/02/2017 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\MUDGUARDS | LHR guard bracket loose | | | 01/02/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CHAS CRACK | rear of chassis cracked | | | 01/02/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TOOLBOX | crack on toolbox hinge | | | 01/02/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WINCH/STRP | Job Added From Invoice | | | 18/01/2017 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 04/01/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | LHF/R bearings adjusted | | | 04/01/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\ELECT P&W | repair rear light assy | | | 04/01/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WINCH/STRP | all bolts need refastening | | | 04/01/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SPRING PACK | both front spring packs missing keepers | | | 04/01/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SHOCK ABS | LHF & LHR stubs u/s | | | 04/01/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SHOCK ABS | middle acle track rod bushes u/s | | | 04/01/2017 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 04/01/2017 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Steering\WHEEL SEAL | Job Added From Invoice | | | 30/12/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | Job Added From Invoice | | | 30/12/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHL HUB | Job Added From Invoice | | | 30/12/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | Remove duals | | | | | | | | | | | | | |
| | | | clear hub | | | | | | | | | | | | | |
| | | | replace inner bearing | | | | | | | | | | | | | |
| | | | repack | | | | | | | | | | | | | |
| | | | resinstall | | | | | | | | | | | | | |
| | | | replace hubcap window | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | move trailers | | | 23/12/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL SEAL | RHS last axle hub cover aone | | | 17/12/2016 | | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP11 | Job Added From Invoice | | | 15/12/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP22 | Job Added From Invoice | | | 13/12/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TRC | Job Added From Invoice | | | 13/12/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 09/12/2016 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 09/12/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\MUDGUARDS | LHR LHM outriggers loose u/s | | | 09/12/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | LHR LHF bearings wont adjust up u/s | | | 09/12/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp\SUSPENSION | LHF water in hub grease u/s | | | 09/12/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Steering\WHEEL SEAL | Job Added From Invoice | | | 16/11/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | DrivLine\WHEEL BRGS | Job Added From Invoice | | | 16/11/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 15/11/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 15/11/2016 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Insp\ANN INSP | Annual Inspection As Per Checklist | Insp\ANN INSP | | 15/11/2016 | | PreventativeMaintenance | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP11 | Job Added From Invoice | | | 15/10/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP21 | Job Added From Invoice | | | 15/10/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WINCH/STRP | Job Added From Invoice | | | 07/10/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body | Job Added From Invoice | | | 30/09/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Elect\TRL LIGHTS | Job Added From Invoice | | | 24/08/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | repair gates | | complete | 23/07/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis | load binders to be replaced | | all good | 23/07/2016 | | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRC | right indicator zip tied on | | complete | 23/07/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body | L/rear o/riggers loose | | complete | 23/07/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body | L/rear o/riggers loose | | | 19/07/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 19/07/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRC | right indicator zip tied on | | | 19/07/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CROSS MBR | L/front oost + eate. rear load rack | | comolete | 19/07/2016 | | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis | cracks on chassis & eates | | comolete | 19/07/2016 | | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | weld gates | | job not complete, trailer back on Friday 22/7/16 | 19/07/2016 | | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis | load binders to be replaced | | | 19/07/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 19/07/2016 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 23/06/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 23/06/2016 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis | cracks on chassis & gates | | | 23/06/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP17 | Job Added From Invoice | | | 09/06/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP17 | Job Added From Invoice | | | 09/06/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP17 | Job Added From Invoice | | | 09/06/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Tyres\TP11 | Job Added From Invoice | | | 09/06/2016 | 0 | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 21/05/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 21/05/2016 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRC | right indicator zip tied on | | | 21/05/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\CROSS MBR | L/front post + gate, rear load rack | | | 21/05/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\REFLECTORS | replace rear chevron plates | | | 15/04/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| | | | replace rear signage | | | | | | | | | | | | | |
| T078 | Wodonga - Workshop | Body\REFLECTORS | move trailer | | | 15/04/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WINCH/STRP | pat ratchet dogs on front and back of trailer | | | 14/04/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\SUZI COIL | replace 7 pin electrical base | | | 14/04/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\ELECT P&W | rewire earth | | | 14/04/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 14/04/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 14/04/2016 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 18/02/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 18/02/2016 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\AIR LEAK | replace maxi relay valve stuck on holding brakes sublet dstr | | repalce failed maxi relay valve | 05/01/2016 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\TRL GATES | weld gates | | | 02/12/2015 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Chassis\WINCH/STRP | load binders to be reolaced | | | 02/12/2015 | | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Body\LIGHTS | left tail liahts faultv | | | 02/12/2015 | | Fault | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Insp\ANN INSP | Carry out internal roadworthv check | | comleted bv GR | 24/10/2015 | | Reair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Susp | Replate front hangers | | measure and cut plates to fit inside hangers bend to follow curve and seld in place | 24/10/2015 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | VehService\DS | D Service As Per Attached Checklist | VehService\DS | | 13/10/2015 | | Service | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes | Record Check Results As Attached To This Job | | | 13/10/2015 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |
| T078 | Wodonga - Workshop | Brakes\BRK RELINE | Carry out brake reline as needed | | full reline done | 13/10/2015 | | Repair | Completed | FL Green Distribution | FlatTop | Wodonga | LHS | 026985 | Wodonga Workshop | TRAILER |