EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
			Insp\RWC COMP													
T566	Wodonga - Workshop	Insp\RWC COMP	RWC INSPECTION			07/08/2025	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	CMV TRUCK & BUS - WODONGA	TRAILER
T566	Wodonga - Workshop	Susp\VCV	Adjust H/CV			07/08/2025	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\Punct	Tyres\Puncture POS 32			29/07/2025	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	BORDER BANDAG PTY LTD	TRAILER
T566	Wodonga - Workshop	Susp\AIR FITTIN	Replace air lines and fittings for airbags.			29/07/2025	718912	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			VehService\DS													
T566	Wodonga - Workshop	VehService\DS	\Parts Supplied By Rapid Hydraulics P/O: WWD959191	VehService\DS		29/07/2025	718912	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Body\TRL REPS PANEL REPAIRS			02/07/2025	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Remove curtains.			13/05/2025	718912	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			Repair Cracks in Chassis.													
T566	Wodonga - Workshop	Chassis\CHAS CRACK	(BCC P/O: WWD933131)			09/04/2025	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	BORDER CRANE CONSULTANTS	TRAILER
T566	Wodonga - Workshop	Chassis\CROSS MBR	Repair/Replace Main X-Brace/ I Beam, behind Landing Leg's.			18/03/2025	718912	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\RWC COMP	Repair Defects			18/03/2025	718912	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Insp\DEFECT	Victorian RWC Inspection. (CMV Truck & Bus Wodonga P/O: WWD928440)			17/03/2025	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	CMV TRUCK & BUS - WODONGA	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Repair Damaged Curtain's. (Sign Effects P/O: WWD923911)			28/02/2025	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	TWIN CITY GRAPHICS	TRAILER
			Insp\RWC COMP													
T566	Wodonga - Workshop	Insp\RWC COMP	POWW0909388			11/01/2025	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\Punct	Tyres\Punct 10-11			11/01/2025	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	BEAUREPAIRES	TRAILER
T566	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8			11/01/2025	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	BEAUREPAIRES	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	Repair Major Cracks at Goosenecks on trailer (Defect)			07/12/2024	718912	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		05/11/2024	718912	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\Punct	Tyres\Punct			18/10/2024	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	BEAUREPAIRES	TRAILER
T566	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2+5+6			27/09/2024	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	BEAUREPAIRES	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service	VehService\DS		24/08/2024	718912	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4			20/06/2024	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	BEAUREPAIRES	TRAILER
T566	Wodonga - Workshop	Drivline\WHEEL ALIGN	Wheel alignment			21/05/2024	354411	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	HUME TRUCK TECHNICS	TRAILER
T566	Wodonga - Workshop	Susp\WHEEL ALIGN	Susp\WHEEL ALIGN			16/05/2024	354411	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	HUME TRUCK TECHNICS	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/05/2024	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\ELECT P&W	REPAIR REAR TOP CLEARANCE LIGHTS.			07/05/2024	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	CRACKS IN BODY & MEZZ FLOOR POSTS ASLO LOCKING HOLES ARE GETTING FLOGGED OUT.			23/03/2024		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\ELECT P&W	MARKERS RHS NOT WORKING.			23/03/2024		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	MEZZ FLOOR STOPPED WORKING.			23/03/2024		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Unknown	SERVICE/ CHECK.			23/03/2024		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAKS.			07/03/2024	354411	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	SOME CURTAIN BUCKLE R/S & R/PS.			26/02/2024	718912	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
					DIAGNOSE AIR BAG FAULT ON FLEET											
					REPAIR AIRLINES * FITTINGS FROM A TO B TRAILER											
					REPAIR BROWN AIR LINE FOR AIR BAG SUPPLY											
T566	Wodonga - Workshop	Susp\SUSPENSION	air bags not raising		RAISE AIR BAGS ALL THE WAY TO POP BACK INTO POSITION	23/01/2024		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/01/2024		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/01/2024		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\ELECT P&W	REPAIR REAR TOP CLEARANCE LIGHTS.			21/01/2024		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\ELECT P&W	MARKER LIGHTS.			21/01/2024		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes\AIR LEAK	AIR LEAKS.			21/01/2024		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		21/01/2024		PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Unknown	SERVICE/ CHECK.			21/01/2024		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP11+12	RR SIDE WALL DAMAGED.			21/01/2024		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\AIR LEAK	REPAIRED LEAKING REAR AIR FITTING.			12/01/2024		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP9B	Tyre Position 8			28/12/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP06	replace tyre			07/12/2023	354408	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP9+10	REPLACE TYRES			29/11/2023	354408	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/10/2023	354405	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\ELECT P&W	REPAIR REAR TOP CLEARANCE LIGHTS.			21/10/2023	354405	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP11+12	RR SIDE WALL DAMAGED.			21/10/2023	354405	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	SOME CURTAIN BUCKLE R/S & R/PS.			21/10/2023	354405	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\ELECT P&W	ELECTRICAL SHORT IN LEAD FROM A TO B.			21/10/2023	354405	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\AIR LEAK	AIR LEAK IN B TRAILER?		NO AUDIBLE LEAK.	21/10/2023	354405	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes\BRAKE ADJ	GREASE, BRAKE ADJUST. TYRE CHECK.			21/10/2023	354405	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED RF LM LR WHEEL BEARINGS.	21/10/2023	354405	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/08/2023	349768	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/08/2023	349768	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP11+12	RR SIDE WALL DAMAGED.			17/08/2023	349768	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			17/08/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/02/2023	287514	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes\AIR FITTIN	Air leak between A + B trailer.			19/02/2023	287514	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/02/2023	287514	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\ELECT P&W	REPAIR REAR TOP CLEARANCE LIGHTS.			19/02/2023	287514	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 +2			01/02/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Albury Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/01/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes\AIR FITTIN	Air leak between A + B trailer.			25/01/2023		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/01/2023		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/01/2023		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	REWIRE MEZ FLOOR. MEZ REPAIRS. MOVED ASSET.			16/11/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\ELECT P&W	Rapid supply rear connection			16/11/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Albury Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/11/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP04	LM INNER TYRE U/S.			02/11/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	CURTAINS HAVE RIPS AND HOLES.			02/11/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	ANGLE RACK DAMAGED.(REPLACE)			02/11/2022		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
					New motors to be installed.											
					Supplied by Vawdrey.											
					POW WW075501											
					Mezz Floor Chain.											
					Supplied by Transpower.											
T566	Wodonga - Workshop	Body\TRL FLOOR	MEZZANINE FLOOR NOT WORKING/ NO CONTROL UNIT EITHER.		POW WW075782	02/11/2022		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\STRAPS	WINCHES NOT WORKING.			02/11/2022		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	HOLES & TEARS IN CURTAINS NEED FIXING.			02/11/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/11/2022		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP1+2	Tyre Position 1 +2			29/10/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes\BRK RELINE	Reline			28/10/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			repair/straighten left side landing leg.													
T566	Wodonga - Workshop	Chassis\TRL LEGS	Repair mountine bracket.			28/10/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/10/2022	264052	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		25/10/2022	264052	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP04	LM INNER TYRE U/S.			25/10/2022	264052	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	CURTAINS HAVE RIPS AND HOLES.			25/10/2022	264052	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	REPAIRED MEZZ DECK UPRIGHTS AND GOOSENECK CRACKS.			25/10/2022	264052	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		22/09/2022		PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			22/09/2022	248556	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		22/09/2022	248556	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			17/08/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\STRAPS	WINCHES NOT WORKING.			17/08/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		17/08/2022		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Curtain repairs			09/08/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			09/07/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Has not travelled since last service	09/07/2022		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/06/2022	205976	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\STRAPS	HOLES IN CURTAINS		Curtains repaired by TCTC Graphics 12/05/2022	12/06/2022	205976	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Multiple spots need patching.			12/06/2022	205976	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\STRAPS	MULTIPLE SPOTS NEED PATCHING			12/06/2022	205976	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	CURTAINS DAMAGED.			12/06/2022	205976	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtains still need repairs			12/06/2022	205976	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Curtains torn (Both Sides) at front of drop need repair.			12/06/2022	205976	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	TORN CURTAINS IN DROP (FRONT AND BACK OF BOTH CURTAINS)			12/06/2022	205976	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	CURTAINS TORN.			12/06/2022	205976	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	Trailer has not been used since last service	12/06/2022	205976	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/05/2022	205976	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\ELECT P&W	REVERSING LIGHTS CONSTANTLY ON WHEN CONNECTED TO P/M 1023.			13/05/2022	205976	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	CURTAIN STRAPS MISSING.			13/05/2022	205976	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/05/2022	205976	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			Curtain torn after buckle catching guard rail at Logic.													
T566	Wodonga - Workshop	Body\DAMAGE	Sent to TC Graphics for repair.			12/05/2022	718912	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check			11/04/2022		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/03/2022	200981	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\STRAPS	MULTIPLE CRACKS IN UPRIGHT, DECK CHAIN TWISTED.			30/03/2022	200981	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtains still need repairs			30/03/2022	200981	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Curtains torn (Both Sides) at front of drop need repair.			30/03/2022	200981	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/03/2022	200981	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/03/2022	190164	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP3+4	RF HAS WORN, NEED REPLACING			03/03/2022	190164	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	STRAPPED DOWN MEZ DECK. PARKED.	03/03/2022	190164	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	CURTAINS DAMAGED.			03/03/2022	190164	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP9+10	supply and fit 2 tyres			06/02/2022	178607	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/02/2022	178715	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\STRAPS	HOLES IN CURTAINS			03/02/2022	178715	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Multiple spots need patching.			03/02/2022	178715	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL WALL	Multiple cracks along wall.			03/02/2022	178715	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\STRAPS	MULTIPLE SPOT HAS CRACK			03/02/2022	178715	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	BOTH SIDE GOOSE NECK HAS CRACK.			03/02/2022	178715	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\STRAPS	MULTIPLE SPOTS NEED PATCHING			03/02/2022	178715	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\STRAPS	MULTIPLE CRACKS IN UPRIGHT, DECK CHAIN TWISTED.			03/02/2022	178715	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP3+4	RF HAS WORN, NEED REPLACING			03/02/2022	178715	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtains still need repairs			03/02/2022	178715	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Curtains torn (Both Sides) at front of drop need repair.			03/02/2022	178715	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED FR RM LR RR WHEEL BEARINGS	03/02/2022	178715	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/01/2022	169635	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\STRAPS	MULTIPLE SPOTS NEED PATCHING			08/01/2022	169635	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER

T566	Wodonga - Workshop	Body\STRAPS	MULTIPLE CRACKS IN UPRIGHT, DECK CHAIN TWISTED.					08/01/2022	169635	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtains still need repairs					08/01/2022	169635	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Curtains torn (Both Sides) at front of drop need repair.					08/01/2022	169635	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP3+4	RF HAS WORN, NEED REPLACING					08/01/2022	169635	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED RF WHEEL BEARING			08/01/2022	169635	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP3+4	supply and fit 2tyres					08/01/2022	169635	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					09/12/2021	158708	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\TRL LEGS	LHS LEG IS BENT					09/12/2021	158708	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED RF LF LM WHEEL BEARINGS.			09/12/2021	158708	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\STRAPS	MULTIPLE SPOT HAS CRACK					09/12/2021	158708	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\LCHAS CRACK	BOTH SIDE GOOSE NECK HAS CRACK.					09/12/2021	158708	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					19/11/2021	150338	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED LF LM WHEEL BEARINGS			19/11/2021	150338	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\STRAPS	MULTIPLE SPOTS NEED PATCHING					19/11/2021	150338	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\STRAPS	MULTIPLE CRACKS IN UPRIGHT, DECK CHAIN TWISTED.					19/11/2021	150338	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\TRL LEGS	STRAIGHTEN/ REPAIR LANDING LEG.					19/11/2021	150338	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check					14/10/2021	136535	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					14/10/2021	136535	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\TRL LEGS	LHS LEG IS BENT					14/10/2021	136535	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS	ADJUSTED RR RM LF WHEEL BEARINGS			14/10/2021	136535	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes\AIR TANKS	REPAIRED AIR LEAKS AND REPLACED DRAIN COCK.					14/10/2021	136535	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\Ute-Tor	POS 4					22/09/2021	128160	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP04	punture repair					18/09/2021	126934	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check					18/09/2021	126934	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP				18/09/2021	126934	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					18/09/2021	126934	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL WALL	Multiple cracks along wall.					18/09/2021	126934	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TAIL LIGHT	Reversing lights still on when connected through heavy duty plug.		CHECKED.			18/09/2021	126934	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS				18/09/2021	126934	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\MUDGUARDS	CURTAIN STRAP ALL CHANGE		CHANGED 90% STRAPS AND BUCKLES			18/09/2021	126934	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes\AIR LEAK	CHECKED AIR LEAKS WITH SOAP BOTTLES. PARK IN YARD.					18/09/2021	126934	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\TRL LEGS	LHS LEG IS BENT					18/09/2021	126934	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					17/08/2021	113063	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	RHS Curtain ratchet needs greasing hard to move.					17/08/2021	113063	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS				17/08/2021	113063	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP02	LF inner tyre s/s					17/08/2021	113063	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Multiple spots need patching.					17/08/2021	113063	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL WALL	Multiple cracks along wall.					17/08/2021	113063	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	DriveLine\WHEEL BRGS	LF and LR bearings need adjustment.					17/08/2021	113063	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			Yard check.															
			Check S-Line															
T566	Wodonga - Workshop	Workshop\MOVE ASSET	Hook us trailers for service.					17/08/2021	113063	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP3+2	Supplyand fit 2 tyres					11/08/2021	113063	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\PRES CHECK	pressure maintenance POS 3-12					11/08/2021	113063	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					16/07/2021	100661	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			Record Check Results As Attached To This Job															
T566	Wodonga - Workshop	Brakes	Brake neadnes not recorded on oaseerwork.					16/07/2021	100661	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TAIL LIGHT	Reverse lights illuminated constantly when plugged into 1023 heavy duty plug.					16/07/2021	100661	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Grease RHS curtain ratchet handle.					16/07/2021	100661	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS				16/07/2021	100661	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\STRAPS	HOLES IN CURTAINS					16/07/2021	100661	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP7+8	replace 2 tyres.					06/07/2021		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			Record Check Results As Attached To This Job															
T566	Wodonga - Workshop	Brakes	Brake neadnes not recorded on oaseerwork.					13/06/2021	88215	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS				13/06/2021	88215	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\Ute-Tor	RR Wheel nuts also check.					13/06/2021	88215	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Workshop\MOVE ASSET	Take yard truck and find trailer - hook up and take to shed for service.					13/06/2021	88215	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					29/05/2021		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
					Conduct De Service													
					Remove and replace Front RHS & LHS Brake Booster													
					Remove and Replace Middle RHS & LHS brake booster													
					adjust wheel bearings on middle axle													
					remove and replace RHS rear airbags													
			D Service As Per Attached Checklist															
T566	Wodonga - Workshop	Veh\Service\DS	Serviced by Viewdrew Dandenong	VehService\DS	Curtain Repair RH & Lh front to rear			29/05/2021		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					30/04/2021		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\LIGHTS	clearance lights still not fixed/replaced					30/04/2021		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS				30/04/2021		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					10/04/2021	59816	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS				10/04/2021	59816	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					30/03/2021		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TAIL LIGHT	LHS tail light still not replaced		no fault found			30/03/2021		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS	caboolture Powe063167			30/03/2021		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres	tyres still need inspection/replaced		tyres OK			30/03/2021		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\TRL LEGS	left leg cracked off chassis					30/03/2021		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp\AIR LEAK	rear right air bag leaking air					30/03/2021		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					06/03/2021	38098	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS	Carry out D service as per service sheet			06/03/2021	38098	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\TRL LEGS	LHS broken off chassis					06/03/2021	38098	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp\AIR BAG	RHS rear bag weeping					06/03/2021	38098	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					18/02/2021	18885	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS	Brown and Hurley to carry out Service P/O WW062032			18/02/2021	18885	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\REFLECTORS	replace 2 damage reflectors		Brown and hurley to carry out repairs P/O WW062032			18/02/2021	18885	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtains have rips					18/02/2021	18885	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\SKID PLATE	skid plate slightly worn					18/02/2021	18885	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp\AIR BAG	RHR axle airbag has slight cracking					18/02/2021	18885	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\Punct	repair puncture Pos 5					19/01/2021	6454	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
					repaired at Viewdrey													
T566	Wodonga - Workshop	Body\TRL REPS	small holes.		rollers neolaced with tri rollers			14/01/2021		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Rowwood Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	holes in curtains					17/12/2020		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtains catch in tracks					17/12/2020		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					12/12/2020	1608	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	small holes					12/12/2020	1608	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS				12/12/2020	1608	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Workshop\MOVE ASSET	Remove trailer from shed and park up					24/11/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Curtains need patches					12/11/2020	100016	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	Check adjustment of mec floor chains		completed at Vawdrey			12/11/2020	100016	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	Deck and uprights		assist Andrew repair cracks and brace uprights			12/11/2020	100016	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\LCHAS CRACK	Cracks in all box corners					12/11/2020	100016	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\LCHAS CRACK	Cracks throughout					12/11/2020	100016	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	leak in deck and air bowl under tray s/s					12/11/2020	100016	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\DAMAGE	Deck upright cracked					12/11/2020	100016	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\TRL LEGS	LHS landing leg bent & drive shaft between legs bent					12/11/2020	100016	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					12/11/2020	100016	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\LCHAS CRACK	Chassis Crack					12/11/2020	100016	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\MUDGUARDS	L rear guard bent					12/11/2020	100016	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	mecc deck not going down/locks don't retract					12/11/2020	100016	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\LCHAS CRACK	frame is cracked inside drop deck. weld broken and plate comine off- have reoported this problem multiole times and provided photos and videos. Has been a problem fr					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\LCHAS CRACK	check welds on drop check section					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	CURTAINS NEED REPAIR					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\LIGHTS	clearance lights still not replaced					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtains still need repair					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\LIGHTS	LHS tail light still needs replaced					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres	tyres still need inspection					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\LIGHTS	clearance lights still not replaced					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\DRV TYRES	tyres need inspection.					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtain needs repairs					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\LIGHTS	clearance lights still not fixed/replaced, LHS tail light still not replaced					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtains still need repairs					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\DRV TYRES	tyres still need inspection/replaced					12/11/2020	100016	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS				12/11/2020	100016	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Workshop\MOVE ASSET	cross load trailer to T556					11/11/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					10/11/2020	999099	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					10/11/2020	999099	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					01/11/2020	999099	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS				01/11/2020	999099	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\CHN/RUB/MIN	replace Front RH bearing for mec deck lock		transpower for chain links Powe058907			16/10/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Workshop\CLEAN	clean up after repairs					16/10/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					25/09/2020	837906	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					25/09/2020	837906	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	mec floor repairs		remounted wire runner			24/09/2020	559095	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
					replaced buckles and straps													
T566	Wodonga - Workshop	Body\TRL REPS	replace buckels and straps		move trailers			24/09/2020	559095	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\REFLECTORS	Job Added From Invoice					24/09/2020	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice					22/09/2020	1	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice					22/09/2020	1	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice					22/09/2020	1	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					20/09/2020	637906	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Veh\Service\DS	D Service As Per Attached Checklist	VehService\DS	replaced rear markers			20/09/2020	637906	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres	L/centre inner flat					20/09/2020	637906	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
					replaced rear markers													
T566	Wodonga - Workshop	Body\LIGHTS	replaced lights where req		CLEARED DEFECT: HVN054600			20/09/2020	637906	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\WHEEL BRGS	adjusted r/front\rear					20/09/2020	637906	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp\SHOCK ABS	l/front loose		tighten loose shocks			20/09/2020	637906	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TRL LIGHTS	4x blinkers hanging down - both sides and clearance lights		also LH tail light assembly			19/09/2020	637906	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TRL LIGHTS	L top clearance					19/09/2020	637906	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TAIL LIGHT	LHR top brake lights s/s					19/09/2020	637906	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TAIL LIGHT	LHR top brake light					19/09/2020	637906	Repair	Completed	FL

T566	Wodonga - Workshop	Elect\TRL LIGHTS	2x blinkers hanging down - both sides						26/07/2020	75713	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp\AIR BAG	RHF 30K airbag leaking						26/07/2020	75713	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\TRL LEGS	LHS landing leg bent & drive shaft between legs bent						26/07/2020	75713	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			LJH front lock for mez floor inop																		
T566	Wodonga - Workshop	Body\TRL WALL	lockine do not retract. floor cannot be drooped						26/07/2020	75713	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	frame is cracked inside drop deck. weld broken and plate comine off- have reoported this problem multiple times and provided photos and videos. Has been a problem fi						26/07/2020	75713	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\DRV TYRES	check tyre, /may need replacing						26/07/2020	75713	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	check welds on drop check section						26/07/2020	75713	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TAIL LIGHT	check tail lights						26/07/2020	75713	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					26/07/2020	75713	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	due for service	VehService\DS					26/07/2020	75713	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\DAMAGE	Deck upright cracked						26/07/2020	75713	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	also A and B trailer (565/566) over due for a service have also reported many times	VehService\DS					26/07/2020	75713	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	repair upright and goose neck cracks						16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP					16/06/2020		PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Curtains need patches						16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	Check adjustment of mez floor chains						16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Holes & rips and rips		As per #290547				16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	Deck and uprights						16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Rips on deck flaps		As per #290547				16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks in all box corners						16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Rips at bottom deck corners		As per #290547				16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Curtains damaged		As per #290547				16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp\SUSPENSION	Bush's u/s		Couldn't fault				16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp\SUSPENSION	monitor bush's		as per #290555				16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	leak in deck and air bowl under tray u/s						16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Rips		As per #290547				16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			LJH front lock for mez floor inop																		
T566	Wodonga - Workshop	Body\TRL WALL	lockine do not retract. floor cannot be drooped						16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Curtains need to be sent for repairs		As per #290547				16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	cracks in uprights		As per #290550				16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtains damaged		As per #290				16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Curtains damaged		As per #290547				16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks throughout						16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			LJH front lock for mez floor inop																		
T566	Wodonga - Workshop	Body\TRL WALL	lockine do not retract. floor cannot be drooped		As per #290559				16/06/2020		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtains need repair		As per #290547				16/06/2020		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					16/06/2020		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Rips at bottom deck corners		As per #290547				16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TRL LIGHTS	2x blinkers hanging down - both sides						16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp\AIR BAG	RHF 30K airbag leaking						16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\TRL LEGS	LHS landing leg bent & drive shaft between legs bent						16/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP18	RHM tyre						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	air leak on left side of mezz floor						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	Chassis Crack						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TRL LIGHTS	L top clearance						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\INDICATORS	brake out and L middle blinker						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\MUDGUARDS	L rear guard bent						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	LHR top brake lights u/s						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TAIL LIGHT	LHR top brake light						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TRL LIGHTS	top right light out rear						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	air leak in mez deck						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	air leak in mez floor						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	mezz deck not going down/locks don't retract						13/06/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					13/06/2020		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	CURTAIN REPAIRS						08/05/2020		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						19/04/2020	84714	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TRL LIGHTS	top right light out rear						19/04/2020	84714	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					19/04/2020	84714	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Brake test results attached						25/11/2019	75714	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TAIL LIGHT	LHR top brake light						25/11/2019	75714	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\MUDGUARDS	RHF guard cracked						25/11/2019	75714	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Curtains damaged						25/11/2019	75714	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks throughout						25/11/2019	75714	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service	VehService\DS					25/11/2019	75714	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	crack in gooseneck		weld/repair cracked goose neck				20/11/2019	1253613	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	mezz deck not working						20/11/2019	1253613	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\LECT P&W	inspect and repairs to wiring and fuse						20/11/2019	1253613	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			LJH front lock for mez floor inop																		
T566	Wodonga - Workshop	Body\TRL FLOOR	Lock does not retract. floor cannot be drooped		Insocected deck locks				19/11/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Repaired pelmet rubber bracket						19/11/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Curtain pole & track damaged		Repaired curtain pole & track				20/10/2019	556344	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Workshop\MOVE ASSET	Move trailers						20/10/2019	556344	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	right rear curtain pole handle broken						19/10/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	air leak in mez deck		unable to check due to being loaded				14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	air leak in mez floor		as per #253686				14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP20	Tyre Position 20						14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	Trailer (Taultliner) Repairs						14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	Chassis Crack						14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\WHL HUB	Hub grease poor - Blue grease						14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TRL LIGHTS	L top clearance						14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\INDICATORS	brake out and L middle blinker						14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\MUDGUARDS	L rear guard bent						14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	buckle's need replacing						14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	cracks in uprights		unable to check correctly due to being loaded				14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\WAC COMP	check tyre pressures		refer to Beau repairs. w/shop not capable of pumping up tyres to correct pressure				14/10/2019	855492	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	air leak in mez deck		as per #253686				14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					14/10/2019	855492	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TAIL LIGHT	LHR top brake lights u/s						14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtains damaged						14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	DrivLine\WHEEL BRGS	adjusted LHF, RHF & RHM						14/10/2019	855492	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	over due for service	VehService\DS					14/10/2019	855492	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres	Job Added From Invoice						29/09/2019	744705	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice						29/09/2019	744705	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice						29/09/2019	744705	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\CLEANDEIN	Job Added From Invoice						29/09/2019	744705	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
					Pulled wheels off & checked reason for excess movement																
					*Axle stubs are very worn, making the bearings spin on the axles & burn the grease, which is rapidly wearing the bearing rollers due to lack of lubrication															
T566	Wodonga - Workshop	DrivLine\WHEEL BRGS	Excess movement in all axles		**Thrust washers were chanaed which took up some of the slack. but will only serve as a temporary fix				17/09/2019	885632	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR FITTIN	Replace emergency coupling at front of trailer						16/09/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\INDICATORS	Repaired damaged LHS indicator						16/09/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\TRL LIGHTS	L top clearance						16/09/2019	885632	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect\INDICATORS	brake out and L middle blinker						16/09/2019	885632	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\MUDGUARDS	L rear guard bent						16/09/2019	885632	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	buckle's need replacing						16/09/2019	885632	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\AIR LEAK	leaking coupling						16/09/2019	885632	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	cracks in uprights						16/09/2019	885632	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service	VehService\DS					16/09/2019	885632	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	DrivLine\WHEEL BRGS	excess movement in all axles						16/09/2019	885632	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						16/09/2019	885632	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						05/08/2019	875666	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					05/08/2019	875666	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	curtains need to be sent for repairs						05/08/2019	875666	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\Punct	Job Added From Invoice						01/08/2019	10	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						28/07/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL LEGS	LH-leg mounts u/s						28/07/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp\AIR BAG	RHR 30K pin holes u/s						28/07/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp\AIR BAG	RHR, perished, slow leak						28/07/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TOOLBOX	toolbox lid needs straightening						28/07/2019		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					28/07/2019		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						06/07/2019	704334	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP19	RHM tyre						06/07/2019	704334	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP18	LHM tyre						06/07/2019	704334	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP14	LH-F inners u/s						06/07/2019	704334	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			LJH front lock for mez floor inop																		
T566	Wodonga - Workshop	Body\TRL WALL	lockine do not retract. floor cannot be drooped						06/07/2019	704334	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	air leak on left side of mezz floor		as per job #236047				06/07/2019	704334	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	air leak in mez deck		As per job #236047				06/07/2019	704334	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	air leak in mez floor		As per job #236047				06/07/2019	704334	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					06/07/2019	704334	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP20	RHM outer						06/07/2019	704334	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL REPS	rips in curtains						06/07/2019	704334	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\CHAS CRACK	Cracks in corners of uprights & deck						06/07/2019	704334	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	DrivLine\WHEEL BRGS	Bearings adjusted as needed						06/07/2019	704334	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis\WHL HUB	Hub grease poor - Blue grease						06/07/2019	704334	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job						08/08/2019	814964	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp\AIR BAG	RHR 30K pin holes u/s						08/08/2019	814964	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp\AIR BAG	RHR, perished, slow leak						08/08/2019	814964	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	leak in deck and air bowl under tray u/s						08/08/2019	814964	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\TRL FLOOR	loaded						08/08/2019	814964	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\DAMAGE	RHM outer u/s						08/08/2019	814964	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body\AIR LEAK	air leak on left side of mezz floor						08/08/2019	814964	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS					08/08/2019	814964	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService\DS	trailer service due next weekend	VehService\DS				

T566	Wodonga - Workshop	Elect|ELECT P&W	Rear roof lights not working				31/03/2019	866368	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|ELECT P&W	rear roof lights not working		#218761		31/03/2019	866368	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|CRN/RAIL/MN	crushed buckle left hand side on rear drop		done		31/03/2019	866368	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|ELECT P&W	rear roof lights not working				31/03/2019	866368	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|ELECT P&W	rear roof lights not working				31/03/2019	866368	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|TRL LIGHTS	rear roof lights not working				31/03/2019	866368	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|TRL LIGHTS	rear right clearance light not working				31/03/2019	866368	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|TRL LIGHTS	roof lights on rear not working				31/03/2019	866368	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|TRL LIGHTS	rear roof lights not working				31/03/2019	866368	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			31/03/2019	866368	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp|AIR BAG	RHR, perished, slow leak				31/03/2019	866368	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	Service Due	VehService|DS			31/03/2019	866368	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|INDICATORS	replaced LH side indicator				28/02/2019	856447	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Workshop|MOVE ASSET	moving trailers for service				24/02/2019	864547	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL RIPS	rips at bottom deck corners				24/02/2019	864547	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				24/02/2019	864547	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	Service	VehService|DS			24/02/2019	864547	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Workshop|MOVE ASSET	move trailers				20/01/2019	855657	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL RIPS	rips on deck flaps				20/01/2019	855657	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis|CHAS CRACK	cracks in all box corners				20/01/2019	855657	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	DrivLine|WHEEL BRGS	adjusted as needed				20/01/2019	855657	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL FLOOR	loaded				20/01/2019	855657	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp|SUSPENSION	monitor bush's				20/01/2019	855657	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp|AIR BAG	RHR 30K pin holes u/s				20/01/2019	855657	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/01/2019	855657	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	Service	VehService|DS			20/01/2019	855657	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Workshop|MOVE ASSET	mec repairs - moving trailer				15/01/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Workshop|MOVE ASSET	mec repairs - moving trailer				15/01/2019		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	VehService|DS	VehService|DS	Service		16/12/2018	943857	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|AIR LEAK	Curtain leaks both sides @ rear				15/12/2018	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	D service Due	VehService|DS			15/12/2018	0	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|FITMENT	Job Added From Invoice				22/11/2018	52747	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|RETREAD	Job Added From Invoice				22/11/2018	52747	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|FITMENT	Job Added From Invoice				21/11/2018	978567	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|RETREAD	Job Added From Invoice				21/11/2018	978567	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				18/11/2018	968557	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS	as per attached:		18/11/2018	968557	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	Service over due	VehService|DS			18/11/2018	968557	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|TRL LIGHTS	driver side rear clearance light not working				10/11/2018	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|TRL LIGHTS	rear roof lights not working				10/11/2018	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|DAMAGE	repairs				21/10/2018	52627	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				21/10/2018	52627	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Workshop|CLEAN	cleaning				21/10/2018	52627	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	Service	VehService|DS			21/10/2018	52627	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				09/09/2018	52667	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			09/09/2018	52667	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|FITMENT	Job Added From Invoice				02/09/2018	144955	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|CLEANSKIN	Job Added From Invoice				02/09/2018	144955	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		completed during service		11/08/2018	142125	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|INDICATORS	Right side rear blinker faulty				11/08/2018	142125	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
					hub inspections												
					supervisor duties												
T566	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS	clean up		11/08/2018	142125	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis|WINCH/STRP	replace buckle and strap				22/07/2018		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|PRES CHECK	Job Added From Invoice				21/07/2018	144055	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				08/07/2018	111945	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|INDICATORS	Right side rear blinker faulty				08/07/2018	111945	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			08/07/2018	111945	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|INDICATORS	right rear indicator not working		replaced RHR indicator		29/06/2018	166555	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|ELECT P&W	intermittent fault in right hand indicator		inspect for trailer light fault, unable to fault at time of inspection		13/06/2018		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|BREAKDOWN	Brake light staying on with park lights on LHS				07/06/2018		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|BRK LIGHT	inspect LHS brake lights on all the time				07/06/2018		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|BREAKDOWN	Light issue				05/06/2018		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TOOLBOX	toolbox lid needs straightening				02/06/2018	1337855	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				02/06/2018	1337855	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
			LJH front lock for mec flour insp														
T566	Wodonga - Workshop	Body|TRL WALL	lockine do not retract. floor cannot be drooped				02/06/2018	1337855	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|AIR LEAK	air leak on left side of mecc floor				02/06/2018	1337855	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			02/06/2018	1337855	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Insp|ANN INSP	Annual inspection As Per Checklist	Insp|ANN INSP			02/06/2018	1337855	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|ELECT P&W	rewire rear tog lights LH & RH				02/06/2018	1337855	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Susp|AIR BAG	replace all BPW airbags				02/06/2018	1337855	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|ELECT P&W	diagnose rear top lights				02/06/2018	1337855	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Workshop|MOVE ASSET	forklift operations for repairs				02/06/2018	1337855	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL LEGS	repair bent leg on LH1				31/05/2018	133215	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|FITMENT	Job Added From Invoice				19/05/2018	113955	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|CLEANSKIN	Job Added From Invoice				19/05/2018	113955	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/05/2018		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|AIR LEAK	leak in deck and air bowl under tray u/s				06/05/2018		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|AIR LEAK	air leak on left side of mecc floor				06/05/2018		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			06/05/2018		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|ELECT P&W	elec repairs				02/05/2018		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				18/03/2018	614571	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL FLOOR	check adjustment of mec floor chains		loaded		18/03/2018	614571	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|DRY TYRES	L/R/O Tyre Low				18/03/2018	614571	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Steering|WHEEL BRGS	adjust all R/H Wheel bearings		ok		18/03/2018	614571	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
			LJH front lock for mec flour insp														
T566	Wodonga - Workshop	Body|TRL WALL	lockine do not retract. floor cannot be drooped		loaded		18/03/2018	614571	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			18/03/2018	614571	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL RIPS	holse and rips				18/03/2018	614571	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|AIR LEAK	leak in deck and air bowl under tray u/s				18/03/2018	614571	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL RIPS	deck and uprights				18/03/2018	614571	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL LEGS	LH-leg mounts u/s				18/03/2018	614571	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|TRL LIGHTS	repairs to lights and reflectors				18/03/2018	614571	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
			temp fix on mec deck after inspection														
T566	Wodonga - Workshop	Body|TRL FLOOR	cark trailers				18/03/2018	614571	Repair	Completed	FL Green Distribution	Tilner	Woodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|RUN OUT	Job Added From Invoice				24/02/2018	505942	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL FLOOR	L/F mec lock not working		Found broken lock spring & no air to solenoid traced air lines & repaired air leaks. Found fan bag valve. Bypassed and tested ok		31/12/2017	700866	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|TRL LIGHTS	no lights work.				31/12/2017	700866	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		Complete during svc		24/12/2017		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			24/12/2017		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|DRY TYRES	L/R/O Tyre Low				24/12/2017		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL RIPS	curtains need patches				24/12/2017		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Steering|WHEEL BRGS	adjust all R/H Wheel bearings				24/12/2017		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL LEGS	straighten legs on B trailer as best as possible and welded in place, replaced foot springs. Legs operational but need to be replaced				08/12/2017	692892	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|BRK LIGHT	Brake Light				11/11/2017		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|DAMAGE	replaced smashed RHS tail lights and assembly				08/11/2017		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
			change battery for fridge motor														
T566	Wodonga - Workshop	DrCab|Elect|BATTERY	motor started and tested				13/10/2017		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				08/10/2017	658531	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			08/10/2017	658531	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes|BRAKE ADJ	inspect fault for no LH brake light when hooked onto (scania) - could not fault trailer with tester				07/10/2017	668570	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|ELECT P&W	rewired truck plug and truck base, new male end wired on also				07/10/2017	668570	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|PRES CHECK	Job Added From Invoice				08/09/2017	637105	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				06/09/2017	637104	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	Service	VehService|DS			06/09/2017	637104	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL RIPS	holes in curtains				24/08/2017	635133	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis|CHAS CRACK	cracks on drop deck				24/08/2017	635133	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis|WINCH/STRP	fit pallet angle carrier				24/08/2017	635133	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL RIPS	LB missing strap RM curtain is ripped		x3 straps replaced		24/08/2017	635133	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL LEGS	spring on foot is broken		replaced with second hand one also put battery on charger		24/08/2017	635133	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis|CHAS CRACK	crack at drop				24/08/2017	635133	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
					LH-F & RH-R locks have broken mounts												
					cut deck to gain access												
T566	Wodonga - Workshop	Body|TRL FLOOR	check wear and operation of deck locks repair as required		fabricate new lock covers for deck & weld		24/08/2017	635133	Repair	Completed	FL Green Distribution	Tilner	Woodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL FLOOR	check adjustment of mec floor chains		need o adjust both rear chains		24/08/2017	635133	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|ELECT P&W	Moved main power fuse to under control box for easier access				24/08/2017	635133	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				17/08/2017	635132	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
			Service														
T566	Wodonga - Workshop	VehService|DS	cracks in combine rail welded	VehService|DS			17/08/2017	635132	Service	Completed	FL Green Distribution	Tilner	Woodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|FITMENT	Job Added From Invoice				17/08/2017	633757	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|ROTATION	Job Added From Invoice				17/08/2017	633757	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres|CLEANSKIN	Job Added From Invoice				17/08/2017	633757	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|CRN/RAIL/MN	repair chain (broken)				15/08/2017	633757	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|ELECT P&W	wire housing refix				15/08/2017	633757	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|HOUSEKEEP	weld doublers on mec lock holes				15/08/2017	633757	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				03/08/2017	628148	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS	cleaning		03/08/2017	628148	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis|CHAS CRACK	crack at drop				03/08/2017	628148	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job				20/05/2017	566611	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis|CHAS CRACK	all coming rabalb have cracks				20/05/2017	566611	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|SHOCK ABS	bushes look worn u/s		ok		20/05/2017	566611	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|MUDGUARDS	RHR mudflap		ok		20/05/2017	566611	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis|WINCH/STRP	fit pallet angle carrier				20/05/2017	566611	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|ELECT P&W	LB top light u/s		replaced LHR top lights and LHR light bar		20/05/2017	566611	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect|ELECT P&W	clearance lights on B trailer smashed		ok		20/05/2017	566611	Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService|DS	D Service As Per Attached Checklist	VehService|DS			20/05/2017	566611	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Insp|ANN INSP	Annual inspection As Per Checklist	Insp|ANN INSP			20/05/2017	566611	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body|TRL FLOOR	fixed air lines on mec deck				20/05/2017	566611	Repair	Completed	FL Green Distribution

T566	Wodonga - Workshop	Elect/ELECT P&W	Job Added From Invoice					14/01/2017	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect/ELECT P&W	Heavy duty plug damage					13/01/2017		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body/DAMAGE	Plug fitting holder bent					13/01/2017		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					30/12/2016	493286	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			Curtains slowly ripping near drop decks															
T566	Wodonga - Workshop	Body/LTRL REPS	Some buckles need reelacing			previously done		30/12/2016	493286	Fault	Comeleted	FL Green Distribution	Tilner	Wodonga	HCU	949995	Woodonwa Workshop	TRAILER
T566	Wodonga - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS				30/12/2016	493286	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis/LEVAS CRACK	all coming rabuilt have cracks					30/12/2016	493286	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService/GHOCK ABS	bushes look worn u/s					30/12/2016	493286	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS		repaired curtain		06/11/2016		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					06/11/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			ABS/ECS alarm flashing on dash															
T566	Wodonga - Workshop	DrCabElect	as per defect notice #13705			refer job no 63482		04/10/2016		Fault	Comeleted	FL Green Distribution	Tilner	Woodonwa	HCU	949995	Woodonwa Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP18	Job Added From Invoice					01/10/2016	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice					01/10/2016	455389	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					24/09/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body/LTRL REPS	LHF rip at drop					24/09/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body	S buckles S straps u/s					24/09/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body	left hand body below mec crack					24/09/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body	LH side back flap need new tye (check)					24/09/2016		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	ABS fault					24/09/2016		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	ABS plugs					24/09/2016		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body	curtain torn passengers side rear gooseneck					24/09/2016		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body	deck stopping when lowering					24/09/2016		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body	check battery charge both trailer					24/09/2016		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body	curtain torn passengers side rear gooseneck					24/09/2016		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
			deck stopping when lowering															
T566	Wodonga - Workshop	Body	-check battery charee both trailers					24/09/2016		Fault	Completed	FL Green Distribution	Tilner	Woodonwa	HCU	949995	Woodonwa Workshop	TRAILER
T566	Wodonga - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS				24/09/2016		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Insp\DEFECT	roadworthy for defect					24/09/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body/MOUNTS	Welding Cracks on chassis (gooseneck). Welding Cracks on chassis			complete		13/08/2016		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect/ELECT P&W	back deck, raining issues					13/08/2016		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP18	Job Added From Invoice					14/07/2016	418488	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP17	Job Added From Invoice					14/07/2016	418488	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					08/07/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis	r/hand top nose cone c/lamp					08/07/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS		LH-F softy lock not operating properly		08/07/2016		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body	left hand body below mec crack					08/07/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					09/06/2016	405943	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body	S buckles S straps u/s					09/06/2016	405943	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body/LTRL REPS	repair curtains @ gooseneck					09/06/2016	405943	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS				09/06/2016	405943	Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis	r/hand top nose cone c/lamp					09/06/2016	405943	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					06/05/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body/LTRL REPS	LHF rip at drop					06/05/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS				06/05/2016		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP				06/05/2016		PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body	S buckles S straps u/s					06/05/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Engine	jump started					05/05/2016	152278	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice					16/04/2016	385795	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body/LTRL REPS	spray paint 4x uprights					13/04/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					05/04/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
						weld cracks on goose neck doobler.												
						Removed left hand rear lock and cog mount welded plate back on lop off lock as stopper remounted. Ground the corners of the doublers around the locking holes. Connected B trailer to the A trailer and parked on the pad.												
T566	Wodonga - Workshop	Body/LTRL REPS	LHF rip at drop			Good to ao		05/04/2016		Repair	Completed	FL Green Distribution	Tilner	Woodonga	HCU	949995	Woodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS		repaired lights		05/04/2016		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice					22/03/2016	339926	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice					22/03/2016	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice					22/03/2016	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP11	Job Added From Invoice					22/03/2016	339926	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body/LTRL FLOOR	inspect and repair mec deck			weld goose neck crack and fit doubler		19/03/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP15	Job Added From Invoice					10/03/2016	362635	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Tyres\TP15	Job Added From Invoice					10/03/2016	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					05/03/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS				05/03/2016		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body/LIGHTS	RH top rear lights not getting power needs wiring loom					21/01/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect	Repair wiring for right top corner indicator					21/01/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect	Repair wiring for right top corner indicator					21/01/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis	Minor cracks RHS on chassis in front of axels					21/01/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Chassis	Repair 2 X major cracks above skid plate			job has been inspected plan to have repaire carried out vawdrey for warrenty		21/01/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService/DS	service due	VehService\DS				21/01/2016		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService	service due					21/01/2016		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService	service due					21/01/2016		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes\BRAKE ADJ	check brakes					21/01/2016		Fault	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Body/LIGHTS	RH top rear lights not getting power needs wiring loom					21/01/2016		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect	fit gearbox to mezz floor and check operation					21/12/2015		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Elect	remove mezz deck gearbox					19/12/2015		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job					12/11/2015		Repair	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
T566	Wodonga - Workshop	VehService/DS	D Service As Per Attached Checklist	VehService\DS				12/11/2015		Service	Completed	FL Green Distribution	Tilner	Wodonga	HCU	949995	Wodonga Workshop	TRAILER
						Fixed clearance lights												
						Replaced load binder strap												
T566	Wodonga - Workshop	Insp\ANN INSP	Carry out internal roadworthy check			Other iobs found that have been out onto new iob		06/11/2015		Repair	Comeleted	FL Green Distribution	Tilner	Woodonwa	HCU	949995	Woodonwa Workshop	TRAILER