EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS Service	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\TP>8	Tyres\TP>8 (27-28)		LOW	######## 628560		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BORDER BANDAG PTY LTD	TRAILER
T615	Wodonga - Workshop	Brakes\BRK RELINE	Tagged out for reline		completed b y AM JW	######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Brakes\AIR FITTIN	Control Air Line between A & B trailer's is Leaking.			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS Service	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS Service	VehServiceUDS	Reline needed asap	######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\TRL REPS	R/F Upright is missing bottom half (in toolbox)			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
			Fit REAR GUARDS TO BAR NOW BOLTS WITH SIDE LOOSE.													
T615	Wodonga - Workshop	Body\MUDGUARDS	HOLES IN GUARDS.													
T615	Wodonga - Workshop	Brakes\AIR LEAK	Control Air Line Between A&B Trailer Leaking		Connected shop air to front of trailers, checked for air leak/s, found split brake hose at trailer coupling (Emergency Brake Side), removed hose clamp and hose, shortened brake hose, refitted brake hose & hose clamp, rechecked for air leaks, all good, packed up all tooling.	######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS Service	VehServiceUDS	Will need reline asap	######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\TP>10	Tyres\TP>10 (29-30)		LOW	######## 628560		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BORDER BANDAG PTY LTD	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS Service	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	/134603	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS Service	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	/134603	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\TRL REPS	Replace curtain rollers.			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	/134603	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS Service	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	/134603	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 29			######## 628560		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BORDER BANDAG PTY LTD	TRAILER
T615	Wodonga - Workshop	Chassis\AIR LEAK	MAJOR AIR LEAK		Replace ifrm airbag	######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Susp\AIR LEAK	TRI AIR NOT STAYING IN AND MAKING TRIP HORRIBLE, PIG ROOTING ALL THE WAY SMASHING ME IN THE BACK WHOLE TRIP- DID PUMP UP, BUT OBVIOUSLY LEAKING.			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		######## 628560		PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Chassis\SCALES	Scales Not Working Correctly			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS Service	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\TP>11+12	Tyres\TP>11+12 (31-32)			######## 628560		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BORDER BANDAG PTY LTD	TRAILER
					-wiring repaired in A trailer right hand side combination light + lights check done											
T615	Wodonga - Workshop	Body\SELECT P&W	Sort out electrical fault in trailer lights.		-sins covered in trailer aluas	######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS Service	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\TOOLBOX	Toolbox Door to be repaired/replace hinge's.			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Susp\AIR LEAK	Tri has No air, even after building up Air, they lose air very quickly.			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
					Travel from Callaway Workshops To Site At Doughty s Rd Truggiana Customer Reports Brakes Locked On Travel											
					To Site											
			Brakes Won't Release.		Found female Rear Suzi Air line Hose Clamp Loose Tighten Loss Hose Clamp test operation All Ok											
T615	Wodonga - Workshop	Brakes\BREAKDOWN	(Callaway Diesel P/O: WW0862560		Return To Callaway Workshoos	######## 628560		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	CALLAWAY DIESEL	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS D Service	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Susp\AIR BAG	TRI AIRBAGS VERY LOW & SCALES WON'T ACTUALLY TELL TRUTH.			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Susp\HCV	AIRBAGS NOT INFLATING.		Found pressure protection valve blocked. Replaced blocked 70psi valve with new 65psi valve. Tested operation and confirmed fault repaired.	######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS D Service	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\TRL REPS	Repair holes in curtains.			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT 11			######## 628560		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUSPHERES	TRAILER
T615	Wodonga - Workshop	Tyres\TP>10	Tyres\TP>10			######## 628560		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUSPHERES	TRAILER
T615	Wodonga - Workshop	Tyres\TP>6	Tyres\TP>6			######## 628560		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUSPHERES	TRAILER
T615	Wodonga - Workshop	Tyres\TP>8	Tyres\TP>8			######## 628560		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUSPHERES	TRAILER
T615	Wodonga - Workshop	Tyres\TP>4	Tyres\TP>4			######## 628560		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUSPHERES	TRAILER
T615	Wodonga - Workshop	Tyres\TP>2	Tyres\TP>2			######## 628560		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUSPHERES	TRAILER
T615	Wodonga - Workshop	Elect\TRL LIGHTS	TRAILER PLUG NOT FITTED PROPERLY.		BREAKDOWN - Inspected and found exposed wires inside of plug and LH indicator wire had rubbed inside of plugged and shorted out. Plug was new. Trailer serviced within the week. Rewired plug and tested to confirm repairs complete	######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS D Service	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\SELECT P&W	Replace ABS Plug.			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	/134603	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Elect\INDICATORS	REAR RIGHT FLASHER LIGHT BROKEN.			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	/134603	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	/134603	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Elect\SLED COIL	No ABS PLUG/ Right Hand Indicator not working.			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Chassis\SLED COIL	driver curtain ratchet keeps catching airlines			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\MUDGUARDS	MUDGUARD DAMAGED.			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS	VehServiceUDS		######## 628560		Service	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Tyres\RUN OUT	12			######## 628560		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	BEAUSPHERES	TRAILER
T615	Wodonga - Workshop	Body\TRL REPS	L/H Curtain Ratchet Faulty			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	Body\TRL REPS	RATCHET PASSENGER SIDE CURTAIN TIGHTENER BROKEN.			######## 628560		Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHB	074952	Wodonga Workshop	TRAILER
T615	Wodonga - Workshop	VehServiceUDS	VehServiceUDS	VehServiceUDS		######## 628560		Service

TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		########	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Elect/TRL LIGHTS	RH clearance light missing			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		########	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Workshop(MOVE ASSET	move set			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes(BRK RELINE	reline			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(TP9+10	Supply and fit 4 tyres			######## 498890	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(TP11+12	Tyre Position 11 + 12			######## 498890	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Drive/un(WHEEL BRGS	need adjustment done			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Susp(SUSPANSION	bush's have movement			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes(BRK RELINE	Full Reline		TCTC supply Brake Drums & Shoe Kits	########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 492247	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Elect/TRL LIGHTS	RH clearance light missing			######## 492247	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 492247	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(UNUDGUARDS	needs new mudguard RHS			########	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Workshop(MOVE ASSET	check for services moving trailers			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(TP1+2	REPLACE 2 TYRES			######## 476658	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(UNUDGUARDS	RH rear guard missing			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(BLOWOUTS	blown tyre at glenfiel		beaunpaires Poww061662	########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
			R/H/R inner and outter tyre blowout												
			Beaunpairs to attend to breakdown												
TIGS	Wodonga - Workshop	Tyres(BLOWOUTS	central west diesel to attend for mechanical reasins (euard and rear indicator)		central west diesel P/O WWD61461	########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body(UNMAGE	side rails bent and broken			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body/TRL WALL	right rear corner baits broken roof			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S	ran out of time	########	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Susp(SUSPANSION	high control valve		yatata kenworth Poww062886	########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 451520	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 451520	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(DAMAGE	crash bar right side minimal damage			######## 451520	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body(DAMAGE	roof repairs			######## 451520	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(AH Callout	tyre failure			######## 43846	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body	Fit new guard R/Centre		unhook and hook A&B Trailers as well	######## 430536	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 427496	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(CHAS CRACK	Cracks in cross bracing under T/table area			######## 427496	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body(DAMAGE	side rails bent and broken			######## 427496	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(CROSS MAR	small crack bottom of cross brace			######## 427496	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body(DAMAGE	all safety rails bent and damaged			######## 427496	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Susp(SUSPANSION	bush's have movement			######## 427496	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 427496	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body/TRL REPS	replaced RH front curtain ratch			######## 422769	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(VTYMENT	Job Added From Invoice			######## 417149	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(RETREAD	Job Added From Invoice			######## 417149	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(SCRAP TYRE	Job Added From Invoice			######## 417149	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Drive/un(WHEEL BRGS	need adjustment done			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Susp(SHOCK ABS	RHM shock starting to weep		previously done	########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(TP9	Tyre Position 9		replaced	######## 429846	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body(TRAIL MANI	Rhrf curtain ratchet		RH rear wall mounts bolts missing LHS cracked	######## 427496	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
					move trailers										
TIGS	Wodonga - Workshop	Body/TRL REPS	bolts are missing from the roof driver-side rear		reasin to wall done and reasin to cross brace while esine	########	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body/TRL REPS	please fix or replace driver side curtain ratchet		previously done	######## 427496	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		########	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Insp(ANN INSP	Annual Inspection As Per Checklist	Insp(ANN INSP		######## 417149	PreventativeMaintenance	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Workshop(MOVE ASSET	organise service clean up shed floor			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body(LIGHTS	LHR on markers			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body(DAMAGE	all safety rails bent and damaged			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body(CHASSEL BRGS	multiple bearings need adjusting			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Susp(SUSPANSION	bush's have movement			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body	Job Added From Invoice			######## 0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body\Pogo	upwright repars		removed upright straightened remounted	########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 401755	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body/TRL REPS	bolts are missing from the roof driver-side rear			######## 401755	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body/TRL REPS	please fix or replace driver side curtain ratchet		parts on order	######## 401755	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 401755	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body(TANK MANI	Rhrf curtain ratchet			######## 401755	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(SLUD COIL	suzi lines leaking			######## 401755	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(CROSS MAR	small crack bottom of cross brace			######## 401755	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body/TRL REPS	front right roof pole bent badly			######## 401755	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	service	VehServicel2S		######## 401755	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body/TRL REPS	Job Added From Invoice			######## 0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 381633	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Elect\ELECT P&W	replace light plugs			######## 381633	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 381633	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 362274	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(CHAS CRACK	Cracks in cross bracing under T/table area			######## 362274	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Drive/un(WHEEL BRGS	need adjustment done			######## 362274	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Susp(SHOCK ABS	RHM shock starting to weep			######## 362274	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Elect\ELECT P&W	replace light plugs			######## 362274	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body(DAMAGE	side rails bent and broken			######## 362274	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 362274	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Elect\ELECT P&W	repair electrical socket			######## 362274	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(VTYMENT	Job Added From Invoice			######## 361814	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(CLEANSKIN	Job Added From Invoice			######## 361814	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(DRV TYRES	R front Duels			######## 361814	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 361814	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(CHAS CRACK	Cracks in cross bracing under T/table area			######## 361814	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Drive/un(WHEEL BRGS	need adjustment done			######## 361814	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(FIFTH WHEE	x bracing under T/table		As per #288346	######## 361814	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Drive/un(WHEEL BRGS	continue to monitor wear			######## 361814	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Susp(SUSPANSION	Cross supports cracking through centre		As per #288346	######## 361814	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 361814	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Susp(SHOCK ABS	RHM shock starting to weep			######## 361814	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Workshop(CLEAN	Redid service sheets for TIGS/616 as it wasn't printed till after service was completed			######## 361814	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Workshop(MOVE ASSET	Picked up next service			######## 361814	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 331518	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(DRV TYRES	R front Duels			######## 331518	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Susp(SUSPANSION	Cross supports cracking through centre			######## 331518	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 331518	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(FREE CHECK	Job Added From Invoice			######## 334023	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 296045	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 296045	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 277444	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(CHAS CRACK	cracks in cross bracing under T/table area			######## 277444	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(TP11	front L and middle left outer's worn		previous job	######## 277444	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Drive/un(WHEEL BRGS	need adjustment done		warranty job	######## 277444	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Elect\ELECT P&W	the electrical lead and abs lead have worn thorugh on the checker plate. I have patched the leads in 3 spots on each. They need something around them to protect them		wrapped with lay flat now	######## 277444	Fault	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 277444	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(FIFTH WHEE	x bracing under T/table			######## 277444	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Drive/un(WHEEL BRGS	continue to monitor wear			######## 277444	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Elect\HOUSKEEP	cover airlines and power leads with layflat			######## 277444	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(LOAD STOCK	Job Added From Invoice			######## 264344	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(VTYMENT	Job Added From Invoice			######## 264344	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(RETREAD	Job Added From Invoice			######## 264344	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 264344	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(TP19	RHM inner tyre		previously done	######## 264344	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(CHAS CRACK	cracks in cross bracing under T/table area			######## 264344	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 264344	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(TP11	front L and middle left outer's worn			######## 264344	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Drive/un(WHEEL BRGS	need adjustment done			######## 264344	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Susp(SHOCK ABS	loose shock			######## 264344	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 251052	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(CHAS CRACK	cracks in cross bracing under T/table area			######## 251052	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 251052	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(LOAD STOCK	Job Added From Invoice			######## 10	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(VTYMENT	Job Added From Invoice			######## 10	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(RETREAD	Job Added From Invoice			######## 10	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 237572	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 237572	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(TP19	RHM inner tyre			######## 237572	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Chassis(CHAS CRACK	cracks in cross bracing under T/table area			######## 237572	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Body\FIFTH WHEE	adjusted T/table			######## 237572	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(LOAD STOCK	Job Added From Invoice			######## 223411	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(VTYMENT	Job Added From Invoice			######## 223411	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(RETREAD	Job Added From Invoice			######## 223411	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(VTYMENT	Job Added From Invoice			######## 217405	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(CLEANSKIN	Job Added From Invoice			######## 217405	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(AH Callout	Job Added From Invoice			######## 217405	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(SCRAP TYRE	Job Added From Invoice			######## 217405	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Insp(ANN INSP	carry out annual inspection			######## 223411	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 223411	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	/074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(AXLURE	rear axle ad replace		previously done	######## 223411	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Drive/un(WHEEL BRGS	Rear axle needs adjusting		checked - no they don't	######## 223411	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		######## 223411	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(VTYMENT	Job Added From Invoice			######## 204878	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Tyres(CLEANSKIN	Job Added From Invoice			######## 204878	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 223411	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		########	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			######## 217405	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		########	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	VehServicel2S	VehServicel2S		########	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			########	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Workshop	VehServicel2S	D Service As Per Attached Checklist	VehServicel2S		########	Service	Completed	FL Green Distribution	Tilner	Wodonga	LHR	074952	Wodonga Workshop	TRAILER
TIGS	Wodonga - Worksh

T615	Wodonga - Workshop	Tyres	Job Added From Invoice			########	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER			
T615	Wodonga - Workshop	Tyres\VITMENT	Job Added From Invoice			########	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER			
T615	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			########	0	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER			
T615	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			########		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER			
T615	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		########		Service	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER			
T615	Wodonga - Workshop	Body\TOOLBOX	remove hinges from old toolbox and prep new toolbox for paint *toolbox sent to TCTC for paint. as we could not source correct colour			########		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER			
T615	Wodonga - Workshop	Workshop\MOVE ASSET	pick up from TCTC			########		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER			
T615	Wodonga - Workshop	Workshop\MOVE ASSET	drop at TCTC			########		Repair	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER			
T615	Wodonga - Workshop	Susp\AIR FITTIN	replaced Tpiece air line			########	7997	Repair	Completed	FL Green Distribution	Tilner	Wodonga	LH8	074952	Wodonga Workshop	TRAILER			