

03871872

PERIODIC MANDATORY VEHICLE  
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspections  
Box 45064 Regent P  
Winnipeg, MB, R2C  
1-204-985-0920

DECAL  
VOID WITHOUT DECAL

Manitoba  
A861505

Date Inspection Started  
17 03 25  
DAY MO. YR.

Date Inspection Completed  
20 03 25  
DAY MO. YR.

Inspection Expiry Date  
31 03 26  
DAY MO. YR.

Station Number  
A5101

Station Name  
Valley Farm & B...

City

Mechanic Number  
A10567

Mechanic Signature  
Z. J. Taylor

Station Phone Number  
842 5113

Vehicle Owner  
John Brown

Address  
500 21-16-26 R. Hb MB R0M 0C0

City

Province

Postal Code  
R0M 0C0

Phone  
842 3617

☒ Pass/Safe Vehicle

☒ Fail/Unsafe Vehicle

☐ Fail/Hazardous

Licence Number  
H5A753

Prov.  
MB

NSC #  
9922015

Odometer Reading  
701351

Odom. Type  
☒ km ☐ mi

Vehicle Identification Number  
5K14ALCV87PV11210

Make  
JST

Model  
1190

Year  
2007

Unit #

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR 14000 KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X	X	Section 1 - Power Train: Defects (if any) 12h exhaust muffler leaking right side
X	X	Section 2 Suspension: Defects (if any) 12h shock absorbers - both lower axle / both side
X		Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection
X		Section 4 - Steering: Defects (if any)
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
X	X	Section 6 - Lamps: Defects (if any) 6h main light not working right side
X		Section 7 - Electrical System: Defects (if any)
X	X	Section 8 - Body: Defects (if any) 3rd floor door right side
X	X	Section 9 - Tire & Wheel: Defects (if any) 7h low tire pressures
X		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1	12	12			90	95		
2	19	18	19	19	60	90	105	95
3	18	18	19	18	100	95	95	90
4								
5								

- THIS INSPECTION IS NOT A WARRANTY -  
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: \_\_\_\_\_ Date: \_\_\_\_\_  
Signature

FVS0022-01-(R-09/15)

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION

Ce document peut être obtenu en français sur demande.