EquipmentName	Workshop	CodeAndSubCode	Description	Schedule	CompletionComments	DateDone	DistanceDone	Worktype	Workstate	EquipmentOwner	MaintenanceGroup	Location	Division	Rego	Supplier	EquipmentType
T616	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		17/07/2026	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	Brake Reline			13/06/2026	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	completed by AM JW Fleet/ Rego: T616-074953 Carried out inspection of curtains as per customers request. Upon Inspection found multiple tears in pocket, found tear/ hole behind buckle, found front tensioner loose.. Carried out repair of tears in pocket, Removed buckle and hook to repair tear behind buckle and replaced new black rave hook	12/06/2026	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\DAMAGE	Body\DAMAGE			05/05/2026	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	ATTARD F & J & SONS PTY LTD	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Reline needed asap	03/04/2026	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Front Upright Not locking in.			03/04/2026	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\MUDGUARDS	HOLES IN GUARDS.		2 left unable to finish	03/04/2026	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	RIP CURTAIN BUCKLE FALLING OFF NEEDS REPAIR PATCH.		Pending	03/04/2026	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS	Reline needed asap	27/02/2026	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)		AIR HOSE BREAKDOWN AND FLAT SPOTTED EVERY TYRE. WIRE COMING OUT OF ALL 12. MECHANICS KNOW ABOUT THIS JOB	28/01/2026	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BORDER BANDAG PTY LTD	TRAILER
T616	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4 (23-24)		AIR HOSE BREAKDOWN AND FLAT SPOTTED EVERY TYRE. WIRE COMING OUT OF ALL 12. MECHANICS KNOW ABOUT THIS JOB	28/01/2026	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BORDER BANDAG PTY LTD	TRAILER
T616	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2 (21-22)		AIR HOSE BREAKDOWN AND FLAT SPOTTED EVERY TYRE. WIRE COMING OUT OF ALL 12. MECHANICS KNOW ABOUT THIS JOB	28/01/2026	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BORDER BANDAG PTY LTD	TRAILER
T616	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)		AIR HOSE BREAKDOWN AND FLAT SPOTTED EVERY TYRE. WIRE COMING OUT OF ALL 12. MECHANICS KNOW ABOUT THIS JOB	28/01/2026	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BORDER BANDAG PTY LTD	TRAILER
T616	Wodonga - Workshop	Tyres\TP7+8	Tyres\TP7+8 (27-28)		AIR HOSE BREAKDOWN AND FLAT SPOTTED EVERY TYRE. WIRE COMING OUT OF ALL 12. MECHANICS KNOW ABOUT THIS JOB	28/01/2026	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BORDER BANDAG PTY LTD	TRAILER
T616	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)		AIR HOSE BREAKDOWN AND FLAT SPOTTED EVERY TYRE. WIRE COMING OUT OF ALL 12. MECHANICS KNOW ABOUT THIS JOB	28/01/2026	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BORDER BANDAG PTY LTD	TRAILER
T616	Wodonga - Workshop	Susp\AIR LEAK	Diagnosis and repair HCV		Airline had blockage cleared line tested	13/01/2026	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		05/01/2026	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Front Right Curtain Rachet Handle Needs Replacing			05/01/2026	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	Serviced Overdue Last Serviced 21/11/25			05/01/2026	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		21/11/2025	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	RHS REAR CURTAIN BUCKLE			21/11/2025	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		29/10/2025	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12 (31-32)			28/10/2025	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BORDER BANDAG PTY LTD	TRAILER
T616	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6 (25-26)			28/10/2025	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BORDER BANDAG PTY LTD	TRAILER
T616	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 27			28/10/2025	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BORDER BANDAG PTY LTD	TRAILER
T616	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 (29-30)			28/10/2025	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BORDER BANDAG PTY LTD	TRAILER
T616	Wodonga - Workshop	Tyres\RUN OUT	Tyres\RUN OUT POS 29			22/09/2025	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BORDER BANDAG PTY LTD -3	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	L/H Handle For Curtain Tighter		REPLACED HANDLE	25/08/2025	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection	Insp\ANN INSP		16/08/2025	627885	PreventativeMaintenance	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		16/08/2025	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\DAMAGE	Remove damaged left side Crash Bars.			15/07/2025	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS D Service Repair Air Leak, Brakes Locked On.	VehService\DS		15/07/2025	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\AIR LEAK	(Callaway Diesel P/O: WW095600)			15/07/2025	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	CALLAWAY DIESEL	TRAILER
T616	Wodonga - Workshop	Chassis\SCALES	Scales Not Working Correctly			21/06/2025	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\WGHT GAUGE	Replace weight scale gauge.			21/06/2025	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2		SIDE WALL DAMAGE	17/06/2025	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BORDER BANDAG PTY LTD	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		31/05/2025	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\TRL LEGS	HANDLE TO LEGS BROKEN & IS IN TOOLBOX.		Previously done Supply load restraint buckle	31/05/2025	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Body\TRL REPS		Supply double bottom strap	28/04/2025	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	IFIX TRUCK CURTAINS	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		24/04/2025	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Repair small holes in curtains.			15/04/2025	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Replace front right curtain ratchet.			15/04/2025	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS D Service	VehService\DS		12/03/2025	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		22/02/2025	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\DAMAGE	Replace left curtain ratchet.			22/02/2025	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\MUDGUARDS	1x NEW MUDGUARD- MUDFLAP LEFT SIDE BACK AXLE.			22/02/2025	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		23/01/2025	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\MUDGUARDS	MUDGUARDS DAMAGED.			03/12/2024	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		03/12/2024	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			19/11/2024	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BEAUREPAIRES	TRAILER
T616	Wodonga - Workshop	Chassis\MUDGUARDS	Repair Rear Guards Both Sides			12/11/2024	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\HCV	Check Ride Height			12/11/2024	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\AIR BAG	Replace Blown Air Bag Rear Axle. (Mechanika Motors P/O: WW090026)			11/11/2024	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	MECHANIKA MOTORS PTL LTD	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		18/10/2024	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP12	Tyres\TP12			08/10/2024	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BEAUREPAIRES	TRAILER
T616	Wodonga - Workshop	Tyres\TP3+4	Tyres\TP3+4			08/10/2024	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BEAUREPAIRES	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	Brake Reline.			20/09/2024	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		17/09/2024	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\MUDGUARDS	Replace right middle guard.			14/08/2024	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		08/08/2024	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	VehService\DS	VehService\DS		16/07/2024	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	CURTAIN AND REMOVE SIDE RAIL BRACKETS.			16/07/2024	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\MUDGUARDS	REPLACE FRONT & MIDDLE GUARDS/REPAIR.			16/07/2024	627885	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\BLOWOUTS	tyre blew out and damaged guard			29/06/2024	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BEAUREPAIRES	TRAILER
T616	Wodonga - Workshop	Tyres\TP1+2	Tyres\TP1+2			04/06/2024	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BEAUREPAIRES	TRAILER
T616	Wodonga - Workshop	Tyres\TP11+12	Tyres\TP11+12			04/06/2024	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BEAUREPAIRES	TRAILER
T616	Wodonga - Workshop	Body\MUDGUARDS	Body\MUDGUARDS			04/06/2024	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP5+6	Tyres\TP5+6			28/05/2024	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BEAUREPAIRES	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service	VehService\DS	303307	27/05/2024	627885	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP9+10	Tyres\TP9+10 Blow out			24/05/2024	627885	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	BEAUREPAIRES	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			27/04/2024	285628	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\HCV	CHECK RIDE HEIGHT CONTROL.			27/04/2024	285628	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		27/04/2024	285628	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	DrivLine\WHEEL BRGS	WHEEL BEARINGS NEED ADJUSTING. WARRANTY.			27/04/2024	285628	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			24/03/2024		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\CHAS CRACK	CRACKED CHASSIS WEBBING.			24/03/2024		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	REPLACED CLEARANCE LIGHTS AND CURTAIN BUCKLES.	24/03/2024		Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP03	Tyre Position 3			19/03/2024		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Albury Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/03/2024		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	CURTAIN ROLLERS STICKING.			10/03/2024		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	WATER LEAKING IN BACK OF TRAILER.			10/03/2024		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/03/2024		Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\STRAPS	RIGHT SIDE RATCHET HANDLE BROKEN.			20/02/2024	242670	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/02/2024	234552	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/02/2024	234552	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Unknown	SERVICE.			03/02/2024	234552	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/01/2024		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/01/2024		Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/12/2023	210819	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/12/2023	210819	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	RELINE RF.			07/12/2023	210819	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP7+8	Tyre Position 7 + 8			19/09/2023		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Albury Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/09/2023	197823	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	CURTAIN ROLLERS STICKING.			08/09/2023	197823	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/09/2023	197823	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	RELINE RF.			08/09/2023	197823	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\Punct	9			08/09/2023		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Albury Workshop	TRAILER
T616	Myrtleford - Workshop	Body\PANELS	CHECKED OVER. ADJUSTED BAR. TIGHTENED LOOSE BOLTS.			02/08/2023		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Myrtleford Workshop	TRAILER
T616	Myrtleford - Workshop	Chassis\FIFTH WHEE	REPLACED TURNTABLE TOP AND BUSHES.			02/08/2023		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Myrtleford Workshop	TRAILER
T616	Myrtleford - Workshop	Chassis\AMB ARM	REPLACED UMBILICAL ARM BEARINGS.			02/08/2023		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Myrtleford Workshop	TRAILER
T616	Myrtleford - Workshop	Brakes\AIR FITTIN	REPLACED AIR FITTINGS.			02/08/2023		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Myrtleford Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/05/2023	157919	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/05/2023	157919	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		26/05/2023	157919	PreventativeMaintenance	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	RELINE RF.			26/05/2023	157919	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	LHS CURTAIN WINDER IS BROKEN. Replace L/H Curtain Rachet (Albury Truck & Trailer)		REPLACED RATCHET.	18/05/2023		Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\STRAPS	Purchase Order Number: WW077227			15/03/2023		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP5+6	Tyre Position 5 + 6			23/02/2023		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Albury Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP9+10	Tyre Position 9 + 10			16/01/2023		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Albury Workshop	TRAILER

T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/01/2023		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	CURTAIN ROLLERS STICKING.			15/01/2023		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/01/2023		Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/12/2022		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	REPLACE RIGHT CURTAIN RATCHET HANDLE.			10/12/2022		Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		10/12/2022		Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	CURTAIN ROLLERS STICKING.			10/12/2022		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP01	Tyre Position 1			08/11/2022		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Albury Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/10/2022	88507	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/10/2022	88507	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP1+2	supply and fit 4 tyres			30/09/2022		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP3+4	Tyre Position 3 + 4			30/09/2022		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	REMOVED AND PATCHED LH CURTAIN. REPLACED ALL ROLLERS. REPAIRED LR UPRIGHT. HUNG CURTAIN.			23/08/2022	73198	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			13/08/2022	70046	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		13/08/2022	70046	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	RIP IN LEFT CURTAIN.		REPAIRED/ CABLE TIED RIP.	13/08/2022	69350	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	DrivLine\WHEEL BRGS	CHECKED LR FOR GREASE AND OIL.			19/07/2022		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/06/2022	47253	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/06/2022	47253	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Elect\INDICATORS	RH indicator 8 to 12			21/06/2022	47253	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\ROTATION	7 to 11			26/05/2022		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/05/2022	41589	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/05/2022	41589	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			15/04/2022	27919	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\SKID PLATE	all gussets on side of skid plate cracked			15/04/2022	27919	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Left hand rear corner ripped at top of trailer.			15/04/2022	27919	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\SKID PLATE	MULTIPLE GUSSETS CRACKED NEAR SKID PLATE BOTH SIDES.			15/04/2022	27919	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Rear left hand side curtain torn at the top.			15/04/2022	27919	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Rear Left Top curtain ripped.			15/04/2022	27919	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	P/S REAR CURTAIN POLE NEEDS TO BE STRAIGHTENED OR REPLACED.			15/04/2022	27919	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		15/04/2022	27919	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Unknown	SERVICE			15/04/2022	27919	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\SHOCK ABS	REPLACED RM SHOCK.			15/04/2022	27919	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP9+10	supply and fit 2 tyre, pos 1 flipped on rim			15/04/2022		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/03/2022	23659	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/03/2022	23659	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			21/01/2022	4629	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		21/01/2022	4629	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			18/12/2021	1	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\HOUSEKEEP	Fit bump rubbers to rear of trailer.			18/12/2021	1	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		18/12/2021	1	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\SKID PLATE	MULTIPLE GUSSETS CRACKED NEAR SKID PLATE BOTH SIDES.			18/12/2021	1	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\AIR FITTIN	REPLACED FITTINGS FROM A TO B TRAILER. REPLACED HUBBO.			18/12/2021	1	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check			02/12/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\PRES CHECK	Pressure Check			16/11/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/11/2021	537	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL WALL	rear left corner leak water, roof			12/11/2021	537	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\HOUSEKEEP	Fit bump rubbers to rear of trailer.			12/11/2021	537	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\HOUSEKEEP	Fit bump rubbers to rear of trailers		#360330	12/11/2021	537	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/11/2021	537	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		12/11/2021	537	PreventativeMaintenance	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\Re-Tor	POS 1 & 2			22/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\Re-Tor	POS 11,12			22/10/2021	312801	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP3+4	supply and fit 2 tyres			22/10/2021	593884	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Albury - Workshop	Tyres\TP5+6	supply and fit 2 tyres; rotate POS 5 to POS 1			22/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP03	RF inner tyre worn.		PREVIOUSLY DONE	08/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\MUDGUARDS	1 x Guard needs replacing.			08/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Left hand rear corner ripped at top of trailer.			08/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL WALL	rear left corner leak water, roof			08/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\MUDGUARDS	Worn Mudguards.			08/10/2021		Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\AIR LEAK	Air leak at the Tri			08/10/2021		Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Rear left hand side pole bent.			08/10/2021		Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/10/2021		Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Rear left hand side curtain torn at the top.			08/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\HOUSEKEEP	Fit bump rubbers to rear of trailer. ABS Light comes on truck dash comes on when lead is plugged in.		Travel to Greenfreight and return. Inspect codes for B & A trailer. Found power and low air codes and advise	08/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\ABS	Also Brakes lock up at slightest touch of pedal or handbrake.		Greg. Clear codes, unable to fault further. Advise test drive needed.	08/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\MUDGUARDS	Worn Mudguards.			08/10/2021		Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\AIR LEAK	Air Leak at Tri			08/10/2021		Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Rear left hand side curtain pole bent.			08/10/2021		Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Rear Left Top curtain ripped.			08/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\HOUSEKEEP	Fit bump rubbers to rear of trailers Travel to Greenfreight and return. Inspect codes for B & A trailer. Found power and low air codes and advise			08/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\EBS FAULTS	Greg. Clear codes, unable to fault further. Advise test drive needed.			08/10/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\Re-Tor	POS 5,6,7,8			24/09/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP11+12	supply and fit 2 tyres			21/09/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP10	fit runout			21/09/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP3+4	supply and fit 2 tyres			02/09/2021	29388	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			02/09/2021	29353	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP03	RF inner tyre worn.			02/09/2021	29353	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL WALL	rear left corner leak water, roof			02/09/2021	29353	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		02/09/2021	29353	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\MUDGUARDS	1 x Guard needs replacing.			02/09/2021	29353	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Left hand rear corner ripped at top of trailer.			02/09/2021	29353	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\DAMAGE	safety rails bent and damaged			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\DAMAGE	crash rail is bent			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL FLOOR	rivets missing			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\SKID PLATE	all gussets on side of skid plate cracked			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\WHEEL BRGS	LR needs adjusting (warranty)			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\SUSPENSION	bush's have movement			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		29/06/2021	27495	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\ELECT P&W	R. side wall one clearance light is loose			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\DAMAGE	safety rails damaged rear left corner leak water, roof			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL WALL	Curtain needs to be removed for repair to be done properly.			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP03	RF inner tyre worn.			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Right Hand Three buckles is missing.		Replaced buckle cut mono bolt cut as well.	29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Workshop\CLEAN	Clean floor before start service			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Workshop\MOVE ASSET	Hook up trailers			29/06/2021	27495	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/05/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/05/2021		Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP04	Fit Runout			05/05/2021	24053	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body	Job Added From Invoice			26/04/2021	0	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	RHR brakes hanging out over 15mm	15/04/2021	17420	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		unable to do repairs due to injury	15/04/2021	17420	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\SUSPENSION	bush's have movement			15/04/2021	17420	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FAILURE	LHM duels need replacing		checked	15/04/2021	17420	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres	LH outer		checked	15/04/2021	17420	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\ELECT P&W	R. side wall one clearance light is loose			15/04/2021	17420	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\DAMAGE	safety rails damaged			15/04/2021	17420	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Workshop\MOVE ASSET	Move trailers for repairs			15/04/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP9+10	Supply and fit 4 tyres			24/03/2021	9983	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP11+12	Tyre Position 11 + 12			24/03/2021	9983	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	reline due soon middle and front axle			24/03/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	front axle due for reline			24/03/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	due for reline - front axle			24/03/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	need reline			24/03/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers			23/03/2021	9983	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Workshop\CLEAN	sort out ajob as pool hand over given			23/03/2021	9983	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\WHEEL ALGN	start reline mid and rear axle		Jack and place on stands	23/03/2021	9983	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/03/2021	4061	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER

T616	Wodonga - Workshop	DrivLine\WHEEL BRGS	multiple need adjusting			12/03/2021	4061	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\WHEEL BRGS	all bearings need adjusting			12/03/2021	4061	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/03/2021	4061	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	brake replacement front axle			12/03/2021	4061	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Workshop\CLEAN	clean up			12/03/2021	4061	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	reline due 12mm-12mm Replaced 1 tyre Extra time on job trying to get inside wheel off, Jammed on Hub could not get it off so pumped up tyre and tole			12/03/2021	4061	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TPOS	driver on phone. He was ok with it			07/03/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\WINCH/STRP	replace binder			18/02/2021	475408	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\TP12	fit a run out			18/02/2021	475406	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice			01/02/2021	294001	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			01/02/2021	294001	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			01/02/2021	294001	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\AH Callout	Job Added From Invoice			01/02/2021	294001	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\SCRAP TYRE	Job Added From Invoice			01/02/2021	294001	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			28/01/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	reline due soon middle and front axle			28/01/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\WHEEL BRGS	all bearings need adjusting			28/01/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL FLOOR	rivets missing			28/01/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	front axle due for reline			28/01/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\SKID PLATE	all gussets on side of skid plate cracked			28/01/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\SUSPENSION	bush's have movement			28/01/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	due for reline - front axle			28/01/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FAILURE	LHM duels need replacing			28/01/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres	LH outer			28/01/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\WHEEL BRGS	LR needs adjusting (warranty)			28/01/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	need reline			28/01/2021		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	ran out of time	28/01/2021		Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			30/12/2020	451312	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			30/12/2020	451312	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		need's reline	20/12/2020	451312	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\SHOCK ABS	RHF shock leaking		previously done	20/12/2020	451312	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FAILURE	LHM duels need replacing			20/12/2020	451312	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		20/12/2020	451312	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres	LH outer			20/12/2020	451312	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\DAMAGE	crash rail is bent			20/12/2020	451312	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\WHEEL BRGS	LR needs adjusting (warranty)			20/12/2020	451312	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	need reline			20/12/2020	451312	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\DAMAGE	roof repairs			19/12/2020	451312	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			11/11/2020	428328	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	front axle due for reline			11/11/2020	428328	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\DAMAGE	safety rails bent and damaged			11/11/2020	428328	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\SKID PLATE	all gussets on side of skid plate cracked			11/11/2020	428328	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\SUSPENSION	bush's have movement			11/11/2020	428328	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	due for reline - front axle			11/11/2020	428328	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		11/11/2020	428328	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			29/10/2020	418029	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			29/10/2020	418029	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job		on 2mm LH 3mm RH	08/10/2020	415980	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	front axle due for reline		due	08/10/2020	415980	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/10/2020	415980	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		08/10/2020	415980	PreventativeMaintenance	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\DAMAGE	safety rails bent and damaged			08/10/2020	415980	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\SKID PLATE	all gussets on side of skid plate cracked			08/10/2020	415980	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\WHEEL BRGS	all bearings need adjusting			08/10/2020	415980	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL FLOOR	rivets missing			08/10/2020	415980	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\CHAS CRACK	cross brace broken at rear axle			08/10/2020	415980	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\SUSPENSION	bush's have movement			08/10/2020	415980	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	due for reline - front axle			08/10/2020	415980	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/09/2020	402709	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\MUDGUARDS	Replace L/Front guard			26/09/2020	402709	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FAILURE	LHM duels need replacing			26/09/2020	402709	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\MUDGUARDS	guard needs replacing			26/09/2020	402709	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\AIR FITTIN	couplinks leaking			26/09/2020	402709	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	front axle due for reline			26/09/2020	402709	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\MUDGUARDS	left front guards broken			26/09/2020	402709	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	service	VehService\DS		26/09/2020	402709	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/09/2020	402709	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body	Job Added From Invoice			19/09/2020	0	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\MUDGUARDS	Job Added From Invoice			19/09/2020	0	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	Job Added From Invoice			29/08/2020	0	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			14/08/2020	382543	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			14/08/2020	382543	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/08/2020	382475	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	driver-side front ratchet is broken			08/08/2020	382475	Fault	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/08/2020	382475	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	replaced rh curtain ratchet on 616			09/07/2020		Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			08/07/2020	363363	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\SHOCK ABS	RHF shock leaking			08/07/2020	363363	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes\BRK RELINE	reline due soon middle and front axle			08/07/2020	363363	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		08/07/2020	363363	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\SHOCK ABS	RHF shock leaking			30/05/2020	342967	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			30/05/2020	342967	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TOOLBOX	safety rail on tool box loose			30/05/2020	342967	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	DrivLine\WHEEL BRGS	multiple need adjusting			30/05/2020	342967	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\CROSS MBR	Cracks in crossmember			30/05/2020	342967	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\SUSPENSION	Angle cross brace broken weld			30/05/2020	342967	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		30/05/2020	342967	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\AIR LEAK	repair air leaks			30/05/2020	342967	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			10/05/2020	332418	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\SUSPENSION	Angle cross brace broken weld			10/05/2020	332418	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	(andrew)	10/05/2020	332418	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	remove upright out of 209 for tr600		install into trailer (was too short)	23/04/2020	537770	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\PRES CHECK	Job Added From Invoice			13/03/2020	295225	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/03/2020	295251	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/03/2020	295251	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\CROSS MBR	Cracks in crossmember			06/03/2020	295251	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice			13/02/2020	27909	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			13/02/2020	27909	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\RETREAD	Job Added From Invoice			13/02/2020	27909	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/01/2020	278722	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/01/2020	278722	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TOOLBOX	safety rail on tool box loose			31/01/2020	278722	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	DrivLine\WHEEL BRGS	multiple need adjusting			31/01/2020	278722	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/12/2019	265544	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/12/2019	265544	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			04/12/2019	252666	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		04/12/2019	252666	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\CHAS CRACK	Diagonal X-member needs weld above centre left axle		Welded by Matt - Monitor	04/12/2019	252666	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\CASE STOCK	Job Added From Invoice			23/11/2019	238810	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			23/11/2019	238810	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			23/11/2019	238810	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			07/11/2019	238811	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres	Rear axle			07/11/2019	238811	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	DrivLine\WHEEL BRGS	LHM and front axle need adjusting		inspected ok	07/11/2019	238811	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		07/11/2019	238811	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			12/10/2019	224657	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FAILURE	rear axle x4 to be replaced		replaced previous	12/10/2019	224657	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres	Rear axle			12/10/2019	224657	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		12/10/2019	224657	Service	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	DrivLine\WHEEL BRGS	LHM and front axle need adjusting			12/10/2019	224657	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FITMENT	Job Added From Invoice			29/09/2019	204878	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\CLEANSKIN	Job Added From Invoice			29/09/2019	204878	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\DAMAGE	replaced l/Front ratchet			21/09/2019	213112	Repair	Completed	FL Green Distribution	Tlner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER

T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			03/09/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres	Rear axle			03/09/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		03/09/2019		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Insp\ANN INSP	Annual Inspection As Per Checklist	Insp\ANN INSP		03/09/2019	200711	PreventativeMaintenance	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\FAILURE	rear axle x4 to be replaced			03/09/2019	200711	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes				03/09/2019	200711	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			31/07/2019		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		31/07/2019		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			06/07/2019	171590	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\CHAS CRACK	gusset cracked right side		Previously completed	06/07/2019	171590	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\CHN/RLR/MN	needs RHF ratchet replaced as it is broken			06/07/2019	171590	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\HOUSEKEEP	trailer need wash as some grub has wiped grease on curtains. trailer need wash as some grab has wiped grease on		Driver to complete	06/07/2019	171590	Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		06/07/2019	171590	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	modify side crash rails and fit angle carrier			06/07/2019	171590	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	RH curtain ratchet faulty			05/06/2019		Fault	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL GATES	Job Added From Invoice			24/05/2019	0	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/05/2019	150050	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\CHAS CRACK	cross bracing broken off		previously completed	19/05/2019	150050	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		19/05/2019	150050	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\CHAS CRACK	gusset cracked right side			19/05/2019	150050	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Tyres\Punct	Job Added From Invoice			18/04/2019	133749	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			26/03/2019	122786	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Elect\ELECT P&W	no top clearance front and rear		previously done	26/03/2019	122786	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL FLOOR	loaded		previously done	26/03/2019	122786	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		26/03/2019	122786	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL REPS	fit and weld load binder bar's			24/03/2019	122089	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Chassis\CHAS CRACK	cross bracing broken off			19/02/2019	102315	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			19/02/2019	102315	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	Service	VehService\DS		19/02/2019	102315	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Elect\ELECT P&W	no top clearance front and rear			20/01/2019	83246	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers			20/01/2019	83246	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	Service	VehService\DS		20/01/2019	83246	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Body\TRL FLOOR	loaded			20/01/2019	83246	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\MOUNTS	LHR bottom mount loose			20/01/2019	83246	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Susp\HCV	very slow to rise			20/01/2019	83246	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			20/01/2019	83246	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			25/12/2018	72581	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS	fit NHVAS and service sticker holder	25/12/2018	72581	Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Workshop\MOVE ASSET	move trailers			25/12/2018	72581	Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Elect\ELECT P&W	repaired adapter plug as required			28/10/2018		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Brakes	Record Check Results As Attached To This Job			16/10/2018		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	VehService\DS	D Service As Per Attached Checklist	VehService\DS		16/10/2018		Service	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Workshop\MOVE ASSET	pick up from TCTC			04/10/2018		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER
T616	Wodonga - Workshop	Workshop\MOVE ASSET	drop at TCTC			04/10/2018		Repair	Completed	FL Green Distribution	Tliner	Wodonga	LHB	074953	Wodonga Workshop	TRAILER