

A01-7
lot 27



Vehicle Standards and Inspection

Power Unit Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A293069

Station #: 71128	Station Name: Warman Truck & Trailer Ltd.
Technician #: 83001	Technician Name: Ron Neufeld
Signing Officer #: 89846	Signing Officer Name: Jody Neufeld

Customer Details:	
Name: Doug Dahl	Address: Box 835, Rosthern, Saskatchewan, S0K 3R0

Inspection Completed Date: 13Mar2026	Inspection Expiry Date: 30Sep2026
--------------------------------------	-----------------------------------

Vehicle Details:	
VIN: 1XP5DB9X63D598113	Odometer Reading: 330119 km
Year: 2003	Vehicle Make/Model: PETERBILT/HEAVY VEHICLE
Plate: 690 LKE	Jurisdiction: Saskatchewan
Unit:	

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

A293069

Power Unit Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71128
Technician #: 83001
Signing Officer #: 89846

Station Name: Warman Truck & Trailer Ltd.
Technician Name: Ron Neufeld
Signing Officer Name: Jody Neufeld

Customer Details:

Name: Doug Dahl

Address: Box 835, Rosthern, Saskatchewan, S0K 3R0

Vehicle Details:

VIN: 1XP5DB9X63D598113
Year: 2003

Odometer Reading: 330119 km

Vehicle Make/Model: PETERBILT HEAVY VEHICLE

Inspection Details:

Pass	Rejected	Corrected	Req Altn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Sun Visor Interior (8)	
x				Horn Operation (5)	
x				Mirrors (8)	
x				Windshield Wipers/Washers (8)	
x				Windshield Defroster/Heater (8)	
		x		Windshield/Other Glass (8)	driver side door window and lock not working properly
x				Gear Position Indicator & Neutral Switch (1)	
x				Instrument Lamps (6)	
x				Accessibility Features/Equip (5)	
x				Auxiliary Heaters (5)	
x				Auxiliary Drive Controls (5)	
x				Emergency Exits (8)	
x				Floor/Step Well Covering (8)	
x				Service/Exit Doors (8)	
x				Indicator Lamps (5)	
x				Instruments/Gauges (5)	
x				Switches (7)	
x				Brake Pedal/Actuator (3)	
x				Clutch/Clutch Pedal (1)	

		x		Fire Extinguisher/Hazard Kit (5)	mount fire extinguisher
x				Seats/Seat Belts/SRS (8)	
x				Steering Column/Components (4)	
x				Auxiliary Controls/Equip (5)	
x				Speedometer/Odometer (5)	
x				Steering Lash/Travel (5)	
x				Accelerator Pedal/Actuator (1)	
x				Engine Shut Down Control (1)	
x				Engine Start Feature (1)	
x				Body Interior/Fixtures (8)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
		x		Lamps (6)	repair bunk lights
			x	Headlamp Aim (6)	day time run lights not working, module unavailable
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
		x		Body/Bumpers (8)	front bumper cracked
		x		Trailer Hitch (10)	adjust 5th wheel
x				Cab Grab Handles/Steps (8)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Sun Visor Exterior (8)	
		x		Mud Flaps/Fenders (8)	Both front fenders need repair(body shop), Left rear fender cracked
x				Trailer Power Cord (7)	
x				Chain/Headache Rack (5)	
x				Auxiliary Compartments (8)	
x				Hybrid Vehicle Drive Systems (1)	
x				Unitized Body Elements (8)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Cab/Hood Safety Catches (8)	
		x		Power Steering System (4)	power steering return line leaking
x				Fuel System (1)	
		x		Battery/Wiring Condition (7)	battery tie down missing
x				Air Suspended Cab (8)	
x				Cab Mounts (8)	
x				Drive Belts (1)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
------	----------	-----------	----------	---------	----------

x				Hyd Brake System/Components (3.1)	
		x		Air Brake System/Components (3.2)	left front drive brake pot jam nut backed off not letting pot release fully
x				Wheel Bearings (9)	
x				King Pins/Ball Joints (4)	
x				Steering Linkage (4)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (4)	
x				Engine/Transmission Mounts (1)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Drive Shaft/Universal Joints (1)	
		x		Exhaust/Emission System (1)	Exhaust pipe off of rear of turbo cracked, exhaust clamp on flex pipe to left stack corroded off

Brake/Tire Measurements

Axle 1-Pass

Wheel1-Or : Tire Tread Depth: 16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 70.0 degrees • Brake Stroke: 1 in

Wheel2-On : Tire Tread Depth: 16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 9/16 in • Cam Rotation: 70.0 degrees • Brake Stroke: 1 in

Axle 2-Pass

Wheel1 : Tire Tread Depth: 16 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 60.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 16 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 5/8 in • Cam Rotation: 70.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 16 in

Brake(1): No Brake

N/A

Axle 3-Pass

Wheel1 : Tire Tread Depth: 15 in

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 15 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 60.0 degrees • Brake Stroke: 1 1/2 in

Wheel3-On : Tire Tread Depth: 10 in

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 60.0 degrees • Brake Stroke: 1 1/2 in

Wheel4 : Tire Tread Depth: 10 in

Brake(1): No Brake

N/A