



Commercial Vehicle Inspection Report

Decal Number: GJ61671
Decal Expiry Date: 2026-May-31
Inspection Number: 21355498

Inspection Result:

PASS

FACILITY: B R & S TRUCK & TRAILER REPAIR / S15610
INSPECTOR: Plaha, Ranjit Singh / 111736
WORK ORDER #:
INSPECTION TYPE: Complete
INSPECTION CLASS: Class 3 - Trailer and Semi-Trailer
INSPECTION REASON: Annual
INSPECTION START: 2025-May-17 10:55 AM PDT
INSPECTION COMPLETE: 2025-May-17 12:30 PM PDT

VEHICLE JUR: British Columbia
PLATE #:
VEHICLE YEAR: 2022
MAKE: FONTAINE
MODEL:
REGI: 13899388
UNIT/FLEET#: 681
VIN: 13N253302N1549784
OWNER/LESSEE NAME: eternity transport ltd, eternity transport ltd
ADDRESS: 19966 wharf st, 19966 wharf st
Maple Ridge, British Columbia
v2x1a1, Canada
VEHICLE GROSS WEIGHT (kg): 0
VEHICLE BODY STYLE: Flat Deck Trailer
VEHICLE ODOMETER:
VEHICLE HUB ODOMETER:
VEHICLE BRAKE TYPE: Air
VEHICLE FUEL TYPE:

Vehicle Identification (VIN) Passed
Section 1 - Power Train Not Applicable
Section 2 - Suspension Passed
Section 3 - Brake System Passed
Section 3A - Air Brakes Passed
Section 3H - Hydraulic Brakes Not Applicable
Section 4 - Steering Not Applicable
Section 5 - Instruments and Auxiliary Equipment Not Applicable
Section 6 - Lamps Passed
Section 7 - Electrical System Passed
Section 8 - Frame and Body Passed
Section 9A - Tires Passed
Section 9B - Wheels Passed
Section 10 - Coupling Devices Passed
Section 11 - Other Vehicle Components Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	33	33	9	9	9	9	
2	Clamp	30	Automatic	33	33	11	11	10	10	
3	Clamp	30	Automatic	33	33	8	8	8	8	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Brake Lining/Pad (mm)

Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	44	48	Lining (Shoe)	18	18	Drum	0.00	0.00
2	50	50	Lining (Shoe)	17	17	Drum	0.00	0.00
3	42	42	Lining (Shoe)	18	18	Drum	0.00	0.00

Comment:

Comment:

Comment:

Inspection Comments: DUST COVER REMOVED

Has this Vehicle been road tested? No

Road Test Date:

Inspector: Plaha, Ranjit Singh

Signature: *Ranjit Singh*

Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-17 02:49 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

No personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

VS00014

4/17/2025 2:49:44 PM PDT