


A04-3



Commercial Vehicle Inspection Report

Decal Number: GH18746
Decal Expiry Date: 2025-Dec-31
Inspection Number: 21177726

Inspection Result:
PASS

FACILITY: A & R MOBILE TRUCK REPAIR LTD / S12450
INSPECTOR: SRAN, HARJINDER / 203335
WORK ORDER #:
VEHICLE JUR: British Columbia
PLATE #: 09688K
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2015
MAKE: MANAC
MODEL:
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2024-Dec-13 09:00 AM PST
INSP. COMPLETE: 2024-Dec-13 11:00 AM PST
REGI: 11185908
UNIT/FLEET#: 576
BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2M5131619F1149696
OWNER/LESSEE NAME: ETERNITY TRANSPORT LTD.,
ADDRESS: 19966 WHARF ST
Maple Ridge, British Columbia
V2X 1A1, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	32
2	Clamp	30	Automatic	32	32
3	Clamp	30	Automatic	32	32

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
7	7	7	7	
10	10	4	4	
5	5	6	7	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	55	58
2	46	62
3	60	56

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	15	15
Lining (Shoe)	17	14
Lining (Shoe)	14	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: SRAN, HARJINDER

Signature:

This Inspection Report was submitted to CVSE on 2024-Dec-13 02:33 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

12/13/2024 2:33:23 PM PST