



Commercial Vehicle Inspection Report

Decal Number: GH07935
Decal Expiry Date: 2026-Jan-31
Inspection Number: 21203705

ACU-33

Inspection Result:

PASS

FACILITY: B R & S TRUCK & TRAILER REPAIR / S15610
INSPECTOR: Plaha, Ranjit Singh / 111736
WORK ORDER #:

INSR. TYPE: Complete
INSR. CLASS: Class 3 - Trailer and Semi-Trailer
INSR. REASON: Annual

INSR. START: 2025-Jan-12 11:00 AM PST
INSR. COMPLETE: 2025-Jan-13 09:30 AM PST

VEHICLE JUR: British Columbia
PLATE #: 62397K
REGI: 11274951
UNIT/FLEET#: 579
VIN: 2M5131611F1149952
OWNER/LESSEE NAME: eternity transport ltd, eternity transport ltd
ADDRESS: 19966 wharf st, 19966 wharf st
Maple Ridge, British Columbia
v2x1a1, Canada

PERMITTED GVW(kg): 999999
VEHICLE YEAR: 2015
MAKE: MANAC
MODEL:

BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) 1st axle replaced both slag ad
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) weld all cracks
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	33	33	12	12	12	12	
2	Clamp	30	Automatic	33	33	8	8	9	9	
3	Clamp	30	Automatic	33	33	11	11	11	11	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	52	50
2	48	46
3	55	59

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	17	17
Lining (Shoe)	17	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	0.00	0.00
Drum	0.00	0.00

Comment:

Inspection Comments: dust cover removed

Has this Vehicle been road tested? No

Road Test Date:

Inspector: Plaha, Ranjit Singh

Signature:

Ranjit Singh

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jan-13 12:35 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

Any personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 26 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection report for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. requesting carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement.

CVSD0014

2025/01/13 12:35:19 PM PST