

04065632

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Safety Box 45064 Regent Postal Outl: Winnipeg, MB, R2C 5C7 1-204-985-0920

Manitoba DECA! C051429

Date Inspection Started: 31/01/26, Station Number: A5293, Station Name: JAZ MECHANICAL LTD, Mechanic Number: M3970, Mechanic Signature: [Signature], Station Phone Number: 204 9976075, Vehicle Owner: BOB PERFANICK TRUCKING INC.

Pass/Safe Vehicle, Licence Number: TB16677, Prov: MB, NSC #: [Blank], Odometer Reading: [Blank], Odom. Type: km, Vehicle Identification Number: 2A91973029LA903758, Make: ARNES, Model: END DUMP, Year: 2020, Unit #: J47

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck, GVWR, KGS, Truck Tractor, Trailer, X Semi-Trailer, Bus, School Bus, Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

Inspection sections: Section 1 - Power Train, Section 2 - Suspension, Section 3 - Brake Systems (3H, 3A), Section 4 - Steering, Section 5 - Instruments & Auxiliary Equipment, Section 6 - Lamps, Section 7 - Electrical System, Section 8 - Body, Section 9 - Tire & Wheel (1B - REAR TIRES ROTATED), Section 10 - Coupling Devices

Brake Inspection Type: A B C D E. Table with columns: Axle, Lining (L, R), Drum/Rotor (L, R), Stroke (L, R). Data for Axle 1: Lining 1/2, 1/2; Drum/Rotor 16.545, 16.549; Stroke 1", 1".

Tread Depth and Air Pressure table. Columns: Axle, Initial/Corrected (L, R) for Tread Depth; Initial/Corrected (L, R) for Air Pressure. Data for Axle 1: Tread 8, 8, 8, 8; Air 100, 100, 100, 100.

- THIS INSPECTION IS NOT A WARRANTY - This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: [Blank]

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required. Vehicle received without repairs by: [Signature] Date: [Blank]