

04065634

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Safety Box 45064 Regent Postal Cntr Winnipeg MB R2C 5G7 1-204-985-0920



C051441

Date Inspection Started: 06 DAY, 02 MO, 26 YR
 Date Inspection Completed: 06 DAY, 02 MO, 26 YR
 Inspection Expiry Date: 28 DAY, 02 MO, 27 YR

Station Number: A512913 Station Name: JAZ MECHANICAL LTD City: _____
 Mechanic Number: M3970 Mechanic Signature: [Signature] Station Phone Number: 204 9976075
 Vehicle Owner: BOB PERFANICK TRUCKING INC.
 Address: _____ City: _____ Province: _____ Postal Code: _____ Phone: _____

Pass/Safe Vehicle Fail/Unsafe Vehicle Fail/Hazardous
 Licence Number: TC11311 Prov: MB NSC #: _____ Odometer Reading: _____ Odom. Type: km mi
 Vehicle Identification Number: 2A90724231MA100390D Make: ARNES Model: END DUMP Year: 1989 Unit #: PB101
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GWR _____ KGS _____ Truck Tractor _____ Trailer _____ Semi-Trailer _____ Bus _____ School Bus _____ Coach Bus _____

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																							
X		Section 1 - Power Train: Defects (if any)																																																																							
X		Section 2 Suspension: Defects (if any)																																																																							
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type: 16H SET ALL BRAKES Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection <table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>1 1/2</td> <td>1 1/2</td> <td>16.568</td> <td>16.562</td> <td>1"</td> <td>1"</td> </tr> <tr> <td>2</td> <td>7/16</td> <td>9/16</td> <td>16.560</td> <td>16.567</td> <td>1"</td> <td>1"</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	1 1/2	1 1/2	16.568	16.562	1"	1"	2	7/16	9/16	16.560	16.567	1"	1"	3							4							5							Final Measurement																						
Axle	Lining			Drum/Rotor		Stroke																																																																			
	L	R	L	R	L	R																																																																			
1	1 1/2	1 1/2	16.568	16.562	1"	1"																																																																			
2	7/16	9/16	16.560	16.567	1"	1"																																																																			
3																																																																									
4																																																																									
5																																																																									
Final Measurement																																																																									
X		Section 4 - Steering: Defects (if any)																																																																							
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																							
X		Section 6 - Lamps: Defects (if any)																																																																							
X		Section 7 - Electrical System: Defects (if any)																																																																							
X		Section 8 - Body: Defects (if any)																																																																							
X		Section 9 - Tire & Wheel: Defects (if any)																																																																							
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <td></td> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>8</td> <td>8</td> <td>7</td> <td>8</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>2</td> <td>9</td> <td>9</td> <td>9</td> <td>9</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	1	8	8	7	8	100	100	100	100	2	9	9	9	9	100	100	100	100	3									4									5								
Axle	Tread Depth				Air Pressure																																																																				
	Initial		Corrected		Initial		Corrected																																																																		
	L	R	L	R	L	R	L	R																																																																	
1	8	8	7	8	100	100	100	100																																																																	
2	9	9	9	9	100	100	100	100																																																																	
3																																																																									
4																																																																									
5																																																																									
X		Section 10 - Coupling Devices: Defects (if any)																																																																							

- THIS INSPECTION IS NOT A WARRANTY - This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature _____ Date: _____