

03945559

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE



Vehicle Standards and Insp. Box 45064 Regent Postal Ct. Winnipeg, MB, R2C 5G7 1-204-985-0920

Manitoba A948255

Date Inspection Started: 12/02/25
 Station Number: A15293 JAZ MECHANICAL LTD
 Mechanic Number: H3970
 Date Inspection Completed: 25/02/25
 Station Name: JAZ MECHANICAL LTD
 Mechanic Signature: [Signature]
 Station Phone Number: 204-997-6075
 Inspection Expiry Date: 28/02/26
 Vehicle Owner: BOB PERVANICK TRUCKING INC.
 Licence Number: PDIK6197 Prov. MB NSC #
 Odometer Reading: 302915 Odom. Type: km
 Vehicle Identification Number: 2WK1ED1D1XJ211K97110314 Make: W15 Model: 4900 Year: 2001 Unit #: 42
 Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																																
X		Section 1 - Power Train: Defects (if any)																																																																																
X		Section 2 Suspension: Defects (if any)																																																																																
X	X	Section 3 - Brake Systems: 3H (3A) Defects (if any) Circle Brake Type 16H- SET ALL BRAKES Brake Inspection Type: (A) B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																																
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>1/2</td> <td>1/2</td> <td>16.563</td> <td>16.562</td> <td>1"</td> <td>1"</td> </tr> <tr> <td>2</td> <td>9/16</td> <td>9/16</td> <td>16.542</td> <td>16.541</td> <td>1 1/8</td> <td>1 1/8</td> </tr> <tr> <td>3</td> <td>5/8</td> <td>5/8</td> <td>16.557</td> <td>16.551</td> <td>1 1/8</td> <td>1 1/8</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7" style="text-align: center;">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	1/2	1/2	16.563	16.562	1"	1"	2	9/16	9/16	16.542	16.541	1 1/8	1 1/8	3	5/8	5/8	16.557	16.551	1 1/8	1 1/8	4							5							Final Measurement																															
Axle	Lining			Drum/Rotor		Stroke																																																																												
	L	R	L	R	L	R																																																																												
1	1/2	1/2	16.563	16.562	1"	1"																																																																												
2	9/16	9/16	16.542	16.541	1 1/8	1 1/8																																																																												
3	5/8	5/8	16.557	16.551	1 1/8	1 1/8																																																																												
4																																																																																		
5																																																																																		
Final Measurement																																																																																		
X		Section 4 - Steering: Defects (if any)																																																																																
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																																
X		Section 6 - Lamps: Defects (if any)																																																																																
X		Section 7 - Electrical System: Defects (if any)																																																																																
X		Section 8 - Body: Defects (if any)																																																																																
X		Section 9 - Tire & Wheel: Defects (if any)																																																																																
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <td></td> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>32</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>1</td> <td>13</td> <td>13</td> <td></td> <td></td> <td>100</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>21</td> <td>21</td> <td>21</td> <td>21</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>20</td> <td>20</td> <td>20</td> <td>20</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected			L	R	L	R	L	R	L	R	32									1	13	13			100	100			2	21	21	21	21	100	100	100	100	3	20	20	20	20	100	100	100	100	4									5								
Axle	Tread Depth				Air Pressure																																																																													
	Initial		Corrected		Initial		Corrected																																																																											
	L	R	L	R	L	R	L	R																																																																										
32																																																																																		
1	13	13			100	100																																																																												
2	21	21	21	21	100	100	100	100																																																																										
3	20	20	20	20	100	100	100	100																																																																										
4																																																																																		
5																																																																																		
X		Section 10 - Coupling Devices: Defects (if any)																																																																																

- THIS INSPECTION IS NOT A WARRANTY - This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature

Date: