

04103812

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba



A06-1

Vehicle Safety Box 45064 Regent Postal Outlet Winnipeg, MB, R2C 5C7 1-204-985-0920

Manitoba



C092589

Date Inspection Started: DAY 15, MO. 06, YR. 2006
 Date Inspection Completed: DAY 17, MO. 06, YR. 2006
 Inspection Expiry Date: DAY 30, MO. 06, YR. 2007

Station Number: A3035
 Station Name: ~~Manitoba~~ Lukes Trucking
 City: _____
 Mechanic Number: M7209
 Mechanic Signature: _____
 Station Phone Number: _____

Vehicle Owner: XL Transportation
 Address: _____
 City: _____ Province: _____ Postal Code: _____ Phone: _____

Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Hazardous

Licence Number: CKW4911 Prov. MB NSC # _____
 Odometer Reading: 64890 Odom. Type: km mi
 Vehicle Identification Number: 2FUPD1D1YB1WA912558 Make: FTL Model: Long Conv. Year: 1998 Unit #: _____
 Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR _____ KGS Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X		Section 2 Suspension: Defects (if any)																																																																						
X	X	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type X 15C - Brake shoe Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>3/4</td> <td>5/8</td> <td>15.000</td> <td>15.000</td> <td>1 1/4</td> <td>1 1/4</td> </tr> <tr> <td>2</td> <td>5/8</td> <td>5/8</td> <td>16.531</td> <td>16.535</td> <td>1 1/4</td> <td>1 1/4</td> </tr> <tr> <td>3</td> <td>5/8</td> <td>5/8</td> <td>16.559</td> <td>16.579</td> <td>1 1/4</td> <td>1 1/4</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="7" style="text-align: center;">Final Measurement</td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	3/4	5/8	15.000	15.000	1 1/4	1 1/4	2	5/8	5/8	16.531	16.535	1 1/4	1 1/4	3	5/8	5/8	16.559	16.579	1 1/4	1 1/4	4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	3/4	5/8	15.000	15.000	1 1/4	1 1/4																																																																		
2	5/8	5/8	16.531	16.535	1 1/4	1 1/4																																																																		
3	5/8	5/8	16.559	16.579	1 1/4	1 1/4																																																																		
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)																																																																						
X	X	Section 6 - Lamps: Defects (if any) X 16 headlamp																																																																						
X		Section 7 - Electrical System: Defects (if any)																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X		Section 9 - Tire & Wheel: Defects (if any)																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>26</td> <td>25</td> <td>25</td> <td>25</td> <td>100</td> <td>100</td> <td>100</td> <td>100</td> </tr> <tr> <td>3</td> <td>25</td> <td>26</td> <td>24</td> <td>23</td> <td>94</td> <td>90</td> <td>88</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1									2	26	25	25	25	100	100	100	100	3	25	26	24	23	94	90	88	100	4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1																																																																								
2	26	25	25	25	100	100	100	100																																																																
3	25	26	24	23	94	90	88	100																																																																
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY - This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: _____

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature _____ Date: _____

