

INVOICE# 5272

DATE: May 1, 2023

DRIVER _____

UNIT# SD 9


ENGINE HOURS: _____

PLEASE DESCRIBE ISSUES WITH TRUCK OR TRAILER

- L1 wheel seal
L7 Replace brake shoes + drum 419.74 mm

- replace fenders on driver side #2 and #3
axle

POSTED

MECHANIC SIGNATURE: 

INVOICE# 5201

DATE: April 13, 2023

DRIVER _____

UNIT# SD9

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUES WITH TRUCK OR TRAILER

POSTED

Grease

- Check hub levels

inspect Everything

MECHANIC SIGNATURE: _____

[Signature]

INVOICE# 4744

DATE: Oct 5/22

DRIVER _____

UNIT# SD4

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUES WITH TRUCK OR TRAILER

- Replace LH #1 fender

POSTED

MECHANIC SIGNATURE: _____

PARTS USED

COUNT

NAME OF PART

PART NUMBER

[illegible]

INVOICE#

4442

DATE: August 14/22

DRIVER

UNIT#

SP9

ENGINE HOURS:

POSTED

PLEASE DESCRIBE ISSUES WITH TRUCK OR TRAILER

- Grease
- Hub levels
- ~~TRH~~ walking beam starting to crack
- #1 axle air tank drain cock
- Drain water out of second air tank

MECHANIC SIGNATURE:

[Signature]

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle						Gross Vehicle Weight registered					
Vehicle Information											
VIN											
Unit Number		Year		Make		Model		Odometer			
SD 9											
Registered Owner's Name								Plate Number			
INV # 4337											
Address						Postal Code		Phone Number			
POSTED											

Drum Brakes:				Disc Brakes:					
		LEFT		FRONT		RIGHT			
psi	mm	psi	mm	mm	mm	mm	mm	psi	mm
16	17	17	32	Drums/Rotors	15	32	15	14	
				Linings/Pads					
				Push Rod Travel					
psi	mm	psi	mm	mm	mm	mm	mm	psi	mm
22	23	20	32	Drums/Rotors	20	32	17	14	
				Linings/Pads					
				Push Rod Travel					
psi	mm	psi	mm	mm	mm	mm	mm	psi	mm
21	21	15	32	Drums/Rotors	18	32	21	21	
				Linings/Pads					
				Push Rod Travel					
psi	mm	psi	mm	mm	mm	mm	mm	psi	mm
				Drums/Rotors					
				Linings/Pads					
				Push Rod Travel					
psi	mm	psi	mm	mm	mm	mm	mm	psi	mm
				Drums/Rotors					
				Linings/Pads					
				Push Rod Travel					
psi	mm	psi	mm	mm	mm	mm	mm	psi	mm
				Drums/Rotors					
				Linings/Pads					
				Push Rod Travel					

Park Brake Lining Left _____ mm Right _____ mm Trans _____ mm
 Wheel Torque Checked ☐ Inner _____ ft lbs Outer _____ ft lbs

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 1 - Power Train

Component	P	F	NA	Component	P	F	NA
1.2. Exhaust System				1.12. Gasoline or Diesel Fuel System (LPG, CNG, & LNG) * SEE APPENDIX A*			

NOTES:

APPENDIX "A"

Component	P	F	NA	Component	P	F	NA
A.1. Liquefied Petroleum Gas (LPG or Propane) Fuel System				A.3. Liquefied Natural Gas (LNG) Fuel System			
A.2. Compressed Natural Gas (CNG) Fuel System							

NOTES:

Section 2 - Suspension

Component	P	F	NA	Component	P	F	NA
2.1. Suspension & Frame Attachments				2.5. Air Suspension			
2.2. Axle Attaching & Tracking Components				2.6. Self-Steer & Controlled-Steer Axle			
2.3. Axle & Axle Assembly				2.7. Shock Absorber/Strut Assembly			
2.4. Spring & Spring Attachment							

NOTES:

Section 3H - Hydraulic Brakes

Component	P	F	NA	Component	P	F	NA
3H.1. Hydraulic System Components				3H.10. Electric Brake System			
3H.6. Air-Over-Hydraulic Brake System				3H.12. Drum Brake System Components			
3H.7. Surge Brake Controller				3H.13. Disc Brake System Components			
3H.8. Vacuum System				3H.19. Brake Performance			
3H.9. Air-Boosted Trailer Brake System							

NOTES:

Section 3A - Air Brakes

Component	P	F	NA	Component	P	F	NA
3A.3. Air System Leakage				3A.16. S-Cam Drum Brake System			
3A.4. Air Tank				3A.17. Brake Shoe Travel (Wedge Brakes)			
3A.8. Brake Valves & Controls				3A.18. Disc Brake System Components			
3A.12. Parking Brake & Emergency Application				3A.20. Anti-Lock Brake System (ABS)			
3A.13. Air System Components				3A.22. Stability Control System (ESC) or (RSS)			
3A.14. Brake Chamber				3A.23. Brake Performance			
3A.15. Drum Brake System Components							

NOTES:

Section 4 - Steering

Component	P	F	NA	Component	P	F	NA
4.1. Steering Control & Linkage				4.5. Self Steer & Controlled-Steer Axle			
4.4. Kingpin							

NOTES:

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 5 - Instruments and Auxiliary Equipment

Component	P	F	NA	Component	P	F	NA
5.1. Fire Extinguisher							

NOTES:

Section 6 - Lamps

Component	P	F	NA	Component	P	F	NA
6.1. Required Lamps				6.3. Retro-Reflective Marking			
6.2. Reflex Reflector							

NOTES:

Section 7 - Electrical System

Component	P	F	NA	Component	P	F	NA
7.1. Wiring				7.3. Trailer Cord (output to towed vehicle)			
7.2. Battery							

NOTES:

Section 8 - Body

Component	P	F	NA	Component	P	F	NA
8.5. Cargo Body				8.11. Refrigeration/Heater Unit Fuel System			
8.6. Frame Rails & Mounts				8.21. Fender/Mud Flap			
8.7. Utilized Body Elements				8.22. Landing Gear on Trailer			
8.8. Cab or Cargo Door				8.23. Sliding Axle Assembly (Sliding Bogie)			
8.9. Cargo Tank or Vessel				8.24. Aerodynamic Device & Attachment			
8.10. Body, Device or Equipment Attached or Mounted to the Vehicle				8.25. Rear Impact Guard (RIG)			

NOTES:

Section 9 - Tires and Wheels

Component	P	F	NA	Component	P	F	NA
9.1. Tire Tread Depth				9.7. Wheel/Rim			
9.2. Tire Tread Condition				9.8. Multi-Piece Wheel/Rim			
9.3. Tire Sidewall & Manufacturer Markings				9.9. Spoke Wheel/Demountable Rim System			
9.4. Tire Inflation Pressure				9.10. Disc Wheel System			
9.5. Wheel Hub				9.11. Wheel Fasteners (Nuts, Bolts, & Studs)			
9.6. Wheel Bearing							

NOTES:

Section 10 - Couplers and Hitches

Component	P	F	NA	Component	P	F	NA
10.1. Hitch Assembly, Structure & Attaching Components				10.6. Automated Coupling Device			
10.2. Secondary Attachment (Safety Chain or Cable)				10.7. Fifth Wheel Coupler			
10.3. Pin/le Hook, Pin Hitch, or Coupler Hitch				10.8. Oscillating Fifth Wheel Coupler			
10.4. Ball Type Hitch				10.9. Ball-Bearing Type Turntable on Trailer			
10.5. Roll-Coupling Hitch							

COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

NOTES:

Certification

The Vehicle for which this Record of Inspection is issued has _____ the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
--------------------	-------------------	-----------------	-----------

Customer Acknowledgment

I understand If a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the Initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the Initial date of inspection, a new inspection must be conducted.	Date (Year/Month/Day)
	Customer Signature

INVOICE# _____

DATE: Jan. 13, 2022

DRIVER _____

UNIT# SD9

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUES WITH TRUCK OR TRAILER

- CUIP
- Adjust brakes
- Grease
- Secure ABS cables #2 axle
- LH dolly leg support broken at bolt
- bolt loose in dolly leg cross support and
missing one support
- Replace leaking hydraulic connector at front

MECHANIC SIGNATURE: _____

INVOICE# 4284

DATE: July 18, 2022

DRIVER _____

UNIT# SD9

POSTED

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUES WITH TRUCK OR TRAILER

- cracks on tub gussets above rests

MECHANIC SIGNATURE: *[Signature]*

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

INV# 2933

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle				Gross Vehicle Weight registered			
Vehicle Information							
VIN		Year		Make		Model	
Unit Number <i>SD9</i>						Odometer	
Registered Owner's Name				Plate Number			
Address				Postal Code		Phone Number	

POSTED

Drum Brakes:

Disc Brakes:

		<u>LEFT</u>		<u>FRONT</u>		<u>RIGHT</u>			
psi	mm	<i>420.61</i>	mm	Drums/Rotors	<i>420.40</i>	mm	psi	mm	
<i>10</i>		<i>17</i>	mm	Linings/Pads	<i>16</i>	mm	<i>7</i>		
			mm	Push Rod Travel		mm	<i>9</i>		
psi	mm	<i>419.37</i>	mm	Drums/Rotors	<i>420.55</i>	mm	psi	mm	
<i>24</i>		<i>22</i>	mm	Linings/Pads	<i>21</i>	mm	<i>14</i>		
			mm	Push Rod Travel		mm	<i>13</i>		
psi	mm	<i>420.65</i>	mm	Drums/Rotors	<i>420.13</i>	mm	psi	mm	
<i>24</i>		<i>18</i>	mm	Linings/Pads	<i>21</i>	mm	<i>24</i>		
			mm	Push Rod Travel		mm	<i>24</i>		
psi	mm		mm	Drums/Rotors		mm	psi	mm	
			mm	Linings/Pads		mm			
			mm	Push Rod Travel		mm			
psi	mm		mm	Drums/Rotors		mm	psi	mm	
			mm	Linings/Pads		mm			
			mm	Push Rod Travel		mm			
psi	mm		mm	Drums/Rotors		mm	psi	mm	
			mm	Linings/Pads		mm			
			mm	Push Rod Travel		mm			

SEAL

Park Brake Lining Left mm Right mm Trans mm
Wheel Torque Checked Inner ft lbs Outer ft lbs

INVOICE# _____

DATE: Jan. 22nd 2021

DRIVER SD9

UNIT# _____

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUE WITH TRUCK OR TRAILER

- 2nd axle RH shock
- 3rd axle RH shock
- all wheels need to be pulled and everything measured.
- Fender replaced on all of LH side.
- 3rd axle RH fender
- rear signal lights always on
- rear light boxes need to be pulled in.
- ABS valve leaking
- ABS light on in dash.
- hub caps

MECHANIC SIGNATURE

X [Signature]

- 100% 100%

- 100% 100% 100% 100%

100% - 100% 100% 100%

- 100% 100% 100% 100% 100%

- 100% 100% 100% 100% 100%

100% 100% 100%

- 100% 100% 100% 100% 100%

100% 100% 100%

- 100% 100% 100% 100% 100%

- 100% 100% 100% 100%

- 100% 100% 100% 100%

INVOICE# _____

DATE: Jan, 22nd 2021

DRIVER SD9

UNIT# _____

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUE WITH TRUCK OR TRAILER

#1 Brake pot LH side Broken

#2 3rd axle RH side Brake pot Broken

1st axle RH side brake pot lines backwards

Brake lines to 1st axle all cut and needed replacing

Slack adjuster ~~pins~~ needed to be moveable.

2nd axle replaced all slack adjuster pins.

2nd and 3rd axle RH side wheel seals:


MECHANIC SIGNATURE

INVOICE # 2722

DATE: Oct 4th 2020

DRIVER: THOMAS

UNIT # SD-9

ENGINE HOURS: _____

POSTED

PLEASE DESCRIBE ISSUE WITH TRUCK OR TRAILER

- RH #1 axle brake pot broken
↳ Re: Re brake pot

- RH #2 axle brake pot broken
↳ Re: Re with new pot

Driver Signature: _____

Mechanic Signature: _____



to be: to my own boy
-BH #3 2/1/6 page boy paper

to be: to page boy
-BH #1 2/1/6 page boy paper

2D-d
LHamm

Oct 14 1960

INVOICE # 2778

DATE: Nov 13/19

DRIVER: _____

UNIT # SD 9

POSTED

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUE WITH TRUCK OR TRAILER

- all new Rubber hub plugs.

#2 LH dust shield.

- Rear ram belt

* #1 axle RH shack. looking

Driver Signature: _____

Mechanic Signature: _____

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY**

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle		Gross Vehicle Weight registered	
Vehicle Information			
VIN 2 C 9 5 B R 3 W 5 J M 1 8 3 0 6 2			
Unit Number SD9	Year 2018	Make <i>Cross</i> BOON <i>counte</i>	Model 380SD
Registered Owner's Name Fire Ridge TRANSPORT			Odometer
Address 7210 Patterson			Plate Number 5SH939
Postal Code		Phone Number	
Drum Brakes: Full inspection/wheels on		Disc Brakes:	

		LEFT	FRONT	RIGHT		
psi	psi	mm	Drums/Rotors	mm	psi	psi
25	25	mm	Linings/Pads	mm	25	25
		36	Push Rod Travel	36		
psi	psi	mm	Drums/Rotors	mm	psi	psi
20	20	mm	Linings/Pads	mm	20	20
		36	Push Rod Travel	36		
psi	psi	mm	Drums/Rotors	mm	psi	psi
16	16	mm	Linings/Pads	mm	16	16
		36	Push Rod Travel	36		
psi	psi	mm	Drums/Rotors	mm	psi	psi
		mm	Linings/Pads	mm		
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
		mm	Linings/Pads	mm		
		mm	Push Rod Travel	mm		
psi	psi	mm	Drums/Rotors	mm	psi	psi
		mm	Linings/Pads	mm		
		mm	Push Rod Travel	mm		

Park Brake Lining	Left	mm	Right	mm	Trans	mm
Wheel Torque Checked	☐	Inner	ft lbs	Outer	ft lbs	

INVOICE # 1865

1755

* ORIGINAL FILED UNDER
MAINTENANCE FOR UNIT 1755
June 6/19

POSTED

* Wire in tarp controls
in Battery Box.

make trailer tarp cord.

INVOICE # 1866

SD9 → Replace front motor and
Chain drive on trailer.
→ Test system - needs new
Tarp assembly

POSTED

CBL