

**COMMERCIAL VEHICLE RECORD OF INSPECTION
TRUCK AND TRUCK-TRACTOR**

Inv # 2934

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle				Gross Vehicle Weight registered			
Vehicle Information							
VIN							
Unit Number 2355		Year		Make		Model	
						Odometer 245811	
Registered Owner's Name						Plate Number	
Address				Postal Code		Phone Number	
POSTED							
Drum Brakes: Pull all wheels. Disc Brakes:							
		LEFT		FRONT		RIGHT	
psi		419.40 mm		Drums/Rotors		419.37 mm	
15 mm		19 mm		Linings/Pads		19 mm	
		mm		Push Rod Travel		mm	
psi		419.38 mm		Drums/Rotors		419.20 mm	
7 mm		21 mm		Linings/Pads		21 mm	
9 mm		mm		Push Rod Travel		mm	
psi		419.61 mm		Drums/Rotors		419.47 mm	
22 mm		20 mm		Linings/Pads		21 mm	
22 mm		mm		Push Rod Travel		mm	
psi		mm		Drums/Rotors		mm	
mm		mm		Linings/Pads		mm	
		mm		Push Rod Travel		mm	
psi		mm		Drums/Rotors		mm	
mm		mm		Linings/Pads		mm	
		mm		Push Rod Travel		mm	
psi		mm		Drums/Rotors		mm	
mm		mm		Linings/Pads		mm	
		mm		Push Rod Travel		mm	
psi		mm		Drums/Rotors		mm	
mm		mm		Linings/Pads		mm	
		mm		Push Rod Travel		mm	
psi		mm		Drums/Rotors		mm	
mm		mm		Linings/Pads		mm	
		mm		Push Rod Travel		mm	
Park Brake Lining Left mm Right mm Trans mm Wheel Torque Checked Inner ft lbs Outer ft lbs							

2355

SERVICE CHECK LIST

OIL CHANGE was done @ 1125 hrs

FUEL FILTERS _____

AIR FILTERS Good

TRANSMISSION OIL LEVEL Good

DIFFERENTIAL OIL LEVELS 1st axle good, 2nd needed some.

FRONT HUB OIL LEVELS Refilled and checked

WINTER INSPECTION

DRAIN AIR TANKS Yes

ALCOHOL SNIFFER LEVEL N/A

CAB HEATER AIR FLOW AND FILTERS Good

HEATED MIRROR FUNCTION Yes

INVOICE# _____

DATE: _____

DRIVER _____

UNIT# 2355

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUE WITH TRUCK OR TRAILER

- fuel filter, ~~VIP~~

- left signal on dash when markers are on.

- Batteries in ~~box~~ battery box needs cleaning

~~Washer fluid~~

- Both steer axle hub caps brittle

- Shock on 2nd axle LH side broken

- Vent on fuel tank both sides

- leakage around oil pan

- replace ~~wind~~ windshield and conversion.

- leak by ~~the~~ cylinder head

air horn cable

MECHANIC SIGNATURE

INVOICE# _____

DATE: _____

DRIVER _____

UNIT# _____

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUE WITH TRUCK OR TRAILER

- LH High Beam
 - Coolant filter (WF2071)
 - Washer fluid fill cap
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____

MECHANIC SIGNATURE _____

Please pay upon receipt of invoice. Thank you!

INVOICE# 2890

DATE: Dec 8/20

DRIVER _____

UNIT# 2355

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUE WITH TRUCK OR TRAILER

- oil change.

- grease

- LH signal light issue

- Lt

POSTED



MECHANIC SIGNATURE



INV# 2888

Maintenance Request

Unit 2355 Date Dec. 4
Driver Joel R Engine Hours 11252

Repairs Needed	Completed By
27 hours left till service	
11279	
POSTED	



Maintenance Request

Unit 2355 Date Nov. 20
Driver Joel R Engine Hours 11088

Repairs Needed	Completed By
Driverside Fender on trailer got Broken	
Small Air leak at Back of Trailer and under Cab.	
Right Front Fender just above wheel is loose	
Front Bump on trailer leaking oil	



Maintenance Request

Unit 2355 Date Nov. 1-30
Driver Joel R Engine Hours 10882

Repairs Needed	Completed By
Front and Back Ram on trailer both have	
Hydraulic leaks their both wet.	
Please Adjust lights Low Beam and High they	CPS
are pointed too low - Please Raise up a bit.	

POSTED



Maintenance Request

Unit 2355 Date Nov. 6-20
Driver JOOR Engine Hours 10944

Repairs Needed	Completed By
Small Air leak at Back of Trailer	CBB
PtO is Leaking oil a little	
Over Right steer tire fender is a little loose	



Maintenance Request

Unit 2355 Date Nov. 8-20
Driver Joel R Engine Hours 10959

Repairs Needed	Completed By
Trailer Drive side centre Hub leak	
Need brighter Headlights High Beam Not even Bright	
Left Flashing lite on Fender Not Working	



Inv # 2778

Maintenance Request

Unit 2355 Date Oct-26-20
Driver Joel Engine Hours 10828

Repairs Needed	Completed By
When I hit Brakes 4way Flasher lites ^{in truck}	
Come on - Right Flashers & lites on	
Back of Truck don't work.	

POSTED



Maintenance Request

Unit 2355 Date Oct. 25
Driver Joel Racicot Engine Hours 10820

Repairs Needed	Completed By
Passenger side wind shield has crack.	
↳ glue in.	



Maintenance Request

Unit 2355 Date Oct. 23-20
Driver Joel R Engine Hours 10812

Repairs Needed	Completed By
Right Flasher on back of truck it makes it work funny Not working	
Sides are leaking back right on Trailer, Front Right door and inside left on trailer	
Windshield sprayer doesn't work properly and spray bottom	
Crack on weld of Trailer Front Left.	



Maintenance Request

Unit 2355 Date Oct 22
Driver Joel R. Engine Hours 10799

Repairs Needed	Completed By
<u>Right Flasher on truck at Back</u>	
<u>Not Working</u>	
<u>Windshield wiper sprayer doesn't</u>	
<u>work right only sprays Bottom</u>	



Maintenance Request

Unit 2355 Date Oct. 15-20
Driver Joel R. Engine Hours 10738

Repairs Needed	Completed By
Just a heads up on my	
trailer Front left side some of	
the weld is cracked	



Maintenance Request

Unit 2355 Date Oct 6-20
Driver Joel R Engine Hours 10688

Repairs Needed	Completed By
Front Steer Tires are bald	Fountain Tire
Right Front hub seal seeping	
on trailer Back Right seal seeping	

1156
10/1/51



Inv #2737

Maintenance Request

Unit 2355 Date Oct. 8-20
Driver Joel R Engine Hours 10712

Repairs Needed	Completed By
<u>Trailer is missing mud flap</u>	

POSTED

INVOICE # _____

DATE: _____

Oct 8th 2020

DRIVER: _____

UNIT # _____

2355

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUE WITH TRUCK OR TRAILER

EH trailer mud flaps

Driver Signature: _____

Mechanic Signature: _____



8

CH 11/16/1971

332

AP 8.11.1971

INVOICE # 2701

DATE: Sept 30/20

DRIVER: _____

UNIT # 2355

ENGINE HOURS: _____

POSTED

PLEASE DESCRIBE ISSUE WITH TRUCK OR TRAILER

- Service unit

- grease

Driver Signature: _____

Mechanic Signature: _____



04/23

- 245026

- 2640155

04/23

5322

05/23 30/50

INVOICE # 2650

DATE: Sept 1st 2020

DRIVER: _____

UNIT # 2355

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUE WITH TRUCK OR TRAILER

- Service / Grease

- LH CAB air bag

- ~~Tightened power steering reservoir clamps~~

- RH mirror bracket replaced

POSTED

Driver Signature: _____

Mechanic Signature: _____



- BH willow 100/1000

- ~~100/1000~~ 200/2000 100/1000

- FH 100 100 100

- 200/2000 / 100/1000

322

100 100 100

INVOICE #

2243

DATE:

Jan 7/20

DRIVER: _____

UNIT #

2355

ENGINE HOURS: _____

POSTED

PLEASE DESCRIBE ISSUE WITH TRUCK OR TRAILER

- Rig up - remove all old hydraulics, install new tank and hoses
- replace back-up lights
- replace hood signal lights

Driver Signature: _____

Mechanic Signature: _____

Original book reviewed -
atlas

atlas (quadrant) reviewed -

has summary on p. 14 -
Western, southern, etc.
reel two sheets over

1910

9322

0.65 m

INVOICE# 6133

DATE: March 28/23

DRIVER CHRIS

UNIT# 2355

ENGINE HOURS: _____

PLEASE DESCRIBE ISSUES WITH TRUCK OR TRAILER

Lower rad pipe gasket Blown
out

POSTED

MECHANIC SIGNATURE: CBB