

# Experian AutoCheck Report

Report run: 06/15/2026 18:58:32 EDT

## 2017 Nissan Altima 2.5 / 2.5 S / 2.5 SL / 2.5 SR / 2.5 SV

Sedan 4D (2.5L 14 SMPI Gasoline)

VIN:	1N4AL3AP7HC489134
Class:	Car - Midsize
Country of Assembly:	United States
Vehicle Age:	9 year(s)
Estimated In Service:	08/16/2017
Last Reported Odometer:	103,227 (05/14/2026)

Owners - 2



Vehicle Usage  
Lease



### AutoCheck Score

Similar vehicles usually range between 65 and 82

### Vehicle History at a Glance

<p><b>State Title Brand</b></p> <p>CLEAN</p>	<p><b>Auction Brand / Issues</b> Hail Damage</p> <p>AUCTION ISSUE REPORTED</p>	<p><b>Accident / Damage</b> Multiple Damage Events</p> <p>MINOR</p>
<p><b>Open Recall Check</b></p> <p>NO OPEN RECALLS</p>	<p><b>Insurance Loss / Transfer</b></p> <p>NO ISSUE</p>	<p><b>Odometer Check</b> Last reported odometer: 103,227 (05/14/2026)</p> <p>NO ISSUE</p>
<p><b>Certified Pre-Owned</b></p> <p>NO CPO INFO AVAILABLE</p>	<p><b>Service / Repair</b> 5 Service Record(s) Reported</p> <p>NO ISSUE</p>	<p><b>Additional History</b> Lien Reported</p> <p>EVENTS REPORTED</p>




### This vehicle is eligible for Buyback Protection

Due to the vehicle's history showing no reported major state title brands. [Terms & Conditions](#)

[Learn More](#)

### Accident & Damage



Airbag Deployed



Structural Damage



Overturned



Minor

Damage Date	Damage Type	Severity
11/26/2021	Collision	Minor
08/05/2022	Collision	Minor
05/14/2026	Hail Damage	Unknown

Accident or damage event(s) have been reported for this vehicle to Experian AutoCheck. An inspection may provide added confidence in the vehicle's condition before purchase.

## Service History

### Service History Summary

Below is a summary of services that have been reported for this vehicle. Please note that not all maintenance events are reported to Experian AutoCheck.

**Regular Oil Changes**

- 3 oil services reported
- Last oil service reported 12/13/2018

**Fluids Maintained**

Information not available.

**Brakes Maintained**

Information not available.

**Tires Maintained**

Information not available.

**A/C & Climate Control**

Information not available.

**Other Services**

- Cabin air filter replaced on 07/17/2018
- Battery replaced on 09/25/2020

### OEM Recommended Services

**100000 Mile Service**

- Adjust Tires to Proper Tire Pressure
- Clean & Adjust Brakes
- Inspect & Reset TPMS Monitor

**105000 Mile Service** Not Yet Due

- Adjust Tires to Proper Tire Pressure
- Clean & Adjust Brakes
- Inspect & Reset TPMS Monitor

## Odometer Check

**Your Vehicle Checks Out**

No odometer brands, rollbacks, rollover or tampering has been reported to AutoCheck from state Division of Motor Vehicles (DMV) or auction sources. AutoCheck also examined the sequence of reported odometer readings to determine if there are any potential discrepancies.

**State Title Odometer Check**

No issues reported

**Auction Odometer Check**

No issues reported

**Odometer Calculation Check**

No issues reported

## Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order.

Vehicle: 2017 Nissan Altima 2.5 / 2.5 S / 2.5 SL / 2.5 SR / 2.5 SV (1N4AL3AP7HC489134) Report Run Date: 06/15/2026 18:58:32 EDT

2017

## Vehicle Prep and Other Pre-Titling Events

Preparation Date: 08/2017

Event Date	Location	Odometer	Data Source	Details
08/16/2017			Independent Source	Vehicle Manufactured and Shipped to Dealer

2017

### Owner 1

Location: CO

Owned From: 10/2017

Usage: Lease

Event Date	Location	Odometer	Data Source	Details
10/05/2017	RIDGELAND, MS	99	Motor Vehicle Dept.	Title(Title #:MS1597046784) (Leased Vehicle)(Lien Reported)
10/09/2017	RIDGELAND, MS		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
12/01/2017	RIDGELAND, MS		Motor Vehicle Dept.	Title(Title #:MS1597046784) (Leased Vehicle)(Lien Reported)
04/24/2018	JACKSON, MS	9,874	Service Record	Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
07/17/2018	JACKSON, MS	14,470	Service Record	Air Filter Changed Multiple Point Vehicle Inspection Engine Serviced Tires or Wheels Service Performed Lube, Oil And/Or Filter Changed
12/13/2018	CO	19,884	Independent Repair Center	Multiple Point Vehicle Inspection Lube, Oil And/Or Filter Changed
01/11/2019	DENVER, CO		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
12/19/2019	DENVER, CO		Motor Vehicle Dept.	Registration Event/Renewal(Leased Vehicle)
09/25/2020	DENVER, CO	33,304	Service Record	Battery Serviced or Replaced Multiple Point Vehicle Inspection Engine Serviced Wipers Replaced And/Or Serviced Tires or Wheels Service Performed
10/14/2020	GOLDEN, CO	33,304	Dealer Record	Vehicle in Dealer Inventory

2020

### Owner 2

Location: CO












Owned From: 11/2020

Usage: Personal

Event Date	Location	Odometer	Data Source	Details
11/24/2020	DENVER, CO		Motor Vehicle Dept.	Title(Title #:004474952) (Lien Reported)
05/11/2021	DENVER, CO		Motor Vehicle Dept.	Registration Event/Renewal
11/26/2021	DENVER, CO		Damage Report	Accident or Damage Reported Minor Damage Reported Right Side Damage or Repair Reported
07/28/2022	DENVER, CO		Motor Vehicle Dept.	Registration Event/Renewal
08/05/2022	CO		State Agency	Collision with a Bicycle(Case #:LK22023937) Accident Reported(Report #:LK22023937)
04/29/2024	DENVER, CO		Motor Vehicle Dept.	Registration Event/Renewal
04/20/2026	DENVER, CO		Motor Vehicle Dept.	Title(Title #:015597368) (Lien Reported)
05/04/2026	MOUNTAIN REGION	103,227	Auto Auction	Reported at Auto Auction
05/14/2026	MOUNTAIN REGION		Auto Auction	Auction Announced as Hail Damage
05/14/2026	AR	103,227	Service Record	Vehicle Recall Service Performed

## Warranty Check

The warranty coverage shown below is an estimate using the best available in-service date, mileage readings, and warranty information. Enter the exact odometer reading below for more accurate results. Experian AutoCheck does not guarantee coverage, please verify these results and coverage details with an authorized dealership.

Coverage Type	Remaining Miles	Remaining Time	Status	Coverage Details
Basic 	-	-		36 months / 36000 miles
Battery 	-	-	-	Contact a certified dealer to verify coverage
Corrosion 	-	-		60 months / Unlimited miles
Powertrain 	-	-		60 months / 60000 miles
Roadside Assistance 	-	-		36 months / 36000 miles Towing service available for 5 years/60,000 miles.
Safety Restraint 	-	15 months		120 months / Unlimited miles Nissan covers supplied seat belt component, that fails to function properly during normal use.

### AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#). If you obtained the report from a lender/dealer, the lender/dealer has been provided with these Terms and Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at [www.autocheck.com/terms](http://www.autocheck.com/terms) or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

### Buyback Protection Terms and Conditions

This vehicle (1N4AL3AP7HC489134) qualifies for [AutoCheck Buyback Protection](#). If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at [www.autocheck.com/bbpterm](http://www.autocheck.com/bbpterm) or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 1515 E. Woodfield Road, Suite 500, Schaumburg, IL 60173.

### About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

### Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.