



Commercial Vehicle Inspection Report

Decal Number: PY16720
Decal Expiry Date: 2026-Apr-30
Inspection Number: 21516325

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: WASSENAAR, MICHAEL ANTHONY / 200357
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2025-Oct-01 09:30 AM MST
INSP. COMPLETE: 2025-Oct-01 10:15 AM MST

VEHICLE JUR: British Columbia
PLATE #: 85634P
LICENCED GVW(kg): 56000
VEHICLE YEAR: 2016
MAKE: FREIGHTLIN
MODEL:

REGI: 14209623
UNIT/FLEET#: S116
BODY STYLE: Flat Deck
ODOMETER: 631609 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 1FVHCYCY9GH#N2308
OWNER/LESSEE NAME: ENVIROBORE DRILLING, LTD
ADDRESS: BOX 144
Fort St John, British Columbia
V1J 0K9, Canada

A08-2

Section	Result	Notes
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	MONITOR AXLE 1 REAR SPRING PINS
Section 3 - Brake System	Not Applicable	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)					Tire Tread Depth (mm)					Steering
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	
1	Clamp	24	Automatic	30	30	16			16	✓
2	Clamp	30	Automatic	42	42	19	19	19	19	
3	Clamp	30	Automatic	42	42	19	19	19	19	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	0	0	Lining (Shoe)	18	18	Drum	419.00	419.00
2	0	0	Lining (Shoe)	14	14	Drum	420.00	420.00
3	0	0	Lining (Shoe)	14	14	Drum	420.00	420.00

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: WASSENAAR, MICHAEL ANTHONY
Signature:
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Oct-01 10:42 AM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSE0014

10/1/2025 10:42:56 AM MST



Commercial Vehicle Inspection Report

Decal Number: PY16729
Decal Expiry Date: 2026-Oct-31
Inspection Number: 21518297

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
INSPECTOR: WASSENAAR, MICHAEL ANTHONY / 200357
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Oct-02 09:20 AM MST
INSP. COMPLETE: 2025-Oct-02 10:00 AM MST

WORK ORDER #:

VEHICLE JUR: British Columbia
PLATE #: 86151J
LICENCED GWV(kg): 999999
VEHICLE YEAR: 2014
MAKE: LODE KING
MODEL:
REGI: 11167596
UNIT/FLEET#: S201
BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
VIN: 2LDSD5335EE058268
OWNER/LESSEE NAME: ENVIROBORE DRILLING, LTD
ADDRESS: BOX 144
Fort St John, British Columbia
V1J0K9, Canada
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	36	36
2	Clamp	30	Automatic	36	30
3	Clamp	30	Automatic	34	34

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	13	13	13	13	
	14	14	14	14	
	12	12	12	12	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	0	0
2	0	0
3	0	0

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	18
Lining (Shoe)	18	18
Lining (Shoe)	17	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	419.00	419.00
Drum	419.00	419.00
Drum	420.00	420.00

Comment:

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date:

Inspector: WASSENAAR, MICHAEL ANTHONY Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Oct-02 10:46 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVS80014

10/2/2025 10:47:09 AM MST



Commercial Vehicle Inspection Report

Decal Number: PY00832
Decal Expiry Date: 2026-Apr-30
Inspection Number: 21300375

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS / N5398
INSPECTOR: JOHNSON, DALE Grant / 108415
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Apr-01 05:15 PM MST
INSP. COMPLETE: 2025-Apr-01 06:15 PM MST

VEHICLE JUR: British Columbia
PLATE #: 55459K
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2004
MAKE: TRAILTECH
MODEL:
REGI: 03186294
UNIT/FLEET#: S221
BODY STYLE: Flat Deck Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2CUDCEXN342014924
OWNER/LESSEE NAME: ENVIROBORE DRILLING, LTD
ADDRESS: BOX 144 RPO
Fort St John, British Columbia
V1J0K9, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) ABS LIGHT
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) LEFT MIDCHIP MARKER
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	28	26	14	14	14	14	
2	Clamp	30	Automatic	32	26	14	14	14	14	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	30	Lining (Shoe)	21	21	Drum		
2	30	30	Lining (Shoe)	21	21	Drum		

Comment: Air Brake Camshaft Rotation performed, Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: JOHNSON, DALE Grant
Road Test Date:
Signature: 
Road Tester:

This Inspection Report was submitted to CVSE on 2025-Apr-04 12:14 PM MST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSGVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

4/4/2025 12:14:11 PM MST