



Commercial Vehicle Inspection Report

Decal Number: GP09076
Decal Expiry Date: 2027-Jun-30
Inspection Number: 21806282

Inspection Result:
PASS

FACILITY:	LEN'S TRANSPORTATION / S6215	INSP. TYPE:	Complete	INSP. START:	2026-Jun-04 07:40 AM PDT
INSPECTOR:	RILEY, ORANE KAMAU / 301039	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2026-Jun-04 10:09 AM PDT
WORK ORDER #:	22607	INSP. REASON:	Annual		

VEHICLE JUR:	British Columbia	REGI:	08677714	VIN:	2A9JT3015PS037130
PLATE #:		UNIT/FLEET#:	<u>120</u>	OWNER/LESSEE NAME:	Len's Transportation Group, DBA Ranger Transport
LICENCED GVW(kg):	999999	BODY STYLE:	Dolly Trailer	ADDRESS:	9470 192 ST Surrey, British Columbia V4N3R9, Canada
VEHICLE YEAR:	1993	ODOMETER:			
MAKE:	ASPEN	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				Steering
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	38.1	38.1	6.4	4.8	6.4	6.4	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	38	79	Lining (Shoe)	18	12	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
Has this Vehicle been road tested? No Road Test Date: 08/06/2026 Road Tester:
Inspector: RILEY, ORANE KAMAU Signature: [Signature]

This Inspection Report was submitted to CVSE on 2026-Jun-09 03:07 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.