

**Invoice from History**

Printed Date: 03/24/2026 **Work Completed: 03/10/2023**

**STEP ENERGY SERVICES - MARCEL DUVAL**  
 1200 - 205 5 AVE  
 CALGARY, AB T2P 2V7  
 Home 780-357-1353 -- Office 780-933-1799 marce

2011 Kenworth - T800 - Caterpillar C-15 ADEM A4/ACERT EPA0  
 Lic # : Odometer In : 498863  
 Unit # : 22FLG06A Odometer Out : 498864  
 VIN # : 1XKDDB9XX BJ947999  
 Engine Hrs In : 5265.5 Engine Hours Out : 5265.5

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
CAMSHAFT 10R8193	1.00	2,858.08	2,858.08	ENGINE - DIAGNOSE Brought unit into shop. Removed valve cover and found that the cam shaft had failed on number 6. Also found rocker shafts damaged.	261.00
ARM, ROCKER 20R3317	12.00	306.05	3,672.60		
BEARING KIT - MAIN 2436718	1.00	1,159.11	1,159.11	CAMSHAFT BEARING(S) - R&I - All - [Includes R&I components to access camshaft bearing.]	464.00
OIL COOLER 10R5676	1.00	1,815.88	1,815.88	CAMSHAFT - R&I - [Includes R&I components to access camshaft.]	1,796.55
GASKET KIT 3362955	1.00	701.81	701.81	MAIN/ROD/THRUST BEARING(S) - R&I - All - [Include R&I of components for access. Does not include R&I oil pan sound suppression panel.]	1,278.90
15//40 ROTELLA TRIPLE CK4 Size: L SL500010048	36.00	7.10	255.60	ENGINE OIL COOLER - R&I - [Includes R&I components to access engine oil cooler.]	1,660.25
COOLANT BULK RED 50/50 CHV 227811-990	44.00	3.56	156.64	AIR COMPRESSOR - R&I After running unit up to temperature found a leak around the air compressor. Had to remove air compressor to find out where the leak was coming from. Found the stud on the air compressor would not go tight. The head of the stud was broke off and pulling through the housing. Removed peanut cover and idler gear then installed new stud and torqued and re installed air compressor.	493.00
FILTER - OIL , CAT 1R1808	1.00	77.19	77.19		
BEARING - ROD 2613450	6.00	98.48	590.88		
BEARING SLEEVE 2165582	7.00	113.13	791.91	****P.O.# 366093**** Hazardous Material	178.61
O RING SEAL 1178801	1.00	53.41	53.41		
O-RING 5E8771	1.00	51.74	51.74		
SEAL- PRESS 1607271	1.00	109.33	109.33		
SEAL 2720390	1.00	249.88	249.88		
GASKET-TURBO 2746851	1.00	63.15	63.15		
GASKET 1978418	2.00	5.99	11.98		
GASKET 1978419	2.00	7.80	15.60		
KIT-STUD EXHAUST MANIFOLD MCBC15ESKCAT	1.00	184.09	184.09		
SEAL 2722462	6.00	57.64	345.84		
SEAL O RING 6V5134	2.00	31.38	62.76		

Email Address: [reception@anarchymechanical.ca](mailto:reception@anarchymechanical.ca)

**Invoice from History**

Printed Date: 03/24/2026 Work Completed: 03/10/2023

**STEP ENERGY SERVICES - MARCEL DUVAL**  
 1200 - 205 5 AVE  
 CALGARY, AB T2P 2V7  
 Home 780-357-1353 -- Office 780-933-1799 marce

2011 Kenworth - T800 - Caterpillar C-15 ADEM A4/ACERT EPAC  
 Lic # : Odometer In : 498863  
 Unit # : 22FLG06A Odometer Out : 498864  
 VIN # : 1XKDDB9XX BJ947999  
 Engine Hrs In : 5265.5 Engine Hours Out : 5265.5

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
SEAL-INTEGRA 2642468	1.00	36.35	36.35		
SEAL-INTEGRA 2642469	1.00	41.24	41.24		
SEAL 2H2665	2.00	12.58	25.16		
SEAL 1250434	1.00	49.15	49.15		
SEAL 2655207	1.00	167.49	167.49		
SEAL-O-RING 2197000	1.00	8.83	8.83		
RING 3H1461	1.00	5.01	5.01		
SEAL-O-RING 3054484	1.00	7.64	7.64		
SEAL O RING 6V5134	2.00	31.39	62.78		
TURBO 20R117	1.00	5,273.93	5,273.93		
GASKET-TURBO 2746851	1.00	66.71	66.71		
STUD 3139550	4.00	49.51	198.04		
LOCK - NUT 2N2766	4.00	15.68	62.72		
GASKET 1978418	1.00	5.90	5.90		
GASKET 1978419	1.00	7.70	7.70		
SEAL-ISOLATI 1685248	1.00	693.90	693.90		
SEAL-PRESS I 2233505	1.00	32.45	32.45		
STUD-BRAKE 3346832	1.00	13.36	13.36		
Shop Supplies			595.37		

Email Address: [reception@anarchymechanical.ca](mailto:reception@anarchymechanical.ca)

**Anarchy Mechanical Ltd**

#100 - 10609 79 Ave  
CLAIRMONT, AB. T8X5G9  
Phone: 780-814-8555 Fax: 780-814-8599

**INVOICE**

**3065**

Org. Est. # 003484

**Invoice from History**

Printed Date: 03/24/2026

Work Completed: 03/10/2023

**STEP ENERGY SERVICES - MARCEL DUVAL**  
1200 - 205 5 AVE  
CALGARY, AB T2P 2V7  
Home 780-357-1353 -- Office 780-933-1799 marce

2011 Kenworth - T800 - Caterpillar C-15 ADEM A4/ACERT EPAC  
Lic # : Odometer In : 498863  
Unit # : 22FLG06A Odometer Out : 498864  
VIN # : 1XKDDB9XX BJ947999  
Engine Hrs In : 5265.5 Engine Hours Out : 5265.5

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----

Org. Estimate 30,252.86 Revisions 0.00 Current Estimate 30,252.86

Labor:	5,953.70
Parts:	20,581.21
HazMat:	178.61
<b>SubTotal:</b>	<b>26,713.52</b>
Tax:	1,335.68
<b>Total:</b>	<b>28,049.20</b>
Bal Due:	\$0.00

[ Payments - Cash - \$28,049.20 ]

Vehicle Received: 2023-03-10

Customer Number : 341

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts is up to the suppliers discretion or one year which ever applies. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Labor will be charged unless covered by supplier for all warranty claims. Anarchy Mechanical Ltd. is only responsible for warranty of parts supplied and installed by Anarchy Mechanical Ltd. staff. Any and all progressive damage caused by continued operation, past component failure is the sole responsibility of the customer. Anarchy Mechanical Ltd. will cover workmanship for 30 days or 100 hours, unless otherwise stated on the original invoice.

\*\*\*YOUR WHEELS MUST BE RE-TORQUED AFTER 50KM. FAILURE TO DO SO COULD RESULT IN DAMAGE TO YOUR VEHICLE OR INJURY WHICH ANARCHY MECHANICAL WILL NOT BE HELD LIABLE FOR\*\*\*

Signature \_\_\_\_\_ Date \_\_\_\_\_

Email Address: [reception@anarchymechanical.ca](mailto:reception@anarchymechanical.ca)