A10-1

BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GM41968
Decal Expiry Date: 2027-Mar-31
Inspection Number: 21707287 2026828

Inspection Result: **PASS**

FACILITY:	ACCURATE TRUCK / S5325	INSP. TYPE:	Complete	INSP. START:	2026-Mar-20 02:00 PM PDT
INSPECTOR:	ABBOTT, WARREN / 300988	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Mar-24 12:00 PM PDT
WORK ORDER #:	W-25899	INSP. REASON:	Annual		

VEHICLE JUR:	British Columbia	REGI:	03471790	VIN:	5PVNV8JV162S10023
PLATE #:	PD2879	UNIT/FLEET#:	32	OWNER/LESSEE NAME:	RELIABLE, EQUIPMENT RENTALS
LICENCED GVW(kg):	14950	BODY STYLE:	Flat Deck	ADDRESS:	20499 WESTMINSTER HWY
VEHICLE YEAR:	2006	ODOMETER:	636792 KM		Richmond, British Columbia
MAKE:	HINO	HUB ODOMETER:			V6V1B3, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	**Passed with Caution**	L/H KINGPIN, LEAK @ STEERING BOX INPUT SHAFT
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	**Passed with Caution**	L/H CENTER DECK BOARD
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	20L	Automatic	50	50
2	Clamp	30	Automatic	36	38

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
5			5	✔
10	10	10	10	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	35	35
2	90	90

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	10	10

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date: Road Tester:

Inspector: ABBOTT, WARREN

Signature:

This Inspection Report was submitted to CVSE on 2026-Mar-24 12:08 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

3/24/2026 12:08:56 PM PDT