



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY10831
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21364440

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS' /
#5398
INSPECTOR: JOHNSON, DALE Grant / 108415
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Tractor and Semi-Trailer
INSP. REASON: Semi-annual

INSP. START: 2025-May-23 12:30 PM PST
INSP. COMPLETE: 2025-May-23 01:30 PM PST

VEHICLE JUR: British Columbia
PLATE #: 87963K
LICENCED GVW(kg): 0
VEHICLE YEAR: 2006
MAKE: LODE KING
MODEL:

REGI: 14622492
UNIT/FLEET#: 357A
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2LDAH283X5E044388
OWNER/LESSEE NAME: AGGRESSIVE ENERGY 2022, INC
ADDRESS: PO BOX 6188
Fort St John, British Columbia
V1J4H7, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) #2,3 LINING SLACKS CAM TUBES
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	32	38	14	14	17	17	
2	Clamp	30	Automatic	26	24	17	17	16	16	
3	Clamp	30	Automatic	28	26	16	14	16	16	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	40	70
2	30	25
3	30	25

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	14
Lining (Shoe)	21	21
Lining (Shoe)	21	21

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: JOHNSON, DALE Grant

Road Test Date

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-26 10:48 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

5/26/2025 11:44:01 AM PST