

A10-3



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY10832
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21364454

Inspection Result:
PASS

FACILITY: NORTHERN B.C. TRUCKERS /
NS398
INSPECTOR: JOHNSON, DALE Grant / 108415
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2025-May-23 02:30 PM MST
INSP. COMPLETE: 2025-May-23 03:30 PM MST

VEHICLE JUR: British Columbia
PLATE #: 87964K
LICENCED GVW(kg): 0
VEHICLE YEAR: 2006
MAKE: LODE KING
MODEL:
REGI: 14622487
UNIT/FLEET#: 3578
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2LDAH30206E044389
OWNER/LESSEE NAME: AGGRESSIVE ENERGY 2022, INC
ADDRESS: PO BOX 6188
Fort St John, British Columbia
V1J4H7, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) #1R 2L&R LINING SLACKS CAM TUBES
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axes	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Clamp	30	Automatic	38	28	16	14	16	16	
2	Clamp	30	Automatic	26	28	17	17	16	17	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axes	Left	Right
1	16	21
2	21	21

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	21
Lining (Shoe)	21	21

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: JOHNSON, DALE Grant

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-May-26 11:49 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

5/26/2025 11:49:16 AM MST