



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: 6770
Decal Expiry Date: 2026-Jan-31
Inspection Number: 21222448

Inspection Result:

PASS

FACILITY: NORTHERN B.C. TRUCKERS /
N5398
INSPECTOR: GRANT, GARY MUNRO / 104568
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2025-Jan-20 03:00 PM MST
INSP. COMPLETE: 2025-Jan-20 04:00 PM MST

VEHICLE JUR: British Columbia
PLATE #: 97937K
LICENCED GVW(kg): 999999
VEHICLE YEAR: 1997
MAKE: PEERLESS
MODEL:

REGI: 04615788
UNIT/FLEET#: 381 341
BODY STYLE: Lowbed Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2PLG0573XVBB86750
OWNER/LESSEE NAME: AGGRESSIVE ENERGY (2022) INC.,
ADDRESS: PO BOX 6188 STN MAIN
Fort St John, British Columbia
V1J4H7, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) REMOUNT AIR VALVE. AIRLINES RUBBING/ AXLE 3L BRAKE POT
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	36	38
2	Clamp	30	Automatic	40	36
3	Clamp	30	Automatic	38	40

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	10	10	10	10	
	10	9	10	9	
	7	11	9	9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	65	70
2	70	65
3	75	70

Comment:

Brake Lining/Pad (mm)

	Left	Right
Lining/Pad	19	19
Lining (Shoe)	19	19
Lining (Shoe)	17	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Left	Right
Rotor/Drum	Drum	Drum
	Drum	Drum
	Drum	Drum

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: GRANT, GARY MUNRO

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jan-30 09:54 AM MST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE014

1/30/2025 9:54:12 AM MST