

Commercial Vehicle Inspection Report

Decal Number: GK06022
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21459976

11-1 Inspection Result:
PASS

FACILITY: ADVANCE TRUCK & HEAVY / S6882
INSPECTOR: PEPPER, CODY CHARLES / 113416
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2025-Jul-26 02:30 PM PDT
INSP. COMPLETE: 2025-Aug-14 10:07 AM PDT

/EHICLE JUR: British Columbia
PLATE #: VY7937
PERMITTED GVW(kg): 48000
/EHICLE YEAR: 1993
MAKE: WESTERN ST
MODEL:

REGI: 08399527
UNIT/FLEET#:
BODY STYLE: Dump Truck
ODOMETER: 32781 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

VIN: 2WLPCCCH1PK931962
OWNER/LESSEE NAME: Coastal Mountain Excavation, Coastal Mountain Excavation
ADDRESS: 8040 Nesters Rd, 8040 Nesters Rd Whistler, British Columbia V8E 0G4, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) lift pump leaking, RH rad support loose
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) #2 drums and linings, maxis not matched on #2 and #3
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) steering box input seal leaking
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) mirror back up lamp out, 2 cab lights on, driver side high beam out
Section 7 - Electrical System	Repaired (same day) elc horn
Section 8 - Frame and Body	Repaired (same day) box cracks
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Repaired (same day) passenger side wiper missing

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Manual	32	32
2	Clamp	30	Manual	30	30
3	Clamp	30	Manual	30	30

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
12			12	✓
13	14	16	17	
17	17	16	16	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	43	41
2	24	26
3	59	63

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	21	21
Lining (Shoe)	16	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	0.00	0.00
Drum	0.00	0.00

Comment: Air brake camshaft rotation performed. Rotor thickness or drum diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: PEPPER, CODY CHARLES

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Aug-14 10:08 AM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

1/14/2025 10:08:10 AM PDT