



2019 International HX

Test Information

Engine	Cummins X15 Signature (15.0)
Engine Serial	CMMNS*6X3u17D1500000000*80099215*0000000000
VIN	3HSDPAPT0KN611246
Driveline	Class 8 6x4
Body	Truck-Tractor MDHD: Conventional
Test Time	Feb. 3, 2026, 2:09 p.m.
File Length	53.27 s

Usage

Label	Value	Units
Engine Odometer	177,022	mi
Odometer (Instrument Cluster #1)	177,020	mi
Engine Total Hours of Operation	10,221.75	h
Aftertreatment 1 Diesel Particulate Filter Soot Load Percent	19	%

Engine On/Off

Engine running

Check Engine Light



MIL - Emissions malfunction

Emissions Deleted/Tampered

No

Faults

<u>DM</u>	<u>Controller Name</u>	<u>SPN Name</u>	<u>FMI Name</u>	<u>Count</u>
Active	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 State	Voltage Above Normal	1
Previous	Engine #1	Aftertreatment SCR Operator Inducement Severity	High-most severe	1
Previous	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Tank Quality	Abnormal Update Rate	1
Previous	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Tank Volume	Abnormal Update Rate	1
Previous	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature 1	Abnormal Update Rate	1
Previous	Brakes - System Controller	J1939 Network #1. Primary Vehicle Network	Erratic, Intermittent, or Incorrect	127
Previous	Instrument Cluster #1	Illumination Brightness Percent	Voltage Below Normal	33
Previous	Instrument Cluster #1	Transmission Oil Temperature 1	Voltage Above Normal	126
Previous	Instrument Cluster #1	Brake Secondary Pressure	Voltage Below Normal	10
Previous	Instrument Cluster #1	Brake Primary Pressure	Voltage Below Normal	1
Previous	Instrument Cluster #1	Source Address 11	Abnormal Update Rate	1
Previous	Instrument Cluster #1	Source Address 0	Abnormal Update Rate	3
Previous	Body Controller	Source Address 0	Data Error	2
Emissions Active	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 State	Voltage Above Normal	1
Emissions Previous	Engine #1	ECU Power Output Supply Voltage #1	Erratic, Intermittent, or Incorrect	1
Emissions Previous	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Tank Quality	Abnormal Update Rate	1
Emissions Previous	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature 1	Abnormal Update Rate	1
Permanent	Engine #1	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 State	Voltage Above Normal	1