



**CERTIFICATE NUMBER**

## Commercial Vehicle Inspection Certificate Traffic Safety Act

### PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

|                                |                          |                       |           |
|--------------------------------|--------------------------|-----------------------|-----------|
| Vehicle Type:                  | Truck                    | Seating Capacity:     |           |
| GVW:                           | 11793 kg                 | Brake Type:           | Hydraulic |
| Owner Name:                    | SOUTHERN CONNECTIONS INC |                       |           |
| Address:                       | 1707 - 19 AVE            |                       |           |
| City:                          | COALDALE                 | Province:             | AB        |
|                                |                          | Postal Code:          | T1M1M5    |
| Telephone Number:              | (403) 795-6622           |                       |           |
| Vehicle Identification Number: | 3C7WRNFL5RG107393        |                       |           |
| Make:                          | Ram                      | Model:                | Chassis   |
| Year:                          | 2024                     | Unit Number:          |           |
| Odometer:                      | 22648 KM                 | Licence Plate Number: |           |
|                                |                          | Province:             | AB        |

**IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE**

### PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

|                                  |                    |
|----------------------------------|--------------------|
| Inspection Facility Name:        | Facility Number:   |
| Caps Diesel & Automotive Ltd     | 15737              |
| Inspection Technician Name:      | Technician Number: |
| Age Dejong                       | A8743              |
| Inspection Technician Signature: | <i>Age Dejong</i>  |
| Inspection Date:                 | 2026/06/17         |

2027/06/17

# COMMERCIAL VEHICLE RECORD OF INSPECTION TRUCK AND TRUCK-TRACTOR

| Section 8 - Body                                                                   |   |   |    |                                       |   |      |
|------------------------------------------------------------------------------------|---|---|----|---------------------------------------|---|------|
| Component                                                                          | P | F | NA | Component                             | P | F NA |
| Vehicle                                                                            |   |   |    |                                       |   |      |
| 8.11. Refrigeration/Heater Unit Fuel System (Reefer or Auxiliary Power Unit (APU)) |   |   | ✓  | 8.24. Aerodynamic Device & Attachment |   | ✓    |

**NOTES:**  
PASSES AT TIME OF INSPECTION

| Section 9 - Tires and Wheels               |   |   |    |                                               |   |      |
|--------------------------------------------|---|---|----|-----------------------------------------------|---|------|
| Component                                  | P | F | NA | Component                                     | P | F NA |
| 9.1. Tire Tread Depth                      | ✓ |   |    | 9.7. Wheel/Rim (Applies to all wheel types)   | ✓ |      |
| 9.2. Tire Tread Condition                  | ✓ |   |    | 9.8. Multi-Piece Wheel/Rim                    |   | ✓    |
| 9.3. Tire Sidewall & Manufacturer Markings | ✓ |   |    | 9.9. Spoke Wheel/Demountable Rim System       |   | ✓    |
| 9.4. Tire Inflation Pressure               | ✓ |   |    | 9.10. Disc Wheel System                       |   | ✓    |
| 9.5. Wheel Hub                             | ✓ |   |    | 9.11. Wheel Fasteners (Nuts, Bolts and Studs) | ✓ |      |
| 9.6. Wheel Bearing                         | ✓ |   |    |                                               |   |      |

**NOTES:**  
MONITOR WHEEL TORQUES AND PRESSURES  
RE-TORQUE ALL WHEELS AT 100km TO 175ft/lbs  
ALL WHEELS BALANCED TO AXLE #1 95psi, AXLE #2 80psi

| Section 10 - Couplers and Hitches                      |   |   |    |                                       |   |      |
|--------------------------------------------------------|---|---|----|---------------------------------------|---|------|
| Component                                              | P | F | NA | Component                             | P | F NA |
| 10.1. Hitch Assembly, Structure & Attaching Components | ✓ |   |    | 10.5. Roll-Coupling Hitch             |   | ✓    |
| 10.2. Secondary Attachment (Safety Chain or Cable)     | ✓ |   |    | 10.6. Automated Coupling Device       |   | ✓    |
| 10.3. Pintle Hook, Pin Hitch, or Coupler Hitch         |   |   | ✓  | 10.7. Fifth Wheel Coupler             |   | ✓    |
| 10.4. Ball Type Hitch                                  |   |   | ✓  | 10.8. Oscillating Fifth Wheel Coupler |   | ✓    |

**NOTES:**  
PASSES AT TIME OF INSPECTION

## Certification

The Vehicle for which this Record of Inspection is issued has **PASSED** (Certificate #8731046) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulation, Alberta Regulation 211/2006 and the applicable Inspection Manual.

| Date of Inspection | Technician Number | Facility Number | Signature                                                                             |
|--------------------|-------------------|-----------------|---------------------------------------------------------------------------------------|
| 2026/06/17         | A8743             | 15737           |  |

## Customer Acknowledgment

I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any Vehicle Inspection Facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)

2026/06/17

Customer Signature





## **Disclaimer**

The information contained in this folder has been provided by the consignor and had not been certified by Ritchie Bros. Auctioneers

Ritchie Bros. Auctioneers in no way certifies the completeness or accuracy of this information

Please inspect the equipment. It is “sold as is” no warranties made or implied

---

Brennan LeBlanc  
Divisional Operations Manager  
Western Canada Agriculture